### District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(505) 393-6161 Fax:(505) 393-0720

<u>District I</u>

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## State of New Mexico

Energy, Minerals and Natural Resources

es

Form C-140 Permit 33634 Revised June 10, 2003

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 (505) 476-3440

# APPLICATION FOR WELL WORKOVER PROJECT

I. Operat	or and Well:									
Operator name & address								OGRID Number		
OCCIDENTAL PERMIAN LTD								157984		
P O BOX 4294										
HOUSTON	TX 772104	1294								
Contact Party								Phone		
Karen Ellis								713-366-5161		
Property Name Well Number								API Number		
NORTH HOBBS G/SA UNIT 441								30-025-05486		
UL - Lot	Section	Town	nship	Range	Feet From The	North/South Line	Feet From The	East/West Lit	ne County	
P 24		13	18S 37E		330	S	330	E	Lea	
II. Works	ver:									
Date Workover Commenced: Previous Producing Pool(s) (Prior to Workover):										
2/6/2006 HOBBS;GRAYBURG-SAN ANDRES										
Date Workover Completed:										
2/10/2006										
IV. Attach follow	a production ding the workow	ecline ci er reflect	nve or tab ing a pos:	ble showing itive product		ths of production pr	ior to the workov	er and at least th	aree months of production	
V. Signat				261						
				Tabana an		y knowledge and be				
Signature	onically	7 Signed		Title Re	gulatory Team L	eader	Date	7/6/2006		
Type or p	rint name <u>E</u> l	lizabetl	h Bush-l	Ivie E	-mail address	Elizabeth_Bush	@oxy.com_Te	lephone No	. 713-366-5303	
This A	IFICATION O application is heap of the production of the productio	F APPF ereby ap biction i	ROVAL: proved ar ncrease. E	nd the above- By copy here		tifies the Secretary o			hereby verifies the data strnent of this Approval and	
Signature I	istrict Sup	erviso	or: Pau	l Kautz		District	l	Date <u>7/6/2</u>	006	

VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT: 7/6/2006

### State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

#### FILE IN TRIPLICATE OIL CONSERVATION DIVISION **DISTRICT I** 1220 South St. Francis Dr. WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-05486 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease 1301 W. Grand Ave, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A NORTH HOBBS (G/SA) UNIT DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 24 1. Type of Well: 8. Well No. 441 Oil Well X Gas Well Other 2. Name of Operator 9. OGRID No. 157984 Occidental Permian Ltd. 3. Address of Operator 10. Pool name or Wildcat HOBBS (G/SA) 1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 4. Well Location Unit Letter P Feet From The SOUTH 330 330 Feet From The **EAST** Line Section 18-S 24 Township Range 37-E **NMPM** County LEA 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3667' GL Pit or Below-grade Tank Application or Closure Depth of Ground Water \_\_ Distance from nearest fresh water well \_\_\_\_ Distance from nearest surface water Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material Pit Liner Thickness 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT **PULL OR ALTER CASING** CASING TEST AND CEMENT JOB Multiple Completion OTHER: OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU. Pull production equipment. 1. Run CNL/GR/CCL from 4296-3296. 2. 3. Perforate the following intervals; 4183-94, 4245-48, and 4267-70 using 2 spf 180 deg sp ph. (40 holes). Stimulate perfs 4222 to 4270 w/3000 g 15% PAD acid in 3 stages using 1000# rock salt as divert. 4. Stimulate perfs 4168-94 w/840 g 15% PAD acid. Run Reda ESP equipment on 127 jts 2-7/8" tbg w/drain valve. Intake set @4111'. 6. Install QCI wellhead connection. NU wellhead. . 7. RDPU. Clean Location. 02/06/2006 Rig Up Date: Rig Down Date: 02/10/2006 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Workover Completion Specialist DATE 02/19/2006 TYPE OR PRINT NAME TELEPHONE NO. Robert Gilbert E-mail address: robert\_gilbert@oxy.com 505/397-8206 For State Use Only APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL IF ANY: