District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(505) 393-6161 Fax:(505) 393-0720

District II

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

I. Operator and Well:

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Form C-140 Permit 42025 Revised June 10, 2003

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 (505) 476-3440

APPLICATION FOR WELL WORKOVER PROJECT

Operator name & address											OGRID Number			
OCCIDENTAL PERMIAN LTD											157984			
PO Box 4294 Houston TX 77210														
		210												
Contact Party Karen Ellis											Phone 713-366-5161			
Property Name Well Number											API Number			
NORTH HOBBS G/SA UNIT 242											30-025-23481			
UL -	Lot S	Section To		wnship Range		Feet From	The No	th/South Line	Feet From T	he East/	East/West Line Coun		y	
N		19	185		38E	420		S 1980			W	Lea		
A-11			W.	-										
=	Workover:		-	D	D - 1 - 1 - D	1/-> /D-1	177 1						-	
Date Workover Commenced: Previous Producing Pool(s) (Prior to Workover): 6/9/2006 HOBBS:GRAYBURG-SAN ANDRES														
	ockover Com	mleted:		HODD	JOIGIL	0100-5711	MINDIG	20						
6/17/2		parties.												
IV.	following the workover reflecting a positive production increase.													
	Signature:													
I hereby	certify that t	he inform	ation ab	ove is tro	e and compl	ete to the best	of my kn	owledge and be	elief.					
Signature Electronically Signed Title Re							Regula	tory Team I	Leader	J	Date	11/20/2006		
Туре	or print	nameEli	izabetl	n Bush-	Ivie E	abeth_Bush	@oxy.com	Telepho	ne No.	713-366-5303	6			
FOR OR	CONSER	ZO TIOM I	тлет	N HOP	DMT 36:									
VI.	CERTIFICA This Applic shows a pos	ATION OI ation is he itive prodi	F APPF reby ap uction i	OVAL: proved an ncrease. I	nd the above- By copy hereo		n notifies					nereby verifies the trnent of this App		
Signati	Signature District Supervisor: Chris Williams								1	_Date	Date 12/7/2006			
VII.	DATE OF 1	NOTIFICA	ATION	то тне	SECRETAL	RY OF THE	TAXATI	ON AND REV	ENUE DEPAR	ETIMENT:	12/7/20	06		

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

DATE

Revised 5-27-2004 FILE IN TRIPLICATE OIL CONSERVATION DIVISION WELL API NO. 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 30-025-23481 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease 1301 W. Grand Ave, Artesia, NM 88210 STATE FEE X DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 19 1. Type of Well: 8. Well No. 242 Oil Well X Gas Well Other 2. Name of Operator 9. OGRID No. 157984 Occidental Permian Ltd. 3. Address of Operator 10. Pool name or Wildcat Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4. Well Location Feet From The 1980 Feet From The West Line Unit Letter N 420 South **NMPM** County Section 19 Township 18-S Range 38-E Lea 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3658' GL Pit or Below-grade Tank Application or Closure -Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water Below-Grade Tank: Volume _____ Pit Liner Thickness mil __ bbls; Construction Material Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data 12. SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT CASING TEST AND CEMENT JOB PULL OR ALTER CASING Multiple Completion OTHER: Open Additional Perfs/Acid Treat OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. Kill well, POOH w/ESP equipment. 2. Drill cement from 4187' to 4200'. Drill out CIBP @4200', fall out to 4220'. Tag on 2nd CIBP @4220'. Start drilling on CIBP. 3. Continue to drill on CIBP @4220'. Push plug to 4235'. CIBP fell out. Drilled out cement stringer from 4290' to 4310', fell out of cement. Tag on CIBP @4350'. 4. RU wireline w/4" cased hole gun & perf @2 jspf, 4142-52', 4157-67', 4195-4205', 4215-32', 4240-47', 4253-66'. 5. Perform 6 stage acid job using 1600 gal 15% HCL & 240 bbl 10# brine. 6. RIH w/pkr. Set @3911'. Pumped scale squeeze using 200 gal NALCO 6490 in 100 bbl fresh water followed by 500 bbl fresh water flush. POOH w/packer & tubing. 7. Run in hole w/ESP equipment on 127 jts of 2-7/8" tbg. Intake set @4070'. 8. RDPU & RU. Clean location. RUPU 06/09/06 RDPU 06/17/06 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 07/06/2006 TELEPHONE NO. 806-592-6280 TYPE OR PRINT NAME E-mail address: Mendy A. Johnson mendy johnson@oxy.com

TITLE

CONDITIONS OF APPROVAL IF ANY:

For State Use Only

APPROVED BY