

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 85655

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NUMBER 30-021-20494
1. Type of Well:C		5. Indicate Type of Lease P
2. Name of Operator HESS CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator P.O. BOX 840 , SEMINOLE , TX 79360		7. Lease Name or Unit Agreement Name MITCHELL
4. Well Location Unit Letter F : 1920 feet from the N line and 1970 feet from the W line Section 9 Township 18N Range 30E NMPM Harding County		8. Well Number 092F
11. Elevation (Show whether DR, KB, BT, GR, etc.) 4345 GR.		9. OGRID Number 495
Pit or Below-grade Tank Application ☐ or Closure ☐		10. Pool name or Wildcat
Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐
Other: **Drilling/Cement** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

10/10/08 spud Mitchell 1830 092F, Rotary Drill to 1030'

10/10/08 WLS @ 164' MIS RUN

10/11/08 rotary drill to 1145' set 8 5/8 csg at 1121' cement, wait on cement nipple up wellhead & BOP, test BOP trip hole

10/12/08 trip, tag cement @ 1070' drill cement float&collar&shoe. Drill 1145' to 1580' circulate. run logs rig up and run csg

10/13/08 run 5 1/2 csg to 1592' cement w/ haliburton Nipple down BOP, set slips, clean mud pits, RD

10/22/08 BOP lub & swab fluid from 1190'

10/26/08 set Arrowset packer @ 1520'

10/27/08 Correlatd Perfs 1455' to 1485' 6 spf @ 60

10/10/2008 Spudded well.

Casing and Cement Program

Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1" Dpth	Pres Held	Pres Drop	Open Hole
10/11/08	Surf	FreshWater	11	8.625	24	J-55	0	1121	470	1.47	prem plus		1000		N
10/13/08	Prod	FreshWater	7.875	5.5	15.5	J-55	0	1592	130	1.85	prem plus		1100		N

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed

TITLE Engineering Tech

DATE 11/21/2008

Type or print name Rita Smith

E-mail address rsmith@hess.com

Telephone No. 432-758-6726

For State Use Only:

APPROVED BY: Ed Martin

TITLE District Supervisor

DATE 1/5/2009 10:59:12 AM