

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720

District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 114663

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NUMBER 30-021-20510
1. Type of Well: C		5. Indicate Type of Lease P
2. Name of Operator HESS CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator P.O. BOX 840, SEMINOLE, TX 79360		7. Lease Name or Unit Agreement Name MITCHELL
4. Well Location Unit Letter <u>G</u> : <u>2310</u> feet from the <u>N</u> line and <u>2150</u> feet from the <u>E</u> line Section <u>23</u> Township <u>18N</u> Range <u>29E</u> NMPM <u>Harding</u> County		8. Well Number 231
11. Elevation (Show whether DR, KB, BT, GR, etc.) 5361 GR		9. OGRID Number 495
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
 Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
 CASING/CEMENT JOB ☐
 Other: **Drilling/Cement** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
 RU, safety meeting rig inspection, spud well, drill, circulate and condition, run surf csg, cement surf csg, test lines, wait on cement, drill plug and cement, circ and condition TOO, run log,
 Run production csg, circ and condition cement production csg, circ cement to surface. Wait on cement,
 Clean pit, ND BOP, RD
 5/15/2010 Spudded well.

Casing and Cement Program

Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1" Dpth	Pres Held	Pres Drop	Open Hole
05/17/10	Surf		12.25	8.625	24	J55	0	1835	600	1.74	C lead				
05/17/10	Surf		12.25	8.625	24	J55	0	1835	200	1.35	C tail				
05/21/10	Prod		7.875	4.5	4.4	IJ	0	3045	135	2.94	C lead				
05/21/10	Prod		7.875	4.5	4.4	IJ	0	3045	355	1.85	midC plus				

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed _____ TITLE Engineering Tech _____ DATE 5/26/2010
 Type or print name Rita Smith _____ E-mail address rsmith@hess.com _____ Telephone No. 432-758-6726

For State Use Only:
 APPROVED BY: Ed Martin _____ TITLE District Supervisor _____ DATE 6/1/2010 1:38:05 PM