

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 115664

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NUMBER 30-021-20513
1. Type of Well: C		5. Indicate Type of Lease P
2. Name of Operator HESS CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator P.O. BOX 840, SEMINOLE, TX 79360		7. Lease Name or Unit Agreement Name WEST BRAVO DOME UNIT
4. Well Location Unit Letter G : 1650 feet from the N line and 1650 feet from the E line Section 19 Township 18N Range 30E NMPM Harding County		8. Well Number 191
11. Elevation (Show whether DR, KB, BT, GR, etc.) 4513 GR		9. OGRID Number 495
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat See Area 13

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐
Other: Perforations/Tubing ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Safety Meeting,

MIRU Schlumberger W/L service. Perforated 5.5" casing [2062'-2078', 2082'-2094'] with 3 3/8", 4 spf, 120° phased guns. Turn over flowing well to productions.

Perforations

Pool: WEST BRAVO DOME CO2 GAS, 96387 Location: G -19-18N-30E 1650 N 1650 E

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
2062	2078		4	3.475			
2082	2094		4	3.475			

Tubing

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed TITLE Engineering Tech DATE 6/14/2010

Type or print name Rita Smith E-mail address rsmith@hess.com Telephone No. 432-758-6726

For State Use Only:

APPROVED BY: Ed Martin TITLE District Supervisor DATE 6/25/2010 1:52:42 PM