

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 1301 W. Grand Avenue, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-06194
1. Type of Well: Oil Well ☐ Gas Well ☐ Other <u>Salt Dome Storage</u>		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator <u>Loco Hills MSF LLC</u>		6. State Oil & Gas Lease No. <u>81-635</u>
3. Address of Operator <u>1231 Old Annette Rd. Aliso Tx 76008</u>		7. Lease Name or Unit Agreement Name: <u>Leonard</u>
4. Well Location Unit Letter <u>L</u> <u>1995</u> feet from the <u>South</u> line and <u>560'</u> feet from the <u>west</u> line Section <u>175</u> Township <u>29E</u> Range <u>NMPM</u> County <u>Sddu</u>		8. Well No. <u>Leonard State #3</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
 TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
 PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
 OTHER: MIT ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- ① Rig up pulling unit
- ② Pull tubing, check for leaks (pressure test)
- ③ Run working string (set packer approx 5' above shoe in casing test @ 350 # for 30 min (chart recorded))
- ④ Pull working string out of hole
- ⑤ Run wires line, locate cavern for changes & depth
- ⑥ Run working string back in hole to approx 600'
- ⑦ Do nitrogen test of cavern @ 300 psi for 4 hrs (chart recorded)
- ⑧ Return cavern for service
- ⑨ Rig pulling unit down

Start date ASAP

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Myron Kimmitt TITLE Terminal Manager DATE 1/25/2021
 Type or print name Myron Kimmitt Telephone No. 575-677-2331
 (This space for State use)

APPROVED BY [Signature] TITLE Staff Manager DATE 2/26/2021
 Conditions of approval, if any:

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 19145

CONDITIONS OF APPROVAL

Operator: LOCO HILLS GSF, LTD 158 Deer Creek Aledo, TX76008				OGRID: 214766	Action Number: 19145	Action Type: C-103R
OCD Reviewer				Condition		
gcordero				None		