

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-37468
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Myox 6 State Com
8. Well Number #12H
9. OGRID Number 229137
10. Pool name or Wildcat Hay Hollow; Bone Spring

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
COG Operating, LLC

3. Address of Operator
2208 W. Main Street Artesia, NM 88210

4. Well Location

Unit Letter **A** : **660** feet from the **N** line and **330** feet from the **E** line
Section **6** Township **26S** Range **28E** NMPM County **Eddy**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3019' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

Notify OCD 24 hrs. prior to any work done

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 60
- Set 5 1/2" CIBP @ 5800'. Circ well w/ MLF. Pressure test csg. Spot ~~25~~ sx cmt @ 5800-5800'. WOC & tag - Must tag @ 5300'
 - Perf & Sqz 60 sx cmt @ 2331-2085'. WOC & Tag (9 5/8" csg & B/Salt)
 - Perf & Sqz 110 sx cmt @ 500' to surface. (T/Salt & 13 3/8" Shoe)
 - Cut off well head, verify cmt to surface, weld on Dry Hole Marker. Must wait 4 hrs after cmt before cut off

Spud Date:

Rig Release Date:

****SEE ATTACHED COA's****

MUST BE PLUGGED BY 3/18/2022

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE: Regulatory Technician

DATE: 3/17/2021

Type or print name: Delilah Flores

E-mail address: Delilah.flores@conocophillips.com

PHONE: 575-748-6946

For State Use Only

APPROVED BY:

TITLE

Staff Manager

DATE

3/18/2021

Conditions of Approval (if any):



CURRENT WELL SKETCH

API: 30-015-37468
 SPUD: 02/09/10 @ 01:00 MST
 FRR: 02/25/10 @ 12:30 MST
 RIG: Patriot #3

Myox 6 State Com #12H
 Hay Hollow, Bone Spring
 Eddy County

Sec 6-26S-28E
 SHL: 660' FNL & 330' FEL
 BHL: 616' FNL & 280' FWL (est.)
 Sec 6-26S-28E
 GL: 3,019'
 KB: 3,036'
 ZERO: 17'

TUBING DETAIL

181 JTS 2 7/8" J-55 NEW TBG
 BHA @5695.16'
 5 1/2" X 2 7/8" 10K AS1-X PKR @5698.21'
 BTM OF PKR @5905.11'

T/Salt@ 450

B/Salt@ 2135

Bell @ 2326

Cherry@ 3243

Brushy@ 5078

B/Sp@ 6058

Average TVD in Lateral 6,404'

KOP @ 5,830'
 EOC @ 8,660'
 EOL @ 10,903'

Surface Casing @ 393'
 13,375" 54.5 ppi H-40 STC
 Circulated 104 sx cement

Intermediate Casing @ 2,281'
 9,625" 36 ppi J-55 BTC
 Circulated 166 sx cement

Production Casing @ 10,903'
 5.5" 17 ppi N-80 LTC
 FC (PBTD) 10,848'
 Notes: 0

Production DV Tool Info:

DV Tool @ 5,867'
 sig 1: 75 sx circulated
 sig 2: 55 sx circulated

32.0771141

-164.1191025

Updated by N. Jancha
 Date: 3/16/2021

HOLE SIZE
 17.5"

MW (ppg)

BHST (F)

Evaluation

No Logs

No Logs

0

0


9.1

7.875"

COG- Proposed

Author:	Abby-BCM & Associates, Inc
Well Name	Myox 6 State Com
Field/Zone	Hay Hollow, Bone Spring
County	Eddy
State	New Mexico
Spud Date	2/9/2010
Well No.	#12H
API #:	30-016-37468
Location	660' FNL & 330' PVL
	6-26S-28E
	3018'
	GL

Description	O.D.	Grade	Weight	Depth	Hole	Cmt Sx	TOC
Surface Csg	13 3/8	H40	48#	393	17 1/2	450	0
Inter Csg	9 5/8	J55	36#	2,281	12 1/4	900	0
Prod Csg	5 1/2	N80	17#	10,903	7 7/8	1,625	0



Formations	
T/Salt	450
B/Salt	2135
Bell	2326
Cherry	3243
Brushy	5078
Bone Spring	6058

13 3/8 CSG @ 393
Hole Size: 17 1/2
3. Perf & Sqz 110 sx cmt @ 500' to surface. (T/Salt & 13 3/8" Shoe)

9 5/8" CSG @ 2,281
Hole Size: 12 1/4
2. Perf & Sqz 60 sx cmt @ 2331-2085'. WOC & Tag (9 5/8" csg & B/Salt)

KOP @ 5830
EOC @ 5660
EOL @ 10,903
TVD @ 6404
1. Set 5 1/2" CIBP @ 5800'. Circ well w/ MLF. Pressure test csg. Spot 25 sx cmt @ 5800-5600'.
DVT @ 5667' Perfs @ TD @ 10,903'

CSG @ 10,903
Hole Size: 7 7/8

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, **Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.**

1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
3. Trucking companies being used to haul oilfield waste fluids to a disposal – commercial or private – shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
8. Produced water **will not** be used during any part of the plugging operation.
9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
11. Class 'C' cement will be used above 7500 feet.
12. Class 'H' cement will be used below 7500 feet.
13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E) Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K) **Potash---** (In the R-111-P Area (Potash Mine Area), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIREMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name 2. Lease and Well Number 3. API Number 4. Unit Letter 5. Quarter Section (feet from the North, South, East or West) 6. Section, Township and Range 7. Plugging Date 8. County (SPECIAL CASES)-----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 21048

CONDITIONS OF APPROVAL

Operator:	COG OPERATING LLC	600 W Illinois Ave	Midland, TX79701	OGRID:	229137	Action Number:	21048	Action Type:	C-103F
OCD Reviewer	Condition								
gcordero	None								