

### U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: SUNDANCE FEDERAL Well Location: T24S / R31E / SEC 4 / County or Parish/State: EDDY /

NENE /

County of Farish/State. LDDT

NM

Well Number: 26 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM104730 Unit or CA Name: Unit or CA Number:

**US Well Number:** 3001533724 **Well Status:** Producing Oil Well **Operator:** OXY USA

INCORPORATED

Accepted for record – NMOCD gc 4/9/2021

### **Notice of Intent**

Type of Submission: Notice of Intent

Type of Action Plug and Abandonment

Date Sundry Submitted: 02/25/2021 Time Sundry Submitted: 05:25

Date proposed operation will begin: 08/07/2021

Procedure Description: see attached procedure.

### **Surface Disturbance**

Is any additional surface disturbance proposed?: No

# **NOI Attachments**

### **Procedure Description**

 $Sundance\_Federal\_26\_Formation\_Tops\_20210225052425.pdf$ 

 $Sundance\_Federal\_26\_Proposed\_Wellbore\_20210208130408.pdf$ 

 $Sundance\_Federal\_26\_PA\_Procedure\_20210208130408.pdf$ 

Sundance\_Federal\_26\_Current\_Wellbore\_20210208130408.pdf

well Name: SUNDANCE FEDERAL Well Location: T24S / R31E / SEC 4 / County or Parish/State: EDDY /

NENE /

Well Number: 26 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM104730 Unit or CA Name: Unit or CA Number:

US Well Number: 3001533724 Well Status: Producing Oil Well Operator: OXY USA

INCORPORATED

# **Conditions of Approval**

# **Specialist Review**

Sundance\_Federal\_26\_PA\_Revised\_Procedure\_20210403103110.pdf

# **Operator Certification**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: JANACEK Signed on: FEB 25, 2021 05:24 AM

Name: OXY USA INCORPORATED

Title: Regulatory Engineer

Street Address: 5 Greenway Plaza, Suite 110

City: Houston State: TX

Phone: (713) 497-2417

Email address: stephen\_janacek@oxy.com

# **Field Representative**

**Representative Name:** 

Street Address:

City: State: Zip:

Phone:

Email address:

# **BLM Point of Contact**

Signature: zota stevens

BLM POC Name: ZOTA M STEVENS BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345998 BLM POC Email Address: ZSTEVENS@BLM.GOV

**Disposition:** Approved **Disposition Date:** 04/03/2021

Dioposition Approved

# Approved BLM procedure

### **Revised Procedure**

- 1.POOH with production equipment. SET CIBP 7804'. DUMP BAIL 35 ft H CMT.
- 2.SPOT 25 SX C CMT 6512'-6225'.
- 3.SPOT 25 SX C CMT 5415'-5127'.
- 4.SPOT 35 SX C CMT 4363'-4012'.
- 5.PERF @ 2000'. SQZ AND CIRC FROM 2000'- SURFACE.
- 10# MLF between plugs. Utilize above ground steel tanks.

# N.M. Oil Cons. DIV-Dist. 2 1301 W. Grand Avenue Artesia, NW 188210 UNITED STATES RTMENT OF THE INTERIOR

Ap	oril 2004)	•		ı		RTME	ENT OF THE	INT		÷.,	A	· .			C	MBNO.	PROVED 1004-0137 rch 31, 200	
***		WELL	COM	/PLE	TION	OR R	ECOMPLE	TÌON	HEROP	J ANE	LOG			ท์	M-104	<u> </u>		
	Type of				_Gas W		Dry Ot	افران	_ <b>*</b>	250	<del></del>	•	)	_			or Tribe N	ame
b.	Type of	Completio	n:	Other	ew Well		Work Over	Deepe	n Plu	g Back	☐ Diff	. Res	SVT, .	7	Unit or	CA Agree	ment Name	and No.
2.		f Operator		. a. C.	omna	<b>~</b> 1/	,		1600					8	. Lease !	Name and	Well No. 7	#2 <i>6</i>
3.	Address	Proc							3a Pho	ne No. (	include ar	ea ce	ode)	8. Lease Name and Well No. Sundance Federal #26 9. AFI Well No.				
		. Box						3a Phone No. (include area code) 432-685-8100					30-015-33724  10. Field and Pool, or Exploratory					
4.							cordance with F FEL, Si			ts)*				ı			•	vare Wes
	At surfa	ice	550				-			<b></b> ,					. Sec., T	, R., M., o	n Block and	1
	At top p	orod. interv	al reporte	ed belov	v	same	<b>!</b>		NFI[	I + N		MIND-Jette		12			/T24S	/R31E
	At total	depth	same	3			•	•		-	, , , ,	Prom			ddy Ć	or Parish Ounty	NM	
14.	Date Sp	oudded 20/04			Date T.I 12/5		ned		16. Date C	ompleted	12/ X Ready	/24	1/04	17	Elevati	ons (DF, F	KB, RT, G	L)*
18	· · · · ·	epth: MI		J	12/3		lug Back T.D.:	MD	<u>L</u> ]D &	X [			roa. ridge Plug	ــــــــــــــــــــــــــــــــــــــ			-	
201		TV		83	50	.,,,		TVD	828	5				-	TVD	)		
<u>21.</u>	Type E	lectric & (	Other Me	chanic	al Logs 1	Run (Su	bmit copy of ea	ich)					ll cored?	K	No _		mit analysi	s)
	HRI	, SDL,	/DSN/	/ML			Was DST run?  Directional Surve							No Yes (Submit report)				
23.		-			ort all s	trings s	et in well)								٠٠	<u>Д</u> (-		
Ho	le Size	Size/Grad	le Wt	. (#/ft.)	Тор	(MD)	Bottom (MD)	, -	Cementer Depth		f Sks. & of Cement	'	Slurry Vol (BBL)	1.	Cement	Top*	Amount	Pulled
<u> 17-</u>	1/2	13-3					1026			1	CIC				surfa			
11_	7/0	8-5. <b>4-</b> 1	/8 3	2 1.6			4210 8350	-		1250 2110		u d&i	4		<u>surfa</u> 2250'			
/_ <del>=</del> _	7/8	4-1		<del></del>			0330			2110	<u> </u>		·		ZZ3U			
_					<del>                                     </del>			ļ				+		_				
24	Tubing	Record			<u> </u>		<b>I</b>	J		<u> </u>				1			<u>l</u>	
	Size	<del></del>	Set (MD	) Pack	er Depth	(MD)	Size	Dept	h Set (MD)	Packer	Depth (MI	D)	Size		Depth	Set (MD)	Packer I	Depth (MD)
<u>2</u> 25.	-3/8 Produc	777 ing Interva		1				26.	Perforation	n Record			•					
_		Formation			To	- 1	Bottom	L,	Perforated		001	Siz			Holes		Perf. Status	
A) B)		_Dela	<u>ware</u>		/8	354	8024	/	854-80	124 (	(A)		$ \frac{2}{}$	25			-	
<u>5</u>																		
D)	Anid E	racture, Tre	- otmoset	Camant	Saucesa													
<u> </u>		epth Interv	al							mount a	nd Type a	f Ma	terial					
						iz w	<u> </u>		/-1/2 16/30			- [	100			FOR I	RECO	RD —
_					FIG	ac w	7 233,00	<u> </u>	10/30	Sand	<u>.                                    </u>	$\dashv$	<u> </u>					
28.	D d		1 4									$\dashv$					225	
D	ate First	Test Date	Hours	Test		Oil BBL	Gas V	Vater	Oil Gra	rvity	Gas		Produc	ction	West of	10 2	005	
2/24		12/28	Tested 24	riodi	uction 1	98		286 286	40.	. 1	Gravi	m)	Pl	ump	oing			1
	hoke ze	Tbg. Press. Flwg. SI	Csg. Press.	24 H Rate	1 :	Oil BBL	Gas \	Water BBL	Gas/Oil Ratio 7 0 4		Well S	Pr	pduc	in	LES IROLE	BABYA UM EN	K GINEEF	₹
		iction - Inte		1	- l.,			r :				-						
	ate First roduced	Test Date	Hours Tested	Test Produ		Oil BBL		Vater BBL	Oil Gra Сотт. А	vity VPI	Gas Gravity	·	Produ	ction	Method			
n		1		1														

28b. Produ	ction - Inte	rval C					<del></del>			
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API	Gas Gravity	Production Method	
Choke Size	Tbg. Press. Flwg.	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas/Oil Ratio	Well Status	<u> </u>	
28c, Prod	uction - Int	erval D		<del> </del>	<del> </del>					·
Date First Produced	Test Date	Hours Tested	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API	Gas Gravity	Production Method	
Choke Size	Tog. Press. Flwg. Sl	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas/Oil Ratio	Well Status	<del></del>	
29. Disp	osition of (	Gas (Sold,	used for fuel,	vented, e	tc.)	<del></del>			<del></del>	
Show	all impor	tant zones	(Include Aq	and conte	nts thereof:	Cored interv	als and all drill-ste and shut-in pressur	m l	tion (Log) Markers	
and r	ecoveries.	т	var iesieu, eu	isinon usca	ı, ume word	pen, nowing	and structin pressur	CS	<del></del>	<del></del>
Form	nation	Тор	Bottom		Desc	criptions, Cont	ents, etc.		Name	Top Meas. Depth
al Anhy aware L l Canyo erry Can izanita ishy Can ie Sprin	ime n yon yon g	4285 4313 5215 5364 6462 8120							_	
X Eld X Su	ectrical/Me indry Notice	chanical L e for plugg	ogs (1 full so	et req'd.) ent verific	ation []	n the appropria Geologic Repo Core Analysis	rt DST Repo			
34. I here	by certify t	hat the for	egoing and a			complete and		ed from all avails	able records (see attached ins	tructions)*
M	(nlage- m-	e i	A- 1.1							
Name	(please pri		Cathy /	Wrigh ///	, ( / -			01/05/05		

# BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the  $90^{th}$  day provide this office, prior to the  $90^{th}$  day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



# United States Department of the Interior

# BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

# Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
  Operations must include adequate measures for stabilization and reclamation of disturbed lands.
  Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
  process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220


Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612 Stephen Janacek

2/5/2021


**Current Wellbore** 


**Sundance Federal #26** 

30-015-33724









Stephen Janacek

2/5/2021


Proposed Wellbore

**Sundance Federal #26** 

30-015-33724

# String 1

Borehole 17.5" Casing 13.325" SA 1026' 900 sxs cmt TOC surface (circ)



Borehole 11" Casing 8.625" SA 4210' 1250 sxs cmt

TOC surface (circ)

String 2

### String 3

Borehole 7.875" Casing 4.5" SA 8350' 2110 sxs cmt TOC 2250' (CBL) Notice of Intent to PA

Sundance Federal #26

30-015-33724

### **Procedure**

10# MLF between plugs. Utilize above ground steel tanks.

POOH with production equipment.

SET CIBP 7804'. DUMP BAIL 5 SX H CMT.

SPOT 25 SX C CMT 6512'-6225'

SPOT 25 SX C CMT 5415'-5127'

SPOT 35 SX C CMT 4363'-4012'

PERF @ 1076'. SQZ AND CIRC 340 SX C CMT TO SURFACE.

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 23206

### **CONDITIONS OF APPROVAL**

Operator:		OGRID:	Action Number:	Action Type:
OXY USA INC P.O. Box 4294	Houston, TX772104294	16696	23206	C-103F

OCD Reviewer	Condition
gcordero	None