Office	Appropriate Distric			New Me				Form C-1831
District I – (575) 39			gy, Minerals	and Natu	ral Resources	WELL API		d July 18, 2013
1625 N. French Dr. <u>District II</u> – (575) 7			CONGERI	ETON	DHUGION	30-025-3004		
811 S. First St., Art	CONSERV			5. Indicate	Type of Lease			
District III – (505) 3 1000 Rio Brazos Ro		10	1220 South			STA		
<u>District IV</u> – (505) 4 1220 S. St. Francis 87505			Santa Fe	e, NM 87	303	6. State Oi	l & Gas Lease No.	
07303	SUNDRY N	NOTICES AND	REPORTS ON	N WELLS		7. Lease N	ame or Unit Agree	ment Name
(DO NOT USE TH DIFFERENT RESE PROPOSALS.)						Grama Ridg		
1. Type of Wel	l: Oil Well	Gas Well	<b>✓</b> Other			8. Well Nu	ımber 1	
2. Name of Open	erator rmian LLC					9. OGRID 372098	Number	
3. Address of C	perator	-				10. Pool na	ame or Wildcat	
5555 San Felipe		ΓX 77056				Grama Ridg	je, Morrow	
4. Well Location Unit Location	Н	1980	feet from the	NORTI	H line and	660 fe	eet from the	AST line
Section	1	8	Township	22S Ra	nge 34E	NMPM	County	LEA
		11. Eleva	ntion (Show wh	nether DR,	RKB, RT, GR	, etc.)		
	12. Che	ck Appropria	te Box to In	dicate Na	ature of Not	ice, Report or 0	Other Data	
4	NOTICE OF	INTENTIO	N TO:	ı	c	NIBSEOLIEN	T REPORT OF	<b>Ξ</b> .
PERFORM REM			ND ABANDON	<b>I</b>	REMEDIAL \			CASING
TEMPORARILY		☐ CHANGE				DRILLING OPNS		
PULL OR ALTE			E COMPL		CASING/CE	MENT JOB		
DOWNHOLE C								
CLOSED-LOOF OTHER:	, 2121FM				OTHER:			
13. Describe							ent dates, including	
		ed work). SEE F r recompletion.	RULE 19.15.7.	14 NMAC	. For Multipl	e Completions: A	ttach wellbore diag	gram of
2. 25sx @ 840 5400'3. 5%% - 520 4. 35sx @ 446 5. 30sx @ 210 6. 30sx @ 114	00' class H cemei 0' 35sx P.S & Tag 85' - 4385'. Tag. 00' - 2000' 42' - 1042' Tag 50 Circ cmt to surl	x Class H. Test to nt g. face. Verify. Cut o			ors			
P&A mud bety	ween all plugs. C	losed loop all fluid	s to license facil	ity.				
4" dia	meter 4' tall	Above Grou	nd Marker			SEE ATTAC	HED CONDITIO	NS
Note	Changes to pr	ocedure						
G 1D .			D: E					
Spud Date:			Rig R	Release Da	te:			
I hereby certify the	hat the informa	tion above is tru	ie and complet	te to the be	st of my know	vledge and belief.		
SIGNATURE	11.1	<i>M</i> .	ТІТІ	_ Regulat	ory Professior	nal	DATE 8/26/202	21
SIGNATURE	Adrian Cova	arruhias			acovarrubia	s@marathonoil.co	m 713-	296-3368
Type or print nar For State Use O	ne		E-ma	ail address			PHONE:	
APPROVED BY Conditions of Ap		1 Forts	TITL	E Comp	oliance Office	er A	DATE 9/8/2	1

## Prior to PAA

MOPLAC

Company:

Lease: Grama Ridge 8

Location:1980'FNL&660FEL,Unit H

Survey:

Ct/St: Lea Co. NM Current Stat.:

WELLBORE DIAGRAM

Well No.: St 1

Sec: 8 Blk: T-22S, R-34E

G.L.: 3566.9' K.B.: 3595' D.F.: DATE: 4-15-20 API # 30-025-30046

Field: Grama Ridge Marrow

Spud :10/3/87 Comp:11/27/87 Initial Form:

Hole Size:

17-1/2"

Surface CSG: Set @: 13-3/8" 48# H-40 ST&C

Circ:

1092' Yes 10-5-87

23/8" tbg 11,332'

Hole Size:

12-1/4" 9-5/8" 3 5261'

Intermed CSG:

9-5/8" 36# & 40# K55

Set@:

Yes 10-15-87

6250' Badspot

Packer@ 11,330' 1.5 profile BP@12,890'

TD @13,570° PB@13,420° Hole Size:

8-1/2"

Long Str. Set @: 7" 26# S-95 LT&C & Seallock

t @:

CMT:

11,550' 375 Sks HLW & 325Sks Cls C 30 min 1500# 11-2-87

**TOC 7000**°

Perfs 27hole,11458'missed,11496',513',527',540'missed,551',556',578',586',598',614',621',630', 660',697',728',748',903',918',933',943',958',967',976',989',12400'missed,12584',

Perfs 13,034',048',207',248',363',

Hole Size:

6-1/8"

Liner:

4-1/2"15.10# P-110 TOL @ 11,217"

Set@: CMT: 13,570"

376Sks Cls H8%Halad 22Mbxed @ 15.6 ppg,

yield 1.18. test to 1800# 11-27-87

MARATHON After PLA

MOPILC

Company:

Lease: Grama Ridge 8

Location:1980'FNL&660FEL,Unit H

Survey:

305X

100-Surt

P.S Varity

305X

353x

H85-4385

TAG

355X PSTAG

1/42-1042

Ct/St: Lea Co. NM

WELLBORE DIAGRAM

Well No.: St 1

Sec: 8 Blk: T-22S, R-34E

G.L.: 3566.9'

K.B.: 3595' D.F.:

DATE: 4-15-20 API#30-025-30046

Field: Grama Ridge Marrow

Spud :10/3/87 Comp:11/27/87 Initial Form:

Current Stat.: DH.M.

Hole Size:

17-1/2"

Surface CSG:

13-3/8" 48# H-40 ST&C

Set @:

1092'

Circ:

Yes 10-5-87

23/8" tbg 11,332'

305x 2100.2000

Hole Size:

12-1/4"

Intermed CSG:

9-5/8" 36# & 40# K55

Yes 10-15-87

Set@:

5261'

---

6250' Badspot

255x @ 8400-8300

Hote Size:

8-1/2"

Long Str.

7" 26# S-95 LT&C & Seallock

Set @:

11,550

CMT:

375 Sks HLW & 325Sks Cls C 30 min 1500# 11-2-87

**TOC 7000**°

Perfs 27hole,11456'missed,11496',513',527',540'missed,551',556',578',586',598',614',621',630', 660',697',728',748',903',918',933',943',958',967',976',989',12400'missed,12584'.

BP@12,890

45 CIBP

W1256X.

P 11,400'

Perfs 13,034',048',207',248',363',

TD @13,570' PB@13,420'

Hole Size:

6-1/8"

Liner:

4-1/2"15.10# P-110 TOL @ 11,217"

Set@:

13,570"

CMT:

376Sks Cls H8%Hatad 22Mbæd @ 15.6 ppg.

yield 1.18, test to 1800# 11-27-87

# CONDITIONS OF APPROVAL FOR PLUGGING AND ABANDONMENT OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office I (Hobbs) at (575)-263-6633 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down.

#### Company representative will be on location during plugging procedures.

- **1.** A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- **2.** Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- **3.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private- shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- **5.** A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can +be released.
- **6.** If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- **8.** Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- **10.** All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- **13.** A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- **14.** All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.
- **16.** When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- **18.** A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).

- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
- A) Fusselman
- B) Devonian
- C) Morrow
- D) Wolfcamp
- E) Bone Springs
- F) Delaware
- G) Any salt sections
- H) Abo
- I) Glorieta
- J) Yates.
- K) Potash---(In the R-111-P Area (Potash Mine Area),

A solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.

**21.** If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing.

### DRY HOLE MARKER REQ.UIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

- 1. Operator name
- 2. Lease and Well Number
- 3. API Number
- 4. Unit letter
- 5. Quarter Section (feet from the North, South, East or West)
- 6. Section, Township and Range
- 7. Plugging Date
- 8. County

#### SPECIAL CASES ----AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

#### SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 44562

#### **CONDITIONS**

Operator:	OGRID:	
MARATHON OIL PERMIAN LLC	372098	
5555 San Felipe St.	Action Number:	
Houston, TX 77056	44562	
	Action Type:	
	[C-103] NOI Plug & Abandon (C-103F)	

#### CONDITIONS

	Created By	Condition	Condition Date
ĺ	kfortner	See attached conditions of approval Note changes to procedure	9/8/2021