ceined w Opp Po Appropriate bistrict 2 1	State of New N	· Iexico	Fe	orm C-103 ¹
Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.	
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION			
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Fr		5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM		STATE FEE 6. State Oil & Gas Lease No.	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Sama PC, WW 67505		o. State Off & Gas Lease No.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name		
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		8. Well Number	
2. Name of Operator	Gas well Uther		9. OGRID Number	
3. Address of Operator			10. Pool name or Wildcat	
4. Well Location Unit Letter :	feet from the	line and	feet from the	line
Section		Range	NMPM County	
<u> </u>	11. Elevation (Show whether D		<u> </u>	
		,,,,		
	ork). SEE RULE 19.15.7.14 NM		nd give pertinent dates, including eompletions: Attach wellbore diagr	
pud Date: hereby certify that the information and an angle of the company of the		best of my knowled	-	
For State Use Only	E-mail addre	ess:	PHONE:	
APPROVED BY:	TITLE		DATE	
- ·				

Apache

CTI Procedure


Date: September 2, 2021

Subject: NEDU 614 CTI


Procedure

- 1. RU WSU, ND WH and NU BOP.
- 2. PU workstring and catch fish 5,608' and POOH with TBG fish.
- 3. RU air-foam unit and MU bit and RIH to cleanout to PBTD (6,865'), POOH.
- 4. MU bit and scraper and clean casing out to PBTD, stand back workstring and prep for casing run.
- 5. RU casing crew and RIH with 4.5" flush joint liner and land casing at 6,850'.
- 6. RU cementers and pump primary liner cement job. RD cementers and WOC.
- 7. RIH w/bit and drill out cement to casing shoe, POOH WS.
- 8. RU WL and perforate 4.5" liner from 6,470'-6,662'.
- RIH w/WS and treatment packer and acidize perforations w/10,000 gals HCL and ball sealers.
 POOH LD WS.
- 10. RIH w/new 1505 IPC 2-3/8" J-55 TBG and injection packer and set at 6,420'
- 11. RDMO WSU and turn well to injection

Current WBD



Proposed WBD



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 47398

CONDITIONS

-	Operator:	OGRID:			
	APACHE CORPORATION	873			
	303 Veterans Airpark Ln	Action Number:			
	Midland, TX 79705	47398			
		Action Type:			
		[C-103] NOI Workover (C-103G)			

CONDITIONS

Created By	Condition	Condition Date
pkautz	None	9/14/2021