Received by Opp Po Appropriate Bistrict O	:26 PM Si	tate of New Me	exico		Form C-103 ¹
<u>District I</u> – (575) 393-6161	Energy, M	inerals and Natu	ral Resources	*******	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283				WELL API NO. 30-015-21	
811 S. First St., Artesia, NM 88210		NSERVATION		5. Indicate Type	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410) South St. Fran		STATE	FEE
<u>District IV</u> – (505) 476-3460	S	anta Fe, NM 87	7505	6. State Oil & C	Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505					
	TICES AND REPO	RTS ON WELLS		7. Lease Name	or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPERTY DESCRIPTION OF THE PROPERTY				T 11011	
DIFFERENT RESERVOIR. USE "APP! PROPOSALS.)	LICATION FOR PERM	II (FORM C-101) FC	JK SUCH	Todd State 2	
1. Type of Well: Oil Well	Gas Well 🔲 O	ther		8. Well Number	001
2. Name of Operator				9. OGRID Num	ıber
Chevron U.S.A INC. 3. Address of Operator				10. Pool name o	or Wildoot
6301 Deauville BLVD, Mi	dland TY 7070	16			Delaware (33745)
4. Well Location	ulariu, IX 1910	, o		iligie vvelis, i	Delaware (33743)
Unit Letter F	. 1980 feet fr	om the NORTH	l line and 198	30 feet fr	om the WEST line
Section 2			nge 31E	NMPM	County EDDY
Section Z			RKB, RT, GR, etc.		County EDD1
	3475' GR	5.10 // //	11112, 111, 311, 6161,	_	
12. Check	Appropriate Bo	x to Indicate N	ature of Notice,	Report or Othe	r Data
NOTICE OF			0115		EDODT OF
NOTICE OF I PERFORM REMEDIAL WORK	INTENTION TO PLUG AND AB			SEQUENT RI	
TEMPORARILY ABANDON			REMEDIAL WORK COMMENCE DRII		ALTERING CASING ☐ P AND A ☑
PULL OR ALTER CASING [CASING/CEMENT		I AND A
DOWNHOLE COMMINGLE			O/ (OII (O/ OEIVIEI (
	<u>.</u>				
OTHER:			OTHER:		
13. Describe proposed or con					
of starting any proposed of proposed completion or r		19.15.7.14 NMAC	C. For Multiple Con	npletions: Attach	wellbore diagram of
proposed completion of r	ecompletion.				
12/1/2021: Tag CIBP at 7143'. P	ump 39 sacks c	lass C cement	from 7143' to 69:	28'	
12/2/2021: Tag TOC @ 6900'. S	pot 56 sacks cla	ss C cement fr	om 6584' to 6434	4'. 4000 Oille ent (O
Spot 43 sacks class C cement fr no injection. Drop down to 4530'					Jordero perforate at 4480
12/3/2021: Tag TOC at 3936'. R					200' to 895'.
12/9/2021: Cut 7-5/8" casing at 8	300' and lay dow	n same. ·			
12/10/2021: RIH with 10-3/4" scr					
12/11/2021: Test CIBP, casing to	o 1000 psi - goo	d. Spot 400 sad	cks Class C from	800' to surfac	e.
					ging of well bore only. Liability under
					ending Location cleanup & receipt of nt Report of Well Plugging) which
Spud Date:		Rig Release Da	ite:		CD Web Page, OCD Permitting @
<u> </u>				<mark>www.emnrd.state.</mark>	nm.us
I hereby certify that the information	n above is true and	complete to the be	est of my knowledge	and belief.	
SIGNATURE HOURS, THE	Tikadanin	_{TITLE} Engir	neer	Г	OATE 12/14/2021
SIGNATURE 7 rages 17	<u>aconeurp</u>	IIILE9			
SIGNATURE Hayes The Type or print name	oodeaux	E-mail address	: Hayes.thibodeaux@	ochevron.com P	HONE: 281-726-9683
For State Use Only					
ADDROVED BY A 24		TITLE	St 1171	r	ATE 12/15/2021
APPROVED BY:Conditions of Approval (if any):	- Common of the	IIILE	Staff Man	agerD	ATE 12/15/2021



EMC Ops Summary - External

TODD '2' STATE 001						Delaware Basin	
Business Unit EMC						Surface UWI 3001521497	
Basic Well Data							
Current RKB Elevation 3,498.00, 9/30/2009		Original RKB Elevation (ft) 3,498.00				Longitude (°) 103° 45' 0.972" W	
Phases							
Actual Start Date	Actual E	nd Date	Phase 1	Phase 2	Time Lo	g Hrs (hr)	Percent Problem Time (%)
8/24/2021 07:00	8/24/2021 12	2:00	PREP	FAC		5.00	
12/1/2021 07:30	12/1/2021 12	2:00	MOB	MOVEON		4.50	
12/1/2021 12:00	12/3/2021 19	9:30	ABAN	CMTPLUG		28.00	10.71
12/8/2021 09:00	12/8/2021 17	' :00	MOB	MOVEON		8.00	
12/8/2021 17:00	12/11/2021 0	7:00	ABAN	CSGPULL		19.50	
12/11/2021 07:00	12/11/2021 1	5:30	ABAN	CMTPLUG		8.50	
			REST	FAC			
			RECLA	FAC			

Rpt # 1, 8/24/2021

HSE meeting, hazard hunt, wellhead gas/pressure check, dig plan review, unload equipment, remove disconnected flow line from location, hand dig around wellhead to expose risers, remove old plumbing, make up new assemblies, install new valves and color code them, backfill excavation, back drag location with backhoe, complete the job, load & secure equipment.

Rpt # 2, 12/1/2021

Arrive on location, hold safety meeting JSA tenet # 1. Check location and well For PSI and Gas Production casing 0 PSI No Gas. Inter casing 0 PSI, showed LEL O/L and CO 15 PPM, Surface casing 0 PSI showed LEL 11% and CO 7 PPM. Rig up equipment install injection head to BOPE. Test BOPE 250 low 1000 high. RIH with 1 1/2" coil loading hole as we RIH. Test casing test good. Tag CIBP at 7143'. Pump 39 sacks class C cement from 7143' to 6928' pulling out of the hole. Wash all equipment. Secure well EOT

Arrive on location, hold safety meeting JSA tenet # 2. Check location and well had LEL only no PSI. Install injection head and BOPE on well. RIH with 1 1/2" coil tubing Tag TOC @ 6900' Pump 100 bbl salt gel. spot 56 sacks class C cement from 6584' to 6434' Pull up to 5353' spot 43 sacks class C cement from 5353' to 5203'. Wash up equipment, call New Mexico OCD talked to Gilbert Cordero about the plan forward to shot perfs at 4480 and attempt to squeeze cement out Gilbert approved the plan forward, wait on Apollo. Apollo arrived with TCP set up and made up TCP RIH to 4480' shot TCP. Attempt to establish njection well pressured up 1250' held with no bleed off. Drop down to 4530' spot 100 sacks class C cement from 4530 to 3978'. wash up equipment. Put 1000 PSI on well Secure well EOT

Rpt # 4, 12/3/2021

Apollo Arrived on location hold safety meeting JSA Tenet # 3. Check location and well Bleed off Pressure from cement job the day before no other pressures no gas. Intermediate and surface casing was bubbling test failed. Rig up Logging equipment RIH tag TOC @ 3936' Do bond log to surface with 0 PSI on well. RIH with bond logging tools to TOC 3936' Do log from TOC to surface with 1000 PSI on well rig down Apollo wire line. Coil crew arrived on location hold safety meeting JSA tenet #3. Rig up to intermediate casing and surface casing Pump into the intermediate casing holding 300 PSI. pump into the surface casing Bleeding off to 250 PSI from 500 PSI. Call NMODC and get plan forward approved with Gilbert Cordero with the NMODC. Set up and RIH with 2" TCP shot holes at 800' establish circulation inside the Intermediate casing. RIH to spot salt gel. Spot salt gel Pull up to 1200 Spot 63 sacks class C cement from 1200' to 895'. Pull up to 810' circulate coil clean and up between production and intermediate casing. POOH with 1/12' coil. rig down coil Secure well EOT.

Rpt # 5 , 12/8/2021

Traveled Rig and Cementing Eq. from Pardue 27-4 to Loc. JSA SWC SIF. Prep wellhead botls on Intermediate Casing. MIRU Rig and Eq.

Rpt # 6, 12/9/2021

Held jsa safety meeting. Check pressure on well and flow down. Do bubble test on surface and intermediate for 30 minutes, intermediate failed. Rig up ubricator. Run wire line and cut 7 5/8 casing with jet cutter at 800 then pull out of hole. Rig down lubricator. Nipple down bsection. Pick up 7 5/8 spear and pull slips and land casing. Nipple up 11 in bop. Rig up floor and tools. Pull lay down 20jts and a piece of 7 5/8. Change out tools to 2 7/8. Shut in and secure well, held debrief meeting.

Rpt # 7, 12/10/2021

Held jsa safety meeting. Check pressure on well. Move casing and tubing around. Tally pipe. Pick up 10 3/4 scrapper with tubing. Run 25 jts 2 7/8 and tag depth 800. Pull stand back all tubing and lay down scrapper. Rig up lubricator. Pick up 10 3/4 cibp and set at 800 then pull out of hole. Rig down lubricator. Shut n and secure well due to strong winds, held debrief meeting.


Rpt # 8 . 12/11/2021

Held jsa safety meeting. Check pressure on well and perform bubble test. Trip in tubing 25 jts 2 7/8 depth 800. Circulate well clean. Pressure test 1000 psi for 15 minutes. Bubble test for 30 minutes. Circulate well with 400 sacks class C 1.32 at 14.8 lbs till circulate. Pull lay down tubing and top off well. Rig down tools, floor and pump equipment. Rig down service unit. Load equipment and move to next well. Rig up crane and nipple down bop, load and haul off, clean up

Company Confidential - Restricted Released to Imaging: 12/16/2021 2:52:49 PM Page 1/1

Report Printed: 12/14/2021

As Plugged WELLBORE DIAGRAM



Updated by:	Hayes Thibodeaux
Date:	8/31/2021

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 66995

CONDITIONS

Operator:	OGRID:
CHEVRON U S A INC	4323
6301 Deauville Blvd	Action Number:
Midland, TX 79706	66995
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	12/15/2021