
Office  Copy To Appropriate District 8:20	State of New Mexico	Form C-103 of 30
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resou	rces Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 300-025- 30192
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION 1220 State of the First S	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		313857
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO CATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name WEST DOLLARHIDE QUEEN SAND UNIT
PROPOSALS.)  1. Type of Well: Oil Well	Gas Well  Other	8. Well Number 111
Name of Operator     RAM ENERGY LLC		9. OGRID Number 309777
3. Address of Operator		10. Pool name or Wildcat
5100 E. SKELLY DRIVE SUITE	#600, TULSA, OK 74135	DOLLARHIDE QUEEN
4. Well Location	100	C
Unit Letter L:_	460 feet from the W line	
Section 29	Township 24S Range 38E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT, 3186KB	Gr, etc.)
12. Check A	Appropriate Box to Indicate Nature of I	Notice, Report or Other Data
NOTICE OF IN	TENTION TO:	CURSEOUENT DEDORT OF
PERFORM REMEDIAL WORK		SUBSEQUENT REPORT OF:  AL WORK   ALTERING CASING   ALTERING   ALTERING CASING   ALTERING CASING   ALTERING CASING   ALTERING   ALTERING CASING   ALTERING CASING   ALTERING   ALTERING CASING   ALTERING CASING   ALTERING   ALT
TEMPORARILY ABANDON		NCE DRILLING OPNS. PAND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING	CEMENT JOB PNR
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM  OTHER:	□ OTHER:	П
		etails, and give pertinent dates, including estimated date
		ltiple Completions: Attach wellbore diagram of
proposed completion or reco	ompletion.	
HOLD SFTY MTG & JSA SBWO CMT E	DELIVERY MEET & GUIDE CMT TRUCK INTO RAM STAGGING	
UP BEGIN TO REMOVE HEAD EARS 11-12-21	BROKEN ON HEAD CUT HEAD OFF PU ON TBJ RELEASE	TAC CIRC WELL W/ MLF POOH W/ 30 JNTS TBJ CWI SDON
	EMAING TBJ TOTAL OF 112 JNTS MIRU WL RIH W/WL SI W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH	ET CIBP @ 3590' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ W W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT
POOH W/ WL RIH W/ WL PERF @ 52		WINE CELOUIS @ 1020 FOOTHWINE TRIPING TO DOMESTIC SOCIETY
11-13-21 HOLD SFTY MTG & JSA RU PUMP E	IR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500#	# RIH W/ TBJ TO 520' RU PUMP MIX & SPOT 50 SXS CLASS "C" CMT @ 520' TO
SURF WASH UP CMT EQUIP POOH	W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE	
Spud Date:	Rig Release Date:	
Spud Bate.	Mig Release Bute.	
I hereby certify that the information a	above is true and complete to the best of my k	nowledge and belief.
SIGNATURE_Kevin Briceland	<sub>TITLE</sub> Consultant	DATE 1/10/21
Type or print name Kevin Bricela	nd E-mail address: Korice	land@ramenergy.net PHONE: 918-947-6413
For State Use Only	1 4	
APPROVED BY:	TITLE Compliance Of	fficer A DATE_ 4/4/22
Conditions of Approval (if ard):		

#### SAGA WDQSU # 111 WIW

1830' FSL & 460 FWL SEC 29, 724S, R38E, LEA COUNTY, NM West Dollarhide Queen Sand Field



4:33 PM :2/5/02

WDQSU #111 WIW

WDQSU WELL BORE SCHEMATICS.xls

TITLE

Agent

June 24, 1988

DATE \_

SIGNED

WELLB	ORE	DIAC	RAM

# 1 Ll	K.B.ELEV.:  K.B.CORRECTION:  G.L.ELEV.: 3175
HOLE SIZE: 12 1/4 "	85/8" 24 # GRADE SET AT 407 '
HOLE SIZE: 7 1/8"	CEMENT WITH 250 SX
*TOP PERF: 3703.  FIELD: Dollahide Queen  FORMATION: Queen  3769-76	5 2 7
*BOT PERF: 3850   3836-3 3843-56  PBTD:	5½" 17 # GRADE  SET AT 3952'  CEMENT WITH 1150 SX STG
LEASE NAME: WDQ5W  WELLBORE DIAGRAM AS OF DATE: 10-31-88  STATE: NM	SECTION: <u>29</u> /830 F54, 460 FWL  ROYALTY INTEREST:  (INJ) (T/A) (SI)

NO. OF COPIES RECEI		~	RECEIV	ED IIII	E 1000		form C Havine	
SANTA FE					0 1300	Î	50. Indient	'Type of Logsn
FILE			MEXICO OIL CO				State	
U.S.G.S.		WELL COMPL	ETION OR RE	COMPLETI	ON REPORT	AND LOG	_	I & Gus Louse No.
LAND OFFICE							B-9519	
							ידדדדד	
OPERATOR '						ł		
Id. TYPE OF WELL							7. Unit Aug	erement Name
IN THE OF HELL	011	[		7				ollarhide
h ming ag aguin.	. WE	LL WEL	LL UAYL	OTHER	Wtr injec	t. well		Sand Unit
b. TYPE OF COMPL		PLU-	o Dirr.	٦			o, i dim oi	Cacea tacino
WELL X OV	ER DEEP	EN BAC	C DIFF.	OTHER			0 W 11 N	
2. Name of Operator	To.					1	9. Well No.	
Sirgo-Collie	f, Inc.						111	
3. Address of Operator			*	<u>.</u>			10. Field and Pool, or Wildcat	
P. O. Box 35	31. Midland	Texas 79	702				Dollarhide Queen	
4. Location of Well							7/7///	
				•			///////	
UNIT LETTERL	1054750	1830	Sou	th	460		((((((	
UNII CEITEN		PCET	FROM THE	TITITE .	TINTI	PEST FROM	12. County	<del>m:////////////////////////////////////</del>
was Hook was	20	2/5	385				Lea	
THE West LINE OF			cc. 38E NMP Compl. (Ready to		Claustiana (1)	7777777		Elev. Cashinghead
•		- 1	•	1704.7	3175 GR	, 11, 11, 01	1, 416.7 19.	3174
1-18-88 20, Total Depth	1-24-88	jg Back T.D.	11-88	, ,				
20. Total Depth	21. Fit	ig Back 1.D.	Nuny	ple Compl., He		rals   Rotary		Cable Tools
3932						→ ; <sup>0-</sup> -	3952'	
14. Producti Interval(	s), of this comple	tion - Top, Botto	m, Name				2	25. Was Directional Survey
22.5			•			d.		
	Queen						Y	es, attached
26. Type Electric and	Olher Logs Run						27. W	as Well Cored
CNL, CBL							No	
28.		CA	SING RECORD (Re	port oil string	s set in well)			
CASING SIZE	WEIGHT LB.			LE SIZE		NTING RECO	80	AMOUNT PULLED
8-5/8"	24#	407		-1/4"		circ 51		
5-1/2"	17#	3952		-7/8"		circ 52		<del> </del>
J-1/2	1111	3772		770	1150 52,	0110 02	O.A.	
						<del></del>		<del> </del>
20		INCO DECODO						
29.		INER RECORD			30.		IBING RECO	ORD
SIZE	ТОР	воттом	SACKS CEMENT	SCREEN	SIZE	OEP	TH SET	PACKER SET
					2-3/8	" 3600	1	3603'
		V						
31. Perloration Record	(Interval, size and	l number)		32.	ACID, SHOT, F	RACTURE, C	EMENT SQL	JEEZE, ETC.
	•		rok	DEPTH	INTERVAL			D MATERIAL USED
3805-50 <b>'</b>				3805-38	50 t	Acidize	w/ 4000	gal 15% NEFE
		•					-	
3703-72				3703-37	721	Acidize	w/ 4000	gal 15% NEFE
*****				3.03 3.		11010100	,	842 4570 4122
13.			PROF	DUCTION				
Date First Production	Produ	ction Method (Flo	wing, gas lift, pump		d type named		Wall Status	(Prod. or Shut-in)
	1					1		Tribul to Shareny
Date of Test	Hours Tested	Choke Size	Production	QII - Iibl.	(3 h.47)	11 Marson	Tu t	Alex Oil Davis
		Chicke State	Test Period		Gus MC	, "Gler	131/1.	Gas Oil Rollo
New Tubles Deser	Contactor			<u></u>				
low Tubing Press.	Casing Pressure	Calculated 24	i- OII — 1361.	Cus - 1	SCF W	uter – Bbl.	Oil	Gravity - API (Corr.)
			×:					
4. Disposition of Gas (	Sold, used for fue	l, vented, etc.)				Test V	Vitnessed By	1
5. List of Attachments								
CNL, CBL, Deviation report								
6. I hereby certify that the information shown on both sides of this form is true and complete to the best of my knowledge and belief.								
- ••							2 w. 114 p	
1	91	16.+1.		_	_			0/ 1000
SIGNED	regide U	Uhitle	TITLE	Agen	<u>t</u>		DATE _ J	une 24, 1988
			1				F	/

# COTTON OILFIELD SERVICES

CALHOUN, La

#### DAILY ACTIVITY REPORT

RAM ENERGY LLC WDQSU # 128 LEA COUNTY, NM API # 30-025-30290

8-18-21

ROAD RIG & EQUIPMENT TO LOCATION SPOT RIG, BASEBEAM & CMT PUMP MIXER COMBO PACKAGE ONTO LOCATION RU PUMP & PUMP LINES HOLD SFTY MTG & JSA HAUL IN CMT UNLOAD CMT RU UNIT OPEN WELL UP ND WELL PU ON TBJ RELEASE PKR POOH W/PKR PKR DRAGGING ALL THE WAY OUT NU WELL CONTROL POOH W/TBJ & PKR LD PKR RIH W/TBJ & MECHANICAL SET CIBP TO 3654' RU PUMP SET CIBP RELEASE OFF CIBP CWI SDON

8-19-21

HOLD SFTY MTG & JSA OPEN WELL UP RU PUMP SET CIBP RELEASE OFF CIBP BREAK CIRC CIRC CLEAN MIX & SPOT 25 SXS CLASS "H" CMT @ 3450'-3650' DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' TEST CSG TO 500# MIX & CIRC WELL W / 9.5 PPG MLF DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' MIX & CIRC WELL W / 9.5 PPG MLF POOH W / TBJ MIRU WL RIH W / CIBP SET CIBP @ 2785' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1340' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RIH W / WL VERIFY CMT POOH W / WL CWI SDON

8-20-21

HOLD SFTY MTG & JSA RIH W/WL PERF #@ 460' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 700# RIH W/TBJ TO 464' RU PUMP MIX & SPOT 55 SXS CLASS "H" CMT @ 464' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 135 LEA COUNTY, NM API # 30-025-30295

8-20-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP ND TREE PU ON TBJ RELEASE PKR POOH W/TBJ MIRU WL RIH W/GAUGE RING TO 3533' POOH W/WL RIH & SET CIBP @ 3,533' RIH W/DUMP BAILER SPOT 35' CMT RIH W/TBJ CIRC CLEAN TEST CSG TO 500# MIX & CIRC WELL W/MLF POOH W/TBJ' CWI SDON

8-21-21

HOLD SFTY MTG & JSA OPEN WELL UP MIRU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RIH W/WL VERIFY CMT POOH W/

WL RIH W/WL PERF #@ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 550# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 106 LEA COUNTY, NM API # 30-025-30157

8-22-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP POOH W/TBJ 33 JNTS RIH W/TBJ & CIBP TO 3650' RU PUMP SET CIBP RELEASE OFF CIBP BREAK CIRC CIRC CLEAN MIX & SPOT 25 SXS CLASS "H" CMT @ 3450'-3650' DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' TEST CSG TO 500# MIX & CIRC WELL W/ 9.5 PPG MLF DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/TBJ CWI SDON

8-23-21

HOLD SFTY MTG & JSA OPEN WELL UP MIRU WL RIH W/CIBP SET CIBP @ 2785' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1340' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RIH W/WL VERIFY CMT POOH W/WL RIH W/WL PERF #@ 460' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# CWI SDON

8-24-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/TBJ TO 460' RU PUMP MIX & SPOT 55 SXS CLASS "H" CMT @ 460' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 129 LEA COUNTY, NM API # 30-025-30291

8-24-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL POOH W / 132 JNTS TBJ & PKR LD PKR RIH W / TBJ & CIBP TO 3650' RU PUMP SET CIBP RELEASE OFF CIBP CWI SDON

8-25-21

HOLD SFTY MTG & JSA OPEN WELL UP BREAK CIRC CIRC CLEAN MIX & SPOT 25 SXS CLASS "H" CMT @ 3450'-3650' DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' TEST CSG TO 500# MIX & CIRC WELL W / 9.5 PPG MLF DISPLACE PLUG WASH UP CMT EQUIP POOH TO

3300' MIX & CIRC WELL W / 9.5 PPG MLF POOH W / TBJ MIRU WL RIH W / CIBP SET CIBP @ 2785' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1340' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RIH W / WL VERIFY CMT POOH W / WL RIH W / WL PERF #@ 460' POOH W / WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# CWI SDON

8-26-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/TBJ TO 460' RU PUMP MIX & SPOT 55 SXS CLASS "H" CMT @ 460' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 131 LEA COUNTY, NM API # 30-025-30293

8-26-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL POOH W / 132 JNTS TBJ & PKR LD PKR RIH W / 50 JNTS TBJ CWI SDON

8-27-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3580' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/TBJ BREAK CIRC CIRC CLEAN TEST CSG TO 500# MIX & CIRC WELL W/9.5 PPG MLF POOH W/TBJ RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

8-30-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 06 LEA COUNTY, NM API # 30-025-12263

8-30-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 132 JNTS TBJ & PKR LD PKR CWI SDON

8-31-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3580' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-1-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 50 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 155 LEA COUNTY, NM API # 30-025-30780

9-1-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 119 JNTS TBJ & PKR LD PKR CWI SDON

9-2-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-3-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 550# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU# 132 LEA COUNTY, NM

#### API#30-025-30294

9-3-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 122 JNTS TBJ & PKR LD PKR CWI SDON

9-7-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-8-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 130 LEA COUNTY, NM API # 30-025-30292

9-8-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT PU ON TBJ UN-SET PKR CIRC WELL W / MLF POOH W / TBJ TOTAL OF 122 JNTS CWI SDON

9-9-21

HOLD SFTY MTG & JSA MIRU WL RIH W/WL SET CIBP @ 3580' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 103 LEA COUNTY, NM API # 30-025-30154 9-10-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 122 JNTS TBJ & PKR LD PKR CWI SDON

9-11-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-13-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 102 LEA COUNTY, NM API # 30-025-30172

9-13-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP RU ROD EQUIP PU ON RODS UN-SEAT PUMP POOH W/  $145\,\mathrm{RODS}$  CWI SDON

9-14-21

HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 120 JNTS TBJ & SN RIH W / WL SET CIBP TO 3600' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL CWI SDON

9-15-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 79 LEA COUNTY, NM API # 30-025-30002 9-15-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP CWI SDON

9-16-21

HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 116 JNTS TBJ & SN RIH W / WL SET CIBP TO 3550' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL CWI SDON

9-17-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 550# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 77 LEA COUNTY, NM API # 30-025-30000

9-20-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON RODS RODS STUCK WORK RODS RU BACK-OFF TOOL BACK RODS OFF POOH W/90 RODS RD ROD EQUIP RU FOR TBJ PU ON TBJ POOH W/85 JNTS TBJ CWI SDON

9-21-21

HOLD SFTY MTG & JSA OPEN WELL UP BEGIN STRIPPING RODS & TUBING SWITCHING BACK & FORTH FROM ROD EQUIP TO TBJ EQUIP FINISH STRIPPING RODS & TBJ OUT OF THE HOLE NU WELL CONTROL RIH W/WL SET CIBP TO 3550' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/TBJ BREAK CIRC TEST TBJ TO 500# CIRC WELL CLEAN CIRC W/MLF POOH W/TBJ TEST CSG TO 500# POOH W/30 JNTS CWI SDON

9-22-21

HOLD SFTY MTG & JSA OPEN WELL UP POOH W/ REMAINING TBJ RU WL RIH W/ CIBP SET CIBP @ 2760' POOH W/ WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/ WL SBWOC RU CIBP RIH W/ WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/ WL RU BAILER & CMT RIH W/ BAILER & CMT DUMP 35' CMT POOH W/ WL RIH W/ WL VERIFY CMT POOH W/ WL & PERF @ 520' POOH W/ WL CWI SDON

9-23-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 153 LEA COUNTY, NM API # 30-025-30357

9-23-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 115 JNTS TBJ & PKR LD PKR CWI SDON

9-24-21

HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 116 JNTS TBJ & SN RIH W / WL SET CIBP TO 3550' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL CWI SDON

9-27-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 12 LEA COUNTY, NM API # 30-025-12271

9-27-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 117 JNTS TBJ & PKR LD PKR CWI SDON

9-28-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3550' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL WASH UP CMT EQUIP CWI SDON

9-29-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU # 101 LEA COUNTY, NM API # 30-025-12271

9-29-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 115 JNTS TBJ & PKR LD PKR CWI SDON

9-30-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3550' POOH W/ WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-1-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU # 21 LEA COUNTY, NM API # 30-025-12270

10-01-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 122 JNTS TBJ & PKR LD PKR CWI SDON

10-02-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP WASH UP CMT EQUIP CWI SDON

10-04-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

### WDQSU # 08 LEA COUNTY, NM API # 30-025-12261

10-04-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/  $9.5\,\mathrm{PPG}$  MLF CWI SDON

10-05-21

HOLD SFTY MTG & JSA OPEN WELL UP POOH W / 122 JNTS TBJ RIH W / WL SET CIBP TO 3580' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL & PERF @ 520' POOH W / WL CWI SDON

10-06-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 90 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

### WDQSU # 81 LEA COUNTY, NM API # 30-025-30011

10-06-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON RODS UN-SEAT PUMP POOH LAYING DOWN 136 RODS CWI SDON

10-07-21

HOLD SFTY MTG & JSA RU FOR TBJ OPEN WELL UP RU FLOOR & TONGS WORK TO UN-SET TAC CNT TO WORK STUCK TAC WORK TAC FREE RU PUMP BREAK CIRC CIRC CLEAN CIRC WELL W/ MLF POOH W/ 112 JNTS TBJ RIH W/WL SET CIBP TO 3600' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL TEST CSG TO 500# CWI SDON

10-08-21

HOLD SFTY MTG & JSA RUWL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RUBAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RUCIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RUBAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-11-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU # 75 LEA COUNTY, NM API # 30-025-29984

10-11-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON RODS UN-SEAT PUMP POOH LAYING DOWN 141 RODS CWI SDON

10-12-21

HOLD SFTY MTG & JSA RU FOR TBJ OPEN WELL UP RU FLOOR & TONGS WORK TO UN-SET TAC WORK TAC FREE RU PUMP BREAK CIRC CIRC CLEAN CIRC WELL W/MLF POOH W/ 125 JNTS TBJ RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# CWI SDON

10-13-21

HOLD SFTY MTG & JSA RU WL RIH W/ CIBP SET CIBP @ 2760' POOH W/ WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/ WL SBWOC RU CIBP RIH W/ WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/ WL RU BAILER & CMT RIH W/ BAILER & CMT DUMP 35' CMT RIH W/ WL VERIFY CMT POOH W/ WL & PERF @ 520' POOH W/ WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/ TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/ TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

## WDQSU # 152 LEA COUNTY, NM API # 30-025-30358

10-14-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 135 JNTS TBJ & PKR LD PKR CWI SDON

10-15-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-18-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU # 18 LEA COUNTY, NM API # 30-025-12257

10-18-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 118 JNTS TBJ & PKR LD PKR CWI SDON

10-19-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3520' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-20-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 43 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 74 LEA COUNTY, NM API # 30-025-29983

10-20-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 50 JNTS TBJ & PKR LD PKR CWI SDON

10-21-21

HOLD SFTY MTG & JSA OPEN WELL UP CNT TO POOH W/TBJ TOTAL OF 112 JNTS LD BHA RIH W/WL SET CIBP TO 3472' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT

POOH & SET CIBP @ 1320' POOH W/ WL RU BAILER & CMT RIH W/ BAILER & CMT DUMP 35' CMT POOH W/ WL CWI SDON

10-22-21

HOLD SFTY MTG & JSA RIH W/WL VERIFY CMT POOH & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU # 113 LEA COUNTY, NM API # 30-025-30231

10-25-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ TRY TO RELEASE PKR HAVING TROUBLE W/ RELEASING PKR BEAT ON PKR RU TONGS CNT TO WORK PKR WORK PKR FREE NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 110 JNTS TBJ & PKR LD PKR RIH W/ 15 JNTS FOR KILL STRING CWI SDON

10-26-21

HOLD SFTY MTG & JSA SBWO CMT DELIVERY MEET & GUIDE CMT TRUCK INTO RAM STAGGING AREA UN-LOAD CMT @ STAGGING YARD REPLACE VALES & SEATS IN TRI-PLEX PUMP SBWO WL FOR CIBP'S MIRU WL RIH W/WL SET CIBP @ 3487' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RU PUMP TEST CSG TO 500# CWI SDON

10-27-21

HOLD SFTY MTG & JSA MIRU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RE-HEAD WL RE-DRESS SETTING TOOL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL CWI SDON

10-28-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 24 LEA COUNTY, NM API # 30-025-12276 10-28-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ TRY TO RELEASE PKR HAVING TROUBLE W/RELEASING PKR BEAT ON PKR RU TONGS CNT TO WORK PKR WORK PKR FREE NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/9.5 PPG MLF POOH W/112 JNTS TBJ & PKR LD PKR MIRU WL RIH W/WL SET CIBP @ 3470' POOH W/WL RIH W/WL DUMP 35' CMT RIH W/15 JNTS FOR KILL STRING CWI SDON

10-29-21

HOLD SFTY MTG & JSA RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 45 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ CWI SDON

WDQSU#111 LEA COUNTY, NM API#30-025-30192

11-11-21

HOLD SFTY MTG & JSA SBWO CMT DELIVERY MEET & GUIDE CMT TRUCK INTO RAM STAGGING AREA UN-LOAD CMT @ STAGGING YARD MIRU UNIT & CMT EQUIP OPEN WELL UP BEGIN TO REMOVE HEAD EARS BROKEN ON HEAD CUT HEAD OFF PU ON TBJ RELEASE TAC CIRC WELL W/MLF POOH W/30 JNTS TBJ CWI SDON

11-12-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 112 JNTS MIRU WL RIH W/ WL SET CIBP @ 3590' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

11-13-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 50 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 72 LEA COUNTY, NM API # 30-025-29964 11-15-21

MIRU UNIT & CMT EQUIP HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ RELEASE TAC CIRC WELL W/ MLF POOH W/ 110 JNTS TBJ MIRU WL RIH W/ WL SET CIBP @ 3472' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL CWI SDON

11-16-21

HOLD SFTY MTG & JSA RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT SDON

WDQSU # 110 LEA COUNTY, NM API # 30-025-30287

11-17-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT UN-SET PKR CIRC WELL W/MLF PU ON TBJ POOH W/ 25 JNTS TBJ CWI SDON

11-18-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 111 JNTS MIRU WL RIH W/ WL SET CIBP @ 3556' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

11-19-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 137 LEA COUNTY, NM API # 30-025-30275

11-23-21

MIRU UNIT & CMT EQUIP HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ RELEASE PKR CIRC WELL W/MLF POOH W/ 114 JNTS TBJ MIRU WL RIH W/WL SET CIBP @ 3472' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT POOH W/WL CWI SDON

11-24-21

HOLD SFTY MTG & JSA RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT SDON

WDQSU # 25 LEA COUNTY, NM API # 30-025-12275

11-29-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT UN-SET PKR CIRC WELL W/MLF PU ON TBJ POOH W/35 JNTS TBJ CWI SDON

12-01-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 116 JNTS MIRU WL RIH W/ WL SET CIBP @ 3555' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

12-02-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 99 LEA COUNTY, NM API # 30-025~30144

12-02-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 149 RODS UN-SET TAC CIRC WELL W / MLF PU ON TBJ POOH W / 15 JNTS TBJ CWI SDON

12-03-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 120 JNTS MIRU WL RIH W/ WL SET CIBP @ 3575' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

12-04-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 45 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 47 LEA COUNTY, NM API # 30-025-12290

12-04-21

HOLD SFTY MTG & JSA CLEAR LOCATION FOR EQUIPMENT TO BE MOVED IN MOVE CMT PUMPING UNIT PAD MIRU ALL EQUIPMENT PU ON TBJ UN-SET PKR CIRC WELL W/MLF POOH W/85 JNTS TBJ CWI SDON

12-06-21

POOH W/ REMAING TBJ TOTAL OF 119JNTS HOLD SFTY MTG & JSA MIRU WL RIH W/WL POOHW/WL RIHW/ SET CIBP @ 3577' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT WL SET CIBP @ 2760' POOH W/ WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/TBJ TO 5620' W/WL PERF@520' POOH W/WL RD RELESE WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RD RELEASE WL CWI SDON

12-07-21

HOLD SFTY MTG & JSA RU PUMP MIX & SPOT 40 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 92 LEA COUNTY, NM API # 30-025-30131 12-07-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 142 RODS UN-SET TAC CIRC WELL W / MLF PU ON TBJ CWI SDON

12-08-21

HOLD SFTY MTG & JSA POOH W/TBJ TOTAL OF 122 JNTS MIRU WL RIH W/WL SET CIBP @ 3487' POOH W/WL RIH W/BAILER & DUMP BAIL 35'CMT POOH W/WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35'CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35'CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL CWI SDON

12-09-21

HOLD SFTY MTG & JSA RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU # 96 LEA COUNTY, NM API # 30-025-30166

12-09-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 50 RODS ROD TONGS MALFUNCTIONED WORK ON TONGS CWI SDON

12-10-21

HOLD SFTY MTG & JSA POOH W/ REMAING RODS TOTAL OF 139 RODS PU ON TBJ UNSET TAC CIRC WELL W MLF POOH W/ TBJ TOTAL OF 122 JNTS MIRU WL RIH W/ WL SET CIBP @ 3487' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT CWI SDON

12-11-21

HOLD SFTY MTG & JSA RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 94 LEA COUNTY, NM API # 30-025-30145 12-12-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT PU ON TBJ RELEASE PKR CIRC WELL W/MLF POOH W/ 112 JNTS TBJ CWI SDON

12-13-21

HOLD SFTY MTG & MIRU WL RIH W/WL SET CIBP @ 3521' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 87 LEA COUNTY, NM API # 30-025-30084

12-14-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT CLEAR LOCATION TO ACCEPT EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 100 RODS CWI SDON

12-15-21

HOLD SFTY MTG & JSA POOH W/ REMAING RODS TOTAL OF 137 RODS PU ON TBJ UNSET TAC CIRC WELL W/ MLF POOH W/ TBJ TOTAL OF 120 JNTS MIRU WL RIH W/ WL SET CIBP @ 3487' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' CWI SDON

12-16-21

HOLD SFTY MTG & JSA RU WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 85 LEA COUNTY, NM API # 30-025-30008

12-16-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT PU ON TBJ UN-SET PKR CIRC WELL W/MLF POOH W/TBJ TOTAL OF 120 CWI SDON

12-17-21

HOLD SFTY MTG & JSA MIRU WL RIH W/WL SET CIBP @ 3612' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' CWI SDON RU WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 35 LEA COUNTY, NM API # 30-025-12289

12-18-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT ND HEAD PU ON TBJ UN-SET PKR CIRC WELL W/MLF POOH W/115 JNTS TBJ MIRU WL RIH W/WL SET CIBP @ 3612' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' RU WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL CWI SDON

12-20-21

HOLD JSA & SFTY MTG RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 40 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT CUT & COVER HEAD

END OF PLUGGING OPERATIONS ON THE WEST DOLLARHIDE QUEEN SANDS UNIT

## COTTON OILFIELD SERVICES

CALHOUN, La

#### DAILY ACTIVITY REPORT

RAM ENERGY LLC WDQSU # 128 LEA COUNTY, NM API # 30-025-30290

8-18-21

ROAD RIG & EQUIPMENT TO LOCATION SPOT RIG, BASEBEAM & CMT PUMP MIXER COMBO PACKAGE ONTO LOCATION RU PUMP & PUMP LINES HOLD SFTY MTG & JSA HAUL IN CMT UNLOAD CMT RU UNIT OPEN WELL UP ND WELL PU ON TBJ RELEASE PKR POOH W/PKR PKR DRAGGING ALL THE WAY OUT NU WELL CONTROL POOH W/TBJ & PKR LD PKR RIH W/TBJ & MECHANICAL SET CIBP TO 3654' RU PUMP SET CIBP RELEASE OFF CIBP CWI SDON

8-19-21

HOLD SFTY MTG & JSA OPEN WELL UP RU PUMP SET CIBP RELEASE OFF CIBP BREAK CIRC CIRC CLEAN MIX & SPOT 25 SXS CLASS "H" CMT @ 3450'-3650' DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' TEST CSG TO 500# MIX & CIRC WELL W / 9.5 PPG MLF DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' MIX & CIRC WELL W / 9.5 PPG MLF POOH W / TBJ MIRU WL RIH W / CIBP SET CIBP @ 2785' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1340' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RIH W / WL VERIFY CMT POOH W / WL CWI SDON

8-20-21

HOLD SFTY MTG & JSA RIH W/WL PERF #@ 460' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 700# RIH W/TBJ TO 464' RU PUMP MIX & SPOT 55 SXS CLASS "H" CMT @ 464' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 135 LEA COUNTY, NM API # 30-025-30295

8-20-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP ND TREE PU ON TBJ RELEASE PKR POOH W/TBJ MIRU WL RIH W/GAUGE RING TO 3533' POOH W/WL RIH & SET CIBP @ 3,533' RIH W/DUMP BAILER SPOT 35' CMT RIH W/TBJ CIRC CLEAN TEST CSG TO 500# MIX & CIRC WELL W/MLF POOH W/TBJ' CWI SDON

8-21-21

HOLD SFTY MTG & JSA OPEN WELL UP MIRU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RIH W/WL VERIFY CMT POOH W/

WL RIH W/WL PERF #@ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 550# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 106 LEA COUNTY, NM API # 30-025-30157

8-22-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP POOH W/TBJ 33 JNTS RIH W/TBJ & CIBP TO 3650' RU PUMP SET CIBP RELEASE OFF CIBP BREAK CIRC CIRC CLEAN MIX & SPOT 25 SXS CLASS "H" CMT @ 3450'-3650' DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' TEST CSG TO 500# MIX & CIRC WELL W/ 9.5 PPG MLF DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/TBJ CWI SDON

8-23-21

HOLD SFTY MTG & JSA OPEN WELL UP MIRU WL RIH W/CIBP SET CIBP @ 2785' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1340' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RIH W/WL VERIFY CMT POOH W/WL RIH W/WL PERF #@ 460' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# CWI SDON

8-24-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/TBJ TO 460' RU PUMP MIX & SPOT 55 SXS CLASS "H" CMT @ 460' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 129 LEA COUNTY, NM API # 30-025-30291

8-24-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL POOH W / 132 JNTS TBJ & PKR LD PKR RIH W / TBJ & CIBP TO 3650' RU PUMP SET CIBP RELEASE OFF CIBP CWI SDON

8-25-21

HOLD SFTY MTG & JSA OPEN WELL UP BREAK CIRC CIRC CLEAN MIX & SPOT 25 SXS CLASS "H" CMT @ 3450'-3650' DISPLACE PLUG WASH UP CMT EQUIP POOH TO 3300' TEST CSG TO 500# MIX & CIRC WELL W / 9.5 PPG MLF DISPLACE PLUG WASH UP CMT EQUIP POOH TO

3300' MIX & CIRC WELL W / 9.5 PPG MLF POOH W / TBJ MIRU WL RIH W / CIBP SET CIBP @ 2785' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1340' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RIH W / WL VERIFY CMT POOH W / WL RIH W / WL PERF #@ 460' POOH W / WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# CWI SDON

8-26-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/TBJ TO 460' RU PUMP MIX & SPOT 55 SXS CLASS "H" CMT @ 460' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 131 LEA COUNTY, NM API # 30-025-30293

8-26-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL POOH W/ 132 JNTS TBJ & PKR LD PKR RIH W/ 50 JNTS TBJ CWI SDON

8-27-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3580' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/TBJ BREAK CIRC CIRC CLEAN TEST CSG TO 500# MIX & CIRC WELL W/9.5 PPG MLF POOH W/TBJ RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

8-30-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 06 LEA COUNTY, NM API # 30-025-12263

8-30-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 132 JNTS TBJ & PKR LD PKR CWI SDON

8-31-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3580' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-1-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 50 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 155 LEA COUNTY, NM API # 30-025-30780

9-1-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 119 JNTS TBJ & PKR LD PKR CWI SDON

9-2-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-3-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 550# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU# 132 LEA COUNTY, NM

#### API#30-025-30294

9-3-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 122 JNTS TBJ & PKR LD PKR CWI SDON

9-7-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-8-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 130 LEA COUNTY, NM API # 30-025-30292

9-8-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT PU ON TBJ UN-SET PKR CIRC WELL W / MLF POOH W / TBJ TOTAL OF 122 JNTS CWI SDON

9-9-21

HOLD SFTY MTG & JSA MIRU WL RIH W/WL SET CIBP @ 3580' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 103 LEA COUNTY, NM API # 30-025-30154 9-10-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 122 JNTS TBJ & PKR LD PKR CWI SDON

9-11-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL CWI SDON

9-13-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 102 LEA COUNTY, NM API # 30-025-30172

9-13-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP RU ROD EQUIP PU ON RODS UN-SEAT PUMP POOH W/  $145\,\mathrm{RODS}$  CWI SDON

9-14-21

HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 120 JNTS TBJ & SN RIH W / WL SET CIBP TO 3600' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL CWI SDON

9-15-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 79 LEA COUNTY, NM API # 30-025-30002 9-15-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP CWI SDON

9-16-21

HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 116 JNTS TBJ & SN RIH W / WL SET CIBP TO 3550' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL CWI SDON

9-17-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 550# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 77 LEA COUNTY, NM API # 30-025-30000

9-20-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON RODS RODS STUCK WORK RODS RU BACK-OFF TOOL BACK RODS OFF POOH W/90 RODS RD ROD EQUIP RU FOR TBJ PU ON TBJ POOH W/85 JNTS TBJ CWI SDON

9-21-21

HOLD SFTY MTG & JSA OPEN WELL UP BEGIN STRIPPING RODS & TUBING SWITCHING BACK & FORTH FROM ROD EQUIP TO TBJ EQUIP FINISH STRIPPING RODS & TBJ OUT OF THE HOLE NU WELL CONTROL RIH W/WL SET CIBP TO 3550' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/TBJ BREAK CIRC TEST TBJ TO 500# CIRC WELL CLEAN CIRC W/MLF POOH W/TBJ TEST CSG TO 500# POOH W/30 JNTS CWI SDON

9-22-21

HOLD SFTY MTG & JSA OPEN WELL UP POOH W/ REMAINING TBJ RU WL RIH W/ CIBP SET CIBP @ 2760' POOH W/ WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/ WL SBWOC RU CIBP RIH W/ WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/ WL RU BAILER & CMT DUMP 35' CMT POOH W/ WL RIH W/ WL VERIFY CMT POOH W/ WL & PERF @ 520' POOH W/ WL CWI SDON

9-23-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 600# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 153 LEA COUNTY, NM API # 30-025-30357

9-23-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 115 JNTS TBJ & PKR LD PKR CWI SDON

9-24-21

HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 116 JNTS TBJ & SN RIH W / WL SET CIBP TO 3550' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL CWI SDON

9-27-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

RAM ENERGY LLC WDQSU # 12 LEA COUNTY, NM API # 30-025-12271

9-27-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 117 JNTS TBJ & PKR LD PKR CWI SDON

9-28-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3550' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL WASH UP CMT EQUIP CWI SDON

9-29-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU#101 LEA COUNTY, NM API#30-025-12271

9-29-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 115 JNTS TBJ & PKR LD PKR CWI SDON

9-30-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3550' POOH W/ WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-1-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

#### WDQSU # 21 LEA COUNTY, NM API # 30-025-12270

10-01-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 122 JNTS TBJ & PKR LD PKR CWI SDON

10-02-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP WASH UP CMT EQUIP CWI SDON

10-04-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

### WDQSU # 08 LEA COUNTY, NM API # 30-025-12261

10-04-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/  $9.5\,\mathrm{PPG}$  MLF CWI SDON

10-05-21

HOLD SFTY MTG & JSA OPEN WELL UP POOH W / 122 JNTS TBJ RIH W / WL SET CIBP TO 3580' POOH W / WL RIH W / WL DUMP BAIL 35' CMT POOH W / WL TEST CSG TO 500# RU WL RIH W / CIBP SET CIBP @ 2760' POOH W / WL RU BAILER RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL SBWOC RU CIBP RIH W / WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W / WL RU BAILER & CMT RIH W / BAILER & CMT DUMP 35' CMT POOH W / WL & PERF @ 520' POOH W / WL CWI SDON

10-06-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 90 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

### WDQSU # 81 LEA COUNTY, NM API # 30-025-30011

10-06-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON RODS UN-SEAT PUMP POOH LAYING DOWN 136 RODS CWI SDON

10-07-21

HOLD SFTY MTG & JSA RU FOR TBJ OPEN WELL UP RU FLOOR & TONGS WORK TO UN-SET TAC CNT TO WORK STUCK TAC WORK TAC FREE RU PUMP BREAK CIRC CIRC CLEAN CIRC WELL W/MLF POOH W/ 112 JNTS TBJ RIH W/WL SET CIBP TO 3600' POOH W/ WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# CWI SDON

10-08-21

HOLD SFTY MTG & JSA RUWL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RUBAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RUCIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RUBAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-11-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

### WDQSU # 75 LEA COUNTY, NM API # 30-025-29984

10-11-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON RODS UN-SEAT PUMP POOH LAYING DOWN 141 RODS CWI SDON

10-12-21

HOLD SFTY MTG & JSA RU FOR TBJ OPEN WELL UP RU FLOOR & TONGS WORK TO UN-SET TAC WORK TAC FREE RU PUMP BREAK CIRC CIRC CLEAN CIRC WELL W/MLF POOH W/ 125 JNTS TBJ RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# CWI SDON

10-13-21

HOLD SFTY MTG & JSA RUWL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

## WDQSU # 152 LEA COUNTY, NM API # 30-025-30358

10-14-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 135 JNTS TBJ & PKR LD PKR CWI SDON

10-15-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3600' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-18-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

## WDQSU # 18 LEA COUNTY, NM API # 30-025-12257

10-18-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W / 9.5 PPG MLF POOH W / 118 JNTS TBJ & PKR LD PKR CWI SDON

10-19-21

HOLD SFTY MTG & JSA OPEN WELL UP RIH W/WL SET CIBP TO 3520' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT POOH & SET CIBP @ 1320' POOH W/WL RU BAILER & CMT RIH W/BAILER & CMT DUMP 35' CMT RIH W/WL VERIFY CMT POOH W/WL & PERF @ 520' POOH W/WL CWI SDON

10-20-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 43 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 74 LEA COUNTY, NM API # 30-025-29983

10-20-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ RELEASE PKR NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 50 JNTS TBJ & PKR LD PKR CWI SDON

10-21-21

HOLD SFTY MTG & JSA OPEN WELL UP CNT TO POOH W/TBJ TOTAL OF 112 JNTS LD BHA RIH W/WL SET CIBP TO 3472' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL TEST CSG TO 500# RU WL RIH W/CIBP SET CIBP @ 2760' POOH W/WL RU BAILER RIH W/BAILER & CMT DUMP 35' CMT POOH W/WL SBWOC RU CIBP RIH W/WL VERFIY CMT

POOH & SET CIBP @ 1320' POOH W/ WL RU BAILER & CMT RIH W/ BAILER & CMT DUMP 35' CMT POOH W/ WL CWI SDON

10-22-21

HOLD SFTY MTG & JSA RIH W/WL VERIFY CMT POOH & PERF @ 520' POOH W/WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

# WDQSU#113 LEA COUNTY, NM API#30-025-30231

10-25-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ TRY TO RELEASE PKR HAVING TROUBLE W/ RELEASING PKR BEAT ON PKR RU TONGS CNT TO WORK PKR WORK PKR FREE NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/ 9.5 PPG MLF POOH W/ 110 JNTS TBJ & PKR LD PKR RIH W/ 15 JNTS FOR KILL STRING CWI SDON

10-26-21

HOLD SFTY MTG & JSA SBWO CMT DELIVERY MEET & GUIDE CMT TRUCK INTO RAM STAGGING AREA UN-LOAD CMT @ STAGGING YARD REPLACE VALES & SEATS IN TRI-PLEX PUMP SBWO WL FOR CIBP'S MIRU WL RIH W/WL SET CIBP @ 3487' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RU PUMP TEST CSG TO 500# CWI SDON

10-27-21

HOLD SFTY MTG & JSA MIRU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RE-HEAD WL RE-DRESS SETTING TOOL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL CWI SDON

10-28-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 60 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 24 LEA COUNTY, NM API # 30-025-12276 10-28-21

MOVE & SPOT BASEBEAM HOLD SFTY MTG & JSA MIRU UNIT OPEN WELL UP PU ON TBJ TRY TO RELEASE PKR HAVING TROUBLE W/RELEASING PKR BEAT ON PKR RU TONGS CNT TO WORK PKR WORK PKR FREE NU WELL CONTROL BREAK CIRC CIRC CLEAN MIX & CIRC WELL W/9.5 PPG MLF POOH W/112 JNTS TBJ & PKR LD PKR MIRU WL RIH W/WL SET CIBP @ 3470' POOH W/WL RIH W/WL DUMP 35' CMT RIH W/15 JNTS FOR KILL STRING CWI SDON

10-29-21

HOLD SFTY MTG & JSA RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 45 SXS CLASS "H" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ CWI SDON

WDQSU # 111 LEA COUNTY, NM API # 30-025-30192

11-11-21

HOLD SFTY MTG & JSA SBWO CMT DELIVERY MEET & GUIDE CMT TRUCK INTO RAM STAGGING AREA UN-LOAD CMT @ STAGGING YARD MIRU UNIT & CMT EQUIP OPEN WELL UP BEGIN TO REMOVE HEAD EARS BROKEN ON HEAD CUT HEAD OFF PU ON TBJ RELEASE TAC CIRC WELL W/MLF POOH W/30 JNTS TBJ CWI SDON

11-12-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 112 JNTS MIRU WL RIH W/ WL SET CIBP @ 3590' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

11-13-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 50 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 72 LEA COUNTY, NM API # 30-025-29964 11-15-21

MIRU UNIT & CMT EQUIP HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ RELEASE TAC CIRC WELL W/MLF POOH W/110 JNTS TBJ MIRU WL RIH W/WL SET CIBP@3472' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT POOH W/WL CWI SDON

11-16-21

HOLD SFTY MTG & JSA RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT SDON

WDQSU# 110 LEA COUNTY, NM API# 30-025-30287

11-17-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT UN-SET PKR CIRC WELL W/ MLF PU ON TBJ POOH W/ 25 JNTS TBJ CWI SDON

11-18-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 111 JNTS MIRU WL RIH W/ WL SET CIBP @ 3556' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

11-19-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 137 LEA COUNTY, NM API # 30-025-30275

11-23-21

MIRU UNIT & CMT EQUIP HOLD SFTY MTG & JSA OPEN WELL UP PU ON TBJ RELEASE PKR CIRC WELL W/MLF POOH W/ 114 JNTS TBJ MIRU WL RIH W/WL SET CIBP @ 3472' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT POOH W/WL CWI SDON

11-24-21

HOLD SFTY MTG & JSA RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT SDON

WDQSU # 25 LEA COUNTY, NM API # 30-025-12275

11-29-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT UN-SET PKR CIRC WELL W/MLF PU ON TBJ POOH W/35 JNTS TBJ CWI SDON

12-01-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 116 JNTS MIRU WL RIH W/ WL SET CIBP @ 3555' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

12-02-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W/TBJ TO 520' RU PUMP MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 99 LEA COUNTY, NM API # 30-025~30144

12-02-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 149 RODS UN-SET TAC CIRC WELL W / MLF PU ON TBJ POOH W / 15 JNTS TBJ CWI SDON

12-03-21

HOLD SFTY MTG & JSA POOH W/ REMAING TBJ TOTAL OF 120 JNTS MIRU WL RIH W/ WL SET CIBP @ 3575' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL PERF @ 520' POOH W/ WL RD RELEASE WL CWI SDON

12-04-21

HOLD SFTY MTG & JSA RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RIH W / TBJ TO 520' RU PUMP MIX & SPOT 45 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W / TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 47 LEA COUNTY, NM API # 30-025-12290

12-04-21

HOLD SFTY MTG & JSA CLEAR LOCATION FOR EQUIPMENT TO BE MOVED IN MOVE CMT PUMPING UNIT PAD MIRU ALL EQUIPMENT PU ON TBJ UN-SET PKR CIRC WELL W/MLF POOH W/85 JNTS TBJ CWI SDON

12-06-21

POOH W/ REMAING TBJ TOTAL OF 119JNTS HOLD SFTY MTG & JSA MIRU WL RIH W/WL POOHW/WL RIHW/ SET CIBP @ 3577' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT WL SET CIBP @ 2760' POOH W/ WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/ WL SET CIBP @ 1320' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/TBJ TO 5620' W/WL PERF@520' POOH W/ WL RD RELESE WL RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# RD RELEASE WL CWI SDON

12-07-21

HOLD SFTY MTG & JSA RU PUMP MIX & SPOT 40 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 92 LEA COUNTY, NM API # 30-025-30131 12-07-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 142 RODS UN-SET TAC CIRC WELL W / MLF PU ON TBJ CWI SDON

12-08-21

HOLD SFTY MTG & JSA POOH W/TBJ TOTAL OF 122 JNTS MIRU WL RIH W/WL SET CIBP @ 3487' POOH W/WL RIH W/BAILER & DUMP BAIL 35'CMT POOH W/WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35'CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35'CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL CWI SDON

12-09-21

HOLD SFTY MTG & JSA RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

# WDQSU # 96 LEA COUNTY, NM API # 30-025-30166

12-09-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 50 RODS ROD TONGS MALFUNCTIONED WORK ON TONGS CWI SDON

12-10-21

HOLD SFTY MTG & JSA POOH W/ REMAING RODS TOTAL OF 139 RODS PU ON TBJ UNSET TAC CIRC WELL W MLF POOH W/ TBJ TOTAL OF 122 JNTS MIRU WL RIH W/ WL SET CIBP @ 3487' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT CWI SDON

12-11-21

HOLD SFTY MTG & JSA RU WL RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 94 LEA COUNTY, NM API # 30-025-30145 12-12-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT PU ON TBJ RELEASE PKR CIRC WELL W/MLF POOH W/ 112 JNTS TBJ CWI SDON

12-13-21

HOLD SFTY MTG & MIRU WL RIH W/WL SET CIBP @ 3521' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 87 LEA COUNTY, NM API # 30-025-30084

12-14-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT CLEAR LOCATION TO ACCEPT EQUIPMENT RU ROD TONGS PU ON RODS UN-SEAT PUMP POOH W / 100 RODS CWI SDON

12-15-21

HOLD SFTY MTG & JSA POOH W/ REMAING RODS TOTAL OF 137 RODS PU ON TBJ UNSET TAC CIRC WELL W/ MLF POOH W/ TBJ TOTAL OF 120 JNTS MIRU WL RIH W/ WL SET CIBP @ 3487' POOH W/ WL RIH W/ BAILER & DUMP BAIL 35' CMT RIH W/ WL SET CIBP @ 2760' POOH W/ WL RIH W/ WL DUMP BAIL 35' CMT POOH W/ WL RIH W/ WL SET CIBP @ 1320' CWI SDON

12-16-21

HOLD SFTY MTG & JSA RU WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 85 LEA COUNTY, NM API # 30-025-30008

12-16-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT PU ON TBJ UN-SET PKR CIRC WELL W/MLF POOH W/TBJ TOTAL OF 120 CWI SDON

12-17-21

HOLD SFTY MTG & JSA MIRU WL RIH W/WL SET CIBP @ 3612' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' CWI SDON RUWL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 55 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT READY TO MOVE

WDQSU # 35 LEA COUNTY, NM API # 30-025-12289

12-18-21

HOLD SFTY MTG & JSA MIRU ALL EQUIPMENT ND HEAD PU ON TBJ UN-SET PKR CIRC WELL W/MLF POOH W/115 JNTS TBJ MIRU WL RIH W/WL SET CIBP @ 3612' POOH W/WL RIH W/BAILER & DUMP BAIL 35' CMT RIH W/WL SET CIBP @ 2760' POOH W/WL RIH W/WL DUMP BAIL 35' CMT POOH W/WL RIH W/WL SET CIBP @ 1320' RU WL RIH W/WL PERF @ 520' POOH W/WL RD RELEASE WL CWI SDON


12-20-21

HOLD JSA & SFTY MTG RIH W/TBJ TO 520' RU PUMP EIR (ESTABLISH INJECTION RATE) NO INJECTION RATE @ 500# MIX & SPOT 40 SXS CLASS "C" CMT @ 520' TO SURF WASH UP CMT EQUIP POOH W/TBJ RIG DOWN ALL EQUIPMENT CUT & COVER HEAD

END OF PLUGGING OPERATIONS ON THE WEST DOLLARHIDE QUEEN SANDS UNIT

# SAGA WDQSU # 111 WIW

1830' FSL & 460 FWL SEC 29, 724S, R38E, LEA COUNTY, NM West Dollarhide Queen Sand Field



WDQSU #111 WIW

WDQSU WELL BORE SCHEMATICS.xls

4:33 PM :2/5/02

WELLBORE	DIAGRAM

	# 14	K.B.ELEV.: K.B.CORRECTION:
		G.L.ELEV.: 3175
HOLE SIZE: 12 1/4"		85/2" 24 # GRADE SET AT 407 '
HOLE SIZE: 77/8"		CEMENT WITH <u>250</u> SX
4" 105 LIMER & 116# 5-55	Coll	apaid cog @ 1190'
*TOP PERF: 3703.  FIELD: Dolla hide a ween  FORMATION: Queen  *BOT PERF: 3850	3703-1 3725-4 3769-7	65 12 07 30
PBTD: ' TOTAL DEPTH 3952' *INDIVIDUAL PERFS:  SPF = HOLES		5½" 17 # GRADE  SET AT 3952 '  CEMENT WITH 150 SX STG
WELLBORE DIAGRAM AS OF DATE:/_C  STATE://M COUNTY:  TOWNSHIP: RANG  OPERATOR: WORK	)-31-88 <u>Lea</u> block:_ ::_38 <i>E</i> legal:_1	section: <u>29</u> -, 1830 F34, 460 FWL
completion date: 3-11-88 curr remarks: Began injection	ENT STATUS: (PMP) (FLO	W) (INJ) (T/A) (SI)

NO. OF COPIES RECLI			RECEIV	FD ::::	- 400	0	1		C-105 red 11-1-8	
DISTRIBUTION	4		· ILCCLIF		6 130	Ō	r		ite Type of Logse	
SANTA FE		NEV	MEXICO OIL CO	NSERVATION	ом сомм	ISSION	- 1	State		
FILE	•	WELL COMPI	ETION OR REC	COMPLETI	ON REP	NA TRC	D LOG		II & Gus Louse No.	
U.S.G.S.		=					[			
LAND OFFICE							Į.	B-951	9	
OPERATOR							\$	./////		
							t	/////		
la. TYPE OF WELL								7. Unit A.	Dollarhide	
	011			1	Wtr in	iect.	well		Sand Unit	
b. TYPE OF COMPLI	ETION . WE	ice Land	.L VAY	N OTHER	WCI III	Jece	WCII		Lease Numo	
NEW W	ORK T	EN PLU	S DIFF.	]						
2. Name of Operator	CR L DCCP	EN L. BAC	K LLI RESVA. LL	J OTHER				9. Woll No		
. 3	To .		2			ě	1	120.700		
Sirgo-Collier 3. Address of Operator	f, Inc.						-	111		
J. Address of Operator			8.	-				10. Field and Pool, or Wildcat		
P. O. Box 353	l, Midland	, Texas 79	9702				_	Dolla	rhide Queen	
4. Location of Well	7.	.,,						11111		
				120				//////		
UNIT LETTERL		1830	Sout	th	460		1	(11111)		
ONIT CETTER	LOCATED	TODO PEET	FROM THE	LINEAN	wiri	TITE !	T FROM	12. County		
		0.4.6	000		/////X		11111		(1111111)	
		TWP. 245 A			77/7/7	77777	77777	Lea	VIIIIIII	
15. Date Spudded		- 1	e Compl. (Ready to	Prod.) 18.			B, RT, G	, etc.) 19	. Elev. Cashinghead	
1-18-88	1-24-88		-11-88		3175'	GR			3174	
20. Total Depth	21. Pl	ug Back T.D.	22. If Multip	ole Compl., Ho		Intervals Drilled By			, Cable Tools	
39.2			Mony				0-3	3952'	:	
14. Productive Interval	s), of this comple	tion - Top, Botto	m, Name						25. Was Directional Survey	
								- 1	Made	
3703-38501 (	)ueen					43			Yes, attached	
26. Type Electric and C	·								Was Well Cored	
	, <b></b>								O	
CNL, CBL								14	<u> </u>	
28.		CA	SING RECORD (Re	port oil string	s set in we	11)				
CASING SIZE	WEIGHT LB.			LE SIZE		CEMENTI			AMOUNT PULLED	
8-5/8"	24#	407	12-	-1/4"	250	sx, ci	rc 51	SX	-	
5-1/2"	17#	3952	7-	-7/8"	1150	sx, ci	rc 52	SX		
29.		INER RECORD			150		71	DINC DCC	2000	
		1	T		30.		10	BING REC	JORD	
SIZE	ТОР	воттом	SACKS CEMENT	SCREEN		SIZE	DEP	THSET	PACKER SET	
					2-	3/8"	3600	1	3603'	
31. Perioration Record	Interval, size and	d number)		32.	ACID, SH	OT, FRAC	TURE. C	EMENT SC	WEEZE, ETC.	
		•	cic	DEPTH	INTERVA				NO MATERIAL USED	
3805-50'				3805-38					gal 15% NEFE	
3003 30		•		3003 30		Inc.	IUIZE	<u> </u>	gar 13% NETE	
3703-72				2702 27	701		112	- 1 7007	2 - 1 IEW MUND	
3703-72				3703-37	12	AC	ldize	W/ 4000	O gal 15% NEFE	
				J						
13.				UCTION						
Date First Production	Produ	ction Method (Flo	nving, gas lift, pump	ning – Size an	d type pun	p)		Wall State	is (Prod. or Shut-in)	
							-			
Date of Test	Hours Tested	Choke Size	Prod'n. For	OII - 1561.	Gus	- MCF	Water	131/1.	Gas Oil Rallo	
		1	Test Period							
low Tubing Press.	Casing Pressur	e Calculated 2	4- OII — 13b1.	Cus - h	ICE	Wuter	– Bbl.	Oil	Gravity - API (Corr.)	
-	·	Hour Hate	.	1						
4. Disposition of Gas (	Sold need for the	d vantad ata l					-1			
1. Disposition of Gds [	sora, asea jor jue	n, venteu, etc.)					Test	(Itnessed I	37	
			1							
5. List of Attachments										
CNL, CBL, Dev	viation rep	ort						indf.		
6. I hereby certify that	the information s	hown on both side	es of this form is tru	e and comple	e to the bi	st of my	mowledge	and belief	(.	
		101						•		
SIGNET A	. 91	whitle	40000	A					Tuno 26 1000	
SIGNED	ing as	- will	TITLE	Agen	<u> </u>			ATE	June 24, 1988	
(0.0)			//						the state of the s	

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 71654

#### **CONDITIONS**

Operator:	OGRID:
RAM ENERGY LLC	309777
5100 East Skelly Drive	Action Number:
Tulsa, OK 74135	71654
	Action Type:
	[C-103] Sub. Plugging (C-103P)

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	None	4/4/2022