U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Repor 04/05/2022

Well Name: FEDERAL L

Well Location: T23N / R7W / SEC 28 /

7072

County or Parish/State:

SWSE / 36.191875 / -107.577072

SANDOVAL/NM

Well Number: 1

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMNM58878

Unit or CA Name:

Unit or CA Number:

US Well Number: 300432082500S1

Well Status: Producing Oil Well

Operator: EPIC ENERGY LLC

# Notice of Intent

Sundry ID: 2664327

Type of Submission: Notice of Intent

Date Sundry Submitted: 03/29/2022

Date proposed operation will begin: 03/29/2022

Type of Action: Plug and Abandonment

Time Sundry Submitted: 11:01

Procedure Description: Please find attached the P&A Procedures, WBD and the Reclamation plan for the subject

well.

#### **Surface Disturbance**

Is any additional surface disturbance proposed?: No

#### **NOI Attachments**

Procedure Description

Federal\_L\_1\_Reclamation\_Plan\_20220329132835.pdf

Federal\_L\_001\_WBD\_PA\_20220329110039.pdf

Federal\_L\_001\_PA\_Procedure\_20220329110022.pdf

Page 2 of 11

Received by OCD: 4/5/2022 3:20:21 PM Well Name: FEDERAL L

Well Location: T23N / R7W / SEC 28 / SWSE / 36.191875 / -107.577072

8 / County or Parish/State: SANDOVAL / NM

Well Number: 1

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMNM58878

**Unit or CA Name:** 

Unit or CA Number:

US Well Number: 300432082500S1

Well Status: Producing Oil Well

Operator: EPIC ENERGY LLC

## **Conditions of Approval**

## **Additional Reviews**

2664327\_NOIA\_1\_3004320825\_KR\_04052022\_20220405112013.pdf

General\_Requirement\_PxA\_20220405111953,pdf 23N07W28OKg\_Federal\_L\_1\_20220405110353.pdf

# **Operator Certification**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: ARLEEN SMITH

Signed on: MAR 29, 2022 01:28 PM

Name: EPIC ENERGY LLC

Titte: Regulatory Specialist

Street Address: 332 RD 3100

City: AZTEC

State: NM

Phone: (505) 327-4892

Email address: ARLEEN@WALSHENG.NET

#### Field Representative

Représentative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

#### **BLM Point of Contact**

**BLM POC Name:** KENNETH G RENNICK

BLM POC Phone: 5055647742

Disposition: Approved

Signature: Kenneth Rennick

BLM POC Title: Petroleum Engineer

BLM POC Email Address: krennick@blm.gov

Disposition Date: 04/05/2022

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

AFMSS 2 Sundry ID 2664327

Attachment to notice of Intention to Abandon

Well: Federal L 1

# CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
  - a. Adjust Plug #3 (Cliff House) to cover BLM formation top pick at 3040'.
  - b. Combine Plug #5 and Plug #6 to cover BLM Kirtland pick at 1218'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

K. Rennick 04/05/2022

# GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
  - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
  - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
  - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
  - 4.1 The cement shall be as specified in the approved plugging plan.
  - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.3 Surface plugs may be no less than 50' in length.
  - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
  - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

- 5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.
  - 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
  - 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
  - 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
  - 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
  - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
  - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain H<sub>2</sub>S.
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), five copies, with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

# BLM FLUID MINERALS P&A Geologic Report

**Date Completed:** 04/05/2022

Well No. Federal L #1 (API# 30-043-20825)		Location	490	FSL	&	1765	FEL	
Lease No. NMNM-58878  Operator Epic Energy, LLC		Sec. 28	T23N Sandoval			R07	R07W	
		County			State	New Mexico		
Total Depth 5387'	PBTD 5296'	Formation	Gallup (	(Mancos)				
Elevation (GL) 6930'		Elevation (KB) 6942'						

Geologic Formations	Est. Top	Est. Bottom	Log Top	Log Bottom	Remarks
San Jose Fm					
Nacimiento Fm			Surface	1064	Surface/possible freshwater sands
Ojo Alamo Ss			1064	1218	Aquifer (possible freshwater)
Kirtland Shale			1218	1302	
Fruitland Fm	,		1302	1586	Coal/Gas/Possible water
Pictured Cliffs Ss			1586	1690	Gas
Lewis Shale			1690	1987	
Chacra			1987	3040	Possible Gas
Cliff House Ss			3040	3206	Water/Possible gas
Menefee Fm			3206	3953	Coal/Ss/Water/Possible O&G
Point Lookout Ss			3953	4114	Probable water/Possible O&G
Mancos Shale			4114	4842	
Gallup			4842	PBTD	O&G/Water
Greenhorn					
Graneros Shale					
Dakota Ss					
Morrison Formation					

# Remarks:

#### P & A

- BLM picks for the Cliff House and Kirtland formation tops vary from Operator.

Reference Well:
1) Formation Tops
Same

Adjust Plug #3 (Cliff House) to cover BLM formation top pick at 3040'.

Combine Plug #5 and Plug #6 to cover BLM Kirtland pick at 1218'.

- The plugs proposed in the P&A procedure, with changes recommended above, will adequately protect any freshwater sands in this well bore.
- Gallup perfs 4986' 5198'.

#### **P&A Procedure**

## EPIC Energy - Federal L #001

Alamito Gallup

490' FNL & 1765' FWL, Section 28, T23N, R7W

Sandoval Co, New Mexico, API #30-043-20825

## Plug & Abandonment Procedure:

Note: All cement volumes use 100% excess outside casing and 50' excess inside pipe. Stabilizing wellbore fluid will be 8.33 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Class G neat 1.15 ft<sup>3</sup>/sk or equivalent. If casing pressure tests tagging plugs will not be required. Cement circulated on surface and production casing strings. Volumes calculated off 4-1/2" 11.6# casing.

#### **Prior to Mobilization**

- 1. Notify BLM & NMOCD
- 2. Verify all cement volumes based on actual slurry to be pumped. Calculations based on 1.15 ft<sup>3</sup>/sk.
- 3. Comply with all COA's from BLM and NMOCD

#### **P&A Procedure**

- 1. MIRU PU and cement equipment
- 2. ND WH, NU BOP, RU rig floor and 2 3/8" handling tools
- 3. POOH 2 3/8" production string set at ~5169'.
- 4. TIH with 4 ½" casing scraper to 4960'. TOOH LD 4 ½" scraper.
- 5. TIH with CICR and set @ 4936'. Roll hole with fresh water. PT tubing to 500 psi. PT casing to 500 psi.
- 1. Plug #1, 4936' 4792' (Gallup top: 4842', Perfs 4986'- 5198'): Sting out of CICR, mix & spot 12 sxs (13.8 ft<sup>3</sup>) of Class G neat cement on top of CICR in balanced plug. PU 200' above plug reverse circulate to clean tubing. WOC and tag plug if casing does not test. Re-spot cement if necessary.
- 2. Plug #2, 4164' 4064' (Mancos Top: 4114'): Mix & spot 12 sx (13.8 ft<sup>3</sup>) Class G neat cement in balanced plug. PU 200' above plug and reverse circulate tubing clean. WOC and tag plug if casing does not test. Re-spot cement if necessary.
- 3. Plug #3, 3200′ 3100′ (Cliff House Top: 3150′): Mix & spot 12 sx (13.8 ft³) Class G neat cement in balanced plug. PU 100′ above plug and reverse circulate tubing clean. WOC and tag plug if casing does not test. Re-spot cement if necessary.

- 4. Plug #4, 2037' 1937' (Chacra Top: 1987'): Mix & spot 12 sx (13.8 ft<sup>3</sup>) Class G neat cement in balanced plug. PU 100' above plug and reverse circulate tubing clean. WOC and tag plug if casing does not test. Re-spot cement if necessary.
- 5. Plug #5, 1636' 1252' (FT Coal Top: 1302', PC Top: 1586'): Mix and spot 33 sx (37.95 ft<sup>3</sup>) Class G neat cement in balanced plug. PUH 100' above plug and reverse circulate tubing clean. WOC and tag plug if casing does not test. Re-spot cement if necessary.
- 6. Plug #6, 1200' 1014' (Ojo Alamo top: 1064', Kirtland: 1150'): Mix and spot 18 sx (20.7 ft<sup>3</sup>) Class G neat cement in balanced plug. PUH 100' above plug and reverse circulate tubing clean. WOC and tag plug if casing does not test. Re-spot cement if necessary.
- 7. Plug #7, 262' Surface (8-5/8" Shoe @ 212'): Note: Cement circulated on surface casing string. Mix and pump 20 sx (23.0 ft<sup>3</sup>) or until cement circulates to surface. Top off cement as necessary.
- 6. ND BOP and cut off wellhead below surface casing flange, top off casing and annulus as necessary. Install P&A marker and cut off and/or remove anchors. RD, MOL Restore location per BLM stipulations. Take pictures from all cardinal directions. Ensure to notify project management of all remaining equipment on location once plugging is complete.

Kyle T. Mason Engineer

#### Federal L#1

#### Proposed P&A

#### Alamito Gallup

490' FNL & 1765' FWL, Section 28, T23N, R7W, Sandoval, NM API: 30-043-20825

Today's Date: 03/28/2022 Spud: 7/19/1988 Completed: 10/5/1988

Elevation: 6960' GL

Ojo Alamo @ 1064' Kirtland @ 1150'

Fruitland @ 1302' Pictured Cliffs @ 1586'


Chacra @ 1987'

Cliff House @ 3150'

Mancos @ 4114'

Gallup @ 4842\*

Hole Size 7.875



8-5/8", 23#, Casing set @ 212' Cement with 155 sx , Circ to surface

Hole Size: 12-1/4"

Plug #7: 8-5/8" Surface Shoe - 262' - Surface Class G neat, 20 sx (23.0 ft<sup>3</sup>)

Plug #6: Ojo Alamo/Kirtland - 1200'-1014' Class G neat, 18 sx (20.7 ft<sup>3</sup>)

Plug #5: Fruitland/PC - 1636'-1252' Class G neat, 33 sx (37.95 ft<sup>3</sup>)

Plug #4: Chacra - 2037'-1937' Class G neat, 12 sx (13.8 ft<sup>3</sup>)


Plug #3: Cliff House - 3200'-3100' Class G neat, 12 sx (13.8 ft<sup>3</sup>)

Plug #2: Mancos - 4164'-4064' Class G neat, 12 sx (13.8 ft<sup>3</sup>)

SET CICR @ 4936' Plug #1: Gallup - 4936'-4792' Class G neat, 12 sx (13.8 ft<sup>3</sup>)

Gallup Perforations 4986'-5198'

PBTD: 5296' TD: 5387' 4-1/2", 11.6#, casing set @ 5384'
Production CMT:
1st stage: 1050 sxs. Circ 65 bbls to surface



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 96233

#### **CONDITIONS**

Operator: C	OGRID:
EPIC ENERGY, L.L.C.	372834
332 Road 3100	Action Number:
Aztec, NM 87410	96233
[A	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By		Condition Date
kpickford	Notify NMOCD 24 Hours Prior to beginning operations	4/8/2022
kpickford	Adhere to BLM approved COAs and plugs. See GEO report.	4/8/2022