Submit 1 Copy To Appropriate District Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District H. (575) 749 1293	State of New Mexic Energy, Minerals and Natural		WELL API NO.	Form C-103 Revised July 18, 2013			
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	OIL CONSERVATION D 1220 South St. Francis Santa Fe, NM 8750	s Dr.	30-015-39850 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.				
SUNDRY NOTICE (DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.)			7. Lease Name or ROGERS	Unit Agreement Name			
	s Well 🔲 Other		8. Well Number	6			
2. Name of Operator SILVERBACK OPERATING II, LLC	<u>}</u>		9. OGRID Numbe 330968	r			
3. Address of Operator 19707 INTERSTATE 10 WEST, SUI	FE 201, SAN ANTONIO TX 78257	7	10. Pool name or V ATOKA, GLORIE	5 N 001			
4. Well Location							
Unit Letter J : 2310 Section 23		ne and2310 nge26E	feet from the NMPM	_EASTline County EDDY			
	1. Elevation <i>(Show whether DR, R)</i> 311' GR	KB, RT, GR, etc.)					

Page 1 of 9

Received by OCD: 8/25/2022 1:22:09 PM

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF	IN	TENTION TO:		SUBSEQUENT	RE	PORT OF:	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	\boxtimes	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON	\Box	CHANGE PLANS		COMMENCE DRILLING OPNS.		P AND A	
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEMENT JOB [
DOWNHOLE COMMINGLE							
CLOSED-LOOP SYSTEM							
OTHER:				OTHER:			
13 Describe proposed or c	omnl	eted operations (Clearly	state all r	pertinent details and give pertinen	t dat	es including estimated	date

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SILVERBACK OPERATING II, LLC PROPOSES TO PLUG AND ABANDON WELL. SEE ATTACHED PROCEDURE.

SEE CHANGES TO PROCEDURE

Spud Date: Rig Release Date: Must be plugged by 8/25/2022
I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE <u>Guildent</u> TITLE_ENGINEERING ADVISORDATE08/25/2022
Type or print name RUDY WILDENSTEIN E-mail address: <u>RWILDENSTEIN@SILVERBACKEXP.COM</u> PHONE: 713-829-0362 For State Use Only
APPROVED BY: <u>DATE</u> TITLE <u>Staff Manager</u> DATE <u>8/25/2022</u> Conditions of Approval (if any):

Rogers #6 30001539850 T18S-R25E-Section 23 Unit J

Run CBL to surface

Silverback Operating II, LLC plans to plug and abandon the Rogers #6 well as follows:

- 1. MIRU all safety equipment as needed. NU BOP and POOH with production equipment.
- Set a CIBP at 2,844' and spot 35sks Class C cement plug to 2,490'. WOC and tag. This will cover the Yeso perfs. (Test CIBP 500psi for 30 minutes before cement)
- 3. Spot 35sks Class C cement plug from 1,174' to 820' to cover top of San Andres and surface casing shoe. WOC and tag. [perf @ 354' & circ cmt to surf]
- 4. Spot 35 sks Class C cement plug from 354' to surface. WOC and tag. Backfill as needed.
- 5. Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics can be found attached.

•

D	ogers #006	Curront		Se	c-TWI	N-RNG:	23-18S-2	26E Unit	J		30-015-39	850	
I I I I I I I I I I I I I I I I I I I	ogers #000	Sourient		Fo	ootage	Calls:	2310' FS	L & 231	0' FEL		Elev 3311	GR	
COMMENTS													
				CASI	IG DET	AIL							
					HOLE	CSG	WGHT	GRADE	Тор	Depth	TOC	SX	
				Α	12 1/4	9 5/8	36	J-55	0	918	circ to surf	1290	
				B	7 7/8	5 1/2	17	L-80	0	3,706	circ to surf	640	
				-		•=			•	,			
											I		
				EOPN	IATION	TOPS							
				FURI	FORM/		TOP (FT)	E	ORMATIC	N		TOP	
				SAN /								IUF	
)	1,124						
				GLOR			2,694						
	A												
				TUBIN	IG DET	AIL							
				C	D	GRADE	WGHT	TOP	BASE				
				2	7/8			0	2,851				
	'												
							1						
EOT 2,851'				PERE	ORATIC	N DETAIL							
,					onane	FORMATI	ON	TOP	BASE		TREA	TMENT	
										238,708 g	als X-Link gel,		Linear
				Α		YESO		2,894	3,573	gel, 3,515	gals 15% HCL	., 302,958 lbs	s 16/30
										Resign C	oated sand		
				'									
Yeso Pfs 2,894-3,573'													
Teso FIS 2,094-3,373			5										
	в												
		660 MD		ļ									
		,660 MD											
	TD: 3	,706 MD											

•

-		400C D			Se	c-TW	N-RNG:	23-18S-2	26E Unit	J		30-015-39	850	
	Rogers #	7006 P	Topos	eu				2310' FS				Elev 3311	' GR	
COMMENTS								+						
COMMENTO	1													
					CASI	NG DET	AIL							
					#	HOLE	CSG	WGHT	GRADE	Тор	Depth	TOC	SX	
					Α	12 1/4	9 5/8	36	J-55	0	918	circ to surf	1290	
					В	7 7/8	5 1/2	17	L-80	0	3,706	circ to surf	640	
										I				
					FORM	MATION	TOPS							
						FORM	ATION	TOP (FT)	F	ORMATIC	N		TOP	
						ANDRES	8	1,124						
					GLOF	RIETA		2,694						
									1	 	_			
					TUD		A.II.							
						NG DET. OD	GRADE	WGHT	ТОР	BASE				
						00	GRADE	WGHT	TOP	DASE	1			
	I										t			
											•			
					PERF	ORATIO	N DETAIL	<u></u>	TOD				THENT	
							FORMATI		TOP	BASE	238,708 g	als X-Link gel	TMENT 13,253 gals	Linear
					A		YESO		2,894	3,573	gel, 3,515	gals 15% HC oated sand	L, 302,958 lbs	s 16/30
2,844			~		PLUG	SS			1	I	I			
		-		-	#	SX	Class	Тор	Bottom	Ht		Notes		Tag
					1	35	С	2,490	2,844	354	CIBP+Ye	so Perfs		Y
Pfs 2,894-3,573'	Α			\bowtie	2	35	С	820	1,174	354	Csg shoe	+ San Andres		Y
											-			Y
					5	- 55	C	0	304	304	Sunacer	ug		Ť
					3	35	С	0	354	354	Surface P	lug		
			\Leftrightarrow											
	PBTD: TD:	3,660 3,706												

CONDITIONS FOR PLUGGING AND ABANDONMENT

OCD - Southern District

The following is a guide or checklist in preparation of a plugging program, this is not all inclusive and care must be exercised in establishing special plugging programs in unique and unusual cases, Notify NMOCD District Office II at (575)-748-1283 at least 24 hours before beginning work. After MIRU rig will remain on well until it is plugged to surface. OCD is to be notified before rig down. Company representative will be on location during plugging procedures.

- 1. A notice of intent to plug and abandon a wellbore is required to be approved before plugging operations are conducted. A cement evaluation tool is required in order to ensure isolation of producing formations, protection of water and correlative rights. A cement bond log or other accepted cement evaluation tool is to be provided to the division for evaluation if one has not been previously run or if the well did not have cement circulated to surface during the original casing cementing job or subsequent cementing jobs. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
- 2. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to a permitted disposal location.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator as well as the contractor, to verify that this permit is in place prior to performing work. Drivers shall be able to produce a copy upon request of an NMOCD Field inspector.
- 4. Filing a subsequent C-103 will serve as notification that the well has been plugged.
- 5. A final C-103 shall be filed (and a site inspection by NMOCD Inspector to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to Meet NMOCD standards) before bonding can be released.
- 6. If work has not begun within 1 Year of the approval of this procedure, an extension request must be file stating the reason the well has not been plugged.
- 7. Squeeze pressures are not to exceed 500 psi, unless approval is given by NMOCD.
- 8. Produced water will not be used during any part of the plugging operation.
- 9. Mud laden fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
- 10. All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
- 11. Class 'C' cement will be used above 7500 feet.
- 12. Class 'H' cement will be used below 7500 feet.
- 13. A cement plug is required to be set 50' above and 50' below, casing stubs, DV tools, attempted casing cut offs, cement tops outside casing, salt sections and anywhere the casing is perforated, these plugs require a 4 hour WOC and then will be tagged
- 14. All Casing Shoes Will Be Perforated 50' below shoe depth and Attempted to be Squeezed, cement needs to be 50' above and 50' Below Casing Shoe inside the Production Casing.

- 16. When setting the top out cement plug in production, intermediate and surface casing, wellbores should remain full at least 30 minutes after plugs are set
- 17. A CIBP is to be set within 100' of production perforations, capped with 100' of cement, WOC 4 hours and tag.
- 18. A CIBP with 35' of cement may be used in lieu of the 100' plug if set with a bailer. This plug will be placed within 100' of the top perforation, (WOC 4 hrs and tag).
- 19. No more than 3000' is allowed between cement plugs in cased hole and 2000' in open hole.
- 20. Some of the Formations to be isolated with cement plugs are: These plugs to be set to isolate formation tops
 - A) Fusselman
 - B) Devonian
 - C) Morrow
 - D) Wolfcamp
 - E)Bone Springs
 - F) Delaware
 - G) Any salt sections
 - H) Abo
 - I) Glorieta
 - J) Yates.
 - K)Potash---(In the R-111-P Area (Page 3 & 4), a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, WOC 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- 21. If cement does not exist behind casing strings at recommended formation depths, the casing can be cut and pulled with plugs set at recommended depths. If casing is not pulled, perforations will be shot and cement squeezed behind casing, WOC and tagged. These plugs will be set 50' below formation bottom to 50' above formation top inside the casing

DRY HOLE MARKER REQUIRMENTS

The operator shall mark the exact location of the plugged and abandoned well with a steel marker not less than four inches in diameter, 3' below ground level with a plate of at least ¼" welded to the top of the casing and the dry hole marker welded on the plate with the following information welded on the dry hole marker:

1. Operator name2. Lease and Well Number3. API Number4. Unit Letter5. QuarterSection (feet from the North, South, East or West)6. Section, Township and Range7. Plugging Date8. County(SPECIAL CASES)------AGRICULTURE OR PRARIE CHICKEN BREEDING AREAS

In these areas, a below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to NMOCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to NMOCD (We typically require a current survey to verify the GPS)

SITE REMEDIATION DUE WITHIN ONE YEAR OF WELL PLUGGING COMPLETION

R-111-P Area

T 18S – R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

T 19S – R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23. Sec 24. Sec 25 Unit D. Sec 26 Unit A- F. Sec 27 Unit A,B,C,F,G,H.

T 19S – R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec 10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec 24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32 Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

T 19S – R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

T 20S – R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec 23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit A-H. Sec 36 Unit B-G.

T 20S – R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P. Sec 19 Unit A,B,G,H,I,J,O,P. Sec 20 – 29. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

T 20S – R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P. Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

T 21S – R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec 23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

T 21S – R 30E

Sec 1 – Sec 36

T 21S – R 31E

Sec 1 – Sec 36

T 22S – R 28E

Sec 36 Unit A,H,I,P.

T 22S – R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S – R 30E

Sec 1 – Sec 36

T 22S – R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit C,D,E,F,K,L,M,N. Sec 25 Unit A,B,C,D. Sec 26 Unit A,B,C,D,G,H. Sec 27 – Sec 34.

T 23S – R 28E

Sec 1 Unit A

T 23S – R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33 Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S – R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec 33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S – R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P. Sec 16 Unit I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec 34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S – R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11. Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S – R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O,P. Sec 10 Unit B – G, K – N. Sec 35 Unit E – P. Sec 36 Unit E,K,L,M,N.

T 25S – R 31E

Sec 1 Unit C,D,E,F. Sec 2 Unit A – H.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Silverback Operating II, LLC	330968
IH10 West, Suite 201	Action Number:
San Antonio, TX 78257	138147
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)
	•

CONDITIONS

Created By		Condition Date
gcordero	None	8/25/2022

Released to Imaging: 9/7/2022 8:02:24 AM

Page 9 of 9

.

Action 138147