Received by OCP: 3/21/2023 5:45:33	AM State of New Me	exico		Form C-103
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	Revised July 18, 2013
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			9-23158
<u>District III</u> – (505) 334-6178	1220 South St. Fra		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		STATE 6. State Oil & Gas I	FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Same 1 0, 1 (11 0)			NMNM03404
	CES AND REPORTS ON WELLS		7. Lease Name or U	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			San Juan 31-6 Unit	
·	Gas Well 🛛 Other		8. Well Number 49	
2. Name of Operator			9. OGRID Number	
Hilcorp Energy Company			372171	
3. Address of Operator		10. Pool name or Wildcat		
382 Road 3100, Aztec NM	[87410		Blanco Mesaver	rde / Basin Dakota
	om the North line and 880 feet from ship 30N Range 06W 11. Elevation (Show whether DR	NMPM , RKB, RT, GR, etc.	San Juan County	,
	6461'	GK		
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WOR COMMENCE DR CASING/CEMEN	ILLING OPNS.□ P T JOB □	AND A
	eted operations. (Clearly state all prk). SEE RULE 19.15.7.14 NMACompletion.			
Upon further review NMOCD is not Kuehling.	requiring a casing integrity log for	the subject well. P	lease see attached ema	il from Monica
				1
Spud Date:	Rig Release Da	ate:		
I hereby certify that the information a	above is true and complete to the be	est of my knowledg	ge and belief.	
SIGNATUREKandís Rol	andTITLE Opera	ations/Regulatory T	echnician Sr, DATE_	3/21/2023
Type or print name For State Use Only				NE:
APPROVED BY: Monica Ku Conditions of Approval (if any):	ushling TITLE Dep	outy Oil and Gas	InspectorDATE	3/21/2023

Kandis Roland

From: Kuehling, Monica, EMNRD < monica.kuehling@emnrd.nm.gov>

Monday, March 20, 2023 4:55 PM Sent:

To: Kandis Roland

Ben Hampton; James Osborn; Bennett Vaughn; Eliza Ann Moehlman; Brett Houston; Cc:

Mandi Walker

Subject: RE: [EXTERNAL] San Juan 31-6 unit 49 (30-039-23158)

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Kandis and Ben

Thank you for your request

After further review

The depth of the Graneros determined to be at 7733

MIT on casing ran from 7768 to surface and passed 4/20/2022 – Witnessed by Lenny Moore

Hilcorp has approval to decline on casing integrity log. Well is cleared.

Please send subsequent stating that casing integrity log is not required by State. Include this email - Let me know what the action id number is and I will go in and approve. This is for a paper trail.

Thank you

Monica Kuehling Compliance Officer Supervisor Deputy Oil and Gas Inspector New Mexico Oil Conservation Division North District

Office Phone: 505-334-6178 ext. 123

Cell Phone: 505-320-0243

Email - monica.kuehling@emnrd.nm.gov

From: Kandis Roland < kroland@hilcorp.com>

Sent: Friday, March 17, 2023 12:00 PM

To: Kuehling, Monica, EMNRD < monica.kuehling@emnrd.nm.gov>

Cc: Ben Hampton

 Shampton@hilcorp.com>; James Osborn <josborn@hilcorp.com>; Bennett Vaughn

<Bennett.Vaughn@hilcorp.com>; Eliza Ann Moehlman <Eliza.Ann.Moehlman@hilcorp.com>; Brett Houston

<Brett.Houston@hilcorp.com>; Mandi Walker <mwalker@hilcorp.com>

Subject: RE: [EXTERNAL] San Juan 31-6 unit 49 (30-039-23158)

Monica.

Please see attached plat.

Thanks.

Kandis Roland HILCORP ENERGY San Juan East/South Regulatory 713.757.5246 kroland@hilcorp.com

From: Kuehling, Monica, EMNRD < monica.kuehling@emnrd.nm.gov >

Sent: Friday, March 17, 2023 12:44 PM To: Kandis Roland < kroland@hilcorp.com >

Cc: Ben Hampton < bhampton@hilcorp.com >; James Osborn < josborn@hilcorp.com >; Bennett Vaughn <Bennett.Vaughn@hilcorp.com>; Eliza Ann Moehlman <Eliza.Ann.Moehlman@hilcorp.com>; Brett Houston

<Brett.Houston@hilcorp.com>; Mandi Walker <mwalker@hilcorp.com>

Subject: RE: [EXTERNAL] San Juan 31-6 unit 49 (30-039-23158)

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Kandis we need an updated wellbore schematic on how it sets today thank you Monica

From: Kandis Roland < kroland@hilcorp.com > Sent: Wednesday, March 8, 2023 12:20 PM

To: Kuehling, Monica, EMNRD < monica.kuehling@emnrd.nm.gov>

Cc: Ben Hampton

bhampton@hilcorp.com>; James Osborn <josborn@hilcorp.com>; Bennett Vaughn <Bennett.Vaughn@hilcorp.com>; Eliza Ann Moehlman <Eliza.Ann.Moehlman@hilcorp.com>; Brett Houston <Brett.Houston@hilcorp.com>; Kandis Roland <kroland@hilcorp.com>; Mandi Walker <mwalker@hilcorp.com>

Subject: RE: [EXTERNAL] San Juan 31-6 unit 49 (30-039-23158)

Monica,

A meeting was never set-up to discuss this issue. Ben Hampton has joined the San Juan East group as the production manager. He has a couple of questions below.

Hilcorp would like to propose to run a caliper log from the top of the perfs at 7864' to the bottom of where the RBP was set at 7,768'. When interpreting the caliper log we would assume anywhere we see 100% metal loss as an indication of an integrity issue. Anywhere we see less than 100% metal loss we would consider the casing to have integrity. Please let us know if this type of log and this interpretation would be acceptable.

Thanks.

Kandis Roland HILCORP ENERGY San Juan East/South Regulatory

713.757.5246

kroland@hilcorp.com

From: Kuehling, Monica, EMNRD < monica.kuehling@state.nm.us>

Sent: Tuesday, May 24, 2022 3:46 PM To: Kandis Roland kroland@hilcorp.com>

Cc: James Osborn < josborn@hilcorp.com >; Brian Roth < broth@hilcorp.com >

Subject: RE: [EXTERNAL] 31 6 unit 49 39-23158

I will have to get back with you on who to include and when Monica

From: Kandis Roland < <u>kroland@hilcorp.com</u>>

Sent: Tuesday, May 24, 2022 1:42 PM

To: Kuehling, Monica, EMNRD < monica.kuehling@state.nm.us >

Cc: James Osborn < josborn@hilcorp.com >; Brian Roth < broth@hilcorp.com >; Kandis Roland < kroland@hilcorp.com >

Subject: RE: [EXTERNAL] 31 6 unit 49 39-23158

Monica,

Thank you on the quick response. Hilcorp has some additional questions around type of log that needs to be ran and would like to discuss the process and timing to insure that we meet requirements. Would we be able to set-up a conference call with you and the SF Engineer/Staff to discuss?

I am more than happy to send out the meeting invite. Just let me know a good time and who to include.

Thank you,

Kandis Roland
HILCORP ENERGY
San Juan East/South Regulatory
713.757.5246
kroland@hilcorp.com

From: Kuehling, Monica, EMNRD < monica.kuehling@state.nm.us >

Sent: Tuesday, April 19, 2022 9:05 AM

To: Farmington Regulatory Techs < farmingtonregulatory techs@hilcorp.com>

Cc: Andy Fordyce <a fordyce@hilcorp.com>
Subject: [EXTERNAL] 31 6 unit 49 39-23158

Good morning all

The well above could not get RBP to set at 7814 and had to move up hole to 7768.

Once RBP set Hilcorp can proceed with approved procedure. However, at this time we do not know if the casing has integrity below depth of RBP - the casing will need to be checked by a Casing Integrity Log from depth of RBP to top of Dakota perforations.

If you have any questions, please let me know

Thank you

Monica Kuehling
Compliance Officer Supervisor
Deputy Oil and Gas Inspector
New Mexico Oil Conservation Division
North District

Office Phone: 505-334-6178 ext. 123

Cell Phone: 505-320-0243

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

The information contained in this email message is confidential and may be legally privileged and is intended only for the use of the individual or entity named above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 199035

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
	Action Number:
Houston, TX 77002	199035
	Action Type:
	[C-103] Sub. (Re)Completion Sundry (C-103T)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	3/21/2023