Received by OCD: 12/23/2022 9:59:03 AM U.S. Department of the Interior BUREAU OF LAND MANAGEMENT	Sundry Print Report 12/22/2022		
Well Name: JULIET FEDERAL COM	Well Location: T24S / R34E / SEC 27 / SENW / 32.189768 / -103.459545	County or Parish/State: LEA / NM	
Well Number: 513H	Type of Well: OIL WELL	Allottee or Tribe Name:	
Lease Number: NMNM77090	Unit or CA Name:	Unit or CA Number:	
US Well Number: 3002549015	Well Status: Drilling Well	<b>Operator:</b> CENTENNIAL RESOURCE PRODUCTION LLC	

#### **Notice of Intent**

Sundry ID: 2630138

Type of Submission: Notice of Intent

Date Sundry Submitted: 08/23/2021

Date proposed operation will begin: 09/04/2021

Type of Action: Other Time Sundry Submitted: 03:44

**Procedure Description:** Centennial Resource Prod, LLC requests to batch set the Juliet Federal Com 513H & 514H wells with offline cementing for the surface and intermediate casings. Please see attached procedures for both the batch setting and offline cement details. The proposed wellbore diagram is also attached.

**Surface Disturbance** 

Is any additional surface disturbance proposed?: No

### **NOI Attachments**

#### **Procedure Description**

Juliet\_Fed\_Com\_513H\_Offline\_Cementing\_Procedure\_20210823154344.pdf

Juliet\_Fed\_Com\_513H\_WBD\_\_Proposed\_\_20210823154338.pdf

513H\_Batch\_Setting\_20210823154333.pdf

Received by OCD: 12/23/2022 9:59:03 AM Well Name: JULIET FEDERAL COM	Well Location: T24S / R34E / SEC 27 / SENW / 32.189768 / -103.459545	County or Parish/State:
Well Number: 513H	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM77090	Unit or CA Name:	Unit or CA Number:
<b>US Well Number:</b> 3002549015	Well Status: Drilling Well	<b>Operator:</b> CENTENNIAL RESOURCE PRODUCTION LLC

#### Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: SARAH FERREYROS Name: CENTENNIAL RESOURCE PRODUCTION LLC Title: Regulatory Manager Street Address: 1001 17th Street, Suite 1800

City: Denver

State: CO

Phone: (720) 499-1454

Email address: Sarah.Ferreyros@cdevinc.com

Field

Representative Name: Street Address: City: State: Phone: Email address:

### **BLM Point of Contact**

BLM POC Name: CHRISTOPHER WALLS BLM POC Phone: 5752342234 Disposition: Approved Signature: Chris Walls BLM POC Title: Petroleum Engineer BLM POC Email Address: cwalls@blm.gov Disposition Date: 12/22/2022

Zip:

Signed on: AUG 23, 2021 03:43 PM

# Juliet Fed Com 513H

# Centennial Offline Cementing Procedure

# 13-3/8" & 9-5/8" Casing

- 1. Drill hole to Total Depth with Rig and perform wellbore cleanup cycles.
- 2. Run and casing to Depth.
- 3. Land casing with mandrel
- 4. Circulate 1.5 csg capacity.
- 5. Flow test Confirm well is static.
- 6. Set Annular packoff and pressure test. Test to 5k.
- 7. Nipple down BOP and install cap flange.
- 8. Skid rig to next well on pad
- 9. Remove cap flange (confirm well is static before removal)
  - a. If well is not static use the casing outlet valves to kill well
  - b. Drillers method will be used in well control event
  - c. High pressure return line will be rigged up to lower casing valve and run to choke manifold to control annular pressure
  - d. Kill mud will be circulated once influx is circulated out of hole
  - e. Confirm well is static and remove cap flange to start offline cement operations
- 10. Install offline cement tool.
- 11. Rig up cementers.
- 12. Circulate bottoms up with cement truck
- 13. Commence planned cement job, take returns through the annulus wellhead valve
- 14. After plug is bumped confirm floats hold and well is static
- 15. Rig down cementers and equipment
- 16. Install night cap with pressure gauge to monitor.
- 17. Will only offline surface and intermediate casing.

13 3/8" Surface job

# **CFL Off-Line Cementing Tool**





9 5/8" Intermediate Job











## Centennial Resource Development New Mexico Multi-Well Pad Drilling Batch Setting Procedures

<u>13-3/8" Surface Casing</u> - CRD intends to Batch set all 13-3/8" casing to a depth approved in the APD. 17-1/2" Surface Holes will be batch drilled by a big rig. Appropriate notifications will be made prior to spudding the well, running and cementing casing and prior to skidding to the rig to the next well on pad.

- 1. Drill 17-1/2" Surface hole to Approved Depth with Surface Preset Rig and perform wellbore cleanup cycles. Trip out and rack back drilling BHA.
- 2. Run and land 13-3/8" 54.5# J55 BTC casing see Illustration 1-1 Below to depth approved in APD.
- 3. Set packoff and test to 5k psi
- 4. Cement
- 5. Install nightcap with Pressure Gauge on wellhead. Nightcap is shown on final wellhead Stack up Illustration #2-2 page 3.
- 6. Skid Rig to adjacent well to drill Surface hole.
- Surface casing test will be performed by the rig in order to allow ample time for Cement to develop 500psi compressive strength. Casing test to 0.22 psi/ft or 1500 psi whichever is greater - not to exceed 70% casing burst.



Illustration 1-1

<u>Intermediate Casing</u> – CRD intends to Batch set all intermediate casing strings to a depth approved in the APD, typically set into Lamar. For the last intermediate section drilled on pad, the associated production interval will immediately follow. Appropriate notifications will be made prior Testing BOPE, and prior to running/cementing all casing strings.

- 1. Rig will remove the nightcap and install and test BOPE.
- 2. Test Surface casing per COA WOC timing (.22 psi/ft or 1500 psi whichever is greater) not to exceed 70% casing burst. Cement must have achieved 500psi compressive strength prior to test.
- 3. Install wear bushing then drill out 13-3/8" shoe-track plus 20' and conduct FIT to minimum of the MW equivalent anticipated to control the formation pressure to the next casing point.
- 4. Drill Intermediate hole to approved casing point. Trip out of hole with BHA to run Casing.
- 5. Remove wear bushing then run and land Intermediate Casing with mandrel hanger in wellhead.
- 6. Cement casing to surface with floats holding.
- 7. Washout stack then run wash tool in wellhead and wash hanger and pack-off setting area.
- 8. Install pack-off and test void to 5,000 psi for 15 minutes. Nightcap shown on final wellhead stack up illustration 2-2 on page 3.
- 9. Test casing per COA WOC timing (.22 psi/ft or 1500 psi whichever is greater) not to exceed 70% casing burst. Cement must have achieved 500psi compressive strength prior to test.
- 10. Install nightcap skid rig to adjacent well to drill Intermediate hole.



Illustration 2-2

<u>Production Casing</u> – CRD intends to Batch set all Production casings, except for the last intermediate hole. In this case the production interval will immediately follow the intermediate section on that well. Appropriate notifications will be made prior Testing BOPE, and prior to running/cementing all casing strings.

- 1. Big Rig will remove the nightcap and install and test BOPE.
- 2. Install wear bushing then drill Intermediate shoe-track plus 20' and conduct FIT to minimum MW equivalent to control the formation pressure to TD of well.
- 3. Drill Vertical hole to KOP Trip out for Curve BHA.
- 4. Drill Curve, landing in production interval Trip for Lateral BHA.
- 5. Drill Lateral / Production hole to Permitted BHL, perform cleanup cycles and trip out to run 5-1/2" Production Casing.
- 6. Remove wear bushing then run 5-1/2" production casing to TD landing casing mandrel in wellhead.
- 7. Cement 5-1/2" Production string to surface with floats holding.

- 8. Run in with wash tool and wash wellhead area install pack-off and test void to 5,000psi for 15 minutes.
- 9. Install BPV in 5-1/2" mandrel hanger Nipple down BOPE and install nightcap.
- 10. Test nightcap void to 5,000psi for 30 minutes per illustration 2-2 page 3.
- 11. Skid rig to adjacent well on pad to drill production hole.



District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Permian Resources Operating, LLC	372165
1001 17th Street, Suite 1800	Action Number:
Denver, CO 80202	169734
	Action Type:
	[C-103] NOI General Sundry (C-103X)
CONDITIONS	

Created By	Condition	Condition Date		
dmcclure	ACCEPTED FOR RECORD	11/17/2023		

CONDITIONS

Action 169734

Page 13 of 13