

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report 1 of 8

Well Name: HUBBELL Well Location: T29N / R10W / SEC 18 / County or Parish/State: SAN

NESE / 36.724845 / -107.918952 JUAN / NM

Well Number: 3P Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: NMSF078716A Unit or CA Name: Unit or CA Number:

US Well Number: 3004534196 Well Status: Producing Gas Well Operator: HILCORP ENERGY

COMPANY

Notice of Intent

Sundry ID: 2764338

Type of Submission: Notice of Intent

Type of Action: Well Test

Date Sundry Submitted: 12/04/2023 Time Sundry Submitted: 02:01

Date proposed operation will begin: 12/11/2023

Procedure Description: Hilcorp Energy is requesting to repair the bradenhead on the subject well per the attached

procedure.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

HUBBELL_3P_BH_REPAIR_Procedure_20231204140056.pdf

Released to Imaging: 12/4/2023 3:06:45 PM

Well Location: T29N / R10W / SEC 18 / County or Parish/State: SAN

NESE / 36.724845 / -107.918952

JUAN / NM

Well Number: 3P

Type of Well: CONVENTIONAL GAS

WELL

Allottee or Tribe Name:

Lease Number: NMSF078716A

Unit or CA Name:

Unit or CA Number:

US Well Number: 3004534196

Well Status: Producing Gas Well

Operator: HILCORP ENERGY

COMPANY

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: PRISCILLA SHORTY Signed on: DEC 04, 2023 02:01 PM

Name: HILCORP ENERGY COMPANY

Title: Regulatory Technician

Street Address: 382 ROAD 3100

City: AZTEC State: NM

Phone: (505) 324-5188

Email address: PSHORTY@HILCORP.COM

Field

Representative Name:

Street Address:

City:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK **BLM POC Title:** Petroleum Engineer

BLM POC Phone: 5055647742 BLM POC Email Address: krennick@blm.gov

Disposition Date: 12/04/2023 **Disposition:** Approved

Signature: Kenneth Rennick

Proposed BH Directive Repair Procedure - NOI Hubbell 3P

API # - 30-045-34196

Procedure:


Hold PJSM prior to beginning any and all operations. Properly document all operations via the JSA process. Ensure that all personnel onsite abide by HEC safety protocol, including PPE, housekeeping, and standard guidelines.


Verify cathodic protection is off and wellhead instrumentation is properly disconnected from the wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.

Verify there is no H2S present prior to beginning operations. If any H2S is present, take the necessary actions to ensure that the location is safe prior to beginning operations.

Observe and record pressures across all string daily, prior to beginning operations. **Notify NMOCD 24 hours prior to starting operations on location.**

- 1. Verify all wellhead valves are operatable.
- 2. Move onto well location with workover rig. Check well pressures on all casing strings and record (daily).
- 3. Check well for H2S and blow down well as necessary.
- 4. RD wellhead and RU BOPs. Function test BOP pipe rams and blind rams.
- 5. Release tbg hanger and TOOH with the 2 3/8" prod tbg.
- 6. RIH with 4.5" RBP. Set RBP above the Mesaverde top perf at +/- 4,468'.
- 7. MIT 4.5" from surface to RBP to 500psi to ensure no leaks. Chart and record test.
- 8. MIRU Wireline. Perforate squeeze holes below 7" shoe in 4.5" casing +/- 50ft below 7" intermediate casing shoe (+/- 4,050').
- 9. MIRU cement package squeeze through production casing at squeeze holes, attempting to circulate cement into the 4.5"x7" annulus. Wait on cement.
- 10.PU 4.5" cement DO BHA and DO cement with air package.
- 11. MIT wellbore from surface to RBP to 500 PSI. Chart and record test.
- 12. Bleed off any Intermediate Casing and/or Surface casing pressure to ensure source of gas has been isolated from the Intermediate and Surface Casing. If Bradenhead pressure is not eliminated, monitor for 90 days.
- 13. Retrieve RBP. Pull OOH.
- 14. TIH with tubing and RTP well on plunger lift.





Priscilla Shorty

From: Tammy Jones

Sent: Friday, November 17, 2023 7:04 AM

To: Kuehling, Monica, EMNRD; Farmington Regulatory Techs

Cc: Vermersch, Thomas, EMNRD

Subject: RE: [EXTERNAL] Hubbell 3P 30-045-34196

Monica - this has been sent to the Area Engineer.

Thanks,

Tammy Jones | HILCORP ENERGY COMPANY | San Juan Regulatory | 505.324.5185 | tajones@hilcorp.com

From: Kuehling, Monica, EMNRD <monica.kuehling@emnrd.nm.gov>

Sent: Thursday, November 16, 2023 3:14 PM

To: Farmington Regulatory Techs < Farmington Regulatory Techs@hilcorp.com>

Cc: Vermersch, Thomas, EMNRD <Thomas.Vermersch@emnrd.nm.gov>

Subject: [EXTERNAL] Hubbell 3P 30-045-34196

CAUTION: External sender. DO NOT open links or attachments from UNKNOWN senders.

Hello

On July 31, 2023 a bradenhead test was witnessed by NMOCD Inspector Thomas Vermersch.

Pressures on the well at time of test

	BH	Intermediate	Production casing
2023	219	534	40

Constant flow on both bradenhead and intermediate during full 30 minute test.

Previous tests

2020	35	262	45
2014	27	89	66
2011	19	137	91

Gas analysis and wellbore schematic have been received. Gas analysis shows same gas on bradenhead and intermediate however, gas on intermediate and bradenhead does not appear to be the same gas as production.

In order to comply with 19.15.16.11, prevent waste and protect fresh water, Hilcorp Energy Company is directed to find source of gas on bradenhead and intermediate and fix or plug within 90 days of the date of this email.

If you have any questions, please let me know.

Thank you

Monica Kuehling Compliance Officer Supervisor Deputy Oil and Gas Inspector New Mexico Oil Conservation Division North District

Office Phone: 505-334-6178 ext. 123

Cell Phone: 505-320-0243

Email - monica.kuehling@emnrd.nm.gov

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 290932

CONDITIONS

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	290932
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created B	Condition	Condition Date
mkuehli	Notify NMOCD prior to moving on - MIT required to be witnessed by NMOCD inspector - bradenhead test required prior to MIT day of MIT	12/4/2023