
Office	State of New Mexico	Form C-103 ¹ of
1625 N. French Dr., Hobbs, NM 88240	Minerals and Natural Resources	Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CC	NSERVATION DIVISION	30-025-46879
<u>District III</u> – (505) 334-6178	20 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		19552
87505 SUNDRY NOTICES AND REP	ORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		South Hobbs G/SA Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 297
2. Name of Operator		9. OGRID Number
Occidental Permian LTD. 3. Address of Operator		157984 10. Pool name or Wildcat
P.O. Box 4294, Houston, TX 77210		Hobbs; Grayburg - San Andres
4. Well Location		Transfer of the state of the st
Unit Letter L : 2443 feet	from the SOUTH line and	952 feet from the WEST line
	rnship 19S Range 38E	NMPM County LEA
11. Elevation 3621' (GL)	(Show whether DR, RKB, RT, GR, etc.)
3021 (GE)		
NOTICE OF INTENTION T PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PLA PULL OR ALTER CASING MULTIPLE CO DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM TO OTHER: 13. Describe proposed or completed operations of starting any proposed work). SEE RULI proposed completion or recompletion. Please see planned procedure attached.	BANDON	ILLING OPNS. P AND A T JOB D D D D D D D D D D D D D D D D D D D
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true an	d complete to the best of my knowleds	ge and belief.
signature <u>Roni Mathew</u>	TITLE Regulatory Advisor	DATE 2/6/2024
Type or print name Roni Mathew For State Use Only	E-mail address: roni_mathew@	PHONE: 713.215.7827
APPROVED BY:	TITLE	DATE
Conditions of Approval (if any):		

Objective: Pull ESP for failure. Set CIBP to isolate lower perfs for conformance reasons.


Job Plan:

- 1. POOH w/ ESP Equipment.
- 2. PU & RIH w/ bit to PBTD 4370'.
- 3. RU WL. Set CIBP ~4330'. RD WL.
- 4. PU & RIH w/ ESP Equipment.
- 5. Return well to production.

Current WBD



Proposed WBD



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 311926

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	311926
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
kfortner	None	2/16/2024