Reserved by OCDA post 2024 FO:43:16 AM State of New Mexico Office	Form Cplige 1 of 1 Revised August 1, 2011			
District I – (575) 393-6161 Energy, Minerals and Natural Reso	WELL API NO.			
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 OIL CONSERVATION DIVIS				
811 S. First St., Artesia, NM 88210 UIL CONSERVATION DIVIS	30-025-22585			
District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505	5. Indicate Type of Lease STATE X FEE			
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.			
87505	LG-6974-0003			
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	State 8 8. Well Number 001			
1. Type of Well: Oil Well X Gas Well Other				
2. Name of Operator	9. OGRID Number			
Novy Oil & Gas, Inc.	162499 10. Pool name or Wildcat			
3. Address of Operator P.O. Box 559 Goddard, KS 67052	Vada; Penn & East Lane; Abo			
4. Well Location				
9. 9. 44. 7	ne and 660 feet from theEastline			
Section 8 Township 10S Range	34E NMPM Lea County			
11. Elevation (Show whether DR, RKB, R				
12. Check Appropriate Box to Indicate Nature of	f Notice, Report or Other Data			
	SUBSEQUENT REPORT OF:			
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON REME	DIAL WORK ALTERING CASING			
TEN ONWINCEMEDIAL VOICE	IENCE DRILLING OPNS. ☐ P AND A XX			
TEINI OTOTICE TO THE TENE	IG/CEMENT JOB PNR			
DOWNHOLE COMMINGLE	11111			
OTHER: OTHER	R: L			
13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For M	fultible Completions: Attach wellbore diagram of			
proposed completion or recompletion.	futtiple Completions. Attach we no or e diagram or			
proposed completion of recompletion.				
SEE ATTACHE	D			
I hereby certify that the information above is true and complete to the best of my	y knowledge and belief.			
increase state and maximum as a second secon				
NOW THE ALL THE ALL THE ALL THE	DATE 1/3/2024			
Type or print name Connie L. Crook E-mail address: Nov	· // (a/kuyer) DATE // S/SOUT			
Type or print name Connie L. Crook E-mail address: Now	Voil @ 20/ COM PHONE: (3/6) 794-7200			
For State Use Only	1			
A 1				
APPROVED BY: Yelly John TITLE Compliance	ce Officer A DATE 2/16/24			
Conditions of Approval (if ar.):				

Plugging Report Novy Oil & Gas, Inc. State 8 #1 API 30-025-22585

- 11/28/2023 Moving in and rig up. Moved compressor equipment away from the wellhead. Removed horses head and unseated the pump. Could not lay down rods due to walking beam interfering with the blocks. Could not roll pump jack over due to bird nest in the belt guard. Removed belt guard and nest. Rolled weights down SION.
- 11/19/2023 Laid down rods and pump. 1357/8", 177 ¾", and 157/8" for sinkers. 391 total rods. Dug out wellhead and plumbed surface and intermediate heads to the steel pit.
- 11/30/2023 Installed BOP and worked anchor free. POOH with 43 stands and anchor hung. Worked through tight spot. Stood back 69 stands of 2 7/8" and 89 stands of 2 3/8" plus a single. Made gauge ring run with junk basket and sat down at 7135'. Stuck, Jarred loose and POOH.
- 12/1/2023 Laid down 2 3/8" tubing due to poor condition. Moved in 2 3/8" workstring. Picked up 4 5/8" tapered mill and start in the hole with tubing. Picked up 150 joints of workstring and SION.
- Tagged up on tight spot at 7140'. Worked mill with tubing tongs. Could nit keep rotation with out getting stuck. Began to spud and was able to get through the tight spot. Worked until relatively clear. POOH with tubing and tool. Made gauge ring run to 9850' without issue. POOH and SION
- 12/5/2023 RIH with 4.25 CIBP and Baker 20 setting tool on wireline. Could not get past bad spot at 7135'. POOH with setting tool. Called in. Brought out a short joint of wash pipe and 4 5/8" shoe. RIH and start working on tight spot with power swivel. Cut for 2.5 hrs and made about 10". Stopped cutting. Lay down swivel and prep to pull tubing in the morning.
- 12/6/2023 POOH with tools. Picked up same 4 5/8" tapered mill and RIH. Tagged up and cleaned up approximately 2' of bad pipe. POOH with tool and made gauge ring run. No issue going through the tight spot. POOH and SION
- 12/7/2023 RIH with CIBP on wireline and could not get past tight spot at 7140'. POOH and made another gauge ring run. Could see tight spot on weight indicator. Called in. Brought out mechanical setting tool and CIBP. RIH with tubing and set CIBP at 9828'. Pumped 50 bbls MLF and laid down 27 joints pipe. SION
- Tubing stuck. Could not work free or get any movement up, down or with rotation. Stretch test ineffective due to split string. Made 17/16" sinker bar run inside tubing and could not get past 5700'. Called OCD. And talked to Gilbert Cordero and discussed issue. Cut tubing at 5630'. POOH and picked up packer. RIH with packer and left swinging at 5146'.
- 12/11/2023 Set packer at 5146' and squeezed below packer to perforations with 625 sx Class H cement. WOC 4 hrs. Released packer and tagged cement at 5441'. Circulated MLF and SION.
- 12/12/2023 POOH with tubing and top off casing with water. Made gauge ring run and ran cement bond log. TOC at 2830'. RIH with tubing and spot 30 sx cement at 4204'. POOH and SION.
- 12/13/2023 Tagged cement at 3881'. POOH with tubing and removed top spool to expose 5 ½" casing. Shut down for weather.
- 12/15/2023 Weld on 17# pull stub. Cut casing at 2814'. Laid down 74 joints casing plus the top and bottom cut offs. Reinstalled wellhead and SION.

Received by QCD: 1/3/2024 10:13:164. Pressured up on perforations to 600# and held. Bled off at the truck and repeatence 3 of 10 with same result. RIH with tubing and spot 60 sx Class C cement with CaCl from 2868'. WOC and tagged at 2647'. POOH and perforated at 2210'. Set packer and pressured up on perfs to 500#. Held. Bled down at truck and repeated. Pulled packer and RIH to 2268' and spot 60 sx cement. POOH and SION.

12/19/2023 Tagged cement at 2167'. Low. Caught circulation and pressured up on 8 5/8" casing to 600# and held. Spot 35 sx cement at 2167'. POOH and perforate at 448'. Pressured up to 550# and held. Bled down at truck and repeated with same results. RIH to 504' and circulated cement to surface inside 8 5/8" casing to surface with 140 sx. Rigged down.

12/20/2020 Dug out and removed the wellhead. Good cement in side the 8 5/8" and existing (old) cement in the 8 5/8" X 13 3/8" annulus. Installed BGM, removed the anchors and moved out equipment.







Plugging Report Novy Oil & Gas, Inc. State 8 #1 API 30-025-22585

- 11/28/2023 Moving in and rig up. Moved compressor equipment away from the wellhead. Removed horses head and unseated the pump. Could not lay down rods due to walking beam interfering with the blocks. Could not roll pump jack over due to bird nest in the belt guard. Removed belt guard and nest. Rolled weights down SION.
- 11/19/2023 Laid down rods and pump. 135 7/8", 177 ¾", and 15 7/8" for sinkers. 391 total rods. Dug out wellhead and plumbed surface and intermediate heads to the steel pit.
- 11/30/2023 Installed BOP and worked anchor free. POOH with 43 stands and anchor hung. Worked through tight spot. Stood back 69 stands of 2 7/8" and 89 stands of 2 3/8" plus a single. Made gauge ring run with junk basket and sat down at 7135'. Stuck. Jarred loose and POOH.
- 12/1/2023 Laid down 2 3/8" tubing due to poor condition. Moved in 2 3/8" workstring. Picked up 4 5/8" tapered mill and start in the hole with tubing. Picked up 150 joints of workstring and SION.
- 12/4/2023 Tagged up on tight spot at 7140'. Worked mill with tubing tongs. Could nit keep rotation with out getting stuck. Began to spud and was able to get through the tight spot. Worked until relatively clear. POOH with tubing and tool. Made gauge ring run to 9850' without issue. POOH and SION
- 12/5/2023 RIH with 4.25 CIBP and Baker 20 setting tool on wireline. Could not get past bad spot at 7135'. POOH with setting tool. Called in. Brought out a short joint of wash pipe and 4 5/8" shoe. RIH and start working on tight spot with power swivel. Cut for 2.5 hrs and made about 10". Stopped cutting. Lay down swivel and prep to pull tubing in the morning.
- 12/6/2023 POOH with tools. Picked up same 4 5/8" tapered mill and RIH. Tagged up and cleaned up approximately 2' of bad pipe. POOH with tool and made gauge ring run. No issue going through the tight spot. POOH and SION
- 12/7/2023 RIH with CIBP on wireline and could not get past tight spot at 7140'. POOH and made another gauge ring run. Could see tight spot on weight indicator. Called in. Brought out mechanical setting tool and CIBP. RIH with tubing and set CIBP at 9828'. Pumped 50 bbls MLF and laid down 27 joints pipe. SION
- 12/8/2023 Tubing stuck. Could not work free or get any movement up, down or with rotation. Stretch test ineffective due to split string. Made 1 7/16" sinker bar run inside tubing and could not get past 5700'. Called OCD. And talked to Gilbert Cordero and discussed issue. Cut tubing at 5630'. POOH and picked up packer. RIH with packer and left swinging at 5146'.
- 12/11/2023 Set packer at 5146' and squeezed below packer to perforations with 625 sx Class H cement. WOC 4 hrs. Released packer and tagged cement at 5441'. Circulated MLF and SION.
- 12/12/2023 POOH with tubing and top off casing with water. Made gauge ring run and ran cement bond log. TOC at 2830'. RIH with tubing and spot 30 sx cement at 4204'. POOH and SION.
- 12/13/2023 Tagged cement at 3881'. POOH with tubing and removed top spool to expose 5 ½" casing. Shut down for weather.
- 12/15/2023 Weld on 17# pull stub. Cut casing at 2814'. Laid down 74 joints casing plus the top and bottom cut offs. Reinstalled wellhead and SION.

Novy Oil & Gas, Inc. State 8 #1 API 30-025-22585 WBD After PA Below Ground Marker Perforate at 448'. Pressure up 13 3/8" 48# casins set @ 398' no communication or rate. Ciculated to surface in 8 5/8" with 435 sx. Circulated with 140 sx frpom 504'. Existing cement in surcase annulus after cutting off wellhead. Perforate at 2210' could not squeeze Spot 60 sx & 35 sx. Top Salt Perf at 2814' Could not squeeze. Spot 60 sx Class C from 2868'. Tagged at 2647' 5 1/2" Stub Yates & Base of Salt. Cut and pull 5 1/2" from 2814' 8 5/8" 48# casing set at 4155' Cemented w/800 sx TOC 3000' Spot 30 sx cement from 4204'. Intermediate shoe & SA top Squeezed 625 sx Class H to cover from top of fish to Abo perfs. Tagged at 5441'. 150% excess Top of 2 3/8" fish at 5630' 5517' Top Glorieta 7005' Top Tubb Perforations 9000' to 9025' Abo Mechnical setting tool @ 8922' 5.5" CIBP at 9828' with cement on top Bough C Perforations 9908' to 9916' Bough C 5 1/2" 17 & 20# casing set at 9965' Cemented w/1000 sx cement TOC at 2830" as per CBL 12/12/23

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 299408

COMMENTS

Operator:	OGRID:
NOVY OIL & GAS, INC	162499
PO Box 559	Action Number:
Goddard, KS 67052	299408
	Action Type:
	[C-103] Sub. Plugging (C-103P)

COMMENTS

Created By		Comment Date
plmartinez	DATA ENTRY PM.	2/19/2024

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 299408

CONDITIONS

Operator:	OGRID:
NOVY OIL & GAS, INC	162499
PO Box 559	Action Number:
Goddard, KS 67052	299408
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
kfortner	Need C103Q and marker photo to release	2/16/2024