eccived by UCD: 12/18/2023 11:31:28 AM U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Repor
Well Name: FEDERAL 27	Well Location: T22S / R32E / SEC 27 / NWNW /	County or Parish/State: LEA / NM
Well Number: 02	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM69376	Unit or CA Name:	Unit or CA Number:
US Well Number: 3002533652	Well Status: Abandoned	Operator: OXY USA INCORPORATED

Subsequent Report

Sundry ID: 2766420

MCC

Type of Submission: Subsequent Report Date Sundry Submitted: 12/18/2023 Date Operation Actually Began: 11/27/2023

Type of Action: Plug and Abandonment Time Sundry Submitted: 08:47

Actual Procedure: THE FINAL WELLBORE AND PA JOB SUMMARY REPORT ARE ATTACHED.

Accepted for record –NMOCD gc2/29/2024

SR Attachments

Actual Procedure

FEDERAL_27_2_PA_SR_SUB_12.18.2023_20231218084742.pdf

k	eceived by OCD: 12/18/2023 11:31:28 AM Well Name: FEDERAL 27	Well Location: T22S / R32E / SEC 27 / NWNW /	County or Parish/State: LEA
	Well Number: 02	Type of Well: OIL WELL	Allottee or Tribe Name:
	Lease Number: NMNM69376	Unit or CA Name:	Unit or CA Number:
	US Well Number: 3002533652	Well Status: Abandoned	Operator: OXY USA INCORPORATED

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: STEPHEN JANACEK

Name: OXY USA INCORPORATED

Title: Regulatory Engineer

Street Address: 5 Greenway Plaza, Suite 110

City: Houston

State: TX

State:

Phone: (713) 497-2417

Email address: stephen_janacek@oxy.com

Field

Representative Name: Street Address: City: Phone: Email address:

BLM Point of Contact

BLM POC Name: JAMES A AMOS BLM POC Phone: 5752345927 Disposition: Accepted Signature: James A Amos

BLM POC Title: Acting Assistant Field Manager BLM POC Email Address: jamos@blm.gov Disposition Date: 12/18/2023

Zip:

Signed on: DEC 18, 2023 08:47 AM

Received by OCD: 12/18/2023 11:31:28 AM

<i>Ceceiveu by OCD</i> . 12/10/2023) 11.31.20 AM			ruge 5 0j
	UNITED STATI EPARTMENT OF THE I REAU OF LAND MAN	INTERIOR	0	ORM APPROVED MB No. 1004-0137 ires: October 31, 2021
ВО	KEAU OF LAND MAN	AGEMENT	5. Deuse Seriar 10.	
Do not use this		ORTS ON WELLS to drill or to re-enter an APD) for such proposals.	6. If Indian, Allottee of	Tribe Name
	NTRIPLICATE - Other instr	ructions on page 2	7. If Unit of CA/Agree	ement, Name and/or No.
1. Type of Well				
Oil Well Ga	s Well Other		8. Well Name and No.	
2. Name of Operator			9. API Well No.	
3a. Address		3b. Phone No. <i>(include area code)</i>	10. Field and Pool or H	Exploratory Area
4. Location of Well (Footage, Sec., 7	F.,R.,M., or Survey Description)	11. Country or Parish,	State
12. CI	HECK THE APPROPRIATE B	BOX(ES) TO INDICATE NATURE O	F NOTICE, REPORT OR OTH	IER DATA
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION	
Notice of Intent	Acidize	Deepen [Hydraulic Fracturing	Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon	Other
Final Abandonment Notice	Convert to Injection	n Plug Back	Water Disposal	
the proposal is to deepen direction the Bond under which the work completion of the involved opera	onally or recomplete horizontal will be perfonned or provide th ations. If the operation results i	lly, give subsurface locations and measure Bond No. on file with BLM/BIA. R in a multiple completion or recompletion	sured and true vertical depths of equired subsequent reports must ion in a new interval, a Form 31	rk and approximate duration thereof. If f all pertinent markers and zones. Attach st be filed within 30 days following 60-4 must be filed once testing has been he operator has detennined that the site

14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/Typed</i>)			
T	itle		
Signature	ate		
Signature D			
THE SPACE FOR FEDER	AL OR STATE OF	FICE USE	
Approved by			
	Title	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any p any false, fictitious or fraudulent statements or representations as to any matter within i		Ifully to make to any department or agency of the U	nited States

(Instructions on page 2)

GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment. If the proposal will involve **hydraulic fracturing operations**, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

NOTICES

The privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and granting approval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.

The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.


BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

Additional Information

Location of Well

0. SHL: NWNW / 990 FNL / 990 FWL / TWSP: 22S / RANGE: 32E / SECTION: 27 / LAT: 0.0 / LONG: 0.0 (TVD: 0 feet, MD: 0 feet) BHL: NWNW / 990 FNL / 990 FWL / TWSP: 22S / SECTION: / LAT: 0.0 / LONG: 0.0 (TVD: 0 feet, MD: 0 feet)

FINAL WELLBORE DIAGRAM 12/18/2023



Federal 27 #002 30-025-33652 PA JOB SUMMARY

AFTER HOLLIDAYS SAFETY STAND DOWN, HPJSM WITH ALL PERSONAL ON LOCA' DISCUSS STOP WORK AUTHORITY GOOD COMMUNICATION AT ALL TIME SUSPEN LOADS ONE TASK AT A TIME PINCH POINTS HAND PLACEMENT UPDATE JSA AS T 11/27/2023 CHANGES, LOAD EQUIPMENT DROVE PULLING UNIT & P&A PUMP ASSOCIATED EQUIPMEN 11/27/2023 THE FEDERAL 27 007 TO THE FEDERAL 27 002 UNLOAD EQUIPMENT SPOT BASE BEAM MIRU AXIS 2141 PU & P&A ASSOCIATED 11/27/2023 EQUIPMENT CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE 5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSC 11/27/2023 FULL OF CMT AND ALREADY CUT OFF) UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH 11/27/2023 SET CO/FO & FUNCTION TEST PICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD 11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 - 1" FIBER GLASS ROD SUBS, RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN 11/27/2023 INSTALL 2-3/8" TIW VALVE 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL DOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION RIG UP STEEL LINE TO FLOW BACK TANK BLEED OFF GAS HEAD F/ CSG PUMP 100	
LOADS ONE TASK AT A TIME PINCH POINTS HAND PLACEMENT UPDATE JSA AS T 11/27/2023 CHANGES, LOAD EQUIPMENT DROVE PULLING UNIT & P&A PUMP ASSOCIATED EQUIPMEN 11/27/2023 THE FEDERAL 27 007 TO THE FEDERAL 27 002 UNLOAD EQUIPMENT SPOT BASE BEAM MIRU AXIS 2141 PU & P&A ASSOCIATED 11/27/2023 EQUIPMENT CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE 5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSG 11/27/2023 FULL OF CMT AND ALREADY CUT OFF) UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH 11/27/2023 SET CO/FO & FUNCTION TEST PICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD 11/27/2023 26' POLISH ROD & 18' – 1" FIBER GLASS ROD SUBS, RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN 11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 INSTALL 2-3/8" TIW VALVE 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL DOCATION 11/28/2023 HPISM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	וחרח
11/27/2023CHANGES,11/27/2023ILOAD EQUIPMENT DROVE PULLING UNIT & P&A PUMP ASSOCIATED EQUIPMEN11/27/2023THE FEDERAL 27 007 TO THE FEDERAL 27 002UNLOAD EQUIPMENT SPOT BASE BEAM MIRU AXIS 2141 PU & P&A ASSOCIATED11/27/2023EQUIPMENTCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSC11/27/2023FULL OF CMT AND ALREADY CUT OFF)UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH11/27/2023SET CO/FO & FUNCTION TESTPICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD11/27/202326' POLISH ROD & 18' - 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 - 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL TO LOCATION11/28/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/2023O PSI, 10-3/4" SURF CSG = 0 PSI	IDED
LOAD EQUIPMENT DROVE PULLING UNIT & P&A PUMP ASSOCIATED EQUIPMEN 11/27/2023 THE FEDERAL 27 007 TO THE FEDERAL 27 002 UNLOAD EQUIPMENT SPOT BASE BEAM MIRU AXIS 2141 PU & P&A ASSOCIATED 11/27/2023 EQUIPMENT CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE 5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSC 11/27/2023 FULL OF CMT AND ALREADY CUT OFF) UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH 11/27/2023 BOLT FROM HORSE HEAD DUE TO RUSTED BOLT) 11/27/2023 SET CO/FO & FUNCTION TEST PICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD 11/27/2023 26' POLISH ROD & 18' - 1" FIBER GLASS ROD SUBS, RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN 11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 - 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL DI COCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	ASK
11/27/2023THE FEDERAL 27 007 TO THE FEDERAL 27 002UNLOAD EQUIPMENT SPOT BASE BEAM MIRU AXIS 2141 PU & P&A ASSOCIATED11/27/2023EQUIPMENTCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSG11/27/2023FULL OF CMT AND ALREADY CUT OFF)UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH11/27/2023SET CO/FO & FUNCTION TESTPICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD11/27/202326' POLISH ROD & 18' - 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 - 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL TO LOCATION11/28/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/20230 PSI, 10-3/4" SURF CSG = 0 PSI	
UNLOAD EQUIPMENT SPOT BASE BEAM MIRU AXIS 2141 PU & P&A ASSOCIATED 11/27/2023 EQUIPMENT CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE 5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSC 11/27/2023 FULL OF CMT AND ALREADY CUT OFF) UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH 11/27/2023 BOLT FROM HORSE HEAD DUE TO RUSTED BOLT) 11/27/2023 SET CO/FO & FUNCTION TEST PICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD 11/27/2023 26' POLISH ROD & 18' – 1" FIBER GLASS ROD SUBS, RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN 11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	Γ FROM
11/27/2023EQUIPMENTCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE 5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSG11/27/2023FULL OF CMT AND ALREADY CUT OFF)UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH11/27/2023BOLT FROM HORSE HEAD DUE TO RUSTED BOLT)11/27/2023SET CO/FO & FUNCTION TESTPICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD11/27/202326' POLISH ROD & 18' - 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 - 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL BACK HOME11/27/2023REW TRAVEL BACK HOME11/27/2023HPJSM WITH ALL PERSONAL ON LOCATION11/28/2023POSI, 10-3/4" SURF CSG = 0 PSI	
CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, DIG OUT CE 5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSG 11/27/2023 FULL OF CMT AND ALREADY CUT OFF) UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH 11/27/2023 SET CO/FO & FUNCTION TEST PICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD 11/27/2023 26' POLISH ROD & 18' – 1" FIBER GLASS ROD SUBS, RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN 11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
5/8" INTER CSG = 0 PSI (LITTLE BLOW) 10-3/4" SURF CSG = 0 PSI NOTE: SURF CSG11/27/2023FULL OF CMT AND ALREADY CUT OFF)UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH11/27/2023BOLT FROM HORSE HEAD DUE TO RUSTED BOLT)11/27/2023SET CO/FO & FUNCTION TESTPICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD11/27/202326' POLISH ROD & 18' - 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 - 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL BACK HOME11/27/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/20230 PSI, 10-3/4" SURF CSG = 0 PSI	
11/27/2023FULL OF CMT AND ALREADY CUT OFF)UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH11/27/2023BOLT FROM HORSE HEAD DUE TO RUSTED BOLT)11/27/2023SET CO/FO & FUNCTION TESTPICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD11/27/202326' POLISH ROD & 18' - 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 - 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023INSTALL 2-3/8" TIW VALVE11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL BACK HOME11/27/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/20230 PSI, 10-3/4" SURF CSG = 0 PSI	LLAR 7-
UNHANG WELL LD PUMPING UNIT HEAD (NOTE: HAD PROBLEMS REMOVING TH 11/27/2023 BOLT FROM HORSE HEAD DUE TO RUSTED BOLT) 11/27/2023 SET CO/FO & FUNCTION TEST PICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD 11/27/2023 26' POLISH ROD & 18' – 1" FIBER GLASS ROD SUBS, RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN 11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 INSTALL 2-3/8" TIW VALVE 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 SECURE WELL SDFN 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	i IS
11/27/2023BOLT FROM HORSE HEAD DUE TO RUSTED BOLT)11/27/2023SET CO/FO & FUNCTION TESTPICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD11/27/202326' POLISH ROD & 18' - 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 - 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023INSTALL 2-3/8" TIW VALVE11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023SECURE WELL SDFN11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL TO LOCATION11/28/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/20230 PSI, 10-3/4" SURF CSG = 0 PSI	
11/27/2023SET CO/FO & FUNCTION TESTPICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD11/27/202326' POLISH ROD & 18' – 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023INSTALL 2-3/8" TIW VALVE11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023SECURE WELL SDFN11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL TO LOCATION11/28/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/20230 PSI, 10-3/4" SURF CSG = 0 PSI	ROAT
PICK UP ON POLISH ROD, RODS STRING WEIGHT = 1 PT, (RODS ARE PARTED) LD 11/27/2023 26' POLISH ROD & 18' – 1" FIBER GLASS ROD SUBS, RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN 11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 INSTALL 2-3/8" TIW VALVE 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 SECURE WELL SDFN 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL BACK HOME 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
11/27/202326' POLISH ROD & 18' – 1" FIBER GLASS ROD SUBS,RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023INSTALL 2-3/8" TIW VALVE11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023SECURE WELL SDFN11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL TO LOCATION11/28/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/20230 PSI, 10-3/4" SURF CSG = 0 PSI	
RU WORK FLOOR AND ROD HANDLING TOOLS, SET UP SAFETY EQUIPMENT, CEN11/27/2023LEVEL RIG OVER HOLEPOOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU11/27/2023INSTALL 2-3/8" TIW VALVE11/27/2023CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS11/27/2023SECURE WELL SDFN11/27/2023CREW TRAVEL BACK HOME11/27/2023CREW TRAVEL TO LOCATION11/28/2023HPJSM WITH ALL PERSONAL ON LOCATIONCHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE11/28/20230 PSI, 10-3/4" SURF CSG = 0 PSI	L-1/4″ X
11/27/2023 LEVEL RIG OVER HOLE POOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 INSTALL 2-3/8" TIW VALVE 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 SECURE WELL SDFN 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
POOH LD 42 – 1" FIBER GLASS RODS, (FOUND PIN BREAK ON ROD # 42 FROM SU 11/27/2023 INSTALL 2-3/8" TIW VALVE 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 SECURE WELL SDFN 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	TER &
11/27/2023 INSTALL 2-3/8" TIW VALVE 11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 SECURE WELL SDFN 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
11/27/2023 CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS 11/27/2023 SECURE WELL SDFN 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	RF) <i>,</i>
11/27/2023 SECURE WELL SDFN 11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
11/27/2023 CREW TRAVEL BACK HOME 11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
11/27/2023 CREW TRAVEL TO LOCATION 11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
11/28/2023 HPJSM WITH ALL PERSONAL ON LOCATION CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 300 PSI, 7-5/8" INTE 11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
11/28/2023 0 PSI, 10-3/4" SURF CSG = 0 PSI	
	R CSG =
RIG UP STEELLINE TO FLOW BACK TANK BLEED OFF GAS HEAD F/ CSG PUMP 100	
	BBLS
OF 10# BW DOWN CSG FOR WELL CONTROL CSG WENT ON VACUUM, MONITOR	WELL
11/28/2023 FOR 15 MINUTES WELL STATIC	
11/28/2023 FUNCTION TEST BOP W/ A GOOD TEST	
11/28/2023 ND 3K X 7-1/16" B-1 WH FLANGE	
NU 3K X 5K X 7-1/16" SPOOL, NU 5K HYD BOP W/ 5K 2-7/8" & 2-3/8" PIPE RAMS	ON
11/28/2023 TOP AND 5K BLINDS ON BOTTOM	
RU WORK FLOOR W/ 2-3/8" TBG HANDLING TOOLS, SET UP SAFETY EQUIP, CENT	ER &
11/28/2023 LEVEL RIG OVER HOLE	
11/28/2023 PERFORM BOP CLOSING DRILL SECURED WELL CREW MET @ MUSTER AREA IN 1	MIN

	PICK UP ON TBG TO SET TBG SLIPS IN POSITION TBG WEIGHT @ 64 PTS ATTEMP TO UNSEAT TAC USING TBG TONGS WORKING PIPE UP & DOWN MULTIPLE TIMES W/ NEGATIVE RESULTS MIRU PS CONTINUE WORKING TBG UP & DOWN ROTATING TBG TO THE RIGHT LEAVING TORQUE ON TBG WHILE WORKING IT F/ 34K TO 64K FINDING NEUTRAL WEIGHT @ 48K GOT TAC UNSEATED LD 2 JTS W/ PS, RDMO PS
11/28/2023	
11/20/2023	RU VACUUM TRUCK ON CELLAR POOH WET W/ 51 OF 2-3/8" L-80 TBG, GOT TO RODS
11/28/2023	SET TAC, CLOSE BOP
11/20/2023	CHANGE OVER TO ROD EQUIPMENT, PICK UP ON RODS, STRING WEIGHT = 10 PTS JAR
	ON STUCK PUMP MULTIPLE TIMES GOT PUMP UNSEATED, RU SUCKER ROD STRIPPER
11/28/2023	
11/20/2023	
11/28/2023	PUMP 20 BBLS OF 10# BW DOWN TBG FOR WELL CONTROL TBG WENT ON VACUUM
,,	CONTINUE STRIPPING RODS OUT OF THE HOLE POOH LD 85 – 1" FG RODS GOT OUT W/
	A TOTAL OF 53 JTS OF 2-3/8" TBG AND 85 – 1" FG RODS PICK UP POLISH ROD &
11/28/2023	STUFFING BOX
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
, -,	CHECK PSI ON WELL 2-3/8" TBG = 100 PSI, 4-1/2" PROD CSG = 180 PSI, 7-5/8" INTER
11/29/2023	CSG = 0 PSI, 10-3/4" SURF CSG = 0 PSI
	BLEED OFF GAS HEAD FROM TBG & CSG PUMP 30 BBLS DOWN TBG & 80 BBLS DOWN
	CSG OF 10# BW FOR WELL CONTROL TBG & CSG WENT ON VACUUM MONITOR WELL
11/29/2023	FOR 15 MINUTES WELL STATIC
11/29/2023	SET CO/FO & FUNCTION TEST
11/29/2023	LD 1-1/4" X 26' POLISH ROD
	CONTINUE POOH LD 132 – 7/8" (N-97) SUCKER RODS, 3 – 1-1/4" SINKER BARS 1 – 3/4"
	SHEER TOOL 1 – 1-1/4" SINKER BAR 4' X 7/8" STABILIZER SUB & 25-150-RHBC-24-5 ROD
11/29/2023	PUMP W/ 16' X 1" GAS ANCHOR
	CHANGE OVER EQUIPMENT TO 2-3/8" TBG HANDLING TOOLS
11/29/2023	BREAK FOR CREW LUNCH
	OPEN BOP UNSEAT TAC CONTINUE POOH W/ 205 JTS OF 2-3/8" L-80 TBG FOR A TOTAL
	OF 258 JTS OF 2-3/8" L-80 TBG, 1 – 4' X 2-3/8" TBG MARKER SUB, 3 JTS OF 2-3/8" L-80
	TBG, 1 – 4.5" X 2-3/8" TAC, 3 JTS OF 2-3/8" L-80 TBG, 1 – 2-3/8" SEAT NIPPLE, 1 – 2-3/8"
11/29/2023	12 SLOT SAND SCREEN, 1 JT OF 2-3/8" MUD ANCHOR JT W/ 2-3/8" BULL PLUG
	MAKE UP 4.5" (3.75" OD) CREST PKR (PLAN IS TO PRESSURE TEST 4.5" PROD CSG TO 500
	PSI F/ 8260' 50' ABOVE TOP PERFS (8310') TO 0' (SURF) RIH W/ 2-3/8" TBG TALLY RIH
	LEAVE PKR SWINGING @ 3546' W/ 114 JTS IN THE HOLE, CLOSE BOP, INSTALL 2-3/8"
11/29/2023	TIW VALVE
11/29/2023	SECURE WELL SDFN
11/29/2023	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
11/30/2023	HPJSM WITH ALL PERSONAL ON LOCATION

.

	CHECK PSI ON WELL 2-3/8" TBG = 100 PSI, 4-1/2" PROD CSG = 100 PSI, 7-5/8" INTER
11/30/2023	CSG = 0 PSI, 10-3/4" SURF CSG = 0 PSI
	BLEED OFF GAS HEAD FROM TBG & CSG PUMP 20 BBLS DOWN TBG & 50 BBLS DOWN
	CSG OF 10# BW FOR WELL CONTROL TBG & CSG WENT ON VACUUM MONITOR WELL
11/30/2023	FOR 15 MINUTES WELL STATIC
11/30/2023	SET CO/FO & FUNCTION TEST
	CONTINUE RIH W/ 4.5" (3.75" OD) CREST PKR TO PRESSURE TEST 4.5" CSG TO ENSURE
	CSG INTEGRITY, RIH W/ 2-3/8" TBG TALLY RIH SET PKR @ 8269' (TMD) (PKR SET 41'
11/30/2023	ABOVE TOP PERFS 8310') W/ 265 JTS IN THE HOLE
	RU PUMP ON 4.5" CSG LOAD BACK SIDE W/ 82 BBLS OF FW TRY TO TEST BACK SIDE
	PUMP 10 BBLS OF FW GOT ON INJ – RATE OF 2 BPM @ 250 PSI (FAIL) UNSEAT PKR
	COME UP HOLE SET PKR @ 7928' (TMD) W/ 254 JTS IN THE HOLE, LOAD BACK SIDE W/
	15 BBLS OF FW TRY TO TEST BACK SIDE PUMP 10 BBLS OF FW GOT ON INJ – RATE OF 1
	BPM @ 350 PSI (FAIL) UNSEAT PKR COME UP HOLE SET PKR @ 7189' W/ 230 JTS IN THE
	HOLE LOAD BACK SIDE W/ 1 BBLS OF FW, PRESSURE UP 4.5" CSG TO 600 PSI HOLD
	CSG TESTED GOOD F/ 7189' في CSG TESTED GOOD F/ 7189
	TO 0' (SURFACE) BLEED OFF PRESSURE UNSEAT PKR, NOTE: UNABLE TO CONTINUE TO
	ISOLATE HOLE ON CSG DUE TO HIGH WIND 30 TO 40 MPH W/ GUST UP TO 55 MPH,
11/30/2023	CLOSE BOP, INSTALL 2-3/8" TIW VALVE
11/30/2023	SECURE WELL SDFN
, ,	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
12/1/2023	HPJSM WITH ALL PERSONAL ON LOCATION
	CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 0 PSI, 7-5/8" INTER CSG = 0
12/1/2023	PSI, 10-3/4" SURF CSG = 0 PSI
	BLEED OFF GAS HEAD FROM TBG & CSG PUMP 20 BBLS DOWN TBG & 50 BBLS DOWN
	CSG OF 10# BW FOR WELL CONTROL TBG & CSG WENT ON VACUUM MONITOR WELL
	FOR 15 MINUTES WELL STATIC
12/1/2023	SET CO/FO & FUNCTION TEST

	7613' (TMD) W/ 244 JTS IN THE HOLE, LOAD BACK SIDE W/ 8 BBLS OF FW TRY TO TEST BACK SIDE PUMP 10 BBLS OF FW GOT INJ – RATE OF 1 BPM @ 350 PSI (FAIL)
	UNSEAT PKR COME UP HOLE SET PKR @ 7553' (TMD) W/ 242 JTS IN THE HOLE, LOAD BACK SIDE W/ 3 BBLS OF FW TRY TO TEST BACK SIDE PUMP 5 BBLS OF FW GOT INJ – RATE OF 1 BPM @ 350 PSI (FAIL)
	UNSEAT PKR COME UP HOLE SET PKR @ 7492' (TMD) W/ 240 JTS IN THE HOLE, LOAD BACK SIDE W/ 1 BBLS OF FW TRY TO TEST BACK SIDE PUMP 5 BBLS OF FW GOT INJ – RATE OF 1 BPM @ 350 PSI (FAIL)
	UNSEAT PKR COME UP HOLE SET PKR @ 7371' (TMD) W/ 236 JTS IN THE HOLE, LOAD BACK SIDE W/ 1 BBLS OF FW TRY TO TEST BACK SIDE PUMP 5 BBLS OF FW GOT INJ – RATE OF 1 BPM @ 300 PSI (FAIL)
	UNSEAT PKR COME UP HOLE SET PKR @ 7313' (TMD) W/ 234 JTS IN THE HOLE, LOAD BACK SIDE W/ 1 BBLS OF FW TRY TO TEST BACK SIDE PUMP 5 BBLS OF FW GOT INJ – RATE OF 1 BPM @ 250 PSI (FAIL)
	UNSEAT PKR COME UP HOLE SET PKR @ 7254' (TMD) W/ 232 JTS IN THE HOLE, LOAD BACK SIDE W/ 1 BBLS OF FW TRY TO TEST BACK SIDE PUMP 5 BBLS OF FW GOT INJ – RATE OF 1 BPM @ 250 PSI (FAIL)
12/1/2023	UNSEAT PKR COME UP HOLE SET PKR @ 7223' (TMD) W/ 231 JTS IN THE HOLE, LOAD BACK SIDE W/ 1 BBLS OF FW TRY TO TEST BACK SIDE PUMP 5 BBLS OF FW GOT INJ – RATE OF 1 BPM @ 250 PSI (FAIL)
	UNSEAT PKR POOH W/ 231 JTS OF 2-3/8" TBG LD 4.5" (3.75" OD) CREST PKR
12/1/2023	MIRU RTX WL RIH W/ 3.62" OD GR/JB TO 8275' (WMD) W/ NO ISSUES POOH W/ GR/JB / MAKE UP 3.50" OD CIBP FOR 4.5" CSG RIH W/ WL SET CIBP @ 8260' (WMD) W/ NO ISSUES PULL UP HOLE W/ WL 50' RBIH LIGHT TAG CIBP @ 8260' (WMD) CONFIRMED PLUG SET SUCCESSFULLY, POOH W/ WL SETTING TOOL RDMO RTX WL
	MAKE UP 4.5" (3.75" OD) CREST PKR, RIH W/ 2-3/8" TBG LEAVE PKR SWINGING @ 1875'
	W/ 60 JTS IN THE HOLE, CLOSE BOP, INSTALL 2-3/8" TIW VALVE
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
12/2/2023	HPJSM WITH ALL PERSONAL ON LOCATION
12/2/2022	CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 0 PSI, 7-5/8" INTER CSG = 0
12/2/2023	PSI, 10-3/4" SURF CSG = 0 PSI
	BLEED OFF GAS HEAD FROM TBG & CSG PUMP 20 BBLS DOWN TBG & 40 BBLS DOWN
17/7/2022	CSG OF 10# BW FOR WELL CONTROL TBG & CSG WENT ON VACUUM MONITOR WELL FOR 15 MINUTES WELL STATIC
	SET CO/FO & FUNCTION TEST
12/2/2023	

	CONTINUE RIH W/ 4.5" (3.75" OD) CREST PKR ON 2-3/8" TBG SET PKR W/ 20 PTS
12/2/2023	COMPRESSION @ 6571' (TMD) W/ 210 JTS IN THE HOLE
	RU PUMP ON 4.5" CSG LOAD BACK SIDE W/ 8 BBLS BW, TEST PKR TO 500 PSI W/ A
12/2/2023	GOOD TEST, CLOSE CSG VALVE AND LEAVE 500 PSI HOLDING PRESSURE ON BACK SIDE
	LOAD BULK TRK W/ 200 SX CLASS H CMT, RU CMT PUMP ON TBG EST- INJ RATE W/ BW
12/2/2023	2.25 BPM @ 250 PSI PUMP TOTAL OF 80 BBLS BW TBG WENT ON VACUUM
	SQZ CSG LEAK F/ 7199' – 8237' W/ 200 SX CLASS H CMT, 42.03 BBLS SLURRY, 15.6# 1.18
	YIELD, COVERING 2711' DISPLACE TOC TO 7000' (199' ABOVE CSG HOLE) DISPLACE W/
	32.06 BBLS OF BW, PUMP CMT RATE 1 BPM @ 0 PSI, NOTE: MIX LAST 100 SXS = 21.01
	BBLS SLURRY W/ 10 LBS OF (LCM) (LOST CIRCULATION MATERIAL) PUMP
	DISPLACEMENT 1 BPM @ 0 PSI AFTER 22 BBLS GONE PUMPING RATE 1 BPM @ 800 PSI,
12/2/2023	ISIP = 500 PSI WASH UP PUMP & FLOW BACK PIT
12/2/2023	SECURE WELL SDFW
	CREW TRAVEL BACK HOME
12/3/2023	CREW TRAVEL TO LOCATION
12/4/2023	HPJSM W/ ALL PERSONAL ON LOCATION
	CHECK PSI ON WELL 2-3/8" TBG = 300 PSI, 4-1/2" PROD CSG = 500 PSI, 7-5/8" INTER
12/4/2023	CSG = 0 PSI, 10-3/4" SURF CSG = 0 PSI
	RU PUMP ON TBG BLEED OFF PSI, LOAD TBG W/ ¾ OF BBL FW PRESSURE TEST SQZ CSG
	TO 600 PSI HOLD PRESSURE F/ 30 MIN W/ A GOOD TEST W/ NO LEAK OFF BLEED OF
12/4/2023	PRESSURE
12/4/2023	SET CO/FO & FUNCTION TEST
	UNSEAT 4.5" (3.75" OD) CREST PKR RIH W/ 2-3/8" TBG TAG TOC @ 6946' (TMD) W/ 222
12/4/2023	JTS IN THE HOLE
	POOH W/ 91 STANDS OF 2-3/8" TBG LD 40 JT OF 2-3/8" TBG & LD 4.5" (3.75" OD) CREST
12/4/2023	PKR
	MAKE UP DRILLING BHA AS FOLLOWS NEW 3-7/8" BIT, 3-1/8" BIT SUB, 6 – 3-1/8" DRILL
12/4/2023	COLLARS, RIH W/ 2-3/8" TBG TAG TOC @ 6946' (TMD) W/ 216 JTS IN THE HOLE, LD 1 JT
12/4/2023	NU 7-1/16" X 3K STRIPPER HEAD
12/4/2023	MIRU POWER SWIVEL ON JT #216
	LOAD WELL W/ 3 BBLS FW BREAK CIRCULATION PUMPING REVERSE 2.5 BPM @ 400 PSI
12/4/2023	GETTING FULL RETURNS ON TBG (REV PIT) CIRCULATE GAS OUT W/ 107 BBLS OF FW,
12/4/2023	SECURE WELL SDFN
12/4/2023	CREW TRAVEL BACK HOME
12/4/2023	CREW TRAVEL TO LOCATION
12/5/2023	HPJSM W/ ALL PERSONAL ON LOCATION
12/5/2023	CHECK PSI ON WELL ALL STRINGS = 0 PSI

	MAKE POWER SWIVEL CONNECTION ON JT #217 LOAD WELL W/ 2 BBLS FW BREAK
	CIRCULATION PUMPING REVERSE 2.5 BPM @ 400 PSI GETTING FULL RETURNS ON TBG
	(REV PIT) BEGIN DRILLING OUT CMT RIH MAKING CONNECTIONS W/ PS, NOTE: WE
	MAKE ALL PS CONNECTIONS BY HAND W/ PS ENGINE SHUT OFF, DRILL OUT 523' F/
	6946' TO 7469' (TMD) W/ 233 JTS IN THE HOLE CIRCULATE HOLE CLEAN W/ 50 BBLS OF
12/5/2023	FW
12/5/2023	SECURE WELL SDFN
12/5/2023	CREW TRAVEL BACK HOME
12/5/2023	CREW TRAVEL TO LOCATION
12/6/2023	HPJSM W/ ALL PERSONAL ON LOCATION
12/6/2023	CHECK PSI ON WELL ALL STRINGS = 0 PSI
	MAKE POWER SWIVEL CONNECTION ON JT #234, LOAD WELL W/ 2 BBLS FW BREAK
	CIRCULATION PUMPING REVERSE 2.5 BPM @ 500 PSI GETTING FULL RETURNS ON TBG
	(REV PIT) CONTINUE DRILLING CMT DRILL 248' F/ 7469' – 7717' (TMD) FELL THRU W/
	241 JTS IN THE HOLE 10' IN ON JT #242, CIRCULATE BOTTOMS UP W/ 40 BBLS OF FW,
	CONTINUE RIH MAKING CONNECTIONS W/ PS RIH F/ 7717' – 8253' TAG CIBP @ 8253'
	(TMD) W/ 258 JTS IN THE HOLE 20' IN ON JT #259, PICK UP 10' LOAD WELL W/ 1 BBL OF
	FW PRESSURE TEST SQZ CSG TO 500 PSI HOLD PRESSURE F/ 30 MIN W/ A GOOD TEST
	W/ NO LEAK OFF BLEED OF PRESSURE, BREAK CIRCULATION PUMPING REVERSE 2.5
	BPM @ 500 PSI GETTING FULL RETURNS ON TBG (REV PIT) DRILL CIBP F/ 8253' – 8254'
	(TMD) FELL THRU & LOST 400 PSI STOP PUMPING REVERSE & CHANGED TO PUMPING
	CONVENTIONAL TO GET MORE FLOW BACK RATE PUMPING RATE 2.5 BPM @ 800 PSI
	GETTING BACK ON RETURNS 2 BPM, CONTINUE RIH MAKING CONNECTIONS W/ PS TAG
	FILL @ 8475' (TMD) W/ 265 JTS IN THE HOLE 21' IN ON JT #266 CIRCULATE HOLE CLEAN
	W/ 150 BBLS OF FW, RDPS AND POOH W/ 7 JTS 2-3/8" TBG EOT @ 8267' W/ 259 JTS IN
12/6/2023	HOLE 43' ABOVE THE TOP PERFS, CLOSE BOP, INSTALL 2-3/8" TIW VALVE
12/6/2023	SECURE WELL SDFN
12/6/2023	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
12/6/2023	
	HPJSM W/ ALL PERSONAL ON LOCATION
12/7/2023	CHECK PSI ON WELL ALL STRINGS = 0 PSI

	RUPS MAKE PS CONNECTION ON JT #260, LOAD WELL W/ 15 BBLS FW BREAK CIRCULATION PUMPING CONVENTIONAL 2.5 BPM @ 800 PSI GETTING BACK 2 BPM ON RETURNS (REV PIT) CONTINUE RIH MAKING CONNECTIONS W/ PS TAG FILL @ 8475' (TMD) W/ 265 JTS IN THE HOLE 21' IN ON JT #266, BEGIN CLEANING OUT FILL MAKING CONNECTIONS W/ PS, NOTE: WE MAKE ALL PS CONNECTIONS BY HAND W/ PS ENGINE SHUT OFF, (DRILL PIECES OF CIBP & SAND) CLEAN OUT 135' F/ 8475' TO 8610' (TMD) W/ 270 JTS IN THE HOLE NOTE: WE GOT TO 8610' AND WE STOP MAKING HOLE, GETTING BACK ON RETURNS PIECES OF RUBBER AND METAL, I LOOK ON THE OCD ONLINE AND FOUND A DOCUMENT AND PBTD SHOWS TO BE AT 8616' PLEASE SEE DOCUMENT ATTACHED. NOTE: CONTACT MR. ANTONIO DE LA FUENTE W/ NMBLM LET HIM KNOW WE STOP MAKING HOLE @ 8610' (NOTE: PBTD @ 8616') DISCUSS PLAN FWD GOT APPROVAL TO SPOT 25 SX CL H CMT @ 8610' – 8272' THEN CONTINUE P&A AS PROGRAM, CIRCULATE THE HOLE CLEAN W/ 90 BBLS OF FW, SWITCH TO 10# BW AND
	PUMPING REVERSE CIRCULATE THE HOLE CLEAN W/ 150 BBLS OF 10# BW (WELL BORE
	IS NOW FULL OF 10# BW)
12/7/2023	
	ND 7-1/16" X 3K STRIPPER HEAD
	POOH W/ 15 STANDS OF 2-3/8" TBG EOT @ 7487' W/ 240 JTS IN HOLE BIT BHA @ 7676' CLOSE BOP, INSTALL 2-3/8" TIW VALVE
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME
	CREW TRAVEL BACK HOME CREW TRAVEL TO LOCATION
	HPJSM W/ ALL PERSONAL ON LOCATION
	CHECK PSI ON WELL ALL STRINGS = 0 PSI
	OPEN TBG & CSG PUMP 30 BBLS DOWN TBG & 60 BBLS DOWN CSG OF 10# BW FOR
	WELL CONTROL TBG & CSG WENT ON VACUUM MONITOR WELL FOR 15 MINUTES WELL
12/8/2023	
	SET CO/FO & FUNCTION TEST
	CONTINUE POOH W/ 120 STANDS OF 2-3/8" TBG, LD DRILLING BHA 6 – 3-1/8" DC, 3-
	1/8" BIT SUB, 3-7/8" BIT
	BREAK FOR CREW LUNCH
	PICK UP 4' X 2-3/8" PERF SUB RIH W/ 2-3/8" TBG EOT @ 4172' (TMD) W/ 134 JTS IN THE
	HOLE, SHUT DOWN OPS / TO WINDY TO RIH W/ TBG WINDS 30 TO 40 MPH W/ GUST
12/8/2023	UPTO 50 MPH, CLOSE BOP, INSTALL 2-3/8" TIW VALVE
	SECURE WELL SDFN
12/8/2023	CREW TRAVEL BACK HOME
12/8/2023	CREW TRAVEL TO LOCATION
12/9/2023	HPJSM W/ ALL PERSONAL ON LOCATION
12/9/2023	CHECK PSI ON WELL ALL STRINGS = 0 PSI
	OPEN TBG & CSG PUMP 30 BBLS DOWN TBG & 60 BBLS DOWN CSG OF 10# BW FOR
	WELL CONTROL TBG & CSG WENT ON VACUUM MONITOR WELL FOR 15 MINUTES WELL
12/9/2023	STATIC
12/0/2023	
12/3/2023	SET CO/FO & FUNCTION TEST

r	
	RU CMT PUMP ON TBG PUMP 40 BBLS OF 10# BW TO CLEAR TBG STRING 1ST PLUG)
	BALANCED PLUG F/ 8610' – 8475' SPOT 25 SX CLASS H CMT, 5.25 BBLS SLURRY,15.6# 1.18 YIELD, COVERING 338' DISPLACE TOC TO 8272' DISPLACE W/ 32.01 BBLS OF 10#
12/0/2022	BW, ISIP = 0 PSI (SLOW VACUUM)
12/9/2023	POOH W/ 15 STANDS LD 10 JTS EOT @ 7068' W/ 236 JTS IN THE HOLE, WASH UP PUMP
12/9/2023	& FLOW BACK PIT
	SECURE WELL SDFW
	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
	HPJSM W/ ALL PERSONAL ON LOCATION
	CHECK PSI ON WELL 2-3/8" TBG & 4-1/2" PROD CSG = ON VACUUM, 7-5/8" INTER CSG =
12/11/2023	0 PSI, 10-3/4" SURF CSG = 0 PSI
	OPEN TBG & CSG PUMP 30 BBLS DOWN TBG & 50 BBLS DOWN CSG OF 10# BW FOR
12/11/2023	WELL CONTROL
12/11/2023	SET CO/FO & FUNCTION TEST
12/11/2023	RIH W/ 31 JTS OF 2-3/8" TBG TAG TOC @ 8331' (TMD) W/ 267 JTS IN THE HOLE
	POOH W/ 132 STANDS OF 2-3/8" TBG LD 3 JTS OF 2-3/8" TBG BREAK 4' X 2-3/8" PERF
12/11/2023	
	MAKE UP 3.62" OD CIBP FOR 4.5" CSG RIH W/ 2-3/8" TBG SET CIBP @ 8260'(TMD) W/
	264 JTS IN THE HOLE 22' IN ON JT #265 LD 1 JT OF 2-3/8" TBG, PICK UP 10' 10' X 2-3/8"
12/11/2023	
12/11/2022	RU CMT PUMP ON TBG CIRCULATE WELL CLEAN W/ 130 BBLS OF 10# BW MIX 13
12/11/2023	GALLONS OF FLEX GEL W/ 65 BBLS OF 10# BW
12/11/2022	PRESSURE TEST CIBP TO 500 PSI HOLD PRESSURE FOR 30 MINUTES W/ A GOOD TEST
12/11/2023	BREAK CIRCULATION W/ 10 BBLS OF 10# BW, 2ND PLUG) SET 4.5" CIBP @ 8260'
	BALANCED PLUG F/ 8260' – 7916' SPOT 25 SX CLASS H CMT, 5.25 BBLS SLURRY,15.6#
	1.18 YIELD, COVERING 338' DISPLACE TOC TO 7922' DISPLACE W/ 30.65 BBLS OF 10#
	BW, LD 10' 10' X 2-3/8" TBG SUBS POOH W/ 15 STANDS LD 10 JTS OF 2-3/8" TBG EOT @
	7010' W/ 224 JTS IN THE HOLE RU CMT PUMP REVERSE OUT W/ 32 BBLS 10# BW, WASH
12/11/2023	UP PUMP & FLOW BACK PIT
12/11/2023	SECURE WELL SDFN
12/11/2023	CREW TRAVEL BACK HOME
12/11/2023	CREW TRAVEL TO LOCATION
12/12/2023	HPJSM W/ ALL PERSONAL ON LOCATION
	CHECK PSI ON WELL ALL STRINGS = 0 PSI
12/12/2023	SET CO/FO & FUNCTION TEST
	RIH W/ 30 JTS OF 2-3/8" TBG TAG TOC @ 7920' (TMD) W/ 253 JTS IN THE HOLE 9' OUT
12/12/2023	
	POOH LD 35 JTS EOT @ 6852' W/ 219 JTS IN THE HOLE
12/12/2023	
12/12/2023	
12/12/2023	RU CMT PUMP ON TBG BREAK CIRCULATION W/ 5 BBLS OF 10# BW 3RD PLUG)
	RU CMT PUMP ON TBG BREAK CIRCULATION W/ 5 BBLS OF 10# BW 3RD PLUG) BALANCED PLUG F/ 6846' – 6502' SPOT 25 SX CLASS C CMT, 5.87 BBLS SLURRY,14.8#
12/12/2023	RU CMT PUMP ON TBG BREAK CIRCULATION W/ 5 BBLS OF 10# BW 3RD PLUG) BALANCED PLUG F/ 6846' – 6502' SPOT 25 SX CLASS C CMT, 5.87 BBLS SLURRY,14.8# 1.32 YIELD, COVERING 378' DISPLACE TOC TO 6474' DISPLACE W/ 25.05 BBLS
12/12/2023	RU CMT PUMP ON TBG BREAK CIRCULATION W/ 5 BBLS OF 10# BW 3RD PLUG) BALANCED PLUG F/ 6846' – 6502' SPOT 25 SX CLASS C CMT, 5.87 BBLS SLURRY,14.8# 1.32 YIELD, COVERING 378' DISPLACE TOC TO 6474' DISPLACE W/ 25.05 BBLS POOH W/ 104 STDS LD 11 JTS & SETTING TOOL
12/12/2023 12/12/2023	RU CMT PUMP ON TBG BREAK CIRCULATION W/ 5 BBLS OF 10# BW 3RD PLUG) BALANCED PLUG F/ 6846' – 6502' SPOT 25 SX CLASS C CMT, 5.87 BBLS SLURRY,14.8# 1.32 YIELD, COVERING 378' DISPLACE TOC TO 6474' DISPLACE W/ 25.05 BBLS

12/12/2022			
12/12/2023	POOH LD 28 JTS EOT @ 5638' W/ 180 JTS IN THE HOLE		
	RU CMT PUMP ON TBG BREAK CIRCULATION W/ 5 BBLS OF 10# BW 4TH PLUG) BALANCED PLUG F/ 5634' – 5290' SPOT 25 SX CLASS C CMT, 5.87 BBLS SLURRY,14.8#		
12/12/2022			
12/12/2023	1.32 YIELD, COVERING 378' DISPLACE TOC TO 5260' DISPLACE W/ 20.35 BBLS		
40/40/2022	POOH W/ 15 STANDS LD 11 JTS OF 2-3/8" TBG EOT @ 4336' W/ 139 JTS IN THE HOLE,		
	WASH UP PUMP & FLOW BACK PIT		
	SECURE WELL SDFN		
	3 HPJSM W/ ALL PERSONAL ON LOCATION		
	CHECK PSI ON WELL ALL STRINGS = 0 PSI		
12/13/2023	SET CO/FO & FUNCTION TEST		
40/10/2020	RIH W/ 30 JTS OF 2-3/8" TBG TAG TOC @ 5271' (TMD) W/ 168 JTS IN THE HOLE 12' IN		
12/13/2023	ON JT #169		
10/10/2020			
12/13/2023	POOH LD 17 JTS EOT @ 4760' W/ 152 JTS IN THE HOLE & PICK UP 6' X 2-3/8" TBG SUB		
	RU CMT PUMP ON TBG BREAK CIRCULATION W/ 5 BBLS OF 10# BW 5TH PLUG)		
	BALANCED PLUG F/ 4760' – 4256' SPOT 35 SX CLASS C CMT, 8.22 BBLS SLURRY,14.8#		
12/13/2023	1.32 YIELD, COVERING 530' DISPLACE TOC TO 4230' DISPLACE W/ 16.37 BBLS		
	POOH LD 6' X 2-3/8" TBG SUB POOH W/ 15 STANDS LD 16 JTS OF 2-3/8" TBG EOT @		
	3233' W/ 106 JTS IN THE HOLE		
12/13/2023	WOC TO TAG		
	RIH W/ 29 JTS OF 2-3/8" TBG TAG TOC @ 4201' (TMD) W/ 135 JTS IN THE HOLE NOTE:		
12/13/2023	NMBLM WITNESS TAG GIVE THE OK TO CONTINUE AS PROGRAM		
42/42/2022			
12/13/2023	POOH W/ 43 STANDS & LD 49 JTS OF 2-3/8" TBG BREAK 4' X 2-3/8" PERF TBG SUB		
12/12/2022	MAKE UP & RIH W/ 4.5" AD-1 PKR RIH W/ 2-3/8" TBG SET PKR @ 751' W/ 24 JTS IN THE		
12/13/2023			
12/12/2022			
	LOAD BACK SIDE W/ 5 BBLS 10# BW PRESSURE TEST PKR TO 500 PSI W/ A GOOD TEST		
	SECURE WELL SDFN		
12/13/2023	CREW TRAVEL BACK HOME.		
12/14/2022	CREW TRAVEL TO ODESSA AXIS YARD FOR MONTHLY SAFETY MEETING, CREW TRAVEL		
12/14/2023	TO LOCATION		
12/14/2022	HPJSM W/ ALL PERSONAL ON LOCATION STAND DOWN ON FOOT PLACEMENT AND 3		
	CHECK PSI ON WELL ALL STRINGS = 0 PSI		
12/14/2023	SET CO/FO & FUNCTION TEST		
	MIRU RTX WL TO WELL PICK UP 1.2" X 1-3/8" CCL 1" X 1-3/8" DOUBLE O-RING TEAR		
	DROP 5" X 1-9/16" FIRING HEAD 3' X 1-9/16" GUN LOADED 6 SPF W/GEO 2.7G CHARGES		
10/10/2000	1.2"X1 9/16" DECENTRALIZER WENT DOWN TO 2650' SHOT 6 SQZ HOLES POOH RDMO		
12/14/2023	WL		
10/1	RU PUMP ON 4.5" CSG LOAD BACK SIDE W/ 1 BBLS FW TEST PKR TO 500 PSI W/ A GOOD		
12/14/2023	TEST, CLOSE CSG VALVE AND LEAVE 500 PSI HOLDING PRESSURE ON BACK SIDE		

	RU CMT PUMP ON TBG EST – INJ RATE W/ 10# BW 2.5 BPM @ 250 PSI PUMP 10 BBLS		
	OF 10# BW W/ FULL RETURNS ON 7-5/8" INTER CSG KEEP PUMPING TO MOVE TRASH		
	OUT CIRCULATE A TOTAL OF 110 BBLS OF 10# BW W/ FULL RETURNS ON SURFACE ON		
12/14/2023	THE 7-5/8" INTER CSG		
	LOAD BULK TRK W/ 400 SX CLASS C CMT, 6TH PLUG) PERF @ 2650' SQZ 270 SX CLASS C		
	CMT, 63.47 BBLS SLURRY,14.8# 1.32 YIELD, COVERING 1500' (23.25 BBLS IN 4.5" PROD		
	CSG) & COVERING 1500' (39.3 BBLS OUT 7-5/8" INTER CSG) DISPLACE TOC TO 1150'		
	DISPLACE W/ 9.08 BBLS, CMT PUMP RATE 1.5 BPM @ 0 PSI, PUMP DISPLACEMENT 2		
	BPM @ 200 PSI W/ FULL RETURNS ON SURFACE ON THE 7-5/8" INTER CSG, ISIP = 0 PSI,		
12/14/2023	WASH UP PUMP & FLOW BACK PIT		
	SECURE WELL SDFN		
	CREW TRAVEL BACK HOME		
	CREW TRAVEL TO LOCATION		
	HPJSM W/ ALL PERSONAL ON LOCATION		
, 10, 2020	CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 4-1/2" PROD CSG = 500 PSI, 7-5/8" INTER CSG =		
12/15/2022	0 PSI, 10-3/4" SURF CSG = 0 PSI		
	SET CO/FO & FUNCTION TEST		
	UNSEAT PKR POOH W/ 24 JTS OF 2-3/8" TBG BREAK & LD 4.5" PKR		
12/13/2023	RIH W/ 2-3/8" TBG OPEN ENDED TAG TOC @ 1185' (TMD) W/ 38 JTS IN THE HOLE		
12/15/2022	NOTE: NMBLM WITNESS TAG GIVE THE OK TO CONTINUE AS PROGRAM		
	POOH LD 38 JTS OF 2-3/8" TBG		
12/15/2025	MAKE UP 4.5" AD-1 PKR SET AD-1 PKR @ 34' W/ 1 JTS IN THE HOLE, LOAD BACK SIDE		
12/15/2022	W/ 1 BBLS 10# BW TEST PKR TO 500 PSI W/ A GOOD TEST		
12/15/2025	MIRU RTX WL TO WELL PICK UP 1.2" X 1-3/8" CCL 1" X 1-3/8" DOUBLE O-RING TEAR		
	DROP 5" X 1-9/16" FIRING HEAD 3' X 1-9/16" GUN LOADED 6 SPF W/GEO 2.7G CHARGES		
42/45/2022	1.2"X1 9/16" DECENTRALIZER WENT DOWN TO 1180' SHOT 6 SQZ HOLES POOH RDMO		
12/15/2023			
	RU CMT PUMP ON TBG EST – INJ RATE W/ 10# BW 2.5 BPM @ 100 PSI PUMP 20 BBLS		
	OF 10# BW W/ FULL RETURNS ON 7-5/8" INTER CSG		
	UNSEAT AND LD 4.5" AD-1 PKR		
	RD WORK FLOOR & ASSOCIATED EQUIPMENT		
	ND 5K HYD BOP, ND 5K X 3K X 7-1/16" SPOOL		
12/15/2023	NU 3K X 7-1/16" WH FLANGE		
	RU CMT PUMP ON 4.5" PROD CSG BREAK CIRC W/ 5 BBLS 10# BW 7TH PLUG) PERF @		
	1180' SQZ 210 SX CLASS C CMT, 49.36 BBLS SLURRY,14.8# 1.32 YIELD, COVERING 1180'		
	(18.29 BBLS IN 4.5" PROD CSG) & COVERING 1180' (30.91 BBLS OUT 7-5/8" INTER CSG)		
	F/ 1180' – 0' (SURF) GOT FULL RETURNS ON 7-5/8" INTER CSG CLOSE VALVE AND LEFT		
	500 PSI ON PROD CSG, WOC TOP OFF HOLE W/ CMT VERIFY CMT AT SURF / RU CMT		
	PUMP ON THE 10-3/4" SURF – CSG TRY TO PUMP CMT W/ NO LUCK 10-3/4" SURF – CSG		
12/15/2023	PRESSURE UP TO 500 PSI W/ NO LEAK OFF. WASH UP PUMP & FLOW BACK PIT		
	RDMO PU & P&A PUMP ASSOCIATED EQUIP, CLEAN LOCATION P&A JOB COMPLETED		
12/15/2023			

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

COMMENTS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	295696
	Action Type:
	[C-103] Sub. Plugging (C-103P)
COMMENTS	

Created By	Comment	Comment Date
plmartinez	DATA ENTRY PM.	3/1/2024

Page 17 of 18

Action 295696

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	295696
	Action Type: [C-103] Sub. Plugging (C-103P)
CONDITIONS	

CONDITIONS

Created By		Condition Date
gcordero	None	2/29/2024

Page 18 of 18

Action 295696