	State of New Mexico	Form C-103
Office District I – (575) 393-6161  Energy	, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210	CONSERVATION DIVISION	30-025-05499
<u>District III</u> – (505) 334-6178	220 South St. Francis Dr.	5. Indicate Type of Lease  STATE  FEE    FEE    ■
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM		19520
87505	EDODTS ON WELLS	
SUNDRY NOTICES AND RI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILI		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PI		North Hobbs G/SA Unit
PROPOSALS.)  1. Type of Well: Oil Well Gas Well	Other Injection	8. Well Number 441
2. Name of Operator	J Other Injection	9. OGRID Number
Occidental Permian LTD		157984
3. Address of Operator		10. Pool name or Wildcat
P.O. Box 4294 Houston, TX 77210-4294		HOBBS; GRAYBURG-SAN ANDRES
4. Well Location		
Unit Letter P: 990 fe	et from theSouth line and	330feet from theEastline
Section 25 T	ownship 18S Range 37E	NMPM County LEA
11. Elevation	on (Show whether DR, RKB, RT, GR, etc	e.)
	3667' (GL)	
12. Check Appropriate	Box to Indicate Nature of Notice,	, Report or Other Data
NOTICE OF INTENTION	TO:   9115	BSEQUENT REPORT OF:
	ABANDON ☐ REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE F		RILLING OPNS. P AND A
PULL OR ALTER CASING   MULTIPLE		
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM		
OTLIED.	□ OTHER:	Liner
OTHER:		
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU	ons. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation	ons. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU	ons. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.</li> </ol>	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.</li> </ol>	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.</li> </ol>	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Cottached.	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at	ons. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Cottached.	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at Spud Date:	ns. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Cottached.  Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at Spud Date:	ns. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Cottached.  Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at Spud Date:	ns. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Cottached.  Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at Spud Date:	Rig Release Date:  Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief.
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at Spud Date:	ns. (Clearly state all pertinent details, ar ILE 19.15.7.14 NMAC. For Multiple Cottached.  Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at Spud Date:	Rig Release Date:  Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief.  DATE 02/13/2024
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at Spud Date:  I hereby certify that the information above is true SIGNATURE Romi Mathew  Type or print name Romi Mathew  For State Use Only	Rig Release Date:  and complete to the best of my knowleds  TITLE Regulatory Advisor  E-mail address: roni_mathew(	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief.  DATE 02/13/2024
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at  Spud Date:  I hereby certify that the information above is true  SIGNATURE Roni Mathew  Type or print name Roni Mathew  For State Use Only	Rig Release Date:  TITLE Regulatory Advisor  E-mail address: roni_mathew(	ge and belief.  DATE 02/13/2024  @oxy.com PHONE: (713) 215-7827
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  Please see procedure and WBD at  Spud Date:  I hereby certify that the information above is true  SIGNATURE Romi Mathew  Type or print name Roni Mathew	Rig Release Date:  and complete to the best of my knowleds  TITLE Regulatory Advisor  E-mail address: roni_mathew(	ge and belief.  DATE 02/13/2024  @oxy.com PHONE: (713) 215-7827

Procedure Continued.

NHSAU 441-25 API: 3002505499 Liner Install

Job Dates: 5/31/2022 - 6/14/2022

5/31/22: Mipu, mi equipment, rupu,

ru equipment, tbg had 150psi, csg had 0psi, tested csg to 500psi, pumped 50bbls fo 10#bw down tbg, well went on vacuum, ndwh, nubop, and ru workfloor. Released 5.5" inj pkr, removed wrap around, pooh standing back 125jts of 2-7/8"duoline, 5.5pkr, rih w/4-3/4bit, pu 6-3 1/8drill collars, rih pu tallying 40jts of ws tbg, secured well in, and sion.

6/1/22: tbg had 150psi, csg had 100psi,

killed well, crew was about to cont rih but rig shut off, mechanic worked on getting the rig started but couldn't, computer was ordered from Odessa, secued well in, and sion.

6/2/22: tbg had 80, csg had 50psi, killed well,

rih pu tallying 85jts, tagged@4235', nu stripperhead, rups, drilled from 4235' down to 4260', got formation, rubber, metal in returns, then made new open hole from 4260' down to 4315', circ well clean, rdps, pooh w/10jts above perfs, and sion.

6/03/2022: tbg/csg had 0 psi, pooh w 117 2 7/8'' jts, 6 3 1/8'' drill collars, 4  $\frac{3}{4}''$  bit, Rih w 4  $\frac{3}{4}''$  bit, bit sub, 4  $\frac{3}{4}''$  string mill 6 3 1/8'' drill collars, 125 2 7/8'' jts, RUPS, break circulation w 180 bbls of fresh water, DO new formation down to new PBTD 4355', worked string mill to dress up hole, RDPS, performed bope closing drill, pooh w 128 2 7/8'' jts, 6 3 1/8'' drill collars, string mill and bit, SION.

6/4/22: Tbg & Csg 80 psi- Kill Well w/ 80 bbls brn- Rih w/Duplex shoe, 14 jts 4" L-80, 10.8# Liner, ran 19 jts 2 3/8 Tbg, Latch on shoe, ran 116 jts 2 7/8 Tbg, Set Duplex shoe @ 4355', Entry Guide @3801'- Unjay off-Pooh w/ 116 jts 2 7/8 Tbg,- RIH w/ 5.5 CICR & 114 jts 2 7/8 Tbg- Set CICR @3720. SION

6/6/22: tbg had 600psi, csg had 0psi, killed

well, ru Petroplex cmt truck, squeezed liner to 1200psi w/86bbls into formation, stung out of cicr, reversed out 11bbls of cmt w/40bbls of 10#bw, and rd cmt trucks. Pooh w/114jts, MST tool, rih w/4 3/4"bit, 6-3 1/8"dc's, 88jts, and sion.

6/7/22: tbg had Opsi, csg had Opsi, rih w/20jts, tagged@3720', nu stripperhead, rups, drilled out cmt retainer from 3720' down to 3722', then cont driling cmt down to 3762', circ well clean, rdps, and sion.

6/8/22: tbg had 0psi, csg had 0psi, rups, cont drilling from 3762' down to liner top @3801', circ well clean, rdps, l&t to 600psi which held ok, nd stripperhead, pooh w/112jts, 6dc's,4-3/4"bit, rih w/3-1/4"bit, 6dc's, 18jts of 2-3/8"tbg, 6jts of 2-7/8" tbg, decided to shut down due to wind, secured well in, and sion.

6/9/22: tbg had Opsi, csg had Opsi, rih w/90jts of 2-7/8"tbg, nu stripperhead, tagged@3801', rups, drilled cmt from 3801' down to 4355' TD, circ well clean, rdps, nd stripperhead, pooh w/20jts, and sion.


6/10/2022: tbg/csg had 0 psi, pooh w 88 2 7/8 " jts, 18 2 3/8" jts, 6 3 1/8" drill collars, 3 ½" bit, RUWL, ran CBL from 4355' to top of liner 3801', looked good, perforated from 4220 ' to 4340' w 2 ¾" guns, got hanged up on the last run and lost last gun in hole, Rih w 3 1/8 " over shot, 1 3/8" grapple, 18 2 3/8" jts, 116 2 7/8" jts, latched on to fish, pooh w tbg and recovered fish, SION.

6/11/22: Rih w/ 4" RBP/4" Pkr 18 jts 2 3/8 Tbg, X-over 116 jts 2 7/8 Tbg- RU Acid Tech, Perfs 4340'- 4280', pump 1800 gals acid, Move Tools to 4280'-4220', Waited for acid, Pump another 1800 gals & Flush w/ 50 bbls Fw- RD Acid tech, Pooh LD 40 jts 2 7/8 WS- SION

6/13/22: tbg had 450psi, csg had 600psi,


killed well, pooh laying down 76jts of 2-7/8ws tbg, laid down 18jts of 2-3/8jts, 4"rbp&pkr, rih w/4" AS1-X inj pkr w/1.50profile, on&off tool, 18jts of 2-3/8 tbg, and 115jts of 2-7/8" of duoline from the derrick. Set pkr @4170', circ well w/110bbls of 10#pkr fluid, tested csg to 600psi which held, unjayed off on&off tool, pooh laying down 115jts of 2-7/8", 18jts of 2-3/8" tbg, on&off tool, and sion.

6/14/22: csg had Opsi, rih w/on&off tool, 13jts of 2-3/8"duoline, 117jts of 2-7/8"duoline tbg, spaced well out, latched onto inj pkr, tested, tested csg to 600psi which also held, rd workfloor, ndbop, and nuwh. Ran MIT on csg to 535psi which passed w/NMOCD, tested tbg to 1500psi, then pumped out pump out plug, hooked up inj line, rdpu, rd equipment, cleaned location, and moved off of location.



TD @ 4355'

Received by OCD: 3/19/2024 12:24:58 PM



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 324685

## **CONDITIONS**

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	324685
	Action Type:
	[C-103] Sub. Workover (C-103R)

## CONDITIONS

Created By		Condition Date
kfortner	None	8/21/2024