

State of New Mexico
Energy, Minerals and Natural Resources

District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-60949
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator IACX Production, LLC,		6. State Oil & Gas Lease No. LG-3591
3. Address of Operator 5001 LBJ Freeway, Suite 300 Dallas, TX 75244		7. Lease Name or Unit Agreement Name Tamarack QF State
4. Well Location Unit Letter <u>D</u> : <u>330</u> feet from the <u>North</u> line and <u>990</u> feet from the <u>West</u> line Section <u>32</u> Township <u>06S</u> Range <u>26E</u> NMPM Chaves County		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,658' GR		9. OGRID Number 329877
10. Pool name or Wildcat Linda; San Andres		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

IACX Production, LLC. plans to plug and abandon the above captioned well as follows:

MIRU plugging unit, ND wellhead, NU BOP, POOH with tubing and BHA, LD BHA, RIH and set CIBP at ~ 909' (50-100' above topmost perf), Pump 65sx Class C cement plug from 909' to surface, WOC, if needed top off cement and WOC again, (reports show full circulation on all casing strings), cut off wellhead, install regulation dry hole marker, clean location as per regulation.

Spud Date:


Rig Release Date:


I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Production Technician DATE 1/10/2025

Type or print name Joel Doporto E-mail address: joeldoporto@iacxproduction.com PHONE: 575-416-3243
For State Use Only

APPROVED BY: _____ TITLE _____ DATE _____
Conditions of Approval (if any): _____





Plugging Plan

Tamarack QF State #1

30-005-60949

State lease LG-3591

Chaves County, NM

1. Set CIBP @ 909'
2. Pump 65sx class C cement plug from 909' – Surface

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 423154

CONDITIONS

Operator: IACX Production LLC 5001 LBJ Freeway, Suite 300 Dallas, TX 75244	OGRID: 329877
	Action Number: 423154
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
loren.diede	Notify the OCD inspection supervisor via email 24 hours prior to beginning Plug & Abandon (P&A) operations.	1/23/2025
loren.diede	A Cement Bond Log (CBL) is required for all Plug & Abandons (P&A) unless a CBL is currently on file with the OCD that can be used to properly evaluate the cement behind the casing.	1/23/2025
loren.diede	Submit the CBL tif file to NMOCD to be uploaded into the Well Log file.	1/23/2025
loren.diede	NMOCD has determined that this well is not in the LPCH area and therefore an above-ground P&A marker is to be used.	1/23/2025
loren.diede	Submit a photo of the P&A marker, showing the API #, with the C-103P subsequent P&A submission.	1/23/2025