Received by WCD:S/8/2025 7:49:06 AM U.S. Department of the Interior BUREAU OF LAND MANAGEMENT		Sundry Print Report 05/08/2025
Well Name: SAND DUNES 34	Well Location: T23S / R31E / SEC 34 / SWNE / 32.2636218 / -103.7645539	County or Parish/State: EDDY / NM
Well Number: 6	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM43744	Unit or CA Name:	Unit or CA Number:
US Well Number: 3001527499	Operator: OXY USA INCORPORATED	

Subsequent Report

Sundry ID: 2850352

Type of Submission: Subsequent Report

Date Sundry Submitted: 05/01/2025

Date Operation Actually Began: 02/14/2025

Type of Action: Plug and Abandonment Time Sundry Submitted: 08:04

Actual Procedure: THE FINAL WELLBORE AND PA JOB NOTES ARE ATTACHED. CUT AND CAP WAS COMPLETE ON 3/18/2025.

SR Attachments

Actual Procedure

SDUNES34_006_PA_SR_SUB_5.1.2025_20250501080418.pdf

Received by OCD: 5/8/2025 7:49:06 AM Well Name: SAND DUNES 34	Well Location: T23S / R31E / SEC 34 / SWNE / 32.2636218 / -103.7645539	County or Parish/State: EDD ?? of Page ? of P
Well Number: 6	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM43744	Unit or CA Name:	Unit or CA Number:
US Well Number: 3001527499	Operator: OXY USA INCORPORATED	

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: STEPHEN JANACEK

Name: OXY USA INCORPORATED

Title: Regulatory Engineer

Street Address: 5 Greenway Plaza, Suite 110

City: Houston

State: TX

State:

Phone: (713) 497-2417

Email address: stephen_janacek@oxy.com

Field

Representative Name: Street Address: Citv: Phone: Email address:

BLM Point of Contact

BLM POC Name: JAMES A AMOS BLM POC Phone: 5752345927 **Disposition:** Accepted Signature: James A Amos

BLM POC Title: Acting Assistant Field Manager BLM POC Email Address: jamos@blm.gov Disposition Date: 05/02/2025

Zip:

Signed on: MAY 01, 2025 08:04 AM

Received by OCD: 5/8/2025 7:49:06 AM

<i>.</i>					8 3
Form 3160-5 (June 2019)			ON	DRM APPROVED MB No. 1004-0137 res: October 31, 2021	
Do not	use this f		ORTS ON WELLS to drill or to re-enter an PD) for such proposals.	6. If Indian, Allottee or Tribe N	ame
	SUBMIT IN 1	TRIPLICATE - Other instru	uctions on page 2	7. If Unit of CA/Agreement, Na	ame and/or No.
1. Type of Well Oil Well	🗌 Gas W	/ell Other		8. Well Name and No.	
2. Name of Operator				9. API Well No.	
3a. Address			3b. Phone No. (include area code)	10. Field and Pool or Explorato	bry Area
4. Location of Well (Foot	age, Sec., T.,R	.,M., or Survey Description)		11. Country or Parish, State	
	12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE (OF NOTICE, REPORT OR OTH	ER DATA
TYPE OF SUBMIS	SSION		TYPI	E OF ACTION	
Notice of Intent		Acidize	Deepen Hydraulic Fracturing	Production (Start/Resume) Reclamation	Water Shut-Off Well Integrity
Subsequent Report	t	Casing Repair	New Construction Plug and Abandon	Recomplete	Other
Final Abandonmen	nt Notice	Convert to Injection	Plug Back	Water Disposal	
the proposal is to deep the Bond under which completion of the invo	pen directiona n the work wil olved operation ndonment Not	Ily or recomplete horizontall l be perfonned or provide the ons. If the operation results in	ly, give subsurface locations and me e Bond No. on file with BLM/BIA. n a multiple completion or recomplet	easured and true vertical depths of Required subsequent reports mus etion in a new interval, a Form 31	k and approximate duration thereof. If f all pertinent markers and zones. Attach t be filed within 30 days following 60-4 must be filed once testing has been e operator has detennined that the site

14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/Typed</i>)		
1	ĩtle	
Signature	Date	
THE SPACE FOR FEDEI	RAL OR STATE OF	ICE USE
Approved by		
	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant o certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any any false, fictitious or fraudulent statements or representations as to any matter within		fully to make to any department or agency of the United States

GENERAL INSTRUCTIONS

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment. If the proposal will involve **hydraulic fracturing operations**, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

NOTICES

The privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and granting approval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.

The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.

BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

Additional Information

Location of Well

0. SHL: SWNE / 1650 FNL / 2310 FEL / TWSP: 23S / RANGE: 31E / SECTION: 34 / LAT: 32.2636218 / LONG: -103.7645539 (TVD: 0 feet, MD: 0 feet) BHL: SWNE / 1650 FNL / 2310 FEL / TWSP: 23S / SECTION: / LAT: 0.0 / LONG: 0.0 (TVD: 0 feet, MD: 0 feet)

.

SAND DUNES 34 FEDERAL 006 30-015-27499-0000 Eddy **FINAL WELLBORE** <u>String 1</u> OD 13.375 in TD 720 ft TOC 0 ft SPOT 155 SX CMT 1388' TO SURFACE. SPOT 150 SX CMT 2969'-1452'. TA AT 1388'. SPOT 150 SX CMT 4444'-2927'. TA AT 2969'. <u>DV Tool</u> Top 3803 ft String 2 OD 8.625 in TD 4235 ft Anhydrite 4112' TOC 0 ft Delaware Lime 4355' Bell Canyon 4390' Cherry Canyon 5267' SPOT 125 SX CMT 6420'-5156'. TAG AT 5183'. <u>DV Tool</u> Top 6031 ft Brushy Canyon 6536' SET CIBP AT 7926'. SPOT 155 SX CMT <u>Perf 2</u> 7976 ft 7926'-6571'. TAG AT 6420' 8012 ft <u>Perf 1</u> 8074 ft <u>String 3</u> OD 5.5 in TD 8290 ft LEFT FISH IN HOLE. TOF AT 8105'. 8130 ft TOC 0 ft

Released to Imaging: 5/9/2025 2:55:23 PM

PBTD 8242 ft

•

SAND DUNES 34 FEDERAL #006 30-015-27499 PA JOB NOTES

Start Date	Remarks
2/14/2025	Crew drove to the location.
2/14/2025	Jsa. Pre trip equip.
2/14/2025	Moved from the Federal 12 #007 to Sand Dunes 34 Federal 6.
2/14/2025	Dug out the cellar. Plumbed up the csg valves. Surf-0 psi. Inter-0 psi. Prod-700 psi. Tbg-150 psi.
2/14/2025	Spotted in the rig. RUPU/Cmt equip.
2/14/2025	Crew ate lunch. Reviewed the Jsa.
2/14/2025	Spotted the pipe racks and catwalk.
2/14/2025	Loaded the tbg w/ 20 bbls brine. Tested the tbg good @ 500 psi.
2/14/2025	Removed the PR/SB. Worked the stuck pump. Sheard the shear tool. Rods are free.
2/14/2025	Pooh LD 97-1.25" FG rods, 173-7/8" steel rods, 4-1.50 k bars, and a parted pull rod.
2/14/2025	Secured the well. SDON.
2/14/2025	Crew drove to the yard
2/18/2025	Crew drove to the location.
2/18/2025	Jsa. Set COFO.
2/18/2025	Surf-0 psi. Inter-0 psi. Prod-200 psi. Tbg-50 psi.
2/18/2025	Bled down the well.
2/18/2025	RUWL. Rih w/ 1 9/16" gun. Couldn't get past 1455'. RDWL.
2/18/2025	Cold call RWLS. Stoodby for WL truck.
	RURWLS. Rih w/ 1.40" gauge ring. Tagged @ 1460'. Removed gauge ring. Ran 1 3/8" weight bars.
2/18/2025	Couldn't get past 1460'. Found dehydrated paraffin on tools.
2/18/2025	Function tested the bop. 250 psi/ 3 sec per cycle. The bop is in good working condition.
2/18/2025	NDWH.
2/18/2025	NUBOP. RUFloor.
2/18/2025	Worked stuck TAC. Couldn't release the TAC.
2/18/2025	Crew performed a bop drill in 1 min.
2/18/2025	Secured the well. Pipe rams are closed. SDON.
2/18/2025	Crew drove to the yard.
2/19/2025	Crew drove to the location.
2/19/2025	Jsa. Set COFO.
2/19/2025	Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.
2/19/2025	RUPS.
	Tbg shows to be J-55. Worked stuck tbg w/ power swivel from 50 pts to 85 pts. Moved the tbg 6'(tbg
	was dragging @ 75 pts). Removed 6' sub. Worked the tbg again w/ the swivel @ 85 pts. Couldn't
	make anymore hole. (Hot oiler that was set up for today canceled. All hot oilers are sold out until
	Monday. Shut down rig until Monday for scheduled Hot oiler).
2/19/2025	RDPS

•

2/19/2025 Secured the well. Pipe rams are closed. SDON. 2/19/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Sur. 4 drove to the location. 2/24/2025 Sur. 5 drofo. 2/24/2025 Sur. 5 drofo. 2/24/2025 Rul Hot oiler, Dpsi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/24/2025 Rul Hot oiler, Hot watered the csg w/ 150 bbls FW @ 220 degrees. 2/24/2025 RuWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 RuWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 Korked stuck tbg from 50 pts to 85 pts. No changes to stuck tbg after pumping water down the well. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Grew drove to the location. 2/25/2025 Grew drove to the location. 2/25/2025 Suf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/25/2025 Suf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875° tbg. 2 jts 2.875° IPC, 5.50° TAC, 3.5 jts 2.875° IPC. Fish left in the hole=1.5 jts 2.875° tbg. 1.25°x24 isset pump w/ parted pult tube inside it above the seat nipple). 2.875 walt		
2/24/2025 Crew drove to the location. 2/24/2025 Sur. 5 et Coro. 2/24/2025 Surt-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/24/2025 RUH to tiler. 2/24/2025 RUH to tiler. 2/24/2025 RUH to tiler. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8060'. RDWL. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8060'. RDWL. 2/24/2025 Grew drove to the bg w/ 100 bbls FW @ 220 degrees. RD Hot oiler. 2/24/2025 Grew performed a bop drill in 1 min. 2/24/2025 Grew drove to the yard. 2/25/2025 Surt-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURVLS. Made a 2.25' gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free rform surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062'' jet cutter. Cut the tbg @ 105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875'' tbg, 2 jts 2.875'' PC, 5.50' TAC, 3.5 jts 2.875'' PC. Fish left in the hole=1.5 jts 2.875'' tbg (1.52''x24 inset pump w/ parted pull tube inside jt above the seat nipple). 2.875 sull plug on 2/25/2025 Secured the well. Pipe rams are clos	2/19/2025	Secured the well. Pipe rams are closed. SDON.
2/24/2025 Jsa. Set Cofo. 2/24/2025 Surf-O psi. Inter-O psi. Prod-O psi. Tbg-O psi. 2/24/2025 Waited on Hot oiler. 2/24/2025 RU Hot oiler. Hot watered the csg w/ 150 bbls FW @ 220 degrees. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 Hot watered the tbg w/ 100 bbls FW @ 220 degrees. RD Hot oiler. 2/24/2025 Grew performed a bop drill in 1 min. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Grew drove to the yard. 2/24/2025 Surf-O psi. Inter-O psi. Prod-O psi. Tbg-O psi. 2/25/2025 Grew drove to the location. 2/25/2025 Surf-O psi. Inter-O psi. Prod-O psi. Tbg-O psi. RURWLS. Made a 2.25° gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126'. LD gauge ring. FRee NoWLS. 2/25/2025 Tbg is free. Poon LD 243 [ts 2.875' tbg. 2 [ts 2.875' IPC, 5.50'' TAC, 3.5 [ts 2.875''IPC, Fish left in the hole=1.5 [ts 2.875'' tbg. 3.285''S'IPC, 4.5.30''AU' dud Anchor w/ a 2.875' bull plug on 2/25/2025 Sottom. Forklift moved out the prod tbg	2/19/2025	Crew drove to the yard.
2/24/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/24/2025 Waited on Hot oiler. 2/24/2025 RU Hot oiler. Hot watered the csg w/ 150 bbls FW @ 220 degrees. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 Korked stuck tbg from 50 pts to 85 pts. No changes to stuck tbg after pumping water down the well. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Crew drove to the yard. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 7/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 7/25/2025 Tbg is 100% free from surface to top of the stuck pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062'' jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 Its 2.875'' tbg, 2 jts 2.875'' IPC, 5.50'' TAC, 3.5 jts 2.875'' IPC. Fish left in the hole=1.5 jts 2.875'' tbg, 3 lts 2.875'' k24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875' bull plug on 2/25/2025 2/25/2025 Secured the well. Pipe rams are closed. S	2/24/2025	Crew drove to the location.
2/24/2025 Waited on Hot oiler. 2/24/2025 RU Hot oiler. Hot watered the csg w/ 150 bbls FW @ 220 degrees. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 Hot watered the tbg w/ 100 bbls FW @ 220 degrees. RD Hot oiler. 2/24/2025 Crew performed a bop drill in 1 min. 2/24/2025 Crew drove to the location. 2/25/2025 Isea Vero to the location. 2/25/2025 Surd- Opsi. Inter-0 psi. Tog-0 psi. RURWLS. Made a 2.25'' gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126'. LD gauge ring. Free pointed stuck tbg 1.25''x24 inset pump w/ parted pull tube inside jt above the seat nipple). 2.875 were nipple, 2.875'' HD, 2.50'' TAC, 3.5 jts 2.875'' IPC. Fish left in the hole=1.5 jts 2.875'' k14' tbg sub, 2.875''x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875'' bull plug on 2/25/2025 2/25/2025 Sectured the well. Pipe rams are closed. SDON. 2/25/2025 Sectured the well. Pipe rams are closed. SDON. 2/25/2025 Sectured the well. Pipe rams are closed. SDON. 2/25/2025 Sectured the well. Pipe rams are closed. SDON.	2/24/2025	Jsa. Set Cofo.
2/24/2025 RU Hot oiler. Hot watered the csg w/ 150 bbls FW @ 220 degrees. 2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 Hot watered the tbg w/ 100 bbls FW @ 220 degrees. RD Hot oiler. 2/24/2025 Worked stuck tbg from 50 pts to 85 pts. No changes to stuck tbg after pumping water down the well. 2/24/2025 Crew performed a bop drill in 1 min. 2/24/2025 Crew drove to the yard. 2/24/2025 Crew drove to the location. 2/25/2025 Sucre OFO. 2/25/2025 Surt-O psi. Inter-O psi. Trod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126'. ID gauge ring. Free pointed stuck tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple). 2.875 wat nipple, 2.875" why 2.875"x24's and screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 5/215/2025 Dotom. Forkift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926', Rur CBL. Spot cmt from 7926'-2/25/2025 5/210205 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Secured the well. Pipe rams are closed	2/24/2025	Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.
2/24/2025 RUWL. Made a TD check w/ sinker bar to 8110'. Rih w/ perf gun. Perf the tbg @ 8080'. RDWL. 2/24/2025 Hot watered the tbg w/ 100 bbls FW @ 220 degrees. RD Hot oiler. 2/24/2025 Korked stuck tbg from 50 pts to 85 pts. No changes to stuck tbg after pumping water down the well. 2/24/2025 Crew performed a bop drill in 1 min. 2/24/2025 Crew drove to the user. 2/24/2025 Crew drove to the location. 2/25/2025 Sat COFO. 2/25/2025 Sat COFO. 2/25/2025 Surt-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RUWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg, 1.25"x24 isand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on Ditor. 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Surf-0 psi. Inter-0 psi. Ptod-0 psi. Tbg-0 psi. BLM (Zota) approved to chan	2/24/2025	Waited on Hot oiler.
2/24/2025 Hot watered the tbg w/ 100 bbls FW @ 220 degrees. RD Hot oiler. 2/24/2025 Worked stuck tbg from 50 pts to 85 pts. No changes to stuck tbg after pumping water down the well. 2/24/2025 Grew performed a bop drill in 1 min. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Crew drove to the yard. 2/25/2025 Sa. Set COFO. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURVLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 52/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the location. 2/26/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the location. 2/26/2025 Secured t	2/24/2025	RU Hot oiler. Hot watered the csg w/ 150 bbls FW @ 220 degrees.
2/24/2025 Hot watered the tbg w/ 100 bbls FW @ 220 degrees. RD Hot oiler. 2/24/2025 Worked stuck tbg from 50 pts to 85 pts. No changes to stuck tbg after pumping water down the well. 2/24/2025 Crew performed a bop drill in 1 min. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Crew drove to the yard. 2/25/2025 Sac. Set COFO. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURVLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126'. Ut gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126'. Ut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 [ts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 50bttom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the yard. 2/26/2025 Crew drove to the spart.		
2/24/2025 Worked stuck tbg from 50 pts to 85 pts. No changes to stuck tbg after pumping water down the well. 2/24/2025 Crew performed a bop drill in 1 min. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Crew drove to the yard. 2/25/2025 Surd- 0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/25/2025 Surd- 0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple, 2.875 seat nipple, 2.875 seat 30, 30" Mud Anchor w/ a 2.875" bull plug on 2/25/2025 bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-2/25/2025 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Secured the vald. 2/26/2025 Son" CIBP @ 7926'. RUWL. 2/26/202		
2/24/2025 Crew performed a bop drill in 1 min. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Crew drove to the joard. 2/25/2025 Crew drove to the location. 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Isa. Set COFO. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126". LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 its 2.875" tbg, 2 its 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 5217'1 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Crew drove to the location. 2/26/2025 Crew drove to the location. 2/26/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Secured the well. Pipe norm are closed. SDON.	2/24/2025	Hot watered the tbg w/ 100 bbls FW @ 220 degrees. RD Hot oiler.
2/24/2025 Crew performed a bop drill in 1 min. 2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Crew drove to the joard. 2/25/2025 Crew drove to the location. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg colars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 2/25/2025 bottom. Forklitt moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the nole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-2/25/2025 2/25/2025 Scured the well. Pipe rams are closed. SDON. 2/25/2025 Crew drove to the location. 2/26/2025 Crew drove to the location. 2/26/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the location. <t< td=""><td></td><td></td></t<>		
2/24/2025 Secured the well. Pipe rams are closed. SDON. 2/24/2025 Crew drove to the yard. 2/25/2025 Secured the work to the location. 2/25/2025 Jsa. Set COFO. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 50ttom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the nole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-2/25/2025 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Grew drove to the location. 2/26/2025 Grew drove to the location. 2/26/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Secured the vell. Beat the		
2/24/2025 Crew drove to the location. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"xd' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 500 totm. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-2/25/2025 5217'9 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the yard. 2/26/2025 2/26/2025 Secured to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 2/26/2025 Secured to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 2/26/2025 Setty visit w/ safety Cpt. Kobie Martin. Went over hand placement 2/26/2025 Crew ate lunch. Reviewed the lsa. 2/26/2025 Crin 180 bbls of sat		
2/25/2025 Crew drove to the location. 2/25/2025 Jsa. Set COFO. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 2/25/2025 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the location. 2/26/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 2/26/2025 Removed protectors and tallied the w/s. 2/26/2025 Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).	2/24/2025	Secured the well. Pipe rams are closed. SDON.
2/25/2025 Jsa. Set COFO. 2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-2/25/2025 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the yard. 2/26/2025 Surf-0 psi. Inter-0 psi. Tbg-0 psi. BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 2/26/2025 Safety visit w' safety Cpt. Kobie Martin. Went over hand placement 2/26/2025 Safety visit w' safety Cpt. Kobie Martin. Went over hand placement 2/26/2025 Crew ate lunch. Reviewed the Isa. 2/26/2025 Safety visit w' safety Cpt. Kobie Martin. Went over		-
2/25/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-5217') 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Crew drove to the yard. 2/26/2025 Curew drove to the location. 2/26/2025 Suft-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 Removed protectors and talled the w/s. 2/26/2025 Removed protectors and talled the w/s. 2/26/2025 Rein V 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag). 2/26/2025 Rein V 243 jts 2.875" tbg. Tagged the CIB	2/25/2025	Crew drove to the location.
RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS.2/25/2025Tbg is free.Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/20252/25/2025bottom.Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 5217)2/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 5.50" CIBP @ 7926'. RDWL.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Circe and tube sat get. Tested the CiBP @ 7926' (good tag).2/26/2025Rin PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circe 180 bbls of sat get. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Circe dthe well. Blind rams are closed. SDON.2/26/2025Circe dthe well. Blind rams are closed. SDON. <td>2/25/2025</td> <td>Jsa. Set COFO.</td>	2/25/2025	Jsa. Set COFO.
stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 5217') 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the yard. 2/26/2025 Crew drove to the location. 2/26/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 Sourd protectors and tallied the w/s. 2/26/2025 Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement 2/26/2025 Crew ate lunch. Reviewed the Jsa. 2/26/2025 Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag). 2/26/2025 Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins. 2/26/2025 Secured the well. Blind rams are closed. SDON. 2/26/2025 Crew drove to the usel. Blind rams are closed. SDON.	2/25/2025	Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.
collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS. 2/25/2025 Tbg is free. Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 5217') 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/26/2025 Crew drove to the yard. 2/26/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 Safety visit w' safety Cpt. Kobie Martin. Went over hand placement 2/26/2025 Crew ate lunch. Reviewed the Jsa. 2/26/2025 Rin PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag). 2/26/2025 Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins. 2/26/2025 Secured the well. Blind rams are closed. SDON. 2/26/2025 Circ work ot the tube due. The part as are closed. SDON. 2/26/2025 Circ work ot the upperf well. Blind rams are closed. SDON. 2/26/2025 Circ work ot the tube. The part as are closed. SDON. 2/26/2025 Circ work ot the tube. The sted the csg good @ 500 psi for 30 mins. 2/26/2025 Secured the well. Blind rams are closed. SDON. 2/26/2025 Crew drove to the yard.		RURWLS. Made a 2.25" gauge ring. Tagged top of insert pump @ 8126'. LD gauge ring. Free pointed
2/25/2025Tbg is free.Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on2/25/2025bottom.2/25/2025Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 2/25/20252/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/20252/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.		stuck tbg. Tbg is 100% free from surface to top of the stuck pump @ 8126' (tbg is stuck below). Tbg
Pool LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 bottom.Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 2/25/2025 5217')2/25/2025 2/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025 2/25/2025Crew drove to the yard.2/26/2025 2/26/2025Crew drove to the location.2/26/2025 2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. BLM (Zota) approved to clange NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/20252/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the type data and closed. SDON.2/26/2025Circ work to the top board.2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.		collars @ 8121' and 8090'. LD free pt tools. Rih w/ a 2.062" jet cutter. Cut the tbg @ 8105'. RDRWLS.
 2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on 2/25/2025 bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 2/25/2025 5217') 2/25/2025 Crew drove to the yard. 2/26/2025 Crew drove to the yard. 2/26/2025 Crew drove to the location. 2/26/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 Removed protectors and tallied the w/s. 2/26/2025 Crew ate lunch. Reviewed the Jsa. 2/26/2025 Crew ate lunch. Reviewed the Jsa. 2/26/2025 Crew ate lunch. Reviewed the Liber @ 7926' (good tag). 2/26/2025 Crew ate lunch. Reviewed the CIBP @ 7926' (good tag). 2/26/2025 Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins. 2/26/2025 Secured the well. Blind rams are closed. SDON. 2/26/2025 Crew drove to the yard. 	2/25/2025	Tbg is free.
 nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on bottom. Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 2/25/2025 5217') 2/25/2025 Secured the well. Pipe rams are closed. SDON. 2/25/2025 Crew drove to the yard. 2/26/2025 Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi. BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a 2/26/2025 Son" CIBP @ 7926'. RDWL. 2/26/2025 Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement 2/26/2025 Crew ate lunch. Reviewed the Jsa. 2/26/2025 Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins. 2/26/2025 Pooh w/ 243 jts to the tbg board. 2/26/2025 Secured the well. Blind rams are closed. SDON. 2/26/2025 Circw drove to the yard. 		Pooh LD 243 jts 2.875" tbg, 2 jts 2.875" IPC, 5.50" TAC, 3.5 jts 2.875" IPC. Fish left in the hole=1.5 jts
2/25/2025bottom.Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 5217')2/25/20255217')2/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.2/26/2025Sob' CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Cirew ate lunch. Reviewed the Jsa.2/26/2025Cire 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.		2.875" tbg (1.25"x24 inset pump w/ parted pull tube inside jt above the seat nipple), 2.875 seat
Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'- 5217')2/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Cire wate lunch. Reviewed the Jsa.2/26/2025Cire 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.		nipple, 2.875"x4' tbg sub, 2.875"x24' sand screen, 3.50'x30' Mud Anchor w/ a 2.875" bull plug on
hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-2/25/20255217')2/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.8LM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/2025S.50" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Circ unch. Reviewed the Jsa.2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/25/2025	bottom.
2/25/20255217')2/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/20255.50" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 its to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.		Forklift moved out the prod tbg. Spotted in the W/S. (BLM (Zota) approved to leave the fish in the
2/25/2025Secured the well. Pipe rams are closed. SDON.2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.2/26/2025SLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/2025Son" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Soured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.		hole (TOF) @ 8105', and set the CIBP 50' above the top perf @ 7926'. Run CBL. Spot cmt from 7926'-
2/25/2025Crew drove to the yard.2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.8LM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/2025S.50" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/25/2025	5217')
2/26/2025Crew drove to the location.2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/20255.50" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/25/2025	Secured the well. Pipe rams are closed. SDON.
2/26/2025Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/20255.50" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/25/2025	Crew drove to the yard.
BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a2/26/20255.50" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	Crew drove to the location.
2/26/20255.50" CIBP @ 7926'. RDWL.2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.
2/26/2025Removed protectors and tallied the w/s.2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.		BLM (Zota) approved to change NOI CIBP from 6586' to 50' above the top perf @ 7926'. RUWL. Set a
2/26/2025Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	5.50" CIBP @ 7926'. RDWL.
2/26/2025Crew ate lunch. Reviewed the Jsa.2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	Removed protectors and tallied the w/s.
2/26/2025Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	Safety visit w/ safety Cpt. Kobie Martin. Went over hand placement
2/26/2025Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	Crew ate lunch. Reviewed the Jsa.
2/26/2025Pooh w/ 243 jts to the tbg board.2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	Rih PU 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag).
2/26/2025Secured the well. Blind rams are closed. SDON.2/26/2025Crew drove to the yard.	2/26/2025	Circ 180 bbls of salt gel. Tested the csg good @ 500 psi for 30 mins.
2/26/2025 Crew drove to the yard.	2/26/2025	Pooh w/ 243 jts to the tbg board.
	2/26/2025	Secured the well. Blind rams are closed. SDON.
	2/26/2025	Crew drove to the yard.
2/27/2025 Crew drove to the location.	2/27/2025	Crew drove to the location.

•

2/27/2025	Jsa. Set COFO.
	Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.
	RURWLS. Ran a CBL from 7926' to surface. Cmt to surface. RDWL.
212112023	Rin w/ 243 jts 2.875" tbg. Tagged the CIBP @ 7926' (good tag). BLM (Zota) requested to spot cmt
0/07/0005	from 7926'-5217'.
	Crew ate lunch. Reviewed the Jsa.
212772025	
	PLM (Zata) requested to spot ant from Z026' E017' FOT @ Z026' w/ 242 its. Spotted 1EE ave Class
0/07/0005	BLM (Zota) requested to spot cmt from 7926'-5217'. EOT @ 7926' w/ 243 jts. Spotted 155 sxs Class
	H Cmt from 7926'-6571', 32.5 bbls, 1.18 yield, 15.6 ppg, covering 1369', disp to 6557' w/ 38 bbls.
	LD 41 jts 2.875" tbg. Pooh w/ 50 jts to the tbg board.
	Secured the well. Pipe rams are closed. SDON.
	Crew drove to the yard.
	Crew drove to the location.
	Jsa. Set COFO.
2/28/2025	Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.
0.00.0005	
2/28/2025	Rih w/ 45 jts 2.875" tbg. Tagged TOC @ 6420' (good tag).BLM Javier witnessed tag and spot.
	BLM (Zota) requested to spot cmt from 7926'-5217'. EOT @ 6420' w/ 197 jts. Spotted 125 sxs Class
	C Cmt from 6420'-5156', 29.3 bbls, 1.32 yield, 14.8 ppg, covering 1246', disp to 5156' w/ 29.8 bbls.
	LD 38 jts 2.875" tbg. Pooh w/ 50 jts to the tbg board. WOC.
2/28/2025	Rih w/ 50 jts 2.875" tbg. Tagged TOC @ 5183' (good tag). LD 23 jts 2.875" tbg.
	EOT @ 4444' w/ 136 jts. Spotted 150 sxs Class C Cmt from 4444'-2927', 35.2 bbls, 1.32 yield, 14.8
	ppg, covering 1517', disp to 2927' w/ 16.9 bbls.
	LD 46 jts 2.875" tbg. Pooh w/ 50 jts to the tbg board.
	Secured the well. Pipe rams are closed. SDON.
	Crew drove to the yard.
	Crew drove to the location.
3/3/2025	
	Surf-0 psi. Inter-0 psi. Prod-0 psi. Tbg-0 psi.
3/3/2025	Set COFO. Rih w/ 50 jts 2.875" tbg. Tagged TOC @ 2969' (good tag).
o /o /o	Spotted 150 sxs Class C Cmt from 2969'-1452', 35.2 bbls, 1.32 yield, 14.8 ppg, covering 1517', disp
	to 1452' w/ 8.4 bbls.
	LD 46 jts 2.875" tbg. Pooh w/ 44 jts to the tbg board.
	Crew performed a bop drill in 1 minute.
	Shut down for high winds. SDON.
	Crew drove to the yard.
	Crew Travel to Location
	Crew HTGSM. Discuss Hand & Finger Placement.
	0 PSI on CSG. 0 PSI on Surface CSG
	RIH w/ 42 Jts of TBG. Tag CMT @ 1388'.
3/5/2025	Est. Rate @ 2 BPM. Spot 37 BBLs (155 sxs) of Class C CMT from 1388' to surface
	Lay down 42 Jts of TBG
2/5/2025	Nipple down BOPE. Top fill 5-1/2 CSG w/ CMT

3/5/2025	Crew took lunch break
3/5/2025	Rig down pulling unit & all plugging equipment
3/5/2025	Crew Travel Home
3/18/2025	CUT AND CAP COMPLETE

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Page 11 of 11

Action 460032

 CONDITIONS

 Operator:
 OXY USA INC
 16696

 P.O. Box 4294
 Action Number:
 460032

 Houston, TX 772104294
 Action Type:
 [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
gcordero	None	5/9/2025