Office				Form	
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and	Natural Resources	WELL API NO.	Revised July 1	8, 2013
<u>District II</u> - (575) 748-1283	OIL CONSERVAT	TION DIVISION	30-045-26497		
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, N	M 87505	6. State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, NM 87505			V0-1509		
SUNDRY NO	TICES AND REPORTS ON W		7. Lease Name o	or Unit Agreement N	lame
(DO NOT USE THIS FORM FOR PROD DIFFERENT RESERVOIR. USE "APP			Mamilau		
PROPOSALS.)			Mary Lou 8. Well Number		
1. Type of Well: Oil Well	Gas Well Other		2		
2. Name of Operator			9. OGRID Numb	ber	
Dugan Production Corp.3. Address of Operator			006515 10. Pool name or	r Wildcat	
PO Box 420, Farmington, NM 8	7499-0420		Bisti Gallup, Sou		
4. Well Location			L.		
	feet from the <u>North</u> line :			_	
Section 32	Township24NRand11. Elevation (Show wheth	nge 10W NMI		County	
	11. Elevation (Snow wheth	6580' GL	<i>c.)</i>		
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [PLUG AND ABANDON	REMEDIAL WO COMMENCE DI		ALTERING CASIN P AND A	ig □ ⊠
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [PLUG AND ABANDON CHANGE PLANS	REMEDIAL WO COMMENCE DI CASING/CEMEI		ALTERING CASIN	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER:	PLUG AND ABANDON] REMEDIAL WO] COMMENCE DI] CASING/CEMEI] OTHER:	RK RILLING OPNS.	ALTERING CASIN P AND A	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com	PLUG AND ABANDON] REMEDIAL WO] COMMENCE DI] CASING/CEMEI] OTHER: e all pertinent details, and	RK RILLING OPNS.	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEME] OTHER: e all pertinent details, an MAC. For Multiple Communication	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEME] OTHER: e all pertinent details, an MAC. For Multiple Communication	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEME] OTHER: e all pertinent details, an MAC. For Multiple Communication	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEME] OTHER: e all pertinent details, an MAC. For Multiple Communication	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEME] OTHER: e all pertinent details, an MAC. For Multiple Communication	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEME] OTHER: e all pertinent details, an MAC. For Multiple Communication	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEME] OTHER: e all pertinent details, an MAC. For Multiple Communication	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re rugan Production plugged the well	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHARGE PLANS COMPL COMPL COMPL COMPLETE CO] REMEDIAL WO] COMMENCE DI] CASING/CEMEI] OTHER: e all pertinent details, an MAC. For Multiple Comment er the attached procedure	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. Ork). SEE RULE 19.15.7.14 N completion.] REMEDIAL WO] COMMENCE DI] CASING/CEMEI] OTHER: e all pertinent details, an MAC. For Multiple Comment er the attached procedure	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re rugan Production plugged the well pud Date:	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMPL COMPL COMPL COMPL COMPLETE COMPL COMPLETE COM	Image: See Date: REMEDIAL WO Image: Commence Display (Commence Display (Comm	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we e.	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re rugan Production plugged the well	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMPL COMPL COMPL COMPL COMPLETE COMPL COMPLETE COM	Image: See Date: REMEDIAL WO Image: Commence Display (Commence Display (Comm	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we e.	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re rugan Production plugged the well pud Date:	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS COMPL COMPL COMPL COMPL COMPLETE COMPL COMPLETE COM	Image: See Date: REMEDIAL WO Image: Commence Display (Commence Display (Comm	RK RILLING OPNS. NT JOB d give pertinent dates mpletions: Attach we e.	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re rugan Production plugged the well pud Date:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Deleted operations. (Clearly state ork). SEE RULE 19.15.7.14 N completion. on 04/15/2025 – 04/21/2025 per Rig Release above is true and complete to the state of the st	Image: See Date: REMEDIAL WO COMMENCE DI COMMENCE DI CASING/CEMEI CASING/CEMEI Image: OTHER: OTHER: e all pertinent details, an MAC. For Multiple Comment MAC. For Multiple Comment For Multiple Comment er the attached procedure See Date: Mathematical procession Image: Comment See Date: Image: Comment Image: Mathematical procession See Date: Comment Image: Mathematical procession See Dateeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeee	RK □ RILLING OPNS.□ □ NT JOB □ d give pertinent dates □ mpletions: Attach we □ e. □ ge and belief. □	ALTERING CASIN P AND A s, including estimate	
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re rugan Production plugged the well pud Date:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 19.15.7.14 N completion. on 04/15/2025 – 04/21/2025 pc Rig Release above is true and complete to t MA	Image: See Date: REMEDIAL WO COMMENCE DI COMMENCE DI CASING/CEMEI CASING/CEMEI Image: OTHER: OTHER: e all pertinent details, an MAC. For Multiple Comment MAC. For Multiple Comment For Multiple Comment er the attached procedure See Date: Mathematical procession Image: Comment See Date: Image: Comment Image: Mathematical procession See Date: Comment Image: Mathematical procession See Dateeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeeee	RK □ RILLING OPNS.□ □ NT JOB □ d give pertinent dates □ ge and belief. □	ALTERING CASIN P AND A s, including estimate ellbore diagram of	ed date
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re ugan Production plugged the well hereby certify that the information IGNATURE <u>Aliph Reena</u> ype or print name <u>Aliph Reena</u> , <u>or State Use Only</u>	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL multiple completions. (Clearly state ork). SEE RULE 19.15.7.14 N completion. on 04/15/2025 – 04/21/2025 pc Rig Release above is true and complete to t ma TITLE E P.E. E-mail address:	Image: Sec Date: REMEDIAL WO COMMENCE DI COMMENCE DI CASING/CEMEI OTHER: e all pertinent details, an MAC. For Multiple Comment er the attached procedure Sec Date: se Date: Image: Comment he best of my knowledge Sec Date:	RK □ RILLING OPNS.□ □ NT JOB □ d give pertinent dates □ d give pertinent dates □ e. □ ge and belief. □ ge and belief. □ Toduction.com PHC	ALTERING CASIN P AND A s, including estimate ellbore diagram of E	ed date
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING [DOWNHOLE COMMINGLE [CLOSED-LOOP SYSTEM [OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re bugan Production plugged the well pud Date: hereby certify that the information IGNATURE <u>Aliph Recent</u> ype or print name <u>Aliph Recent</u>	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL pleted operations. (Clearly state ork). SEE RULE 19.15.7.14 N completion. on 04/15/2025 – 04/21/2025 pc Rig Release above is true and complete to t MA	Image: Second	RK □ RILLING OPNS.□ □ NT JOB □ d give pertinent dates □ d give pertinent dates □ e. □ ge and belief. □ roduction.com PHC	ALTERING CASIN P AND A s, including estimate ellbore diagram of E	ed date

•

Dugan Production P&A'd the well per the following procedure on **04/15/2025 - 04/21/2025**:

- MI&RU Aztec Rig 481 and cement equipment. Spot & RU.
- Check pressures, Tubing 28 psi, Casing 28 psi, BH 0 psi.
- ND WH & NU BOP. LD rods & 2-3/8" rod string and production tubing.
- Check pressures, Tubing 0 psi, Casing 0 psi, BH 0 psi.
- PU workstring & 4¹/₂" string mill to 4471'. RT string mill.
- Check pressures, Tubing 0 psi, Casing 5 psi, BH 0 psi.
- PU 4¹/₂" CIBP and set @ 4420'. Loaded and circulated hole w/70 bbls water.
- Pressure tested casing to 650 psi for 30 minutes. Casing held, good test.
- MIRU WL and performed CBL from 4420' to surface.
- Sent copy of CBL & revised procedure to NMOCD. Copy of communications attached.
- **Plug I, Gallup**: Spot Plug I, Inside 4½" casing above the CIBP w/36 sks 41.4 cu ft Class G neat cement to cover Gallup. Displaced w/15.3 bbls water. WOC overnight. Tagged TOC at 3980'. Good tag. **Plug I, Inside 4½**" casing, 36 sks, 41.4 cu ft, Gallup top & perforations, 3980'-4268'.
- Plug II, Mancos-DV Tool: Spot Plug II, Inside 4½" casing from 3704' to 3503' w/16 sks, 18.4 cu ft Class G neat cement to cover the Mancos top -DV Tool. Displaced w/13.5 bbls water. Plug II, Inside 4½" casing, 16 sks, 18.4 cu ft, DV Tool Mancos, 3503'–3704'.
- Plug III, Mesaverde-Lower Chacra-Upper Chacra: Spot Plug III, Inside 4½" casing from 2168' to 1476' w/54 sks, 62.1 cu ft to cover the Mesaverde, Lower Chacra & Upper Chacra tops. Displaced w/5.7 bbls water. Plug III, Inside 4½", 54 sks, 62.1 cuft, Mesaverde-Lower Chacra & Upper Chacra, 1476'-2168'.
- Plug IV, Pictured Cliffs: Spot Plug IV, Inside 4½" casing from 1097' to 896' w/16 sks, 18.4 cu ft Class G neat cement to cover the Pictured Cliffs top. Displaced w/3.4 bbls water. Plug IV, inside 4½" casing, 16 sks, 18.4 cu ft, Pictured Cliffs, 896'-1097'.
- Plug V, Fruitland: Spot Plug V, Inside 4½" casing from 724' to 233' w/38 sks, 43.7 cu ft Class G neat cement to cover the Fruitland top. Displaced w/0.9 bbls water. Plug V, Inside 4½" casing, 38 sks, 43.7 cu ft, Fruitland, 233'-724'.
- Plug VI, Kirtland-Surface Casing shoe Surface: RU WL services. Shoot perforations @ 220' for Surface. RD WL and verified all shots fired. TIH to 230'. Establish rates through squeeze holes at 2.1 bpm, 50 psi. Swap to cement. Spot & Squeeze Plug VI, inside/outside 4½" casing w/98 sks, 112.7 cu ft cement to cover the Kirtland top & surface casing shoe to surface. Circulated 1 bbl cement through BH. WOC 4 hours. Cut wellhead off. Tagged TOC at 12' inside casing and 0' inside annulus. Good tag. Plug VI, Inside/Outside 4½" casing, perforations at 220', EOT at 230', 98 sks, 112.7 cu ft, Kirtland-Surface casing shoe Surface, 0'–230'.
- Fill up cellar & install dry hole marker w/24 sks, 27.6 cu ft Class G neat cement.
- Clean location. RD Aztec 481. PU tools and trash. Empty pits. Move out.
- Witnessed by NMOCD rep on location Clarence Smith.
- Well P&A'd 04/21/2025.

Subsequent P & A Schematic

Page 3 of 7

Mary Lou # 2 API: 30-045-26497 Sec 32 T24N R10W 1980' FNL & 1980' FEL San Juan County, NM Lat: 36.271825, Long: -107.917053

8-5/8" J-55 24# casing @ 217'. Cemented with 159 Cu.ft.

Plug VI, Inside/Outside 4¹/₂" casing, Perforations at 220', EOT at 230', 98 sks, 112.7 cu ft, Kirtland-Surface casing shoe – Surface, 0'–230'

Plug V, Inside 4¹/₂" casing, 38 sks, 43.7 Cu. ft, Fruitland, 233'-724'

Plug IV, inside 4¹/₂" casing, 16 sks, 18.4 Cu.ft, Pictured Cliffs, 896'-1097'

Plug III, Inside 4½", 54 sks, 62.1 Cu ft, Mesaverde-Lower Chacra & Upper Chacra, 1476'-2168'


Plug II, Inside 4¹/₂" casing, 16 sks, 18.4 cu ft, DV Tool – Mancos, 3503'-3704'

Cemented Stage I w/ 200 sks 50/50 poz, 254 Cu.ft. **DV tool @ 3604**'. Stage II w/ 450 sks 65-35-12 & 50 sks Poz, 1059 Cu.ft. Total 1313 cement.

CIBP @ 4420'. Plug I, Inside 4½" casing, 36 sks, 41.4 Cu ft, Gallup top & perforations, 3980'-4420'

Gallup Perforated @ 4470'-4729'

4 ¹⁄₂" 10.5 # casing @ 4838', Hole size 7-7/8"



Mary Lou # 2 API: 30-045-26497 Sec 32 T24N R10W 1980' FNL & 1980' FEL San Juan County, NM Lat: 36.271825, Long: -107.917053

Elevation ASL: 6580' GL, 6592' KB

Formation Tops (Referenced for P & A)

- Surface Casing 217'
- Kirtland 275'
- Fruitland 663'
- Pictured Cliffs 1033'
- Lewis 1070'
- Upper Chacra 1590'
- Lower Chacra 1750'
- Mesaverde 2110'
- DV tool 3604'
- Mancos 3654'
- Gallup 4150'
- Gallup Perfs 4470'-4729'

Tyra Feil

From:	Kuehling, Monica, EMNRD <monica.kuehling@emnrd.nm.gov></monica.kuehling@emnrd.nm.gov>
Sent:	Thursday, April 17, 2025 3:49 PM
То:	Aliph Reena; AWS Units - Alex Robles; Tyra Feil; Smith, Clarence, EMNRD
Subject:	RE: [EXTERNAL] RE: Dugan_Mary_Lou_2_CBL.pdf

CAUTION: This email originated from outside your organization. Exercise caution when opening attachments or clicking links, especially from unknown senders.

NMOCD approves below

Thank you

Monica Kuehling Compliance Officer Supervisor Deputy Oil and Gas Inspector New Mexico Oil Conservation Division North District Cell Phone: 505-320-0243 Email - monica.kuehling@emnrd.nm.gov

From: Aliph Reena <Aliph.Reena@duganproduction.com>
Sent: Thursday, April 17, 2025 12:30 PM
To: AWS Units - Alex Robles <arobles@aztecwell.com>; Tyra Feil <Tyra.Feil@duganproduction.com>; Kuehling, Monica, EMNRD
<monica.kuehling@emnrd.nm.gov>; Smith, Clarence, EMNRD <Clarence.Smith@emnrd.nm.gov>
Subject: [EXTERNAL] RE: Dugan_Mary_Lou_2_CBL.pdf

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

RE: Dugan Production Corp. Mary Lou # 2 API: 30-045-26497

Please see the attached CBL for Dugan Production's Mary Lou # 2. Based on the CBL, we request the following changes to the original approved NOI.

- The TOC appear to be around 230'.
- A section below the DV tool from 3650'-3970' has been noted, but there is some acceptable cement bonding in that section looking at the Variable Density curve. We do not expect to get a rate through there and therefore request not to perforate that section of casing. We request to do an **inside plug for Plug II, Mancos DV tool plug** as approved in the original NOI.

- **Plug V:** Will split the plugs. Will do Fruitland plug as inside plug. For Kirtland-Surface plug, we will do inside/outside by perforating at 220'. Will squeeze and do an inside/outside plug for Kirtland-Surface and circulate cement to surface through BH.
- We also have a good test on the casing.

If the requested changes are acceptable to NMOCD, please let us know and we will proceed accordingly.

Aliph Reena P.E Engineering Supervisor Dugan Production Corp. Cell: 505-360-9192

From: AWS Units - Alex Robles <arobies@aztecwell.com>
Sent: Thursday, April 17, 2025 11:34 AM
To: Aliph Reena <<u>Aliph.Reena@duganproduction.com</u>>
Cc: Tyra Feil <<u>Tyra.Feil@duganproduction.com</u>>; MONICA <<u>monica.kuehling@emnrd.nm.gov</u>>; VIRGIL <<u>vlucero@blm.gov</u>>;
clarence.smith@emnrd.nm.gov
Subject: Dugan_Mary_Lou_2_CBL.pdf

CAUTION: This email originated from outside your organization. Exercise caution when opening attachments or clicking links, especially from unknown senders.

Alex Prieto Rig Manager – San Juan Basin Aztec Well Servicing Co. P.O. Box 100 Aztec, New Mexico 87410 Cell: 505-419-9882 Office: 505-334-6191 Arobles@aztecwell.com



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator: 0	OGRID:
DUGAN PRODUCTION CORP	6515
PO Box 420	Action Number:
Farmington, NM 87499	487242
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
loren.diede	None	7/23/2025

Page 7 of 7

Action 487242