

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT Sundry Print Report

Well Name: PINON Well Location: T30N / R14W / SEC 13 / County or Parish/State: SAN

NWSW / 36.811691 / -108.265686 JUAN / NM

Well Number: 1E Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: NMNM6899 Unit or CA Name: **Unit or CA Number:**

US Well Number: 300452418600S1 **Operator: DUGAN PRODUCTION**

CORPORATION

Notice of Intent

Sundry ID: 2869529

Type of Submission: Notice of Intent Type of Action: Plug and Abandonment

Date Sundry Submitted: 08/25/2025 Time Sundry Submitted: 02:43

Date proposed operation will begin: 09/11/2025

Procedure Description: Dugan Production plans to plug and abandon the well per the following procedure: 1) PU & tally 2-3/8" workstring. Run 41/2" casing scraper to 6275'. RIH & set 41/2" CIBP @ 6245'. Dakota perforations are from 6295'-6488'. 2) Run CBL from 6245' to surface. All plugs are designed assuming good cement behind 41/2" casing for this NOI. Will make necessary changes to the plugs after reviewing the CBL. 3) Attempt to pressure test casing to 650 psi for 30 minutes. 4) Plug I, Dakota Perforations-Dakota-Graneros: Spot Plug I inside 4½" casing above the CIBP from 6245' to 6095' w/12 sks, 13.8 cu ft Class G neat cement to cover the Dakota perforations, Dakota and Graneros tops. Plug I, Inside 4½" casing, 14 sks, 16.1 cu ft, Dakota perforations-Dakota top-Graneros, 6095'-6245'. 5) Plug II, Gallup: Spot Plug II inside 41/2" casing from 5460' to 5310' w/12 sks (13.8 cu ft) Class G cement to cover the Gallup top. Plug II, Inside 41/2" casing, 12 sks, 13.8 cu ft, Gallup, 5310'-5460'. 6) Plug III, Mancos-DV: Spot Plug III inside 41/2" casing from 4549' to 4368' w/15 sks (17.25 cu ft) Class G cement to cover the DV tool & Mancos top. Plug III, Inside 41/2" casing, 15 sks, 18.25 cu ft, Mancos-DV, 4368'-4549'. 7) Plug IV, Mesaverde, Lower Chacra & Upper Chacra: Spot Plug IV inside 41/2" casing from 3278' to 2652' w/50 sks, 57.5 cu ft Class G neat cement to cover the Mesaverde, Lower Chacra & Upper Chacra tops. Plug IV, Inside 41/2" casing, 50 sks, 57.5 cu ft, Mesaverde-Lower Chacra-Upper Chacra, 2652'-3278'. 8) Plug V, Pictured Cliffs-Fruitland: Spot Plug V inside 4½" casing from 1688' to 1310' w/30 sks, 34.5 cu ft Class G cement to cover the Pictured Cliffs & Fruitland tops. Plug V, Inside 4½" casing, 30 sks, 34.5 cu ft, Pictured Cliff-Fruitland, 1310'-1688'. 9) Plug VI: Kirtland-Surface Casing-Surface: Spot Plug VI inside 41/2" casing from 267' to surface w/22 sks, 25.3 cu ft to cover the Kirtland top & surface casing shoe to surface. Plug VI, Inside 4½", 22 sks, 25.3 cu ft, Kirtland- Surface Casing-Surface, 0-267'. 10) Cut wellhead. Tag TOC at surface. Fill cement in case needed. 11) Install dry hole marker. Clean location.

Page 1 of 3

eceived by OCD: 9/3/2025 2:18:13 PM Well Name: PINON County or Parish/State: SAN 2 of Well Location: T30N / R14W / SEC 13 /

NWSW / 36.811691 / -108.265686

Well Number: 1E Type of Well: CONVENTIONAL GAS **Allottee or Tribe Name:**

Unit or CA Name:

Unit or CA Number:

JUAN / NM

Operator: DUGAN PRODUCTION US Well Number: 300452418600S1

CORPORATION

Surface Disturbance

Lease Number: NMNM6899

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Pinon_1E_Rec_Plan_7_2_25_20250903122359.pdf

Pinon_1E_proposed_PA_planned_wellbore_schematic_20250903122358.pdf

Pinon_1E_proposed_PA_formation_tops_9_2_25_20250903122358.pdf

Pinon_1E_proposed_PA_planned_work_20250903122358.pdf

Pinon_1E_proposed_PA_current_wellbore_schematic_20250903122357.pdf

Conditions of Approval

Additional

General_Requirement_PxA_20250903140518.pdf

2869529_1E_3004524186_NOIA_KR_09032025_20250903140440.pdf

Pinon_1E_Geo_KR_20250903140302.pdf

Page 2 of 3

eived by OCD: 9/3/2025 2:18:13 PM Well Name: PINON County or Parish/State: SAN Well Location: T30N / R14W / SEC 13 /

NWSW / 36.811691 / -108.265686

JUAN / NM

Well Number: 1E Type of Well: CONVENTIONAL GAS **Allottee or Tribe Name:**

Unit or CA Name: Lease Number: NMNM6899 **Unit or CA Number:**

US Well Number: 300452418600S1 Operator: DUGAN PRODUCTION

CORPORATION

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: TYRA FEIL Signed on: SEP 03, 2025 12:24 PM

Name: DUGAN PRODUCTION CORPORATION

Title: Authorized Representative Street Address: PO BOX 420

City: FARMINGTON State: NM

Phone: (505) 325-1821

Email address: TYRAFEIL@DUGANPRODUCTION.COM

Field

Representative Name: Aliph Reena

Street Address: PO Box 420

City: Farmington State: NM **Zip:** 87499-0420

Phone: (505)360-9192

Email address: Aliph.Reena@duganproduction.com

BLM Point of Contact

BLM POC Name: KENNETH G RENNICK BLM POC Title: Petroleum Engineer

BLM POC Phone: 5055647742 BLM POC Email Address: krennick@blm.gov

Disposition: Approved Disposition Date: 09/03/2025

Signature: Kenneth Rennick


Page 3 of 3

Dugan Production plans to plug and abandon the well per the following procedure:

- PU & tally 2-3/8" workstring. Run 4½" casing scraper to 6275'. **RIH & set 4½" CIBP @ 6245**'. Dakota perforations are from 6295'-6488'.
- Run CBL from 6245' to surface. All plugs are designed assuming good cement behind 4½" casing for this NOI. Will make necessary changes to the plugs after reviewing the CBL.
- Attempt to pressure test casing to 650 psi for 30 minutes.
- Plug I, Dakota Perforations-Dakota-Graneros: Spot Plug I inside 4½" casing above the CIBP from 6245' to 6095' w/12 sks, 13.8 cu ft Class G neat cement to cover the Dakota perforations, Dakota and Graneros tops. Plug I, Inside 4½" casing, 14 sks, 16.1 cu ft, Dakota perforations-Dakota top-Graneros, 6095'-6245'.
- Plug II, Gallup: Spot Plug II inside 4½" casing from 5460' to 5310' w/12 sks (13.8 cu ft) Class G cement to cover the Gallup top. Plug II, Inside 4½" casing, 12 sks, 13.8 cu ft, Gallup, 5310'-5460'.
- Plug III, Mancos-DV: Spot Plug III inside 4½" casing from 4549' to 4368' w/15 sks (17.25 cu ft) Class G cement to cover the DV tool & Mancos top. Plug III, Inside 4½" casing, 15 sks, 18.25 cu ft, Mancos-DV, 4368'-4549'.
- Plug IV, Mesaverde, Lower Chacra & Upper Chacra: Spot Plug IV inside 4½" casing from 3278' to 2652' w/50 sks, 57.5 cu ft Class G neat cement to cover the Mesaverde, Lower Chacra & Upper Chacra tops. Plug IV, Inside 4½" casing, 50 sks, 57.5 cu ft, Mesaverde-Lower Chacra-Upper Chacra, 2652'-3278'.
- Plug V, Pictured Cliffs-Fruitland: Spot Plug V inside 4½" casing from 1688' to 1310' w/30 sks, 34.5 cu ft Class G cement to cover the Pictured Cliffs & Fruitland tops. Plug V, Inside 4½" casing, 30 sks, 34.5 cu ft, Pictured Cliff-Fruitland, 1310'-1688'.
- Plug VI: Kirtland-Surface Casing-Surface: Spot Plug VI inside 4½" casing from 267' to surface w/22 sks, 25.3 cu ft to cover the Kirtland top & surface casing shoe to surface. Plug VI, Inside 4½", 22 sks, 25.3 cu ft, Kirtland- Surface Casing-Surface, 0-267'.
- Cut wellhead. Tag TOC at surface. Fill cement in case needed.
- Install dry hole marker. Clean location.

Current Wellbore Schematic

Pinon #1E 30-045-24186 Basin Dakota 1790' FSL & 890' FWL S13-T30N-R14W San Juan County, NM



Hole 12 ¼", Casing 8-5/8" 24# @ 217" Cemented w/ 150 sks Class B Cement circulated.

4 ½" 10.5# casing @6588. Hole 7-7/8"

1st stage: 175 sks Class B 8% gel + 200 sks class B. (Total slurry 572 cu ft). Stage tool @ 4499'. 2^{nd} stage w/ 400 sks 65-35 +12% gel, 100 sks Class B neat (Total slurry 1200 cu ft). 875 sks total.


1 1/2" Tubing to 6436'

Dakota perforations from 6295'-6488'

4 ½" 10.5 # casing @ 6588', Hole size 7-7/8"

Planned P & A Schematic

Pinon #1E 30-045-24186 Basin Dakota 1790' FSL & 890' FWL S13-T30N-R14W San Juan County, NM



Hole 12 ¼", Casing 8-5/8" 24# @ 217" Cemented w/ 150 sks Class B Cement circulated.

Plug VI, Inside 4 ½", 22 sks, 25.3 Cu.ft, Kirtland- Surface Casing-Surface, 0-267'

Plug V, Inside 4 $\frac{1}{2}$ " casing, 30 sks, 34.5 Cu.ft, Pictured Cliff-Fruitland, 1310'-1688'

Plug IV, Inside 4 $1\!\!/\!\!2$ casing, 50 sks, 57.5 Cu.ft, Mesaverde-Lower Chacra-Upper Chacra, 2652'-3278'.

Plug III, Inside 4 ½" casing, 15 sks, 18.25 Cu.ft, Mancos-DV, 4368'-4549'

4 1/2" 10.5# casing @6588. Hole 7-7/8"

1st stage: 175 sks Class B 8% gel + 200 sks class B. (Total slurry 572 cu ft). Stage tool @ 4499'. 2^{nd} stage w/ 400 sks 65-35 +12% gel, 100 sks Class B neat (Total slurry 1200 cu ft). 875 sks total.

Plug II, Inside 4 ½" casing, 12 sks, 13.8 Cu.ft, Gallup, 5310'-5460'

CIBP at 6245'. Plug I, Inside 4 ½" casing, 14 sks, 16.1 Cu.ft, Dakota Perforations-Dakota top-Graneros, 6095'-6245'.

Dakota perforations from 6295'-6488'

4 ½" 10.5 # casing @ 6588', Hole size 7-7/8"

Pinon #1E

30-045-24186 Basin Dakota 1790' FSL & 890' FWL S13-T30N-R14W San Juan County, NM

Elevation ASL: 5938' GL

Formation Tops (Operator Submitted)

- · Ojo Alamo Surface
- Surface Casing 217'
- Kirtland 194'
- Fruitland 1410'
- Pictured Cliffs 1638'
- Lewis 1867'
- Chacra Upper- 2752'
- Chacra Lower 2920'
- Mesaverde 3228'
- Mancos 4468'
- DV tool 4499'
- Gallup 5410'
- Greenhorn 6175'
- Graneros 6241'
- Dakota 6292'
- Dakota perforations 6295'-6488'



United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington District Office 6251 College Boulevard, Suite A Farmington, New Mexico 87402 http://www.blm.gov/nm



CONDITIONS OF APPROVAL

September 3, 2025

Notice of Intent - Plug and Abandonment

Operator: Dugan Production Corporation

Lease: NMNM 006899

Well(s): Pinon 1E, US Well # 30-045-24186

Location: NWSW Sec 13 T30N R14W (San Juan, NM)

Sundry Notice ID #: 2869529

The Notice of Intent to Plug and Abandon is accepted with the following Conditions of Approval (COA):

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. The following modifications to your plugging program are to be made: a. No changes to the procedure.
- 3. <u>Notification:</u> Farmington Office is to be notified at least 24 hours before the plugging operations commence at (505) 564 7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

K. Rennick 9/3/2025

GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
 - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
 - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
 - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
 - 4.1 The cement shall be as specified in the approved plugging plan.
 - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.3 Surface plugs may be no less than 50' in length.
 - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
 - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

2

- 5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.
 - 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
 - 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
 - 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
 - 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
 - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
 - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain H_2S .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), through the Automated Fluid Minerals Support System (AFMSS) with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

BLM - FFO - Geologic Report

Date Completed 9/03/2025

 Well No.
 Pinon 1E
 Surf. Loc.
 1790 FSL
 890 FWL

 US Well No.
 30-045-24186
 NWSW
 13
 T. 30N R. 14W

Lease No. NMNM 006899

County San Juan State New Mexico

Operator Dugan Production Corporation Formation Basin Dakota

TVD 6570 PBTD 6556 Elevation KB N/A

Elevation GL 5938

| Geologic Formations | Est. tops | Remarks |
|----------------------|-----------|---------------------------|
| Kirtland | 194 | |
| Surface Casing | 217 | |
| Fruitland Fm | 1410 | Cool/ goo/ possible water |
| | | Coal/ gas/ possible water |
| Pictured Cliffs | 1638 | Possible gas/ water |
| Lewis Shale (Main) | 1770 | Source rock |
| Huerfanito Bentonite | 2400 | Reference bed |
| Chacra (Upper) | 2752 | Possible gas/ water |
| Lewis Shale Stringer | 2800 | Source rock |
| Chacra (Lower) | 2920 | Possible gas/ water |
| Lewis Shale Stringer | 3100 | Source rock |
| Cliff House Ss | 3228 | Possible gas/ water |
| Menefee Fm | 3380 | Coal/ water/ possible gas |
| Point Lookout Fm | 4050 | Possible gas/ water |
| Mancos Shale | 4468 | Source rock |
| DV Tool | 4499 | |
| Gallup | 5410 | Oil & gas |
| Greenhorn | 6175 | |
| Graneros Shale | 6241 | |
| Dakota Ss | 6292 | Oil & gas |
| Dakota Perfs (Top) | 6295 | |
| (Bottom) | 6488 | |

Remarks: Reference Well:

| The available raster logs confirms the formation tops selected by the operator. No changes to the procedure. | N/A, raster logs associated to the well |
|--|---|
| | |
| | |
| | |
| | |
| | |

Prepared by: Kenneth Rennick

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 502515

CONDITIONS

| Operator: | OGRID: |
|-----------------------|-------------------------------------|
| DUGAN PRODUCTION CORP | 6515 |
| PO Box 420 | Action Number: |
| Farmington, NM 87499 | 502515 |
| | Action Type: |
| | [C-103] NOI Plug & Abandon (C-103F) |

CONDITIONS

| Created By | | Condition Date |
|-------------|--|-------------------|
| loren.diede | Notify the OCD inspection supervisor via email 24 hours prior to beginning Plug & Abandon (P&A) operations. | 9/3/2025 |
| loren.diede | Submit photo and GPS coordinates of the P&A marker with the final P&A reports. The API# on the photo is to be clearly legible. | 9/3/2025 |