

**State Of New Mexico**  
**Energy, Minerals and Natural Resources Department**

08-Dec-25

**Landmark Energy Partners, LLC**  
15409 Fountain Creek Lane  
Edmond, OK 73013

**Pre Enforcement Notification**

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

*INSPECTION DETAIL SECTION*

---

[30-025-08608] CONE JALMAT YATES POOL UNIT #108                      OGRID: 332519                      O-13-22S-35E 660 FSL 1980 FEL

<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Inspection No.</b>
12/8/2025	Routine Inspection	[BZL] Barbara Lydick	iBZL2534265350
<b>Violation</b>	<b>Title</b>	<b>Corrective Action Due</b>	
cBZL2534268670	19.15 Oil and Gas Mechanical Integrity Failure Recorded <i>(Auto Generated Violation - MIT Failure exits.)</i>	3/8/2026	
cBZL2534268671	19.15.26 Injection Detection of Deficient Mechanical Integrity <i>(5 yr MIT FAILED-ran chart 9 min continuous pressure loss WELL UST BE SHUT IN ASAP)</i>	3/8/2026	

---

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.