

30-015-42568

JUL 12 2019 PM 01:56



United States Department of the Interior



BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968

In Reply Refer To:
3186
(3186.1)
Big Eddy Unit
NMNM68294X

JUL 08 2019

XTO Energy Inc.
Attn: Greg Davis
EMHC.W4.4A.541
22777 Springwoods Village Pkwy
Spring, Texas 77389-1425

Re: Paying Well Determination
Big Eddy Unit No. DI28 277H
SHL: NW $\frac{1}{4}$ NW $\frac{1}{4}$, Sec. 15, T.21S., R.29E. (NMLC62940)
BHL: NE $\frac{1}{4}$ SE $\frac{1}{4}$, Sec. 13, T.21S., R.29E. (NMNM06748)
Big Eddy Unit
Eddy County, New Mexico

Gentlemen:

We have determined that under existing conditions the Big Eddy Unit (BEU) No. DI28 277H well is **not** capable of producing unitized substances from the Bone Spring Formation in unit paying quantities. The well was completed in the Bone Spring Formation on December 4, 2014. Since the well was determined to be a nonpaying unit well, a drilling and spacing unit must be established for the well so that a communitization agreement can be approved by the New Mexico State Office.

If you have any questions, please call Lewis Tromp, Petroleum Engineer at (307) 261-7628.

Sincerely,

/s/ J. David Chase

J. David Chase
Chief, Reservoir Management Group

cc: NMSO, James Glover
CFO, Chris Walls