Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-021-20506
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE A
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	West Bravo Dome Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other CO2 Supply	8. Well Number 221J
2. Name of Operator	9. OGRID Number
Hess Corporation	9. OGRID Nulliber 495
3. Address of Operator PO Box 840	10. Pool name or Wildcat (96387)
Seminole TX 79360	West Bravo Dome CO2 Gas
4. Well Location	
Unit Letter J: 1980 feet from the SOUTH line and	feet from the EAST line
Section 22 Township 19N Range 29E	NMPM County HARDING
11. Elevation (Show whether DR, RKB, RT, GR, etc.	.)
4601'	
12. Check Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTENTION TO	OCCUPAT DEPORT OF
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WO	RK ☐ ALTERING CASING ☐ ☐ RILLING OPNS.☐ P AND A ☐
-	 -
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE	II JOB 🔲
DOWNHOLE COMMINGLE	
OTHER: clean out	
OTHER: clean out	nd give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completed operations.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completed operations.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO.	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO.	empletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO.	empletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO.	empletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Spud Date: 4/23/2010 Rig Release Date:	ge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO.	ge and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Spud Date: 4/23/2010 Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled. SIGNATURE TITLE Engineering Telegraphics.	ge and belief. DATE 9/9/2010
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Spud Date: 4/23/2010 Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowled site. RDMO. TITLE Engineering Telestate Use Only Type or print name Rita C. Smith E-mail address: rsmith@hese.	ge and belief. DATE 9/9/2010 PHONE: 432-758-6726
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Spud Date: 4/23/2010 Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowled site. RDMO. TITLE Engineering Telestate Use Only Type or print name Rita C. Smith E-mail address: rsmith@hese.	ge and belief. DATE 9/9/2010 PHONE: 432-758-6726
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Coproposed completion or recompletion. Intent week of 9/17/2010 Day 1 MIRU. Kill well with 4% KCL. NDWH & NU BOP's. Day 2 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Day 3 ND BOP's & NU WH. Return well to production. Clean site. RDMO. Spud Date: 4/23/2010 Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled. SIGNATURE TITLE Engineering Telegraph of the state of the set of the set of the best of the set of	ge and belief. Ch DATE 9/9/2010 SS.COM PHONE: 432-758-6726