

LEASE ROAD







Release/Excavation Area (contamainated soils scraped from surface)



Williams Battery

30-015-24072

Section 25, T18S-R26E

Eddy County, NM

SAMPLE DIAGRAM(Not to Scale)

Xenco Laboratories# 431073 & 431074 Report Date: 11/21/2011

Prepared by Amber Cannon Environmental Regulatory Agent

WILLIAMS BATTERY

Analytical Report- 426981 & 426978	Sample Area	Sample Date	Sample Type	Depth	BTEX	GRO	DRO	TOTAL	Chlorides
Comp-#1	Release Area	11/1/2011	Comp/Auger	1'	ND	ND	55.4	55.4	4,480
Comp-#2	Release Area	11/1/2011	Comp/Auger	2'	ND	ND	ND	ND	5,020
Comp-#3	Release Area	11/1/2011	Comp/Auger	2'.	ND	ND	ND	ND	3,760
Comp:#4	Release Area	11/1/2011	Comp/Auger	3'	ND	ND	ND	ND	3,520

Site Ranking is TWENTY (20). Depth to Ground Water <50' (approx. 35', Section 25-18S-26E, per NMOSE).

All results are ppm.Chlorides for documentation. X - Sample Points

Released: 189 B/PW; Recovered: 120 B/PW. Release Date: 9/18/2011

Analytical Report 431074

for Yates Petroleum Corporation

Project Manager: Amber Cannon
Williams Battery
30-015-24072
21-NOV-11

Collected By: Client



Celebrating 20 Years of commitment to excellence in Environmental Testing Services



12600 West I-20 East Odessa, Texas 79765

Xenco-Houston (EPA Lab code: TX00122):

Texas (T104704215-10-6-TX), Arizona (AZ0765), Arkansas (08-039-0), Connecticut (PH-0102), Florida (E871002) Illinois (002082), Indiana (C-TX-02), Iowa (392), Kansas (E-10380), Kentucky (45), Louisiana (03054) New Hampshire (297408), New Jersey (TX007), New York (11763), Oklahoma (9218), Pennsylvania (68-03610) Rhode Island (LAO00312), USDA (S-44102)

Xenco-Atlanta (EPA Lab Code: GA00046): Florida (E87429), North Carolina (483), South Carolina (98015), Utah (AALII), West Virginia (362), Kentucky (85) Louisiana (04176), USDA (P330-07-00105)

Xenco-Miami (EPA Lab code: FL01152): Florida (E86678), Maryland (330)
Xenco-Tampa Mobile (EPA Lab code: FL01212): Florida (E84900)
Xenco-Odessa (EPA Lab code: TX00158): Texas (T104704400-TX)
Xenco-Dallas (EPA Lab code: TX01468): Texas (T104704295-TX)
Xenco Phoenix (EPA Lab Code: AZ00901): Arizona (AZ0757)
Xenco-Phoenix Mobile (EPA Lab code: AZ00901): Arizona (AZM757)
Xenco Tucson (EPA Lab code: AZ000989): Arizona (AZ0758)





21-NOV-11

Project Manager: Amber Cannon Yates Petroleum Corporation

105 South Fourth St. Artesia, NM 88210

Reference: XENCO Report No: 431074

Williams Battery

Project Address: 25-18S-26E, Eddy County

Amber Cannon:

We are reporting to you the results of the analyses performed on the samples received under the project name referenced above and identified with the XENCO Report Number 431074. All results being reported under this Report Number apply to the samples analyzed and properly identified with a Laboratory ID number. Subcontracted analyses are identified in this report with either the NELAC certification number of the subcontract lab in the analyst ID field, or the complete subcontracted report attached to this report.

Unless otherwise noted in a Case Narrative, all data reported in this Analytical Report are in compliance with NELAC standards. Estimation of data uncertainty for this report is found in the quality control section of this report unless otherwise noted. Should insufficient sample be provided to the laboratory to meet the method and NELAC Matrix Duplicate and Matrix Spike requirements, then the data will be analyzed, evaluated and reported using all other available quality control measures.

The validity and integrity of this report will remain intact as long as it is accompanied by this letter and reproduced in full, unless written approval is granted by XENCO Laboratories. This report will be filed for at least 5 years in our archives after which time it will be destroyed without further notice, unless otherwise arranged with you. The samples received, and described as recorded in Report No. 431074 will be filed for 60 days, and after that time they will be properly disposed without further notice, unless otherwise arranged with you. We reserve the right to return to you any unused samples, extracts or solutions related to them if we consider so necessary (e.g., samples identified as hazardous waste, sample sizes exceeding analytical standard practices, controlled substances under regulated protocols, etc).

We thank you for selecting XENCO Laboratories to serve your analytical needs. If you have any questions concerning this report, please feel free to contact us at any time.

Respectfully,

Brent Barron II

Odessa Laboratory Manager

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994.

Certified and approved by numerous States and Agencies.

A Small Business and Minority Status Company that delivers SERVICE and QUALITY

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Atlanta - Corpus Christi - Latin America



Sample Cross Reference 431074



Yates Petroleum Corporation, Artesia, NM

Williams Battery

Sample Id	Matrix	Date Collected	Sample Depth	Lab Sample Id
Comp E-1	S	11-01-11 14:20	1 - 1 ft	431074-001
Comp E-2	S	11-01-11 14:40	2 - 2 ft	431074-002
Comp S-2	S	11-01-11 15:30	2 - 2 ft	431074-003
Comp S-3	S	11-01-11 15:45	3 - 3 ft	431074-004

CASE NARRATIVE



Client Name: Yates Petroleum Corporation

Project Name: Williams Battery



Project ID:

30-015-24072

Work Order Number: 431074

Report Date: 21-NOV-11 Date Received: 11/08/2011

Sample receipt non conformances and comments:

None

Sample receipt non conformances and comments per sample:

None



Certificate of Analysis Summary 431074

Yates Petroleum Corporation, Artesia, NM

Project Name: Williams Battery

Project Id: 30-015-24072
Contact: Amber Cannon

Project Location: 25-18S-26E, Eddy County

Date Received in Lab: Tue Nov-08-11 02:30 pm

Report Date: 21-NOV-11
Project Manager: Brent Barron II

								Project Mai	nager.	Brem Barron II	
	Lab Id:	431074-	001	431074-0	02	431074-0	03	431074-0	04		
Analysis Daguestad	Field Id:	Comp F	E-1	Comp E	-2	Comp S-	-2	Comp S	-3		
Analysis Requested	Depth:	1-1 f	:	2-2 ft		2-2 ft		3-3 ft			
	Matrix:	SOLI	D	SOLIE	,	SOLID	.	SOLIE	•		
	Sampled:	Nov-01-11	14:20	Nov-01-11	14.40	Nov-01-11	15:30	Nov-01-11	15:45		
Anions by E300	Extracted:										
,	Analyzed:	Nov-14-11	12.20	Nov-14-11	12.20	Nov-14-11	12,20	Nov-14-11	12:20		
	Units/RL:	mg/kg	RL	mg/kg	RL	mg/kg	RL	mg/kg	RL		
Chloride		4480	93 1	5020	93.4	3760	97.3	3520	48.3		
Percent Moisture	Extracted:										
	Analyzed:	Nov-11-11	14.35	Nov-11-11	14 35	Nov-11-11	14·35	Nov-11-11	14.35		
	Units/RL:	%	RL	%	RL	%	RL	%	RL		
Percent Moisture		9,79	1.00	10.1	1.00	13.7	1 00	13,0	1,00		

This analytical report, and the entire data package it represents, has been made for your exclusive and confidential use. The interpretations and results expressed throughout this analytical report represent the best judgment of XENCO Laboratories XENCO Laboratories assumes no responsibility and makes no waitanty to the end use of the data hereby presented. Our habitity is limited to the amount involved for this work order unless otherwise agreed to in writing.

Houston - Dallas - San Antonio - Atlanta - Tampa - Boca Raton - Latin America - Odessa - Corpus Christi

Brent Barron II

Odessa Laboratory Manager



Flagging Criteria

- X In our quality control review of the data a QC deficiency was observed and flagged as noted. MS/MSD recoveries were found to be outside of the laboratory control limits due to possible matrix /chemical interference, or a concentration of target analyte high enough to affect the recovery of the spike concentration. This condition could also affect the relative percent difference in the MS/MSD.
- **B** A target analyte or common laboratory contaminant was identified in the method blank. Its presence indicates possible field or laboratory contamination.
- **D** The sample(s) were diluted due to targets detected over the highest point of the calibration curve, or due to matrix interference. Dilution factors are included in the final results. The result is from a diluted sample.
- E The data exceeds the upper calibration limit; therefore, the concentration is reported as estimated.
- F RPD exceeded lab control limits.
- J The target analyte was positively identified below the quantitation limit and above the detection limit.
- U Analyte was not detected.
- L The LCS data for this analytical batch was reported below the laboratory control limits for this analyte. The department supervisor and QA Director reviewed data. The samples were either reanalyzed or flagged as estimated concentrations.
- H The LCS data for this analytical batch was reported above the laboratory control limits. Supporting QC Data were reviewed by the Department Supervisor and QA Director. Data were determined to be valid for reporting.
- K Sample analyzed outside of recommended hold time.
- JN A combination of the "N" and the "J" qualifier. The analysis indicates that the analyte is "tentatively identified" and the associated numerical value may not be consistent with the amount actually present in the environmental sample.
- * Surrogate recovered outside laboratory control limit.

BRL Below Reporting Limit.

RL Reporting Limit

MDL Method Detection Limit SDL Sample Detection Limit LOD Limit of Detection

PQL Practical Quantitation Limit MQL Method Quantitation Limit LOQ Limit of Quantitation

DL Method Detection Limit

NC Non-Calculable

+ Outside XENCO's scope of NELAC Accreditation. ^ NELAC or State program does not offer Accreditation at this time.

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994.

Certified and approved by numerous States and Agencies.

A Small Business and Minority Status Company that delivers SERVICE and QUALITY

Houston - Dallas - San Antonio - Atlanta - Midland/Odessa - Tampa/Lakeland - Miami - Phoenix - Latin America

	Phone	Fax
4143 Greenbriar Dr. Stafford, TX 77477	(281) 240-4200	(281) 240-4280
9701 Harry Hines Blvd, Dallas, TX 75220	(214) 902 0300	(214) 351-9139
5332 Blackberry Drive, San Antonio TX 78238	(210) 509-3334	(210) 509-3335
2505 North Falkenburg Rd, Tampa, FL 33619	(813) 620-2000	(813) 620-2033
5757 NW 158th St. Miami Lakes, FL 33014	(305) 823-8500	(305) 823-8555
12600 West I-20 East, Odessa, TX 79765	(432) 563-1800	(432) 563-1713
6017 Financial Drive, Norcross, GA 30071	(770) 449-8800	(770) 449-5477
3725 E. Atlanta Ave, Phoenix, AZ 85040	(602) 437-0330	

Page 10 of 11

XENCO-Environmental Lab of Texas

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

12600 West I-20 East Odessa, Texas 79765 Phone: 432-563-1800 Fax: 432-563-1713

	Project Manager: Ambe	r Cannon														Pro	ojec	t Nar	ne: _	A III	ian	ns t	sati	ery	<u>/_</u>					
	Company Name Yates	Petroleum Corporat	ion														P	ojec	t #: <u>_</u>	30-0	<u>15-2</u>	2407	2							
	Company Address: 105 S	outh 4th Street														1	Proje	act L	oc: <u>2</u>	25-18	IS-2€	E, E	ddy (Coun	ıty					
	City/State/Zip: Artes	ia, NM 88210																PC)#:_1	032	020									
	Telephone No: 5757	48-4111				Fax No:		<u>575</u>	-748	-458	5					Repor	t Fo	rmat	: [ĭ∫s	tanda	ard			TRR	(P		NPC	ŒS	
	Sampler Signature:	loope	<u> </u>	Ċ	011011	e-mail:			aca	ann	on	<u>@</u> y	/ate	spet	гој	eum.co	m													1
(lab use	only) /	Chit.															\vdash			TCL		Analy.	ze ro	or:	_	_	T	7	ŀ	ļ
	1#431073/43	1074									۰						上			TOTA		二			-				48, 72 hrs	
ORDER	(#: 1010101110	70 . 1			T			-	7	resen	vatio	n & #	of Cor	tainer	-	Matrix	8138	او			Se	ام		260	i				₹.	_
LAB # (lab use only)	FIELD CO	DE	Beginning Depth	Ending Depth	Date Sampled	Time Sampled	Field Filtered	Total # of Containers	ice	HNO3	Ę	H ₂ SO ₄	NaySyO ₃	None	Other (Specify)	DW=Drnking Water SL=Sludge GW = Groundwater S=Soll/Sold NP=Non-Potable Specify Other	TPH. 418.1 8015M 8	TPH. TX 1005 TX 1006	Cations (Ca, Mg. Na, K)	Anions (Ct, SO4, Alkalinity)	Metals As Aq Ba Cd Cr Pb Hq Se	Volatiles	Semivolatifes	BTEX 8021B/5030 or 8TEX 8260	RCI	NO.RM	Chlorides		RUSH TAT (Pre-Schedule) 24.	Standard TAT
ol	Comp E-	1	1'	1'	11/1/2011	2:20 PM		1	Х							s	x							х];	x			Х
02	Comp E-	2	2'	2'	11/1/2011	2:40 PM		1	х							s_	х							x		;	x _	Ш		X
03	Comp S-	2	2'	2'	11/1/2011	3:30 PM		1	X							S	х					L		x		;	x _			Х
04	Comp S-	3	3,	3'	11/1/2011	3:45 PM		1	х							s	х				\perp			х	\downarrow	;	<u>x </u>		_	х
				L								\perp					L	Ш			\perp					\perp				_
								_	_	\perp		\perp					L	Ш	_	\perp		↓_			_	_	\perp		_	ļ
									\perp		\perp						L		\perp		\perp	_	Ш		\bot		\perp			_
										\perp	\perp						L				\perp				_				_	
											\perp				\perp		L		_	\perp	_ _				\perp				_	
								_[\perp									Ш			L			\perp			1	\coprod	_	_
								_	_	\perp	\perp	\perp			╛		L	Ш	\perp	_	_				_	\bot	_	ot	_	
									\perp			\perp					L		\perp		\perp		Ш	\perp			\perp		_	
	PLEASE PUT CH	LORIDES						_		\perp				Ш			L	Ш			\perp		Ш	\dashv				Ш	_	_
	ON SEPARATE I									\perp	\perp	1					L			\perp	\bot							Ш	\bot	_
Special Ir	structions:	TPH: 8015B, BT	EX: 80	21B 8	& Chlorides.	Please show	ВТ	EX	resu	ilts	as r	ng/k	g. T	hank	(yo	u.						omm iners					Q.	. . (NI	21
																			voc:	s Fre	e of	Head	spa	ce?			X	<u> </u>	N N	
Relinquish	ed by	Date		ne	Received by										Dat	e	Time	9	La be i Custo	s on ody s	cont eals	ainer on co	(s) ontai	ner(s)	**	XQXXX) ",%] 	Ň N	
Relinquish		Date	Tin	_	Received by										Date		Time	•	Custo Samp	idy's ble H v Sar	eals and l	on co Delive /Cher	ooler ered nt Re	r(s). :p ?	OHL	(\mathcal{T}	्रा	2 4 Z) (
Relinquish	ed by	Date	Tin	ne	Received by ELC	ot: rrand	6							11/2	,Date 9 /		Time	3	Temp	O Z erat	ر (ure L	G Jpon	Rece	eıpt:		3	۲. ر) .	c	



XENCO Laboratories

Attanta, Boca Raton, Corpus Christi, Dallas Houston, Miami, Odessa, Philadelphia Phoenix, San Antonio, Tampa Document Title: Sample Receipt Checklist

Document No.: SYS-SRC

Revision/Date: No. 01, 5/27/2010

Effective Date: 6/1/2010 Page 1 of 1

Prelogin / Nonconformance Report - Sample Log-In

Client: Vales	•		
Date/Time: 11/8/11 /4:30			
Lab ID#: 131073/431074			
Initials:			
Sample Receipt Checkl	ist		
d Samples as ion?	Blue Water	No	
Samples on ice? Shipping container in good condition?	Yes No	None	
3. Custody seals intact on shipping container (cooler) and bottles?	Yes No	N/A	
4. Chain of Custody present?	(Yes No		
5. Sample instructions complete on chain of custody?	Yes No		
6. Any missing / extra samples?	Yes No		
7. Chain of custody signed when relinquished / received?	Yes No		
8. Chain of custody agrees with sample label(s)?	Yes No		
9. Container labels legible and intact?	Yes No		
10. Sample matrix / properties agree with chain of custody?	Yes No	-	
11. Samples in proper container / bottle?	Yes No		
12. Samples properly preserved?	Yes No	N/A	
13. Sample container intact?	Yes No		
14. Sufficient sample amount for indicated test(s)?	Yes No		
15. All samples received within sufficient hold time?	Yes No		
16. Subcontract of sample(s)?	Yes No	(N/A)	
17. VOC sample have zero head space?	Yes No	N/A	
18. Cooler 1 No. Cooler 2 No. Cooler 3 No.	Cooler 4 No.	Cooler 5 No.	
	ibs	°C lbs	<u>°C</u>
Nonconformance Docume	ntation		
Contact:Contacted by:	Date/Time	:	
Regarding:			
Corrective Action Taken:			
Check all that apply: Cooling process has begun shortly after sampling	event and out of temp	erature	
condition acceptable by NELAC 5.5.8.3.1.a.1 □ Initial and Backup Temperature confirm out of ter			

☐ Client understands and would like to proceed with analysis

Analytical Report 431073

for Yates Petroleum Corporation

Project Manager: Amber Cannon
Williams Battery
30-015-24072
21-NOV-11

Collected By: Client



Celebrating 20 Years of commitment to excellence in Environmental Testing Services



12600 West I-20 East Odessa, Texas 79765

Xenco-Houston (EPA Lab code: TX00122):

Texas (T104704215-10-6-TX), Arizona (AZ0765), Arkansas (08-039-0), Connecticut (PH-0102), Florida (E871002) Illinois (002082), Indiana (C-TX-02), Iowa (392), Kansas (E-10380), Kentucky (45), Louisiana (03054) New Hampshire (297408), New Jersey (TX007), New York (11763), Oklahoma (9218), Pennsylvania (68-03610) Rhode Island (LAO00312), USDA (S-44102)

Xenco-Atlanta (EPA Lab Code: GA00046):

Florida (E87429), North Carolina (483), South Carolina (98015), Utah (AALI1), West Virginia (362), Kentucky (85) Louisiana (04176), USDA (P330-07-00105)

Xenco-Miami (EPA Lab code: FL01152): Florida (E86678), Maryland (330)
Xenco-Tampa Mobile (EPA Lab code: FL01212): Florida (E84900)
Xenco-Odessa (EPA Lab code: TX00158): Texas (T104704400-TX)
Xenco-Dallas (EPA Lab code: TX01468): Texas (T104704295-TX)
Xenco Phoenix (EPA Lab Code: AZ00901): Arizona (AZ0757)
Xenco-Phoenix Mobile (EPA Lab code: AZ00901): Arizona (AZM757)
Xenco Tucson (EPA Lab code: AZ000989): Arizona (AZ0758)





21-NOV-11

Project Manager: Amber Cannon Yates Petroleum Corporation

105 South Fourth St. Artesia, NM 88210

Reference: XENCO Report No: 431073

Williams Battery

Project Address: 25-18S-26E, Eddy County

Amber Cannon:

We are reporting to you the results of the analyses performed on the samples received under the project name referenced above and identified with the XENCO Report Number 431073. All results being reported under this Report Number apply to the samples analyzed and properly identified with a Laboratory ID number. Subcontracted analyses are identified in this report with either the NELAC certification number of the subcontract lab in the analyst ID field, or the complete subcontracted report attached to this report.

Unless otherwise noted in a Case Narrative, all data reported in this Analytical Report are in compliance with NELAC standards. Estimation of data uncertainty for this report is found in the quality control section of this report unless otherwise noted. Should insufficient sample be provided to the laboratory to meet the method and NELAC Matrix Duplicate and Matrix Spike requirements, then the data will be analyzed, evaluated and reported using all other available quality control measures.

The validity and integrity of this report will remain intact as long as it is accompanied by this letter and reproduced in full, unless written approval is granted by XENCO Laboratories. This report will be filed for at least 5 years in our archives after which time it will be destroyed without further notice, unless otherwise arranged with you. The samples received, and described as recorded in Report No. 431073 will be filed for 60 days, and after that time they will be properly disposed without further notice, unless otherwise arranged with you. We reserve the right to return to you any unused samples, extracts or solutions related to them if we consider so necessary (e.g., samples identified as hazardous waste, sample sizes exceeding analytical standard practices, controlled substances under regulated protocols, etc).

We thank you for selecting XENCO Laboratories to serve your analytical needs. If you have any questions concerning this report, please feel free to contact us at any time.

Respectfully,

Brent Barron II

Odessa Laboratory Manager

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994.

Certified and approved by numerous States and Agencies.

A Small Business and Minority Status Company that delivers SERVICE and QUALITY

Houston - Dallas - San Antonio - Austin - Tampa - Miami - Atlanta - Corpus Christi - Latin America



Sample Cross Reference 431073



Yates Petroleum Corporation, Artesia, NM

Williams Battery

Sample Id	Matrix	Date Collected	Sample Depth	Lab Sample Id
Comp E-1	S	11-01-11 14:20	1 - 1 ft	431073-001
Comp E-2	S	11-01-11 14:40	2 - 2 ft	431073-002
Comp S-2	S	11-01-11 15:30	2 - 2 ft	431073-003
Comp S-3	S	11-01-11 15:45	3 - 3 ft	431073-004

CASE NARRATIVE



Client Name: Yates Petroleum Corporation

Project Name: Williams Battery



Project ID:

30-015-24072

Work Order Number: 431073

Report Date: 21-NOV-11 Date Received: 11/08/2011

Sample receipt non conformances and comments:

None

Sample receipt non conformances and comments per sample:

None

Analytical non nonformances and comments:

Batch: LBA-874899 BTEX by EPA 8021B

SW8021BM

Batch 874899, Ethylbenzene, o-Xylene recovered below QC limits in the Matrix Spike. Benzene, Toluene recovered below QC limits in the Matrix Spike and Matrix Spike Duplicate.

Samples affected are: 431073-002, -001, -003, -004.

The Laboratory Control Sample for Toluene, Benzene, Ethylbenzene, o-Xylene is within laboratory Control Limits

Batch: LBA-874915 TPH By SW8015B Mod

SW8015B_NM

Batch 874915, 1-Chlorooctane recovered above QC limits . Matrix interferences is suspected; data not confirmed by re-analysis

Samples affected are: 431073-001 S,431073-001 SD,431073-002,431073-001,431073-003. o-Terphenyl recovered above QC limits Data not confirmed by re-analysis. Samples affected are: 614198-1-BLK,431073-001 S,431073-001 SD,431073-003,431073-001,431073-002.



Certificate of Analysis Summary 431073

Yates Petroleum Corporation, Artesia, NM

Project Name: Williams Battery



Project Id: 30-015-24072

Contact: Amber Cannon

Project Location: 25-18S-26E, Eddy County

Date Received in Lab: Tue Nov-08-11 02:30 pm

Report Date: 21-NOV-11

Project Manager: Brent Barron II

	,,		·					I TOJECE IVIA	mager.	Brent Barron II	
	Lab Id:	431073-0	001	431073-0	02	431073-	003	431073-	004		
Analysis Requested	Field Id:	Comp E	-1	Comp E	-2	Comp S	5-2	Comp S	3-3		
Anulysis Requesieu	Depth:	1-1 ft	1	2-2 ft		2-2 ft		3-3 ft			
	Matrix:	SOLIE)	SOLID)	SOLII)	SOLII)		
	Sampled:	Nov-01-11	14.20	Nov-01-11	14:40	Nov-01-11	15.30	Nov-01-11	15.45		
BTEX by EPA 8021B	Extracted:	Nov-15-11	12.15	Nov-15-11	12.15	Nov-15-11	12 15	Nov-15-11	12.15		
	Analyzed:	Nov-15-11	14 36	Nov-15-11	14·59	Nov-15-11	15 22	Nov-15-11	15.45		
	Units/RL:	mg/kg	RL	mg/kg	RL	mg/kg	RL	mg/kg	RL		
Benzene		ND	0 00110	ND	0 00111	ND	0 00115	ND	0 00114		
Toluene		ND	0 00220	ND	0 00222	ND	0 00231	ND	0.00229		
Ethylbenzene		ND	0 00110	ND	0 00111	ND	0 00115	ND	0 00114		
m_p-Xylenes		ND	0 00220	ND	0 00222	ND	0.00231	ND	0 00229		
o-Xylene		ND	0.00110	ND	0 00111	ND	0 00115	ND	0 00114		
Total Xylenes		ND	0 00110	ND	0 00111	ND	0 00115	ND	0 00114		
Total BTEX		ND	0 00110	ND	.0 00111	ND	0 00115	ND	0 00114		
Percent Moisture	Extracted:										
	Analyzed:	Nov-11-11	14.35	Nov-11-11	14 35	Nov-11-11	14.35	Nov-11-11	14.35		
	Units/RL:	%	RL	%	RL	%	RL	%	RL		
Percent Moisture		9.79	1.00	10.1	1.00	13.7	1 00	13.0	1 00		
TPH By SW8015B Mod	Extracted:	Nov-12-11	15.00	Nov-12-11	15.00	Nov-12-11	15 00	Nov-12-11	15.00		
	Analyzed:	Nov-14-11	08:41	Nov-14-11 (09:12	Nov-14-11	09 43	Nov-14-11	10 14		
	Units/RL:	mg/kg	RL	mg/kg	RL	mg/kg	RL	mg/kg	RL		
C6-C10 Gasoline Range Hydrocarbons		ND	16.6	ND	168	ND	174	ND	17.2		
C10-C28 Diesel Range Hydrocarbons		55 4	166	ND	16.8	ND	17 4	ND	17.2		
Total TPH		55 4	16.6	ND	16.8	ND	174	ND	172		

This analytical report, and the entire data package it represents, has been made for your exclusive and confidential use. The interpretations and results expressed throughout this analytical report represent the best judgment of XENCO Laboratories. XENCO Laboratories assumes no responsibility and make no warrunty to the end use of the data hereby presented. Our liability is limited to the amount involved for this work order unless otherwise agreed to in writing.

Houston - Dallas - San Antonio - Atlanta - Tampa - Boca Raton - Latin America - Odessa - Corpus Christi

Brent Barron II Odessa Laboratory Manager



Flagging Criteria

- X In our quality control review of the data a QC deficiency was observed and flagged as noted. MS/MSD recoveries were found to be outside of the laboratory control limits due to possible matrix /chemical interference, or a concentration of target analyte high enough to affect the recovery of the spike concentration. This condition could also affect the relative percent difference in the MS/MSD.
- B A target analyte or common laboratory contaminant was identified in the method blank. Its presence indicates possible field or laboratory contamination.
- D The sample(s) were diluted due to targets detected over the highest point of the calibration curve, or due to matrix interference. Dilution factors are included in the final results. The result is from a diluted sample.
- E The data exceeds the upper calibration limit; therefore, the concentration is reported as estimated.
- F RPD exceeded lab control limits.
- J The target analyte was positively identified below the quantiation limit and above the detection limit.
- U Analyte was not detected.
- L The LCS data for this analytical batch was reported below the laboratory control limits for this analytic. The department supervisor and QA Director reviewed data. The samples were either reanalyzed or flagged as estimated concentrations.
- H The LCS data for this analytical batch was reported above the laboratory control limits. Supporting QC Data were reviewed by the Department Supervisor and QA Director. Data were determined to be valid for reporting.
- K Sample analyzed outside of recommended hold time.
- JN A combination of the "N" and the "J" qualifier. The analysis indicates that the analyte is "tentatively identified" and the associated numerical value may not be consistent with the amount actually present in the environmental sample.
- * Surrogate recovered outside laboratory control limit.

BRL Below Reporting Limit.

RL Reporting Limit

SDL Sample Detection Limit MDL Method Detection Limit

LOD Limit of Detection

PQL Practical Quantitation Limit MQL Method Quantitation Limit

LOQ Limit of Quantitation

DL Method Detection Limit

NC Non-Calculable

+ Outside XENCO's scope of NELAC Accreditation.

^ NELAC or State program does not offer Accreditation at this time.

Recipient of the Prestigious Small Business Administration Award of Excellence in 1994.

Certified and approved by numerous States and Agencies.

A Small Business and Minority Status Company that delivers SERVICE and QUALITY

Houston - Dallas - San Antonio - Atlanta - Midland/Odessa - Tampa/Lakeland - Miami - Phoenix - Latin America

	Phone	Fax
4143 Greenbriar Dr, Stafford, TX 77477	(281) 240-4200	(281) 240-4280
9701 Harry Hines Blvd , Dailas, TX 75220	(214) 902 0300	(214) 351-9139
5332 Blackberry Drive, San Antonio TX 78238	(210) 509-3334	(210) 509-3335
2505 North Falkenburg Rd, Tampa, FL 33619	(813) 620-2000	(813) 620-2033
5757 NW 158th St, Miami Lakes, FL 33014	(305) 823-8500	(305) 823-8555
12600 West I-20 East, Odessa, TX 79765	(432) 563-1800	(432) 563-1713
6017 Financial Drive, Norcross, GA 30071	(770) 449-8800	(770) 449-5477
3725 E Atlanta Ave, Phoenix, AZ 85040	(602) 437-0330	

Page 6 of 15 Final 1 000

Page 14 of 15

XENCO-Environmental Lab of Texas

CHAIN OF CUSTODY RECORD AND ANALYSIS REQUEST

12600 West 1-20 East Odessa, Texas 79765 Phone: 432-563-1800 Fax: 432-563-1713

	Project Manager:	Amber Cannon			··											Pro	jec	t Na	ne:	Wi	llia	ms	Ba	<u>atte</u>	ry						
	Company Name	Yates Petroleum Corporat	ion														Pr	rojec	t#:	30-	015	-240)72								
	Company Address:	105 South 4th Street														Р	roje	ect L	oc:	25-1	8 <u>5-</u> 2	26E,	Edd	ly Co	unty	<u></u>					
	City/State/Zip:	Artesia, NM 88210																P) #: _.	103	2020										_
	Telephone No:	575 ₇ 748-4111				Fax No:		575	-748	4585	<u> </u>				_	Report	Fo	rma	:	×	Stan	dard	ı		Эτ	RRP	,		NPDI	ES	
	Sampler Signature:	Umbe	~(<u> </u>	1711027	e-mail:			aca	nne	on(<u>@</u> .y:	ates	pet	role	eum.co	m														
(lab use	only) /	Chit.														,				TC	LP	Ana	lyze	For	丁	Т	\top	П			
ORDE	r#:431073/4	131074							Pr	eserva	ation	8#0	of Cont	ainers	_	Matrix	8	T		101	-	-	7	+	$\frac{1}{2}$					24, 48, 72 hr	
_AB # (lab use only)) CODE	Beginning Depth	Ending Depth	Date Sampled	Time Sampled	Field Fittered	Total # of Containers	ioe	HNO.	100 H	HOEN	Na ₂ S ₂ O ₃	None	Other (Specify)	DW=Drnking Water SL=Sludge GW = Groundwater S=Sol/Solid NP=Non-Potable Snectry Other	TPH. 418.1 8015M 8015B	TPH TX 1005 TX 1006	Cations (Ca, Mg, Na, K)	Anions (Ci, SO4, Alkalınıty)		Metals As Ag Ba Cd Cr Pb Hg Se	Volatiles	Semivolatiles BTEX 80218/6030 or RTEX 8260	BC!	Z W O Z	Chiondes		MUDII TAT I TAT II	RUSH IAT (Pre-Schedule) 24, 4	Standard TAT
ol	Com	p E-1	1'	1'	11/1/2011	2:20 PM		1	х							s	х						I)	<u>(</u>	I	x		I	T	X
02	Corr	np E-2	2'	2'	11/1/2011	2:40 PM		1	х	_	\perp	_				S	х				_	4)	4	\perp	X			_	X
03	Com	p S-2	2'	2'	11/1/2011	3:30 PM		1	_	_	_	1	1_		_	_ S	х	1		_	\dashv	_	4	_ \	4	1	X	\vdash	1	4	X
04	Com	p S-3	3,	3'	11/1/2011	3:45 PM		1	X	_	\bot	4		\dashv	_	<u>s</u>	х	L		\dashv	_	+	4		4	_	X	\vdash	_	4	X
			ļ						-	-	+	+		\vdash	\dashv			-	-	\dashv	+	+	+	+	+	+	+	\vdash	+	+	
			 					-		+	╁	╁	+-	-	-{		-	Н	-	-	\dashv	+	+	+	+	+	+-	H	-	+	_
							-	-	-	+	+-	+	+-	-	-		-	-	-	+	+	+	+	+	+	+	+	\vdash	+	+	-
								-	-	+	╫	╁	+	-	1		-	Н	-+	\dashv	+	+	+	 -	十	+	+	\vdash	+	十	-
								-	+	-	+	+	+	\dashv	1		-		-	\dashv	+	+	+	+	\dagger	+	+-	H	+	T	
			 				-	7	十	+	+	\dagger			1					十	_	+	\top	+	T	†	1	\vdash	\top	†	
							\exists	7		1	T	T		\exists	7					\top	1	\top	1	1	1	1		П	T	1	
	PLEASE PUT	CHLORIDES																					T								_
		TE REPORT										\prod											floor	floor					$oxed{oxed}$		_
Special l	nstructions:	TPH: 8015B, BT	EX: 80	21B &	& Chlorides.	Please show	ВТ	EX	resu	lts a	s m	g/kg	g. Tr	ank	yo	<i>1</i> .			Sam	ple	Cont	Comi ainer	rs In	ntact?		,	5	? ?) N		a',
Relinquish L Relinquish	Moei (a)	Date Date	Tin ろう Tin	ne C	Received by										Date Date	9	Time	-	Labe Cust Cust Sam	ody ody ple l	n cor seals seals Hand	of Hea ntain s on s on d Deli er/Cla	cool	i) itaine ler(s ed Ren	er(s) }		ع	1000 DO	N N N N N N N Lone S		
Relinquish	ed by	Date	Tin	ne	Received by ELC	rnaud	10							11/8	Date 7/	11 14	Time	3	Tem	pera	ture	Upor	n Re	aceip	ot:		Q.	O) °C	3	



XENCO Laboratories

Attanta, Boca Raton, Corpus Christi, Dallas Houston, Miami, Odessa. Philadelphia Phoenix, San Antonio, Tampa Document Title: Sample Receipt Checklist

Document No.: SYS-SRC

Revision/Date: No. 01, 5/27/2010

Effective Date: 6/1/2010 Page 1 of 1

Prelogin / Nonconformance Report - Sample Log-In

1/otes		•		
Dient: V M ts				
420-01121071				
ab ID#: 1,310 73/ 431 0 79				
Sample Receipt Check	klist			
	Div	(Markey)	NI.	
1. Samples on ice?	Blue	Water	No	-
2. Shipping container in good condition?	(Yes)	No	None	
3. Custody seals intact on shipping container (cooler) and bottles?	Yes	No	N/A	
4. Chain of Custody present?	Yes	No		
5. Sample instructions complete on chain of custody?	Yes	No		
6. Any missing / extra samples?	Yes	(No		
7. Chain of custody signed when relinquished / received?		No		
8. Chain of custody agrees with sample label(s)?	Yes	No		
9. Container labels legible and intact?	Yes	No		
10. Sample matrix / properties agree with chain of custody? 11. Samples in proper container / bottle?	Yes	No -		
12. Samples properly preserved?	Yes	No No	N/A	
13. Sample container intact?	Yes	No	N/A	
14. Sufficient sample amount for indicated test(s)?	Yes	No		
15. All samples received within sufficient hold time?	Yes	No		
16. Subcontract of sample(s)?	Yes	No	(N/A)	
17. VOC sample have zero head space?	(Yes)	No	NVA	
18. Cooler 1 No. Cooler 2 No. Cooler 3 No.	Cooler 4 N		Cooler 5 No.	
	C lbs		lbs	°C
		<u>'</u>	103	
Nonconformance Docum	entation		-	
Contact: Contacted by:		Date/Time:_		
Regarding:				
			······································	
Competing Action Taken.	· · · · · · · · · · · · · · · · · · ·			
Corrective Action Taken:			•	
			····	
Check all that apply: Cooling process has begun shortly after sampling condition acceptable by NELAC 5.5.8.3.1.a.		out of temper	ature	
□ Initial and Backup Temperature confirm out of te	mperature co	onditions		
☐ Client understands and would like to proceed with	th analysis			