

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
MAR - 8 2012  
NMOCD ARTESIA

Form C-141  
Revised August 8, 2011

Submit a Copy to Appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*nmlb1208347706*

**OPERATOR**  Initial Report  Final Report

Name of Company: <b>Canyon E&amp;P Company</b> <i>269864</i>	Contact: Travis White
Address: 911 Lake Carolyn Pkwy, Ste 104 Irving, TX 75039	Telephone No.: 214-265-7101
Facility Name: Double L Queen	Facility Type: Tank Battery
Surface Owner <i>State</i>	Mineral Owner
API No. <i>30-005-60078</i>	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>A</i>	<i>1</i>	<i>15s</i>	<i>29e</i>	<i>330</i>	<i>N</i>	<i>330</i>	<i>E</i>	<i>Chaves</i>

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release: Overflow	Volume of Release: 20 bbl of water; 10 bbl of crude	Volume Recovered: 0
Source of Release: Switch failure	Date and Hour of Occurrence: 3/4/2012 overnight	Date and Hour of Discovery: 3/4/2012 around 11 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Automatic switch on main battery tank failed causing the tank overflow.		
Describe Area Affected and Cleanup Action Taken.* Overrunning of the top of tank battery and the wind gusts of 50 mph caused the crude to spray over the ground and building east of the tank battery. Effected area is between 100-150ft. Covered ground oil with dirt and building was pressure washed. Crude still remains on building. Plans to continue pressure washing as well as properly dispose effect dirt on ground.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Travis White</i>	Signed By <i>[Signature]</i> Approved by Environmental Specialist:	
Title: <i>Agent</i>	Approval Date: <i>MAR 23 2012</i>	Expiration Date:
E-mail Address: <i>travis@eddyedreger.com</i>	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b>	Attached <input type="checkbox"/>
Date: <i>3-8-12</i> Phone: <i>214-265-7101</i>	<i>4/23/2012</i>	<i>JCP-1063</i>

\* Attach Additional Sheets If Necessary

**Bratcher, Mike, EMNRD**

---

**From:** Travis White [travis@eddyedreyer.com]  
**Sent:** Thursday, March 08, 2012 4:15 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** FW: Spill Notice  
**Attachments:** 20120308171938848.pdf

Mike,

Per our conversation, here is the C-141. Please advise on the next step Canyon needs to take.

Thanks,

Travis White  
Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101  
Fax: (214)363-4191

-----Original Message-----

**From:** [EddyDreyerScanner@eddyedreyer.com](mailto:EddyDreyerScanner@eddyedreyer.com) [mailto:[EddyDreyerScanner@eddyedreyer.com](mailto:EddyDreyerScanner@eddyedreyer.com)]  
**Sent:** Thursday, March 08, 2012 4:20 PM  
**To:** Travis White  
**Subject:**

This E-mail was sent from "EddyDreyerScanner" (LC155).

Scan Date: 03.08.2012 17:19:38 (-0500)  
Queries to: [EddyDreyerScanner@eddyedreyer.com](mailto:EddyDreyerScanner@eddyedreyer.com)

## Bratcher, Mike, EMNRD

---

**From:** Travis White [travis@eddyedreyer.com]  
**Sent:** Thursday, March 08, 2012 3:32 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** RE: Contact

Mike,

Could you give me a call real quick?

### *Travis White*

Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101  
Fax: (214)363-4191

---

**From:** Travis White  
**Sent:** Thursday, March 08, 2012 9:57 AM  
**To:** 'mike.bratcher@state.nm.us'  
**Subject:** Contact

### *Travis White*

Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101  
Fax: (214)363-4191

## Bratcher, Mike, EMNRD

---

**From:** Travis White [travis@eddyedreyer.com]  
**Sent:** Friday, March 09, 2012 7:40 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** RE: Contact

Thanks, Mike. I will forward this to the proper people. I will try to find the well # it was associated with but when I asked I was told it's just the main tank battery. I'll see what I can do.

### *Travis White*

Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101  
Fax: (214)363-4191

---

**From:** Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]  
**Sent:** Friday, March 09, 2012 8:35 AM  
**To:** Travis White  
**Subject:** RE: Contact

Travis,

Sorry for not calling. Our email server was down most of the day yesterday so I just got your email this morning. One thing I will need for processing the C-141 and moving forward is the well number the release is associated with. I think there are over 40 wells in the Double L Queen, so I will need that.

For remediation, typically, OCD will require any highly contaminated/saturated soils to be excavated and hauled to an approved disposal. I believe the closest disposal in that area will be Gandy/Marley. Representative samples will then need to be obtained in the affected area and sent to a lab for analyses. What needs to be done after that will be based on the analytical data and some site specific conditions, such as depth to ground water. Since it sounds like there was a large "overspray" area, it would be a possibility to address that area without excavation.

There are several environmental contractors around this area that specialize in cleaning up these events, and are familiar with what the regulatory agencies require for remedial actions. If you want to consider that, I can't recommend any one specifically, but could provide some contact numbers for a few in the area.

### *Mike Bratcher*

NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
575-748-1283 Ext. 108  
575-626-0857  
[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)

---

**From:** Travis White [mailto:travis@eddyedreyer.com]  
**Sent:** Thursday, March 08, 2012 3:32 PM

**To:** Bratcher, Mike, EMNRD  
**Subject:** RE: Contact

Mike,

Could you give me a call real quick?

*Travis White*

Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101

Fax: (214)363-4191

---

**From:** Travis White  
**Sent:** Thursday, March 08, 2012 9:57 AM  
**To:** 'mike.bratcher@state.nm.us'  
**Subject:** Contact

*Travis White*

Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101

Fax: (214)363-4191

## Bratcher, Mike, EMNRD

---

**From:** Travis White [travis@eddyedreyer.com]  
**Sent:** Monday, March 12, 2012 1:09 PM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** RE: LL well

Excellent. Nothing else to report from my end at the moment. If you need anything from me just let me know.

Travis White  
Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101  
Fax: (214)363-4191

-----Original Message-----

**From:** Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]  
**Sent:** Monday, March 12, 2012 1:56 PM  
**To:** Travis White  
**Subject:** RE: LL well

Travis,

Yes, this will work. The API number for this well should be 30-005-60078 and is in Unit letter A.

Thanks,

Mike Bratcher  
NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
575-748-1283 Ext. 108  
575-626-0857  
[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)

-----Original Message-----

**From:** Travis White [<mailto:travis@eddyedreyer.com>]  
**Sent:** Monday, March 12, 2012 11:09 AM  
**To:** Bratcher, Mike, EMNRD  
**Subject:** FW: LL well

Mike,

Here is a photo of the nearest well. Will this suffice for your location question?

Travis White  
Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900

Dallas, TX 75206

Phone: (214)265-7101

Fax: (214)363-4191

-----Original Message-----

From: Mike Myers [<mailto:mike@canyonep.com>]

Sent: Monday, March 12, 2012 11:36 AM

To: Travis White

Subject: LL well

For your forms

**Bratcher, Mike, EMNRD**

---

**From:** Bratcher, Mike, EMNRD  
**Sent:** Monday, March 12, 2012 12:56 PM  
**To:** 'Travis White'  
**Subject:** RE: LL well

Travis,

Yes, this will work. The API number for this well should be 30-005-60078 and is in Unit letter A.

Thanks,

Mike Bratcher  
NMOCD District 2  
811 S. First Street  
Artesia, NM 88210  
575-748-1283 Ext. 108  
575-626-0857  
[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)

-----Original Message-----

From: Travis White [<mailto:travis@eddyedreyer.com>]  
Sent: Monday, March 12, 2012 11:09 AM  
To: Bratcher, Mike, EMNRD  
Subject: FW: LL well

Mike,

Here is a photo of the nearest well. Will this suffice for your location question?

Travis White  
Regulatory Analyst  
Eddy Dreyer Financial Services  
4925 Greenville Ave., Suite 900  
Dallas, TX 75206

Phone: (214)265-7101  
Fax: (214)363-4191

-----Original Message-----

From: Mike Myers [<mailto:mike@canyonep.com>]  
Sent: Monday, March 12, 2012 11:36 AM  
To: Travis White  
Subject: LL well

For your forms

WILSON LEAD COMPONENT

DOUBLE L WIRE UNIT  
TR #22 WELL #1 NE 1/4 NE 1/4  
SEC. 1. TISS. R29E  
UA 08910160530