

Bratcher, Mike, EMNRD

From: Burton, Michael R [mburton@blm.gov]
Sent: Wednesday, April 18, 2012 7:52 AM
To: Bratcher, Mike, EMNRD
Subject: East Shugart 24 injection line leak.
Attachments: East Shugart 24 injection line leak.docx

Mike,

Here is some info for the injection line leak I told you about yesterday. I will continue to send more info.

Thanks

Mike Burton

BLM-CFO

Environmental Protection Specialist

575-234-2226 office

575-361-3574 cell

mburton@blm.gov

East Shugart #24

Injection line leak

01/04/2012

I received a call from Billy Botts of Americo Energy informing me of the release of PW from an injection line going to the East Shugart #24. The spill occurred on the edge of an old spill location that had been reclaimed. The area has been Arc cleared. When I arrived on site I photo'd the area. Mr. Botts estimated the release to be approx 5 bbls. I informed Mr. Botts that the site needs to be delineated. Americo had a backhoe respond and dug approx 9' next to the broke line until the soil started to clean up. The pipe had 7 holes in it in a 20' span. Mr. Botts informed me that their plan was to fix the leak and start delineation asap. I have researched the location and there are no archeology issues involved with the location of the spill.

01/10/2012

I met with John Able on location. John works for Hungry Horse. John did the field sampling. Three sample points. #1 was the bottom of a 12' hole under the release point. #2 was south side of the hole. #3 was north of the hole. Results from the samples; SP 1 4657 PPM, SP 2 9645 PPM, SP 3 9645 PPM.