GW-190

General Correspondence

YEAR(S): 2008



BILL RICHARDSON Governor

DIANE DENISH Lieutenant Governor

NEW MEXICO ENVIRONMENT DEPARTMENT

Petroleum Storage Tank Bureau

1914 West Second Street Roswell, New Mexico 88201 Phone (575) 624-6123 Fax (575) 624-2023

www.nmenv.state.nm.us



RON CURRY Secretary

JON GOLDSTEIN Deputy Secretary

JIM NORTON Director

2

December 2, 2008

Mr. Joshua Morrissette BJ Services Company, U.S.A. 11211 FM 2920 Tomball, Texas 77381

RE: No Further Action Status at the BJ Services, 2401 Sivley, Artesia, New Mexico

Facility #: 965001

RID #: 3114

Dear Mr. Goodwin:

The New Mexico Environment Department (Department) has reviewed the following for the subject site:

- 1. On-Site Investigation Report dated April, 1998. (Dames & Moore).
- 2. Monitor Well Replacement and Groundwater Sampling Report dated May, 2004 (Brown & Caldwell)
- 3. Monitor Well Sampling Report dated February, 2006 (Brown & Caldwell).
- 4. Monitor Well Sampling Report dated February, 2007 (Brown & Caldwell).
- 5. Notification of Monitor Well Plugging Activities October, 2008 (Brown & Caldwell).

The Department concurs that this site does not pose an immediate threat to public health or the environment based upon the following current site-specific conditions:

 Monitoring wells DM-1 and DM-2 were installed in 1997 following the removal of a used oil underground oil tank adjacent to the maintenance bay. These wells (DM-1 & DM-2) became dry and were replaced by monitoring wells DM-1B & DM-2B May 2004. During monitoring well installation for wells DM-1B & DM-2B, laboratory samples collected for soil and groundwater contamination were non-detect for contaminants of concern. Mr. Joshua Morrissette December 2, 2008 Page 2

- 2. Groundwater analyticals collected for years 2004 & 2006 from the two new wells was below laboratory detection limits for all contaminants of concern.
- 3. Depth to groundwater at the site is 27 feet below ground surface.
- 4. Soil type related to the site consists of loose silty sand to approximately 20' bgs overlying silty clay to 28' bgs. The saturated zone consists of silty sand to 40' bgs.
- 5. A total of six soil borings and four monitoring wells have determined the vertical and horizontal extent of soil contamination. Soil contamination indicates that the release was from the former used oil tank.
- 6. All monitoring wells including DM-1, DM-2 and replacement wells DM-1B and DM-2B have been properly plugged and abandoned.

Therefore, the Department is not requiring additional work at this time. However, the Department does reserve the right to require additional work in the future, should information become available which indicates that a threat to public health or the environment exists.

If you have any questions, please contact me at (575) 624-6123. Thank you for your cooperation in this matter.

Sincerely,

T.C. Shapard Project Manager

TCS:tp

 cc: Lynn M. Wright, Brown & Caldwell, 1415 Louisiana, Suite 2500, Houston, TX 77002 James H. Davis, Ph.D., Bureau Chief Joyce Shearer, Manager, PSTB Remedial Action Program Marlene Cordova, Financial Manager, Reimbursement Section Gary Beatty, Manager, EHD District IV Lorena Goerger, Team Leader, PSTB Elmer Smith, Carlsbad Field Office Trina Page, Administrator, PSTB 1415 Louisiana Suite 2500 Houston, Texas 77002

Tel: (713) 759-0999 Fax: (713) 308-3886

www.brownandcaldwell.com

October 20, 2008



Mr. T.C. Shapard Underground Storage Tank Bureau New Mexico Environment Department District 4 1914 W. Second Street Roswell, New Mexico 88201

129062.001

SUBJECT: BJ SERVICES COMPANY, U.S.A. ARTESIA, NEW MEXICO FACILITY NOTIFICATION OF MONITOR WELL PLUGGING ACTIVITIES NMED FACILITY NO. 2914

Dear Mr. Sharpard,

In response with the New Mexico Environment Department Petroleum Storage Tank Bureau work plan approval letter dated January 11, 2008, monitoring wells DM-1B and DM-2B at the subject facility have been plugged and abandoned. The plugging activities were performed on June 19, 2008. All work was performed in accordance with the Rules and Regulations Governing Well Driller Licensing; Construction, Repair and Plugging of Wells from the Office of the State Engineer by a New Mexico licensed water well driller. Waste associated with the plugging activities was removed and properly disposed of offsite. A copy of a letter from the drilling company that plugged the monitoring wells is attached.

If you have any questions regarding this report, please contact Lynn Wright at 713-646-1126.

Very truly yours,

BROWN AND CALDWELL

nUng

Lynn M. Wright, P.G. Supervising Geologist

cc: Mr. Joshua Morrissette, BJ Services Company, U.S.A

ATTACHMENT

GEOPROJECTS INTERNATIONAL Inc. 8834 Circle Drive • Austin, Texas 78736 Telephone (512) 288-3777 • Facsimile (512) 288-0908

September 3, 2008

Mr. Lynn Wright Brown & Caldwell 1415 Louisiana Ste 2500 Houston, TX 77002

RE: WELL ABANDONMENTS BJ SERVICES COMPANY, USA 2401 SILVEY ROAD ARTESIA, TX NMED FACILITY NO. 2914

Dear Mr. Wright:


Thank you for the opportunity to participate in the abandonment of the shallow Monitoring Wells DM-1B and DM-2B at the above referenced facility. Both wells were abandoned under our New Mexico License number WD-1311. Both wells were plugged with hydrated bentonite from the total depth of 30-ft each to 2-ft below ground level and completed with a cement cap from 0-ft to 2-ft.

If I can be of any further assistance, please feel free to call me at (512)-288-3777.

Sincerely, GEOPROJECTS INTERNATIONAL, INC.

Randy Duff

Project Manager



a shirt and the second

` ;...

R: COMPLETE THIS SEC	TION	COMPLETE THIS SECTION ON DELIVERY
lete Items 1, 2, and 3. Also complete If Restricted Delivery is desired. Our name and address on the reverse t we can return the card to you.		A signature X Lunda Cole Agent
this card to the back of the the front if space permits.	e malipiece,	B. Received by (Printed Name) C. Date of Delivery
Addressed to:		D. Is delivery address different from item 17 Yes If YES, enter delivery address below: No
Mr. T. C. Shapard		
erground Storage Tank exico Environmental D District 4	(Bureau)epartment	
1914 W. Second Stre	et	3. Service Type
Roswell, New Mexico 88	8201	Certified Mall D Express Mall Registered Z/Return Receipt for Merchandise
		4. Restricted Delivery? (Extra Fee)
lumber r from service label)		7003 3110 0000 8672 9034
3811, February 2004	Domestic Re	turn Receipt

÷,