

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

MAR 28 2013

NMOC ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

*when submitting*

nJMW1310239402 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	CJ Summers		
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216		
Facility Name	Sand Dunes 28 Federal #1 SWD	Facility Type	SWD		
Surface Owner	BLM	Mineral Owner		Lease No.	NM 40659

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E					Eddy

Latitude N 32.27641° Longitude W 103.78047°

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	650 bbls	Volume Recovered	590 bbls
Source of Release	Tank overflow due to broken triplex pump	Date and Hour of Occurrence	03/24/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen, James Amos-BLM and Mike Bratcher-OCD		
By Whom?	Chancey Summers	Date and Hour	03/25/2013 @ 9:08 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*



A broken triplex pump caused a tank to overflow spilling 650 bbls of produced water onto the ground. 590 bbls of produced water were recovered via vacuum truck and the pump was repaired.

Describe Area Affected and Cleanup Action Taken.\*

A broken triplex pump caused a tank to overflow spilling 650 bbls of produced water onto the ground. 590 bbls of produced water were recovered via vacuum truck and the pump was repaired. Remediation will be performed in accordance with an approved plan from the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 
Printed Name: Chancey Summers	Signed By: Mike Bratcher
Title: HES Specialist	Approval Date: APR 12 2013 Expiration Date:
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: May 12, 2013
Date: 3-27-13 Phone: (575) 397-8216	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-1617

**C-141 Release for Sand Dunes 28 Fed #1 SWD**

Warren, JeanMarie, EMNRD

**Sent:** Friday, April 05, 2013 3:14 PM

**To:** Chancey.Summers@oxy.com

**Cc:** Bratcher, Mike, EMNRD

Good afternoon CJ,

I was wondering if you would be able to help us out, we cannot seem to find this well with this Unit letter, Section, Township, and range listed for the release on 3/24/2013.

Would you please advise us of the correct API on this location?

You have listed: J-28-23s-31e

We do not have a well with the name listed in the subject line in that area.

Also when submitting future C-141's to us, please use the API not the Lease No.

That would help us out so very much. Thank you for your assistance. We greatly appreciate it.

Hope to hear from you soon.

Have a great weekend.

*Jean-Marie Warren  
Business Operations Specialist  
NM-OCD District II, Artesia  
(575) 748-1283, ext. 101*

## Bratcher, Mike, EMNRD

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Thursday, March 28, 2013 9:06 AM  
**To:** Bratcher, Mike, EMNRD; jvancure@blm.gov; jamos@blm.gov  
**Cc:** C J Summers; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141 Sand Dunes 28 Federal #1 SWD  
**Attachments:** Initial C-141, sent 3-28-13 Sand Dunes 28-1.pdf

Attached is the initial C-141 for a leak at the Sand Dunes 28 Federal #1 SWD on 3/24/2013 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

## Bratcher, Mike, EMNRD

---

**From:** Chancey\_Summers@oxy.com  
**Sent:** Monday, March 25, 2013 9:18 AM  
**To:** Chancey\_Summers@oxy.com; jamos@blm.gov; jvancure@blm.gov; Bratcher, Mike, EMNRD; cbrunson@bbcinternational.com; jgilkey@bbcinternational.com; kathy@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** RE: SAND DUNES 28 FED 1 SWD EAST TRIPLEX PUMP

Please note corrections and updates below.

Thank You  
C.J. Summers  
HES Advisor  
Cell # 575-631-9436  
Office # 575-397-8216  
Chancey\_Summers@oxy.com  
"When the blind lead the blind, get out of the way!"

---

From: Summers, Chancey J  
Sent: Monday, March 25, 2013 9:08 AM  
To: Jim Amos; Jennifer Van Curen; Mike Bratcher (Mike.Bratcher@state.nm.us); Cliff P. Brunson; Jennifer Gilkey (jgilkey@bbcinternational.com); Kathy Purvis; Ken Swinney  
Subject: SAND DUNES 28 FED 1 SWD EAST TRIPLEX PUMP

This is to inform you that Oxy Permian South had a leak at the Sand Dunes 28 Fed 1 SWD on March 24, 2013. Oxy released 650 bbls of produced water. Oxy recovered 590 bbls. Triplex pump broke causing tank to overflow. The leak is located in Sec 28 Township 23S Range 31 East of Eddy County. Oxy will conduct some initial remediation of the site. BBC will delineate at a later date. C-141 to follow. Driving directions: Off highway 128 go south on pure gold road take 4th road to SWD. If you have any questions let me know.

Thank You  
C.J. Summers  
HES Advisor  
Cell # 575-631-9436  
Office # 575-397-8216  
Chancey\_Summers@oxy.com<mailto:Chancey\_Summers@oxy.com>  
"When the blind lead the blind, get out of the way!"

## Bratcher, Mike, EMNRD

---

**From:** Chancey\_Summers@oxy.com  
**Sent:** Monday, March 25, 2013 9:08 AM  
**To:** jamos@blm.gov; jvancure@blm.gov; Bratcher, Mike, EMNRD;  
cbrunson@bbcinternational.com; jgilkey@bbcinternational.com;  
kathy@bbcinternational.com; kswinney@bbcinternational.com  
**Subject:** SAND DUNES 28 FED 1 SWD EAST TRIPLEX PUMP

This is to inform you that Oxy Permian South had a leak at the Sand Dunes 28 Fed 1 SWD on March 24, 2013. Oxy released 590 bbls of produced water. I am currently waiting on recovery amounts will update when I find out. Triplex pump broke causing tank to overflow. The leak is located in Sec 28 Township 23S Range 31 East of Eddy County. Oxy will conduct some initial remediation of the site. BBC will delineate at a later date. C-141 to follow. Driving directions: Off highway 128 go south on pure gold road take 4th road to SWD. If you have any questions let me know.

Thank You  
C.J. Summers  
HES Advisor  
Cell # 575-631-9436  
Office # 575-397-8216  
[Chancey\\_Summers@oxy.com](mailto:Chancey_Summers@oxy.com)

"When the blind lead the blind, get out of the way!"