`

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

. . .

1220 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505		
Telease Notification and Corrective Action		
NMW1314055065	OPERATOR Initial R	eport 🔲 Final Report
Name of Company: BOPCO, L.P. 260737	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Indian Flats Bass Federal SWD Tank BatteryFacility Type: Exploration and ProductionBattery is located 1340 ft, North of Well #6 API 30-015-22673Facility Type: Exploration and Production		
Surface Owner: Federal Mineral Owne	r: Federal API No. 30	0-015-22673
LOCATION OF RELEASE		
Unit LetterSectionTownshipRangeFeet from theNoJ3521S28E1652Source		ounty Eddy
Latitude N. 32.434001 Longitude W. 104.055557		
NATURE OF RELEASE		
Type of Release: Produced Water		overed: 10 Bbls.
Source of Release: Produced water tank overflowed	Date 4/25/13 time unknown Date 4/25/13	r of Discovery: 5:00 p.m.
Was Immediate Notice Given? If YES, To Whom? NMOCD Emergency #104 Xes No Not Required		
By Whom? Tony Savoie	Date and Hour: 4/26/13 at 8:00 a.m.	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse.	
☐ Yes ⊠ No	REC	FIVED
If a Watercourse was Impacted, Describe Fully.*	tercourse was Impacted, Describe Fully.*	
MAY 17 2013		
	NMOCÍ	D ARTESIA
Describe Cause of Problem and Remedial Action Taken.*		
The Strainer on the suction to the SWD plugged up causing the pump alarm system failed to report high tank levels and high discharge press		ith the incoming water. The
Describe Area Affected and Cleanup Action Taken.*		
The area was being remediated as a result of previous spills associated	with the SWD pump failure. New impervious containme	ent has been constructed
around the SWD pump and oil production tanks. The area around the SWD tanks was scheduled for a soil boring event due to chloride levels that could not		
be delineated with a backhoe in that area. An air rotary rig has been scheduled to do the delineation. The area impacted was on top of several prior spills that stayed primarily around the SWD tanks and the caliche tank battery pad area.		
The remediation will continue as planned. The containment will be constructed around the SWD tanks upon achieving closure status for leaks and spills.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger		
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability		
should their operations have failed to adequately investigate and remed		
or the environment. In addition, NMOCD acceptance of a C-141 repo federal, state, or local laws and/or regulations.	it does not reneve the operator of responsibility for comp	mance with any other
	OIL CONSERVATION DIVISION	
Signature: Buy Danie	A +	
	Approved by Environmental Specialist: Signed By Milly Beamice	
Printed Name: Tony Savoie	MAY 2 0 2013	
Title: Waste Management and Remediation Specialist	Approval Date: Expiration Dat	2:
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached
Date: 5/16/13 Phone: 432-556-8730	Remediation per OCD Rule & f Guidelines. SUBMIT REMEDIATION	
* Attach Additional Sheets If Necessary		2RP-1656
June 20,2013		

