

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1326734243

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Enterprise Field Services LLC 1000347	Contact	Jim Heap
	PO Box 4324, Houston, TX 77252	Telephone No.	432-686-5404
Facility Name	Pipeline ROW, Mercury Fee Line	Facility Type:	Gas Gathering Pipeline
Surface Owner	Private-McDonald	Mineral Owner	NA
		Lease No.	NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	18	23S	28E					Eddy

Latitude 32.29873 N Longitude -104.11864 W

NATURE OF RELEASE

Type of Release	Natural Gas	Volume of Release	248 MCF	Volume Recovered	0
Source of Release	Pipeline Leak	Date and Hour of Occurrence	09/06/2013 06:45 (MDT)	Date and Hour of Discovery	09/06/2013 07:30 (MDT) finish
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Suspected internal corrosion. The line was isolated, blown-down and scheduled for repair.

Describe Area Affected and Cleanup Action Taken.*

Any impacted area will be determined when the line is excavated; landowner will be notified. Current observation shows no release of liquids to the surrounding area. Repair schedule is not known at the time of this report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Jon Fields</u>	OIL CONSERVATION DIVISION	
Printed Name: Jon Fields	Approved by District Supervisor: Signed By <u>Mike Brannon</u>	
Title: Director - Environmental Compliance	SEP 24 2013	Expiration Date:
E-mail Address: <u>snolan@eprod.com</u>	Approval Date:	Attached <input type="checkbox"/>
Date: <u>9-9-2012</u> Phone: <u>713-318-6595</u>	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	

* Attach Additional Sheets If Necessary

nJMW 1326331184

iJMW 1326736844

PROPOSAL NO LATER THAN:
October 24, 2013

2RP-1929




ENTERPRISE PRODUCTS PARTNERS L.P.
ENTERPRISE PRODUCTS HOLDINGS LLC
(General Partner)

ENTERPRISE PRODUCTS OPERATING LLC

September 9, 2013

7012 1010 0003 3760 7437

Return Receipt Requested



Mr. Mike Bratcher
New Mexico Oil Conservation Division
District 2 Office
811 South First Street
Artesia, New Mexico 88210

**RE: Form C-141 Report for Enterprise Products
Gas Loss Reported in the Carlsbad Gathering Field**

Mr. Bratcher:

Pursuant to 29 (19.15.29) NMAC please find enclosed the requisite C-141 Form for the September 6, 2013 release from our Mercury Fee gathering line in our Carlsbad Gathering Field, Eddy County. The leak is a suspected internal corrosion failure.

If you have any questions or need more information, please contact Jim Heap by phone at 432-686-5404, by email at jkheap@eprod.com or me at 713-318-6595.

Regards,

A handwritten signature in cursive script that reads "Jon E. Fields".

Jon E. Fields
Director, Field Environmental

/sjn
attachments