

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1331055247		OPERATOR	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company OXY USA WTP LP 16696		Contact CAMPBELL, RODNEY		
Address 329 Marathon Rd, Lakewood		Telephone No. (575) 628-4167		
Facility Name INDIAN BASIN GAS PLANT		Facility Type GAS PROCESSING FACILITY		
Surface Owner		Mineral Owner INDIAN BASIN		Lease No.


LOCATION OF RELEASE

Unit Letter G	Section 23	Township 21-S	Range 23-E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	------------------	---------------	---------------	------------------	---------------	----------------	----------------

Latitude 32°27'52.502" Longitude 104°34'28.004"

NATURE OF RELEASE

Type of Release Gas	Volume of Release 206.4 MCF	Volume Recovered 0
Source of Release Residue Flare	Date and Hour of Occurrence 10/8/2013 2:32:00 PM	Date and Hour of Discovery 10/8/2013 2:32:00 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Cause: OXY INDIAN BASIN GAS PLANT FLARED 206.4 MCF OF RESIDE SALES GAS DUE TO HIGH OXYGEN CONTENT. Remedial Action Taken: OPERATIONS SAMPLED THE STABILIZER DISCHARGE AND LINE 4 WITH PORTABLE OXYGEN ANYALIZER, BUT DIDN'T FIND THE SOURCE OF OXYGEN.		
Describe Area Affected and Cleanup Action Taken.* N/A		



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney Campbell</i>	OIL CONSERVATION DIVISION	
Printed Name: RODNEY CAMPBELL	Accepted for record NMOCD	
Title: HES Specialist	Approved by District Supervisor:	Approval Date: NOV 06 2013
E-mail-Address: RODNEY_CAMPBELL@OXY.COM	Expiration Date:	Conditions of Approval:
Date: 10-11-13	Phone: (575) 628-4167	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

FJMW 1327034125

iJMW 1331055536

Like approval by
BLM

2RP-
2050