

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

JUN 17 2014

Form C-141
Revised October 10, 2003

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

RECEIVED

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company : Legacy Reserves Operating, LP	Contact : Freddie Gibbs
Address : PO Box 10848, Midland, TX 79702-7848	Telephone No. :
Facility Name : DRICKEY QUEEN #23	Facility Type: Oil Well

Surface Owner : BLM	Mineral Owner:	Lease No. : API #30-005-00972
---------------------	----------------	-------------------------------

LOCATION OF RELEASE

Unit Letter M	Section 3	Township 14S	Range 31E	Feet from the 660'	North/South Line FSL	Feet from the 660'	East/West Line FWL	County: CHAVES
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude 33.126722 N Longitude -103.816024 W

NATURE OF RELEASE

Type of Release : Produced Fluids	Volume of Release : Unknown	Volume Recovered: -0- bbls
Source of Release : Flow Line Leak	Date and Hour of Occurrence: 6/4/14 Unknown	Date and Hour of Discovery: 6/5/14
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM/Angel Mayes- left msg on voicemail, talked to BLM Rep Al & NMOCD/Geoffrey Leking	
By Whom? Kimberly M. Wilson with Talon/LPE	Date and Hour : 5/29/14 @ 8:50 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* *Depth to g H₂O 7100'*

Describe Cause of Problem and Remedial Action Taken.* A flow line leak causing a release of unknown barrels of mixed fluids. All wells were shut in and the flow line was repaired. Talon/LPE was contacted for initial site assessment and to generate a work plan.

Describe Area Affected and Cleanup Action Taken.* The leak was discovered approximately 500' south of the location. Flow path was down the raven off the caprock approximately 900-feet long by 1-4 feet wide. The overspray area measured approximately 150-feet by 100-feet. Talon personnel mobilized to the location on 6/6/14.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Freddie Gibbs</i>	OIL CONSERVATION DIVISION	
Printed Name: Freddie Gibbs	Approved by District Supervisor: <i>Environmental Specialist</i>	
Title: Production Superintendent	Approval Date: <i>6/26/14</i>	Expiration Date: <i>8-21-14</i>
E-mail Address: fgibbs@legacylp.com	Conditions of Approval: <i>Site Samples required. Delivered</i>	Attached <input type="checkbox"/>
Date: 6/6/2014 Phone: 432.211.6369		<i>06-14-3117</i>

* Attach Additional Sheets If Necessary

not remediated & hearer as per NMOCD guides. Final. C-141 due 8-21-14

*ogrid 240974
ATO 1417752893
PTO 141775259*