

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

HOBBS OCD

Form C-141  
Revised August 8, 2011

Submittal Copy to appropriate District Office in accordance with 19.15.29 NMAC.

JUL 14 2014

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report


Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Prize 27 Federal #2 Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-025-31902

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	27	22S	32E					Lea County, NM

Latitude N 32.35709° Longitude W 103.65617°

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	10 bbls oil, 25 bbls produced water	Volume Recovered	8 bbls oil, 20 bbls produced water
Source of Release	Failed coupling on the pump caused the tanks to spill over	Date and Hour of Occurrence	06/23/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Tomas Oberding, Geoffrey Leking-NMOCD; Jennifer Van Curen- BLM		
By Whom?	Kathy Purvis	Date and Hour	06/23/2014 @ 2:23 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Failed coupling on the pump caused the tanks to spill 10 bbls of oil and 25 bbls of produced water onto the ground. A vacuum truck recovered 8 bbls of oil and 20 bbls of produced water and the coupling was replaced.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 30' x 20' on location. Remediation will be completed in accordance with a remediation plan approved by NMOCD and the BLM.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:					
Printed Name:	Chancey Summers	Approved by Environmental Specialist:			
Title:	HES Specialist	Approval Date:	7-14-14	Expiration Date:	9-17-14
E-mail Address:	Chancey.Summers@oxy.com	Conditions of Approval:			Attached <input type="checkbox"/>
Date:	7-10-14	Phone:	(575) 397-8216	7-14-3172	

\* Attach Additional Sheets If Necessary

*Delimited remediate as per NMOCD guidance. Submit final C-141 by 9-17-14*

*Ogrid 16696  
n 70 10 19 554275  
p 70 14 19 55 444*

JUL 14 2014