


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

Submit a Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

*NA 14226-1434* *#246289* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	RKI XPLORATION AND PRODUCTION	Contact	BRANDON RIPLEY, PRODUCTION FOREMAN
Address	5315 BUENA VISTA DR., CARLSBAD, NM	Telephone No.	575-689-5431
Facility Name	near the East Pecos Fed Com 22-7H	Facility Type	OIL WELL
Surface Owner	WORTH ROSS	Mineral Owner	
		API No.	30-015- <i>42287</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	22	26S	29E	250	SOUTH	990	EAST	Eddy

*32.009664* } *103.965325* } → START Latitude *32°00.92* Longitude *-103°57.88* END: LAT *32°00.92* LONG *-103°57.92*  
*32.014536*  
*103.965081*

NATURE OF RELEASE

Type of Release	Salt Water	Volume of Release	260 BBLS	Volume Recovered	0 BBLS
Source of Release	UNAUTHORIZED TRUCK DUMP	Date and Hour of Occurrence	UNKN	Date and Hour of Discovery	JULY 8, 2014
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MIKE BRATCHER, OCD	2:00 P.M.	
By Whom?	BRANDON RIPLEY	Date and Hour	JULY 8, 4:00 P.M.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

SALT WATER SPILL, APPARENTLY FROM UNAUTHORIZED TRUCK DUMP, APPROXIMATELY 2 LOADS (260 BBLS). LAND OWNER REP, OCD, RKI, APEX/TITAN VISITED SITE ON JULY 10, 2014. APEX RETRIEVED SOIL SAMPLES. FURTHER WORK TO BE DETERMINED BY RESULTS OF TEST.

Describe Area Affected and Cleanup Action Taken.\*

NO CLEAN-UP ACTION TAKEN UNTIL PROBLEM IS MORE CLEARLY IDENTIFIED.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jody Noerdlinger</i>		OIL CONSERVATION DIVISION	
Printed Name: JODY NOERDLINGER		Approved by Environmental <i>Mike Bratcher</i>	
Title: REGULATORY ANALYST		Approval Date: <i>8/14/14</i>	Expiration Date: <i>N/A</i>
E-mail Address: JNOERDLINGER@RKIXP.COM		Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	
Date: 7/15/2014	Phone: 405-996-5774	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-2442

## Bratcher, Mike, EMNRD

---

**From:** Jody Noerdlinger <JNoerdlinger@rkixp.com>  
**Sent:** Thursday, July 17, 2014 4:33 PM  
**To:** Brandon Ripley; Bratcher, Mike, EMNRD; treed@apexc.com  
**Cc:** Charles Ahn; Heather Brehm  
**Subject:** East Pecos Spill  
**Attachments:** EAST PECOS SPILL\_C-141.pdf

Mike, I'm sending the attached C-141 on the recent East Pecos spill to Artesia, but I thought I'd email you a copy, as well. Please let me know if you think there's anything that should be added. Thanks.

Jody Noerdlinger  
Regulatory Analyst  
RKI Exploration and Production  
Oklahoma Tower  
210 Park Avenue, Suite 800  
Oklahoma City, OK 73102  
Office: 405-996-5774  
Cell: 405-414-0151  
[jnoerdlinger@rkixp.com](mailto:jnoerdlinger@rkixp.com)