

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

OCT 22 2014

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Antelope Ridge Compressor Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		Lease No.	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
L	34	23S	34E					Lea

Latitude N 32.25809° Longitude W 103.46365°

## NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	70 bbls	Volume Recovered	50 bbls
Source of Release	Failure of manway gasket on heater treater	Date and Hour of Occurrence	03/14/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen-BLM and Geoffrey Leking-OCD		
By Whom?	Chancey Summers	Date and Hour	03/15/2013 @ 6:25 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*


Failure of a manway gasket on a heater treater caused 70 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck and the gasket was repaired.

Describe Area Affected and Cleanup Action Taken.\*

Failure of a manway gasket on a heater treater caused 70 bbls of produced water to leak onto the ground. 50 bbls of produced water were recovered via vacuum truck and the gasket was repaired. Remediation will be performed in accordance with an approved plan from NMOCD and the BLM.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: 

Printed Name: Chancey Summers

Approved by District Supervisor:



Title: HES Specialist

Approval Date: 10-23-14

Expiration Date: 12-23-14

E-mail Address: Chancey.Summers@oxy.com

Conditions of Approval:

Attached ☐

Date: 3-27-13

Phone: (575) 397-8216

Site Supervisor  
Debra P. Anderson  
NMOCD gaskets. Submit and C-141  
by 12-23-14

IRP-3391

og rid 16696  
F70 1429 62 8484  
N70 1429 62 9273  
P70 1429 62 9070

\* Attach Additional Sheets If Necessary

OCT 27 2014