

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**RECEIVED**  
MAY 08 2013  
NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Three copies to appropriate District Office in accordance with Rule 116 on back side of form

**Release Notification and Corrective Action**

*njmw 1312 855239*

**OPERATOR**  Initial Report  Final Report

Name of Company : Oxy Permian LTD (192463)	Contact : Chris Jones
Address : 1502 W. Commerce, Carlsbad, NM 88220	Telephone No. : 575-628-4121
Facility Name : North Burton Flats Battery	Facility Type: Central Tank Battery
Surface Owner : Federal	Mineral Owner
API#: Lease #: NM 18293	

**LOCATION OF RELEASE**

Unit Letter D	Section 23	Township 20S	Range 28E	Feet from the	North/South Line	Feet from the	East/West Line	County: Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	--------------

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release : Produced Fluids	Volume of Release : 40 bbls	Volume Recovered: 10 bbls
Source of Release : Heater Treater	Date and Hour of Occurrence: 3/17/2013 7:00 am	Date and Hour of Discovery: 3/17/2013 7:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD/Mike Bratcher & BLM/Jim Arnos	
By Whom: Jonathen Haver 575-706-9249	Date and Hour : 3/18/2013 2:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A flange leaked on the heater treater causing a release of 40 barrels of produced fluids. The heater treater was taken out of service, repaired and put back into production. A vac truck was immediately called to the location and recovered 10 barrels of produced fluids.

Describe Area Affected and Cleanup Action Taken.\* The area impacted measured approximately 10'x60' around the heater treater. Talon/LPE has been contracted to complete site assessment and remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Chris Jones	Approved by District Supervisor: Signed By 	
Title: HES Specialist	Approval Date: <b>MAY 08 2013</b>	Expiration Date:
E-mail Address: Christopher Jones@oxy.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION</b>	Attached <input type="checkbox"/>
Date: 3/18/2013 Phone: 575-628-4121	<b>PROPOSAL NO LATER THAN:</b>	

\* Attach Additional Sheets If Necessary

**June 8, 2013**

2RP-1649