

3R-1014

**Release Report/ General
Correspondence**

**DENIED C-141
Williams RA**

Date: 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Williams Four Corners LLC	Contact Mitch Morris
Address 188 CR 4900, Bloomfield, NM 87413	Telephone No. 505-632-4708
Facility Name Jicarilla 146-20	Facility Type Pipeline

Surface Owner Jicarilla Apache	Mineral Owner	API No.
--------------------------------	---------------	---------

LOCATION OF RELEASE

RCUD SEP 24 '14

Unit Letter B	Section 4	Township 25N	Range 5W	Feet from the	North/South Line	Feet from the	East/West Line	County Rio Arriba
---------------	-----------	--------------	----------	---------------	------------------	---------------	----------------	-------------------

OIL CONS. DIV.

DIST. 3

Latitude N36° 26.007' Longitude W107° 21.656'

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 5 BBL	Volume Recovered 0 BBL
Source of Release Pipeline	Date and Hour of Occurrence 9/01/2014, 2:30 PM	Date and Hour of Discovery 9/01/2014, 2:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Bryce Hammond, Jicarilla Oil and Gas	
By Whom? Matt Webre, Environmental Supervisor	Date and Hour 9/02/2014, 7:30 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

An operations tech vehicle struck a drip line resulting the drip valve breaking, resulting in 5 BBL of produced water leaking to the ground.

Describe Area Affected and Cleanup Action Taken.*

The operations tech immediately blocked in the well, stopping the release. The well will remain blocked-in until all repairs are made. The repaired valve was locked out/tagged out. Remedial activity for the impacted soil is being evaluated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:



Printed Name: Mitch Morris

Title: Environmental Specialist

E-mail Address: mitch.morris@williams.com

Date: 9/16/2014

Phone: 505-632-4708

A

DENIED

BY: Cory Smith

DATE: 11/3/15 (505) 334-6178 Ext. 115

A

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary