

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

FEB 2 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: Big Eddy Unit 143 (2RP-2415)	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-32955

LOCATION OF RELEASE

Unit Letter N	Section 19	Township 21S	Range 28E	Feet from the 660	North/South Line South	Feet from the 1896	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude N 32.460336 Longitude W 104.128163

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 8 bbls	Volume Recovered: None
Source of Release: Wellhead Stuffing box	Date and Hour of Occurrence: 7/27/14 time unknown	Date and Hour of Discovery: 7/27/14 at approximately 9:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



The packing in the stuffing box failed. The wellhead was equipped with an E-pot designed to shut down the unit in case of a stuffing box failure. The E-pot failed to operate properly. The stuffing box packing was re-placed and the E-pot float switch was replaced.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 2,625 sq.ft. of caliche well pad area. All of the fluid soaked into the ground. The spill area was left as is pending remediation activities.

Basin Environmental Services began the remediation activities on 11/21/14 and completed the field work on 12/12/14, a total of 1760 cubic yards of soil was hauled to Lea Lands. Reference the Soil Closure Request dated January 2015

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist: 	
Title: Waste Management and Remediation Specialist		Approval Date: 2/2/15	Expiration Date: NA
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 2/2/15	Phone: 432-556-8730	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2415