

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
200 Rio Brazos Road, Aztec, NM 87410  
District IV  
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Westall A State #1	Facility Type	Tank Battery

Surface Owner	State	Mineral Owner	API No. 30-015-03798
---------------	-------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	36	17S	29E					Eddy

Latitude N 32.78815° Longitude W 104.02333°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	20 bbls	Volume Recovered	15 bbls
Source of Release	Tank Battery	Date and Hour of Occurrence	10/25/2013	Date and Hour of Discovery	10/25/2013 @ 10:24 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

a Watercourse was Impacted, Describe Fully.\*

NM OIL CONSERVATION  
ARTESIA DISTRICT

Describe Cause of Problem and Remedial Action Taken.\*

JUN 06 2014

A 4" valve separated at thread seam on the production tank. Replaced the 4" valve.

RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Initially 20 bbls of oil were released due to a 4" valve that failed on the production inside the tank battery. We were able to recover 15 bbls of oil with a vacuum truck. The spill was contained inside the tank battery. All free fluid has been recovered. BBC International completed remediation in accordance with the remediation plan approved by Mike Bratcher of NMOCD on April 1, 2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Robert Grubbs Jr.

Approved by Environmental Specialist:

Title: Senior Environmental Coordinator

Approval Date: 4/23/15

Expiration Date: N/A

E-mail Address: rgrubbs@concho.com

Conditions of Approval:

Final

Attached ☐

ate: 06-05-2014

Phone: (432) 661-6601

\* Attach Additional Sheets If Necessary

2RP-2034