

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUN 4 2015

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1515649001

Name of Company Devon Energy Production <i>60137</i>	OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report	
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Contact Mike McMahan	
Facility Name Burton Flat Deep Unit 52	Telephone No. 575.706.41.65	
	Facility Type Oil	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-40693

LOCATION OF RELEASE

Unit Letter H	Section 3	Township 21S	Range 27E	Feet from the 4000	North/South Line FNL	Feet from the 50	East/West Line FEL	County EDDY
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	---------------------	-----------------------	----------------

Latitude: 32.51155

Longitude: 104.1685

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 2 BBL	Volume Recovered 0 BBL
Source of Release Pin Hole leak in transfer line	Date and Hour of Occurrence 6/1/15 at 1:30 PM	Date and Hour of Discovery 6/1/15 at 1:30 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos - BLM	
By Whom? Gilbert Sanchez	Date and Hour 6/2/15 8:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

June 01, 2015 on the Burton Flat Deep Unit 52/56 at 1:30 pm A Devon lease operator found a pin hole leak on the water transfer line. A 5" clamp was placed over the pin hole to stop the leak.

Describe Area Affected and Cleanup Action Taken.*

Tex-Mex vacuum truck was called out to empty line for repairs and clean up. A 2 BBL spill of produced water and 0 recovered on side of lease road on pasture. Environmental company will be called to evaluate area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jeanette Barron</i>	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Signed By <i>Mike Barron</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Jeanette.barron@dvn.com	Approval Date: <i>6/5/15</i>	Expiration Date: <i>N/A</i>
Date: 6/4/15 Phone: 575.748.1813	Conditions of Approval:	
	Remediation per O.C.D. Rules & Guidelines	
	SUBMIT REMEDIATION PROPOSAL NO	
	LATER THAN: <i>7/9/15</i>	

* Attach Additional Sheets If Necessary

2RP-3031

Bratcher, Mike, EMNRD

From: Barron, Jeanette <Jeanette.Barron@dvn.com>
Sent: Thursday, June 04, 2015 4:12 PM
To: jamos@blm.gov; jrobertson@blm.gov; shughes@blm.gov; Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: McMahan, Mike; Sanchez, Gilbert
Subject: Burton Flat Deep Unit 52-56 C-141
Attachments: C-141 Burton Flat Deep Unit 52-56 spill 6.1.15.doc; Burton Flat Deep Unit 52.56 Pic 1 of 2.jpg; Burton Flat Deep Unit 52.56 Pic 2 of 2.jpg; Burton Flat Deep 52-56 spill 6.1.15..pdf

Please see attached.

Have a great evening! ☺

Thanks,

Jeanette Barron

Field Admin Support-Production

Devon Energy Corporation

P.O. Box 250

Artesia, NM 88211

575 748 1813 Direct

jeanette.barron@dvn.com

devon

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.