

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

<b>OPERATOR</b> <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: PLU #144 Flowline; The flow line spill was located on the PLU #140 Tank Battery pad	Facility Type: Exploration and Production	
Surface Owner: State	Mineral Owner:	API No. 30-015-30541

LOCATION OF RELEASE

Unit Letter E	Section 32	Township 23S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.26294° Longitude: W 103.91075°

NATURE OF RELEASE

Type of Release: crude oil	Volume of Release: 6 bbls	Volume Recovered: 1 bbl
Source of Release: flow line	Date and Hour of Occurrence: 6/15/15 @ unknown	Date and Hour of Discovery: 6/15/15 @ 1:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

NM OIL CONSERVATION  
ARTESIA DISTRICT

JUN 22 2015

RECEIVED

If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Describe Cause of Problem and Remedial Action Taken.\*

Corrosion caused a release of oil from the #144 flowline. Flow path from the release gathered around production equipment on the PLU #140 Battery.

Describe Area Affected and Cleanup Action Taken.\*

The spill impacted approximately 1,200 sq. ft. of caliche on the PLU 140 tank battery pad. A vacuum truck was called and recovered 1 bbl of oil. The area will be remediated in accordance to the NMOCD and BLM guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins		Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman		Approval Date: <i>6/25/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com		Conditions of Approval:	
Date:		Attached <input type="checkbox"/>	
Phone: 432-214-3704		Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: *7/30/15*

2RP-3067

\* Attach Additional Sheets If Necessary

## **Patterson, Heather, EMNRD**

---

**From:** Blevins, Bradley <BBlevins@BassPet.Com>  
**Sent:** Monday, June 22, 2015 8:31 AM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Savoie, Tony A.; Blevins, Bradley  
**Subject:** Initial C-141 PLU 144  
**Attachments:** Initial C-141 PLU #144 Flowline.pdf

Mike/ Heather

Please find the attached initial C-141 for the release that occurred on the PLU 144 flowline. The spill area is at the PLU 140 battery. If you have any questions please let me know. Thank you

Brad Blevins  
Assistant Remediation Foreman  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
[bblevins@basspet.com](mailto:bblevins@basspet.com)