NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

JUL 1 4 2015

Form C-141 Revised August 8, 2011

2RP- 3122

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit L Copy to appropriate District Office in RECEacoordance with 19.15.29 NMAC.

Sauta PC, INIVI 67505													
Release Notification and Corrective Action													
NAB1519828986						OPERATOR			🛛 Ini	tial Report		Final Report	
Name of Company Oxy Permian Ltd. //0/04/0						Contact Chancey Summers							
Address 6 Desta Drive, Midland, TX 79705						Telephone No. (432) 685-5824							
Facility Name Two Marks 36 State #4 SWD Battery						Facility Type Battery							
Surface Owner State Mineral Owner						API No. 30-15-34833							
				LOCA	ATIC	N OF REI	EASE						
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County													
		_											
M	M 36 21S 24E							Eddy County, NM					
Latitude N 32.42960° Longitude W 104.45840°													
NATURE OF RELEASE													
Type of Release Oil and produced water							Volume of Release 0.5 bbl oil, Volume Recovered 0 bbls						
						14.5 bbls produced water							
Source of Release Leak in a 2.875" steel oil dump line						Date and Hour of Occurrence			Date and Hour of Discovery				
Was Immediate Notice Given?						06/24/2015 If YES, To Whom?							
☐ Yes ☐ No ☐ Not Required													
By Whom? Kathy Purvis, BBC International						Date and Hour 06/25/2015 @ 11:17 am							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.							
☐ Yes ☒ No													
If a Waterco	urse was Imp	acted, Descr	ibe Fully.	*		•							
Describe Cause of Problem and Remedial Action Taken.*													
Describe Car	ise of Proble	m and Keme	uiai Actio	п такеп."									
		ump line spil	led 0.5 bb	l oil and 14.5 bbl	s of pro	oduced water o	nto the ground.	The line	was repai	red or replac	ed and	no fluids	
were recover	ed.												
Describe Are	a Affected a	nd Cleanup A	Action Tal										
The affected	area is appro	oximately 60'	x 60' on	location. Remedi	iation v	will be complet	ed in accordance	with a	remediation	n plan appro	ved by	NMOCD.	
I hereby cert	fy that the ir	ıformation gi	ven above	is true and comp	lete to	the best of my	knowledge and	understa	ınd that pu	rsuant to NM	OCD r	ules and	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the enviro	nment. In ad	ldition, NMC	CD accep	tance of a C-141	report	does not reliev	e the operator of	respons	sibility for	compliance	with an	y other	
federal, state	or local law	s an d/or reg u	rlations.										
						OIL CONSERVATION DIVISION							
Signature:													
Deintad Mass	n Chance	Cumeran				Approved by	Environmental R	Specialis	V/4 K) KARBALA	<u> </u>	i	
Printed Name	z. Chancey	Summers					مراء ماء -		•	. 1 .	^		
Title: HES	Lead					Approval Dat	e: 1111115)	Expiration	Date:	1		
E mail Add.	ann Chana	ou Cummen	@av	•		Complisher C	· A		-				
E-mail Address: Chancey Summers@oxy.com						Conditions of Approval: Remediation per O.C.D. Rules & Guide lineshed							
Date:	7- <i>13-</i>	15	Phone:	(432) 685-58	324	CURMIT RF	MEDIATION	PRO	POSAL	ИО			
* Attach Addi	tional Sheet	s If Necess		•		ATED TU		Ulle	<u> </u>			100 210	

LATER THAN:_

Bratcher, Mike, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Tuesday, July 14, 2015 2:21 PM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

Cc:

C J Summers; Susan Miller; cbrunson@bbcinternational.com;

kswinney@bbcinternational.com; jgilkey@bbcinternational.com

Subject:

Initial C-141, Two Marks 36 State #4 Battery, dump line leak

Attachments:

Initial C-141, Two Marks 36 State #4 SWD Battery, dump line leak.pdf

Attached is the initial C-141 for a leak that occurred at the Two Marks 36 State #4 Battery on 06/24/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com

Patterson, Heather, EMNRD

From:

Kathy Purvis <kathy@bbcinternational.com>

Sent:

Thursday, June 25, 2015 11:17 AM

To:

Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD

C J Summers: Susan Miller: cbrunson@bbcinternational.com;

Cc:

Subject:

kswinney@bbcinternational.com; jqilkey@bbcinternational.com; Kathy Purvis

Two Marks 36 State #4 SWD Battery

This is to inform you that Oxy Permian had a leak at the Two Marks 36 State #4 SWD Battery on June 24, 2015. Oxy spilled 0.5 bbl of oil and 14.5 bbls of water due to a leak in a 2.875" steel oil dump line. The preliminary report shows the leak measuring approximately 30' x 30' on location. No fluids were recovered. The release is located in the SE ¼ of Section 36, T21S, R24E of Eddy County, NM. BBC International will remediate the location at a later date and an initial C-141 will follow. Driving directions: From Carlsbad, go North on Hwy 285 to mile marker 44, go left on Water Hole Rd 1 mile to Big Walt Battery sign, go an additional 5 miles to next Big Walt Battery sign, pass the Big Walt Battery, turn right and continue to location. API# 30-015-34833, GPS coordinates: N 32.43013° W 104.44950°

Kathy Purvis BBC International, Inc. 1324 W. Marland Hobbs, NM 88240 Phone: (575) 397-6388

Fax: (575) 397-0397

Email: kathy@bbcinternational.com