

RECEIVED

APR 28 2014

NMOCD ARTESIA

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
100 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Perkins/Cottonmouth 4" SWD line	Facility Type	4" SWD line

Surface Owner	Federal	Mineral Owner		API No.	30-015-23849 (closest well)
---------------	---------	---------------	--	---------	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	30	26S	29E					Eddy

Latitude N 32.01545° Longitude W 104.02163°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	40 bbls	Volume Recovered	0 bbls
Source of Release	4" SWD poly transmission line	Date and Hour of Occurrence	Unknown	Date and Hour of Discovery	08/07/2012
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD; Jim Amos, Terry Gregston, & Legion Brumley-BLM		
By Whom?	Josh Russo	Date and Hour	08/08/2012 @ 9:55 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4" SWD line was found leaking from a faulty emergency repair clamp. The 4" SWD line was removed from service.

Describe Area Affected and Cleanup Action Taken.*

Initially an estimated 40 bbls were released from the faulty poly line. There was very little standing fluid from the release and therefore we were unable to recover any produced water with a vacuum truck. From the source, the fluid traveled down slope in a stream measuring 2'-3' x 300'. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD and by Randal Pair of the BLM via email on 03/10/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <i>Robert Grubbs</i>	Signed By <i>Mike Bratcher</i>	
Printed Name: Robert Grubbs	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>1/13/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>rgrubbs@concho.com</i>	Conditions of Approval: <i>N/A</i>	Attached <input type="checkbox"/>
Date: <i>1-22-14</i>	Phone: (432) 661-6601	

* Attach Additional Sheets If Necessary

Note: See data from 4/9/14 Sample date
Also: Large portion of this spill area was
washed away during September 2014 flood

2RA-1255