1000 Rio Brazos Road, Aztec, NM 87410 1220 South St. Francis Dr. accordance with 19.15.29 NMAC. 1220 S. st. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 accordance with 19.15.29 NMAC. Release Notification and Corrective Action MAB 152.1721 876 //550PERATOR Initial Report Final Report Name of Company: Nadel and Gussman Permian, LLC Contact: Bill Dougherty Address: 601 N. Marienfeld, Suite 508, Midland, TX 79707 Telephone No.325-998-7107 Facility Name: Aid State #10 Facility Type: Oil Well Surface Owner State of NM Mineral Owner Surface Owner State of NM Unit Letter Section Township Range Feet from the Feet from the East/West Linc County G 13 17 S 28 E 1650 NORTH 2310 EAST EDDY Latitude Volume of Release N/A Volume Recovered 71.52 BBLS Source of Release Date and Hour of Occurrence Date and Hour of Discovery 7/30/2015 1:00 PM MST T/30/2015 1:00 PM MST Was Immediate Notice Given? Yes No Not Required Heather Patterson with the OCD	District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210				State of New Mexico Energy Minerals and Natural Resou			l Resources	Form C-141 Revised August 8, 2011 Submit 1 Copy to appropriate District Office in				
Name PC, NM 6/2013 Release Notification and Corrective Action Mane of Compary: Nucleat and Gussman Permina, L1C Contact Bill Dougherty Address: 601 Numeric Ides Sign, Midland, TX 79707 Facility Type: Oil Well Contact Bill Dougherty Address: 601 Numeric Ides Sign, Midland, TX 79707 Contact Bill Dougherty Address: 601 Numeric Ides Sign, Midland, TX 79707 Contact Bill Dougherty ADT To Sign Idea Idea Idea Idea Idea Idea Idea Idea	District IV				1220 South St. Franci			eis Dr.	accordance with 19.15.29 NMAC.				
MB 155/170PERATOR Initial Report Name of Compary: Nudlet and Gussman Permian, L1C Contact: Bill Dougherty Technology Address: 601 N. Maranefeld, Subject 508, Midland, TX '9707 Facility Type, Oil Well API No. 30-015-38462 Surface Owner: State of NM Mineral Owner API No. 30-015-38462 Unit Letter Scation Toorship Reg. Fee from the North/Scath Line County EAST API No. 30-015-38462 Unit Letter Scation Toorship Reg. Fee from the North/Scath Line County EAST County EAST Unit Letter Scation Toorship Reg. Fee from the North/Scath Line County EAST County EAST Unit Letter Scation Toorship Reg. Fee from the North/Scath Line County EAST County EAST Unit Release Oil and Water Super Scattere Dage and Heart O'Courtere Dage and Heart O'Courtere Maxer Galesia Toor No Required Type of Release NA East/Wert Line County EAST Mark Introduction No Regulated Type of Release NA East/Wert Line County EAST Numme Recovered 71:52 BBLS Super of Release Oil and Water Super Scattere Dage and Heart 720120 12:00 PM MST Proceed Release Type of Release NA Art Rest O'Line Heart All All All All All All All All All Al	Santa Fe, INVI 8/505												
Name of Company: Naded and Gussman Permian, LLC Contact: Bill Dougherty Address: 601. M. Marineldi, Suite 508. Mulland, TX '9707 Techpione N.252:998-7107 Facility Name: Aid State #10 Facility Type: Oil Well Surface Owner State of NM Mineral Owner Loc Attion OF RELEASE County Unit Letter Section G 13 T7 S 28 E Feer from the Noth/South Line Feet from the East'West Line County EDS Manway Caster Caster Date and Hour of Decovery Manway Caster Leek Volume of Release NA Volume of Release NA Manway Caster Leek 79202015 Easter Date and Hour of Decovery Manway Caster Leek 79202015 Easter Date and Hour of Decovery Manway Caster Leek 79202015 Easter Date and Hour of Decovery Manway Caster Leek 79202015 Easter ARTESTA DISTRICT Was a Watercourse Reached? Ves No Not Required Not Required Was a Watercourse was Impacted, Doctrine Fully.* AUG 4 2015 ARTESTA DISTRICT Marway gaster was taking on the heart retater. A Double RY was and the contain at 515 PM. Sacked ep all fluid inside the bern. Bill Dougherty sprayed miero blaze on the vegetation on 7312/2015.	Release Notification and Corrective Action												
Address: 601 N. Marinelid, Suite 508, Midland, TX 79707 Telephone No.325.998.7107 Facility Name: Aid State 710 Facility Type: 0il Well Surface Owner State of NM Mineral Owner Lottater Section Township Range: Feet from the North/South Line Feet from the East/West Line County Bit Letter Section Township Range: Feet from the North/South Line Feet from the East/West Line County Line Letter Section Township Range: Feet from the North/South Line Feet from the East/West Line County Surface Owner State of NM Nat URE OF RELEASE Volume Recovered 71.52 BB1.5 Source of Release Oil and Waar Volume of Release NA Volume Recovered 71.52 BB1.5 Source of Release Oil and Waar Volume of Release NA Volume Recovered 71.52 BB1.5 Source of Release Coll and Waar Volume of Release NA Volume Recovered 71.52 BB1.5 Manway Gasket Leak 730/2015 Early Hours 730/2015 1 00 PM MST NM OIL-CONSERPLATION Was Immediate Note: Glover? Yes (Sin No I YYES, To MM OIL ConSERPLATION Markay gasket was tange on the heater treater. No I YYES, Volume Immediate Note: MATESIA DISTRICT Marecourse was Impacted, Doscribe Fully.* A													
Surface Owner State of NM Mineral Owner API No. 30-015-38462 Loc ATION OF RELEASE LOCATION OF RELEASE Unit Letter Section Township Range Feet from the NoRTH 2310 East/West Linc Coenty Latitude Longitude NORTH 2310 East/West Linc Coenty Summe of Release OII and Water NATURE OF RELEASE Volume Recovered 71:52 BBLS Summe of Release OII and Water Date and Hour of Docurrence Date and Hour of Docurrence Manway Gasket Leak 730/2015 Early Hours 730/2015 1:00 PM MST Was Immediate Notec Given? Yes Not Required Heather Patterson with the OCD Wy Woon?? Bit Dougherty Due and Hour of Docurrence ARTESIA DISTRICT Was a Watercourse Reached? Yes Not Required Heather Patterson with the OCD Was a Watercourse was Impacted, Describe Fully.* AUG 4 2015 Describe Area Affected and Cleanup Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. AUG 4 2015 Describe Area Affected and Cleanup Action Taken.* Receiver and the of oblas of water were releaseed. A majority of the spill was contained within the berm, exce													
LOCATION OF RELEASE Unit Letter Section Township Range Feet from the less East/West Line 2310 County EAST G 13 17.8 28.E Feet from the less East/West Line 2310 County EAST Latitude Longitude NATURE OF RELEASE Type of Release Oil and Water Volume of Release NA Volume Recovered 71.52 BBLS Source of Release Date and Hour of Occurrence Date and Hour of Discovery 730/2015 1:00 PM MST MI OIL CONSERVATION Was Immediate Notice Given? Vs No In the Conservery Ant CRE OF RELEASE Type of Release Oil and Water Volume of Release NA Volume and Hour of Discovery 730/2015 1:00 PM MST MI OIL CONSERVATION Was Immediate Notice Given? Vs No If YES, Volume Impacting the Watercourse MI OIL CONSERVATION Was advatercourse was impacted, Describe Fully.* All 6 2 2015 Describe Cause of Problem and Remedial Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. Advalue							Facility Type: Oil Well						
Unit Letter Section Township Range Feet from the 1650 NoRTH Feet from the 2310 EastWest Line County County Image: County of the submitted of the	Surface Owner State of NM Mineral Own						r API No. 30-015-38462						
G 13 17 S 28 E 1650 NORTH 2310 EAST EDDY Latitude		·	·		• · · · · · · · · · · · · · · · · · · ·			·r					
NATURE OF RELEASE Type of Release Oil and Water Volume of Recovered 71.52 BBLS Source of Release Oil and Water Date and Hour of Decoverece Manay Gasket Leak 7/30/2015 Early Hours Was Immediate Notice Given? If YES, To Whom? Was a Watercourse Reached? Yes Was a Watercourse Reached? Yes If Y SS, Volume Impacting the Watercourse. ARTESIA DISTRICT If a Watercourse was Impacted, Describe Fully.* Date and Hour of Decovery. ARTESIA DISTRICT AUG AUG 4 2015 Describe Cause of Problem and Remedial Action Taken.* RECEIVED Matway gasket was leaking on the heater treater. A buohe for Source of Received on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* RECEIVED A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the hest of my knowledge and understand that pursuant to NMOCD rules and regulationsal dive for usections for releases which may endanger		1 [
Type of Release Oil and Water Volume of Release NA Volume Recovered 71.328 BLS Source of Release Date and Hour of Decourance Date and Hour of Decourance 7/30/2015 Early Hours 7/30/2015 100 PM MST Manway Gasket Leak TYES, To Mom? TYES, To Mom? TWE Show MST 7/30/2015 2:00 PM MST Was Immediate Notice Given? Date and Hour of Decourance TYES, To Mom? NM OIL CONSERVATION Was a Watercourse Reached? Yes No Date and Hour 7/30/2015 2:00 PM MST NM OIL CONSERVATION If a Watercourse was Impacted, Describe Fully.* Date and Hour 7/30/2015 2:00 PM MST NM OIL CONSERVATION Manway gasket was leaking on the heater treater. A Bubit R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. RECEIVED Describe Area Affected and Cleanup Action Taken.* RECEIVED Nate was earlied by the wind. A double R vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Note of the ooil inside and outside of the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside the berm. Micro Blaze was sprayed onto the vegetation. Wewas and the a sample results a final report winds was	LatitudeLongitude												
Source of Release Date and Hour of Occurrence Date and Hour of Discovery Manway Gasket Leak TYES, To Whom? TYES, To Whom? Was Immediate Notice Given? If YES, To Whom? If YES, To Whom? By Whom? Bill Dougherty Date and Hour 7/02/015 2:00 PM MST NM OIL CONSERVATION Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ARTESTA DISTRICT Was a Watercourse was Impacted, Describe Fully.* If YES, Volume Impacting the Watercourse. AUG Describe Cause of Problem and Remedial Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* RECEIVED A double K vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. A double to water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double K vacuum truck sucked up all oil inside the berm and send the results to Hearter Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and mendiate of my knowledge and understand that pursuant to NMOCD rules and regulationsal field to adequately investigate and remediate copen	NATURE OF RELEASE												
Marway Gaster Leak 7/30/2015 Learly Hours 7/30/2015 1 00 PM MST Was Immediate Notice Given? Yes No Not Required If YES, To Mhom? Nim Oll. CONSERVATION By Whom? Bill Dougherty Date and Hour 7/30/2015 2:00 PM MST Nim Oll. CONSERVATION Was a Watercourse Reached? If YES, To Whom? ARTESTA DISTRICT If a Watercourse was Impacted, Describe Fully.* AUG 4005 Describe Cause of Problem and Remedial Action Taken.* RECEIVED Marway gaster was leaking on the heater treater. A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/3/2015. Describe Area Affected and Cleanup Action Taken.* RECEIVED Approx. 3.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. Ihreey certify had the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regort will be the origon size true of a C-141 report does not reliver the operator of liability.			Water										BLS
Yes No Not Required Heather Patterson with the OCD By Whon? Bill Dougherty Date and Hour 7/30/2015 2:00 PM MST NM OIL CONSERVATION Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ARTESIA DISTRICT If a Watercourse was Impacted, Describe Fully.* AUG 4 2015 Describe Cause of Problem and Remedial Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. Abuilto K Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* RECEIVED A double K vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* Action Taken.* A double K vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is mice and complete to the NMOCD marked as "Final Report" does not relieve the operator of liability should their operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. In a							7/30/2015	Early Hours					
By Whom? Bill Dougherty Date and Hour 7/30/2015 2:00 PM MST NM OIL CONSERVATION Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ARTESIA DISTRICT If a Watercourse was Impacted, Describe Fully.* AUG 4 2015 Describe Cause of Problem and Remedial Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. RECEIVED A Double R Vacuum track arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* A double R vacuum track arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* Approx. 3:52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. 1 hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform orreletive actions for re									OCD				(
If a Watercourse was Impacted, Describe Fully.* AUG 4 2015 Describe Cause of Problem and Remedial Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the bern. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* RECEIVED A double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the bern. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* Approx.3.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the herm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other tederal, state, or local laws and/or regulations. Signature: Quark Approved by							Date and Hour 7/30/2015 2:00 PM MST NM OIL CON						
If a Watercourse was Impacted, Describe Fully.* AUG 4 2015 Describe Cause of Problem and Remedial Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. ADuble R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* RECEIVED Aduble R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* Approx. 3.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other tederal, state, or local laws and/or regulations. Signature: Quell LONSERVATION DIVISION Signature: Approved by	Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse.						
Describe Cause of Problem and Remedial Action Taken.* RECEIVED Manway gasket was leaking on the heater treater. A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* A Double R Vacuum truck arrived on location Taken.* Approx. 5.32 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public headling investigate and remediate contamination that pose a threat to ground water, surface ware, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Quarket Approved by Environmental Specialist: Market Regulatory Analyst Approved by Environmental Specialist: E-mail Address:spresley@naguess.com Conditions of Approval	If a Watercou	Irse was Imn									A	UG A	2015
Manway gasket was leaking on the heater treater. A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* Approx. 5.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operators have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Signature: Approved by Environmental Specialist: Market as anyle for the soil and soft of the soil and for regulations. Conditions of Approval: Signature:	4 2015												
Manway gasket was leaking on the heater treater. A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* Approx. 5.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operators have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Signature: Approved by Environmental Specialist: Market as anyle for the soil and/or regulations. Conditions of Approval Expiration Date: Market as a	Describe Cause of Problem and Remedial Action Taken.*										FD		
A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on 7/31/2015. Describe Area Affected and Cleanup Action Taken.* Approx. 5:32 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Quality investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
Approx. 3.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. The acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Signature: OIL CONSERVATION DIVISION Printed Name: Sarah Prestey Approval Date: §15/15 Expiration Date: MA E-mail Address:spresley@naguss.com Conditions of Approval: Signation per O.C.D. Rules & Guidelint@gened Date: 8/4/2015 Phone: 432-682-4429 SubMit REWEDIATION BROPOSAL NO	A Double R Vacuum truck arrived on location at 5:15 PM. Sucked up all fluid inside the berm. Bill Dougherty sprayed micro blaze on the vegetation on												
Approx. 3.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind. A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation. We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remetiate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: Quark Laws and/or regulations. Signature: Quark Laws and/or regulations. Vittle: Regulatory Analyst E-mail Address:spresley@naguss.com Conditions of Approval: Title: Refuel Tapper 432-682-4429		a Affected a	nd Cleanup /	Action Ta	ken.*								<u></u>
We will take a sample of the soil inside and outside of the berm and send the results to Heather Patterson of the OCD. Once we have the sample results a final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Market Regulatory Analyst Approval Date: \$15115 E-mail Address:spresley@naguss.com Conditions of Approval: Bate: 8/4/2015 Phone: 432-682-4429	Approx. 3.52 bbls of oil and 66 bbls of water were released. A majority of the spill was contained within the berm, except for some oil spray that was carried by the wind.												
final report will be submitted. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: QUL CONSERVATION DIVISION Printed Name: Sarah Presley Approved by Environmental Specialist: Title: Regulatory Analyst Approval Date: \$\[0.5]{5}\$ Expiration Date: NA E-mail Address:spresley@naguss.com Conditions of Approval: Date: 8/4/2015 Phone: 432-682-4429	A double R vacuum truck sucked up all oil inside the berm. Micro Blaze was sprayed onto the vegetation.												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Sarah Presley Approval Date: \$15/15 E-mail Address:spresley@naguss.com Conditions of Approval: Date: \$44/2015 Phone: 432-682-4429													
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Sarah Presley Approval Date: \$15115 Title: Regulatory Analyst Approval Date: \$15115 E-mail Address:spresley@naguss.com Conditions of Approval: Atte: \$14/2015 Phone: 432-682-4429	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. Signature: OIL CONSERVATION DIVISION Signature: Approved by Environmental Specialist: Printed Name: Sarah Presley Approved by Environmental Specialist: Title: Regulatory Analyst E-mail Address:spresley@naguss.com Conditions of Approval: Date: 8/4/2015 Phome: 432-682-4429	public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability												
federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Signature: OIL CONSERVATION DIVISION Printed Name: Sarah Presley Approved by Environmental Specialist: Title: Regulatory Analyst Approval Date: \$1515 E-mail Address: Spresley@naguss.com Conditions of Approval: Date: \$8/4/2015 Phone: 432-682-4429	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health												
Signature: Signature: Signature: Signature: Approved by Environmental Specialist: Printed Name: Sarah Presley Approved by Environmental Specialist: Approved by Environmental Specialist: Title: Regulatory Analyst Approval Date: \$15115 Expiration Date: E-inail Address:spresley@naguss.com Conditions of Approval: Signediation per O.C.D. Rules & Guidelinesched Image: State	federal, state, or local laws and/or regulations.												
Printed Name: Sarah Presley Approved by Environmental Specialist: Title: Regulatory Analyst Approval Date: \$\begin{tabular}{lllllllllllllllllllllllllllllllllll							OIL CONSERVATION DIVISION						
Printed Name: Sarah Presley Image: Sarah Presley Title: Regulatory Analyst Approval Date: \$15115 E-mail Address:spresley@naguss.com Conditions of Approval: Date: 8/4/2015 Phone: 432-682-4429 UBMIT REMEDIATION PROPOSAL NO Image: Approval Provide	Signature: Xevallfusly												
E-mail Address:spresley@naguss.com Conditions of Approval: Date: 8/4/2015 Phone: 432-682-4429 Sumediation per O.C.D. Rules & Guidelin@ched Difference	Printed Name: Sarah Presley						Approved by	y Environmental	Speciali	^{st:}	$ \leq $	2~	
Date: 8/4/2015 Phone: 432-682-4429	Title: Regula	töry Analyst		Approval Da	ate: 8 5 15		Expiration	Date:	NA	3			
Date: 8/4/2015 Phone: 432-682-4429	E-mail Addro	ess:spresley@	@naguss.com	Conditions c	of Approval:								
Date: 3/4/2015 Phone: 432-082-4429 SUBMIT REMEDIATION PROPOSAL NO							amodiation per O.C.D. Rules & Guide integened						
					-082-4429	<u>.</u>	UBMIT R	EMEDIATION	V PHO	DOSAL I	άψ	1.0	D XIRS

Patterson, Heather, EMNRD

From: Sent: To: Subject: Attachments: Sarah Presley <spresley@naguss.com> Tuesday, August 04, 2015 3:58 PM Patterson, Heather, EMNRD RE: Aid State #10 Aid State #10.C-141.08 04 2015.pdf

Heather,

I have attached the C-141 for this spill. Please let me know if you would rather me send in the hard copy.

Thank you for your help!

Sarah Presley

Nadel and Gussman Permian, L.L.C. 601 N. Marienfeld, Suite 508 Midland, TX 79701 Ph: 432-682-4429 Fax: 432-682-4325 spresley@naguss.com

From: Bill Dougherty
Sent: Thursday, July 30, 2015 7:31 PM
To: 'heather.patterson@state.nm.us'
Cc: Bill Dougherty; Joel Martin; Mike McCurdy; Sarah Presley; Jason Hammons; Raven Vasquez
Subject: Aid State #10

Ms. Patterson these are the pictures from the spill on Aid State #10 if you will allow me to I would like to spray micro blaze on the vegetation that has the over spray. I have a sample kit coming from Trace Analysis to collect the samples for testing. I will give you a call first thing in the morning.

Thanks. Bill Dougherty Nadel and Gussman N.M. Field Superintendent 325-998-7107

1

ENVIRONME	INTAL RELEASE NOTIFICATION
Date:	Call-In Sheet Notice received by:
Name of Company/Phone #	Ail State #10 Facility Name
<u>30-015-38462 (najbe)</u> , <u>13</u> API# <u>Sec.</u> T	173 ASC. 7/30/15 (orlate 7/29/15) Township Range Date of Occurrence
<u>7/30/07</u> Date/Hour of Discovery Type of Release	
Briefly Describe Cause of Problem and action tak	ien: Heater Treater Manura
masker blev n	con: Heater Treater Manung Costly in lineal containment
- some onerspra Bill DougherAry MadelyG	y on partine (no pouliz)
Notice given by: Name/Company	Date/Hour Immediate Notice given
Date C-141 received:	814115 2RP-3185
**************************************	ARE NOTIFICATION Call-In Sheet Notice received by:
Name of Company/Phone #	Facility Name
Date of Occurrence Date/Hour of Fla	are Type of Release
Flared MCF Volume Volume Recover	 red
Briefly Describe Cause of Problem and action tak	ken:
Notice given by: Name/ Company	Date/Hour Immediate Notice given
Date C-141 received:	