

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

AB1530140875

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company Cimarex Energy		Contact Christine Alderman	
Address 600 N Marienfeld Ste 600 Midland TX		Telephone No. 432-853-7059	
Facility Name Hornsby 35 Fed 3H		Facility Type production	
Surface Owner Federal		Mineral Owner	API No. 30-015-42208

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	35	26S	27E	210	S	1310	W	Eddy

Latitude 32.0005684 Longitude -104.1651154

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 59 bbls	Volume Recovered 55 bbls
Source of Release 4" poly flow line	Date and Hour of Occurrence 7/26/15	Date and Hour of Discovery 7/26/15
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Shelly Tucker	
By Whom? Christine Alderman	Date and Hour 7/27/15 1:33 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

NA


Describe Cause of Problem and Remedial Action Taken.*

Poly line ruptured due to pressure. 45 bbls were contained within a lined containment and were recovered. 14 bbls were on location pad just outside of containment and 10 bbls were recovered.

Describe Area Affected and Cleanup Action Taken.*

Environmental consulting company (Diversified) will be on location to sample and develop work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Christine Alderman		Approved by Environmental Specialist: 	
Title: ESH Supervisor		Approval Date: 10/28/15	Expiration Date: N/A
E-mail Address: calderman@cimarex.com		Conditions of Approval: REMEDIAL ACTION PER O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 7/30/15 Phone: 432-853-7059		SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 11/20/15	

* Attach Additional Sheets If Necessary

NM OIL CONSERVATION
ARTESIA DISTRICT
OCT 27 2015

RECEIVED

2RP-3359

Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Tuesday, October 27, 2015 12:44 PM
To: Tucker, Shelly
Cc: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Gloria Garza
Subject: RE: Hornsby 35 Fed 3H (30-015-42208)
Attachments: Hornsby35Fed3H.doc

Here you go.

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982



From: Tucker, Shelly [mailto:stucker@blm.gov]
Sent: Tuesday, October 27, 2015 10:25 AM
To: Christine Alderman
Cc: mike.bratcher@state.nm.us; Patterson, Heather, EMNRD (Heather.Patterson@state.nm.us); Gloria Garza
Subject: Re: Hornsby 35 Fed 3H (30-015-42208)

I do not have a C-141 or a WP for this release...what is the status?

The BLM approval/acceptance does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular

stucker@blm.gov



On Mon, Jul 27, 2015 at 2:15 PM, Tucker, Shelly <stucker@blm.gov> wrote:
Thank you for your notification...

Sincerely,

Shelly J. Tucker

Environmental Protection Specialist
Bureau of Land Management

620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular

stucker@blm.gov



NOTE: BLM approval does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

On Mon, Jul 27, 2015 at 12:32 PM, Christine Alderman <calderman@cimarex.com> wrote:

Yesterday, 7/26/2015, we had a release at the above mentioned lease. A 4" poly flow-line ruptured near the transfer pump. The release was the result of a faulty check valve causing the line to overpressure.

A total of 59 bbls were released. 45 bbls were in a lined containment and were recovered. 14 bbls were just outside of the containment on the location pad, and 10 bbls were recovered.

A C-141 will be sent ASAP, and a work plan will be developed.

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982



Patterson, Heather, EMNRD

From: Christine Alderman <calderman@cimarex.com>
Sent: Monday, July 27, 2015 12:33 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov
Cc: Gloria Garza
Subject: Hornsby 35 Fed 3H (30-015-42208)

Yesterday, 7/26/2015, we had a release at the above mentioned lease. A 4" poly flow-line ruptured near the transfer pump. The release was the result of a faulty check valve causing the line to overpressure.

A total of 59 bbls were released. 45 bbls were in a lined containment and were recovered. 14 bbls were just outside of the containment on the location pad, and 10 bbls were recovered.

A C-141 will be sent ASAP, and a work plan will be developed.

Christine Alderman

ESH Supervisor – Permian Basin

Mobile: 432-853-7059

Office: 432-620-1982

